Appendix

Crash analysis



Inner Loop North Transformation Planning Study Crash reports were obtained from New York State Accident Location Information System (ALIS) data for the period between August 1, 2014 and July 31, 2019. The crash study limits include the Inner Loop (NYS Route 940T) along with its connecting ramps and the adjacent roadway network made up of Allen Street, Cumberland Street, Lyndhurst Street, Delevan Street, East Main Street, and Union Street.

Crashes are categorized as fatal, injury, property damage only (PDO) or non-reportable (NR). A crash is considered non-reportable if there is no personal injury and either:

- a) No motorist report was filed,
- b) No dollar value of vehicular damage was entered into the report, or
- c) The amount of vehicular damage did not exceed \$1,000.

A total of 2,290 crashes were received. A total of 895 were screened out because they fell outside the crash study limits. The remaining 1,395 crashes were reviewed, locations were checked for accuracy, and the location data were corrected as necessary. A total of 353 crashes either fell outside the analysis limits or occurred in a parking lot; therefore, 1,042 applicable crashes were documented during the 5-year study period. The number of crashes occurring within the study area and their location is summarized in Exhibit 1. A breakdown of crashes by severity is included in Exhibit 2. Exhibit 3 illustrates where crashes are clustered along the Inner Loop mainline and its ramps while Exhibit 4 shows the same information for the adjacent roadway network. Exhibits 5, 6, and 7 present a breakdown of crashes by Light Condition, Weather Condition, and Roadway Surface Condition.

Exhibit 1 Crash Summary by Location								
Location	Total	Percent						
Inner Loop Mainline (NYS Route 940T)	251	24%						
Inner Loop Ramps	109	11%						
Adjacent Roadway Network – Segments	53	5%						
Adjacent Roadway Network – Intersections	629	60%						
TOTAL	1,042	100%						

Exhibit 2 Crash Severity								
Severity Total Percent								
Fatal	0	0%						
Injury	192	18%						
Property Damage Only (PDO)	452	44%						
Non-Reportable (NR)	398	38%						
TOTAL	1,042	100%						

Exhibit 5 Crashes by Light Condition								
Light Condition Total Percent								
Daylight	748	72%						
Dark-Road Lighted	247	24%						
Dusk	24	2%						
Dawn	9	1%						
Dark-Road Unlighted	5	<1%						
Unknown	9	1%						
TOTAL	1,042	100%						

Exhibit 6 Crashes by Weather Condition								
Weather Condition Total Percent								
Clear	509	49%						
Cloudy	302	29%						
Rain	123	12%						
Snow	85	8%						
Sleet/Hail/Freezing Rain	8	1%						
Other	1	<1%						
Unknown	14	1%						
TOTAL	1,042	100%						

Exhibit 7 Crashes by Roadway Surface Condition								
Roadway Surface Condition Total Percent								
Dry	678	65%						
Wet	242	23%						
Snow/Ice	103	10%						
Slush	4	<1%						
Other	1	<1%						
Unknown	14	1%						
TOTAL	1,042	100%						

There were no fatalities during the study period. Less than 20% of the crashes occurring within the study limits resulted in at least one personal injury. The majority of crashes resulted in property damage only with a substantial number considered non-reportable. Most crashes occurred during daylight hours. Weather and its effect on pavement surface condition do not appear to have contributed substantially to the crash experience along the Inner Loop.

Exhibit 8, 9, and 10 present a breakdown of crashes by type. Each exhibit relays information on one of four locations: Inner Loop Mainline (NYS Route 940T), Inner Loop Ramps, Adjacent Roadway Network - Segments, and Adjacent Roadway Network - Intersections.

Exhibit 8 Crash Types – Inner Loop Mainline (NYS Route 940T)								
Crash Type Total Percent								
Rear End	98	39%						
Fixed Object	54	22%						
Overtaking	53	21%						
Other	41	16%						
Head On	3	1%						
Left Turn (Against Other Car)	1	<1%						
Right Angle	1	<1%						
TOTAL	251	100%						

A substantial number of mainline crashes occur along the Inner Loop just east of I-490. Many are rear ends and related to westbound evening peak period queuing (backups from I-490). Additionally, ponding under the Saint Paul Street, North Clinton Avenue, Joseph Avenue, and North Street bridges was noted to cause hydroplaning, resulting in collisions with other vehicles or fixed objects.

Exhibit 9 Crash Types – Inner Loop Ramps								
Crash Type Total Percent								
Fixed Object	52	48%						
Rear End	27	25%						
Overtaking	21	19%						
Other	6	6%						
Left Turn (Against Other Car)	1	1%						
Right Angle	1	1%						
Sideswipe	1	1%						
TOTAL	109	100%						

The majority of ramp crashes occur along the roadways connecting the Inner Loop and I-490: Ramp 490A (3, 3%), Ramp 490B (19, 17%), Ramp 490C (29, 27%), and Ramp 490D (31, 28%). The remaining 27 (25%) crashes are scattered across the rest of the corridor. Ramps SE and B did not have any recorded crashes during the 5-year study period.

Exhibit 10 Crash Types – Adjacent Roadway Network – Segments								
Crash Type Total Percent								
Overtaking	24	45%						
Rear End	15	28%						
Fixed Object	4	8%						
Other	4	8%						
Right Angle	4	8%						
Sideswipe	1	2%						
Unknown	1	2%						
TOTAL	53	100%						

Just over half (53%) of the crashes on the adjacent roadways occurred on the westbound segment of Cumberland Street between St. Paul and North Street. There was a notable crash experience in this area related to on-street parking. Collisions involved drivers pulling in and out of parking places.

Exhibit 11 Crash Types – Adjacent Roadway Network – Intersections									
Crash Type	Total	Percent							
Rear End	171	27%							
Right Angle	157	25%							
Overtaking	137	22%							
Left Turn (Against Other Car)	41	7%							
Other	32	5%							
Fixed Object	25	4%							
Bicycle	13	2%							
Pedestrian	12	2%							
Right Turn (With Other Car)	10	2%							
Left Turn (With Other Car)	8	1%							
Right Turn (Against Other Car)	7	1%							
Head On	6	1%							
Sideswipe	4	<1%							
Unknown	6	1%							
TOTAL	629	100%							

Rear ends, right angles, and overtaking crashes make up about two-third of the intersection crashes. These types of crashes are typical for urban intersections. A breakdown by location is included in Exhibit 12.

Exhibit 12 Intersection Crashes by Locat	ion	
Location	Total	Percent
Ramp P at Plymouth Street	3	<1%
Allen Street EB at Plymouth Street	2	<1%
Allen Street WB at Plymouth Street	8	1%
Allen Street EB at State Street	47	7%
Allen Street WB at State Street	41	6%
Allen St WB at Mill Street	2	<1%
Cumberland Street EB at St. Paul Street	63	9%
Cumberland Street WB at St. Paul Street	61	9%
Cumberland Street WB at Westcott Street	2	<1%
Cumberland Street EB at N. Clinton Avenue	42	6%
Cumberland Street WB at N. Clinton Avenue	35	5%
Cumberland Street EB at Joseph Avenue	18	3%
Cumberland Street WB at Joseph Avenue	37	5%
Cumberland Street WB at North Street	18	3%
Delevan Street at North Street	5	1%
Lyndhurst Street at North Street	4	1%
Lyndhurst Street at Scio Street	20	3%
Delevan Street at Scio Street	7	1%
Lyndhurst Street at Lays Aly	1	<1%
Lyndhurst at N. Union Street	4	1%
E. Main Street at University Avenue/Pitkin Street	16	2%
E. Main Street at University Avenue/Inner Loop	93	14%
E. Main Street at N. Union Street	57	8%
N. Union Street at University Avenue	40	6%
N. Union Street at Inner Loop	3	<1%
TOTAL	682	100%

Rear end and right angle collisions are the most common crash type and make up the majority of incidents at the intersections of Allen Street (both directions) and State Street. Crashes at the intersections of Cumberland Street with Saint Paul Street, East Main Street at University Avenue and the Inner Loop, East Main Street at North Union Street, and North Union Street at University Avenue are also similar. Crashes at those locations primarily involve overtaking, rear ends, and right angles. The intersection of eastbound Cumberland Street with North Clinton Avenue notably experiences overtaking, left turn (against another car), and right angle collisions. The left turn collisions may be related to the angled approaches, extensive set back to the stop line on the westbound approach, and the large number of lanes. Collectively, driver error (i.e. inattention, unsafe actions, improper movements) was listed as the leading contributing factor.


The NYSDOT identifies three categories of locations where safety is a concern based on a statistical analyses of accident history. The categories are:

- a) Priority Investigation Location (PIL) Location where there is a 99.9% level of confidence a problem exists. These locations have high crash rates. Typically, the rate is approximately two and one-half to three times greater than the statewide average rate for similar facilities. If the location is a specific intersection fulfilling the above criteria it is characterized as a Priority Investigation Intersection (PII).
- b) Safety Deficient Location (SDL) Location where there is a 90.0% level of confidence a problem exists. These locations have high crash rates that exceed the statewide average for similar locations. The only definitive difference between a site being characterized as an SDL and PIL is the level of confidence that a problem exists.
- c) High Accident Location (HAL) This is a combination of PIL and SDL locations.


NYSDOT Safety Information Management System (SIMS) reports for the Inner Loop (NYS Route 940T) from I-490 to its terminus at North Union Street were reviewed for the year 2019. The report listed no Priority Investigation Intersection (PIIs), Safety Deficient Locations (SDLs), or high accident locations (HALs) in the study area; however, there was one Priority Investigation Location (PIL) and eight Specialty PILs as summarized in Exhibit 13.

	Exhibit 13 Priority Investigation Locations (PILs) Summary									
Year	Location (Refe	rence Markers)	Reason(s)							
	Begins At	Ends At	Redsort(s)							
2019*	940T43011000	940T43011001	Snow/Ice/Slush Road, All F.O. and Run- Off Road, Speed Related							
2019*	940T43011002	940T43011005	Rear-End, Speed Related							
2019*	940T43011003	940T43011006	Aggressive Driving							
2019*	940T43011004 940T43011008		Large Truck							
2019*	940T43011005	940T43011007	Wet Road							
2019*	940T43011005	940T43011009	Speed Related							
2019*	940T43011007	940T43011013	Snow/Ice/Slush Road, All F.O. and Run- Off Road							
2019*	940T43011008	940T43011014	Right-Angle							
2019	940T43011010	940T43011014	Rear-End							
*Specia	alty Priori <mark>ty Invest</mark>	igation Location (P	IL) - Unusually high concentrations of							
specific	specific crash types									


Reference markers for the Inner Loop start at the interchange with I-490 and increase as one travels east. The majority of the PILs appear at the western end of the Inner Loop. The interchange ramps between the Inner Loop and I-490 are located in the PIL from 940T43011000 to 940T43011001. The PIL from 940T43011002 to 940T43011005 matches the rear-end pattern noticed on the raised section of the Inner Loop over State Street and Plymouth Avenue.




























TE 213 (9/79)													
COUNTY:	MONROE		P.I.N.:	NOT APPLICAB		ROUTE NO. OR					CASE No.:		
	TOWN			NOT THE LIGHT	INNER LOOP (NYS 940T) AND RAMPS					FILE		-	
	CITY				AT INTERSECTION WITH/OR BETWEEN:					BY:	PSC	_	
	VILLAGE OF	ROCHEST	ER		-	FROM I-490 INT	ERCHANGE TO	INNER LOOP TE	RMINUS AT N. UNION ST		DATE	5/13/2020	-
TIME PERIOD		FROM: 8/1/14	TO:	ENVIRONMENT Use Codes from at right) for these	n MV 104 (shown	Light Conditions: 1. Daylight 2. Dawn		Roadway Surface 1. Dry 2. Wet	ce Condition: Weather: 1. Clear 2. Cloudy				
		0/1/14	11211114	at righty for these	-	Dawn Dusk Dark Road Lig Dark Road Ur		3. Muddy 4. Snowlice 5. Slush 10. Other	3. Rain 4. Snow 5. Sleet/Hail/Fre 6. Fog/Smog/Sn 10. Other				
No. OF MONTH	IS:	6	0	S		SNOI					¹ Use Codes from	MV 104 Police Report	
CRASH No.	CASE No.	DATE	TIME	No. of VEHICLES	SEVERITY	LIGHT CONDITIONS	ROADWAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING FACTORS	DIRECTION	TYPE ¹	DESCRIPTION	REFERENCE MARKER
1	35355313	8/1/2014	8:36:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLOUDY	UNSAFE LANE CHANGE	SOUTH	OVERTAKING	VEHICLE#1 WAS SOUTHBOUND ON THE RAMP TO E MAIN ST. FROM THE INNERLOOP. VEHICLE#2 ALSO SOUTHBOUND ENTERED VEHICLE#1'S LANE AND STRUCK VEHICLE#1 ON THE LEFT SIDE.	
2	35361949	8/2/2014	11:40:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLOUDY	FOLLOWING TOO CLOSELY	NORTH	REAR END		
3	35355321	8/8/2014	8:10:00 PM	2	PROPERTY DAMAGE	DUSK	DRY	CLEAR	FOLLOWING TOO CLOSELY	WEST	REAR END		940T43011006
4	35380871	8/27/2014	5:18:00 PM	3	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	WEST	OTHER	Driver 1 skladd that she was west bound on the inner loop, stopped for stopped traffic ahead and was struck from behind by Vehicle 2. Driver 2 skladd that she stopped for Vehicle 1, was struck from behind by Vehicle 3 and was pushed into Vehicle 1. Driver 3 skladd that she was westound on the Inner Loop an uninvolved vehicle in front of her changed from the right to the left lane and was unable to shop before shiking Vehicle 2. There were on inturies or arrest. Vehicle 3 was kneed the John and Son	940T43011002
5	35388670	9/5/2014	8:01:00 AM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY, REACTION TO OTHER UNINVOLVED VEHICLE	EAST	REAR END	Driver 2 skled that she was easbound on the Inner Loop in the right lane, an uninvolved vehicle in front of her made an atrupt lane change to avoid another uninvolved stopped vehicle ahead, Vehicle 2 stopped and was struck from behind by Vehicle 1. Driver 1 stated that he was easbound on the Inner Loop, Vehicle 2 stopped abruptly and was unable to stop Vehicle 1 before striking Vehicle 2. There were no Indires slows or arrests.	940T43011004
6	35398836	9/10/2014	3:25:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLOUDY	UNSAFE LANE CHANGE	EAST	OVERTAKING	OP V-2 WAS E/B ON THE INNER LOOPIN THE LEFT LANE. OP- V1 WAS ALSO E/B ON THE INNER LOOP IN THE RIGHT LANE. OP V-1 ATTEMPTED TO CHANGE LANES AND STRUCK V-2.	940T43011003
7	35397330	9/13/2014	10:45:00 AM	1	PROPERTY DAMAGE	DAYLIGHT	WET	RAIN	UNSAFE SPEED	WEST	OTHER	PDAA - OPV-1 TRAVELING INNER LOOP WB TO 490 WB LOST CONTROL OF V-1 ON 490 WB. V-1 LEFT THE ROADWAY AND STRUCK GUIDE RAIL END ON NORTH SHOULDER. NYS DOT NOTFIED. CLOSED.	490143022026
8	35430576	10/7/2014	3:35:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLOUDY	FOLLOWING TOO CLOSELY	WEST	REAR END	V1 traveling westbound on the Innerloop in the City of Rochester was following too closely behind V2. V2 stopped quickly due to heavy traffic. V1 then collided with V2 and came to rest in the roadway.	940T43011004
9	35436083	10/7/2014	11:12:00 PM	2	PROPERTY DAMAGE	DARK-ROAD LIGHTED	WET	RAIN	UNSAFE SPEED	WEST	OVERTAKING	OP V-1 WB NNER LOOP MIDDLE LANE. OP V-2 WB NNER LOOP MIDDLE LANE. V-2 PASSES V-1 IN PASSING LANE STRKING V-1 N LEFT SIDE OF VEHICLE & BATTLE THEN LEAVES THE SCENE. OP V-1 UNABLE TO PROVIDE ANY INFORMATION ON STRKING VEHICLE. MEMBER CHECKED THE AREA WITH NREATIVE RESULTS. CRI.	940T43011011
10	35426488	10/9/2014	4:52:00 PM	3	PROPERTY DAMAGE AND INJURY	DAYLIGHT	DRY	CLOUDY	FOLLOWING TOO CLOSELY	WEST	OTHER		940T43011004
11	35449657	10/22/2014	1:56:00 AM	2	PROPERTY DAMAGE	DARK-ROAD LIGHTED	WET	CLOUDY	FOLLOWING TOO CLOSELY	WEST	REAR END		940T43011005
12	35444913	10/24/2014	5:24:00 PM	1	PROPERTY DAMAGE AND INJURY	DAYLIGHT	DRY	CLOUDY	FOLLOWING TOO CLOSELY	WEST	OTHER	VEHICLE! WAS WESTBOUND ON THE INVERLOOP. UNINVOLVED VEHICLE PUT ON THE BRAKES ABRUBILLY WHICH FORCED VEHICLE!! TO PUT ON HIS BRAKES. OPERATOR OF V-1 LOST CONTROL OF VEHICLE AND STRUCK PAVEMENT CAUSING DAMAGE TO RIGHT SIDE OF MOTORCYCLE.	940T43011006
13	35447752	10/27/2014	5:42:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	SOUTH	REAR END	V1 rightlane of Inner Loop, Rt 490 W/B, C/Rochester, approximately 0.5 mi from Rt 490, and slopped in taffic. V2 Operator failed to observe slopped traffic and rear ended V1, causing minor damage to the rear of V1 and the front of V2.	940T43011004
14	35455062	11/2/2014	1:45:00 AM	1	PROPERTY DAMAGE	DARK-ROAD LIGHTED	WET	CLOUDY	UNSAFE SPEED	EAST	OTHER	V-1 traveling to fast going around the curve loses control and strikes cement barrier on 490 east bound to the innerloop. No injuries, V-1 towed to John and Sons.	490143022027
15	35464069	11/9/2014	3:15:00 PM	2	NUURY	DAYLIGHT	DRY	CLOUDY	UNSAFE SPEED	EAST	REAR END	V-1 AND V-2 TRAVELING E/B ON THE INNER LOOP IN THE CITY OF ROCHESTER. V-1 IN THE FAR RICH IDRIVING LAIR. COMES AROUND BLIND CURVE APPROACHING THE SCO ST AND UNIVERSITY AVE EXIT RAMP. V-2 ALSO IN THE RIGHT LAIR AND ACCORDING TO WITHOUSESS AT THE SCENE. TRAVELING AT A HIGH HATE OF SPEED AROUND THE BILIND CURVE IS UNIVERSITY AND EXISTENCE STATEMENT OF SECRET RANGE OF THE SINDRUCT OF STREED THE LIGHT AND SESSEMENT SECRET ALL INCHEST ASSEMENT DAMAGING SAME. DRIVER OF V-2 AND PASSENGER FALL OFF THE BOTTORCYCLE AST IF ALLS TO THE LEFT AND SLIDES APPROXIMATELY 20 FEET E/B ON THE ROADWAY, MALE DRIVER OF V-2 AND FEMALE PASSENGER ARE TRAVENOTED TO STRONG HOSPITAL VAR RURAL METRO AMBULANCE. DRIVER OF V-2 SUSTAINS INJURY TO HIS CLAYCLE AND VARIOUS SCRAPES AND BRUISES. FEMALE PASSENGER OF V-2 SUSTAINS INJURYS TO HER LEFT THIMBS AND PANT OF HER CHEST. NO NUTURES TO DRIVER OF V-1 REPORTED. NO TOWS NECESSARY, EXCHANGE OF INFORMATION FACLITATED. DRIVER OF V-2 SSUED VARBOUS THANDS AND THE CHEST. THE COLOSELY, AND THE MOST SECRET OF COLOSELY, AND THE HIS OFFICE SECRET OF COLOSELY, AND THE THE SECRET SECRED. SECRET OF COLOSELY, AND THE THRESS PECH DEB. WITHESS THE METHESS THANDS AND THE WITHESS TO HER LEFT THANDS AND THE THRESS PECH DEB. WITHESS THE WITHESS THANDS AND THE SESTER OF THE SESTER OF WITHESS TO HER LEFT THANDS AND THE THRESS SECRED.	940T43011015

TE 213 (9/79)						ROUTE NO. OR	CTDEET NAME						
COUNTY:	MONROE		P.I.N.:	NOT APPLICAB	LE	INNER LOOP (N					CASE No.:		_
	TOWN CITY					AT INTERSECT					FILE: BY:	PSC	-
	VILLAGE OF	ROCHESTI	ER		_				RMINUS AT N. UNION ST		DATE:		-
TIME PERIOD		FROM: 8/1/14	TO: 7/31/19	ENVIRONMENT Use Codes from at right) for these	n MV 104 (shown e categories	Light Conditions:	jhted	Roadway Surfar 1. Dry 2. Wet 3. Muddy 4. Snowlice 5. Slush 10. Other					
No. OF MONTH	S:	6	0	S		ONS					¹ Use Codes from	MV 104 Police Report	
CRASH No.	CASE No.	DATE	TIME	No. of VEHICLES	SEVERITY	LIGHT CONDITIONS	ROADWAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING FACTORS	DIRECTION	TYPE ¹	DESCRIPTION	REFERENCE MARKER
16	35465277	11/11/2014	7:50:00 AM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY, REACTION TO OTHER UNINVOLVED VEHICLE	SOUTH-WEST	REAR END	V-1 and V-2 both traveling southwest bound in the left hand lane on the Inner Loop West. V-1 was haveling behind V-2. An uninvolved vehicle halvas in front of V-2 came to a sudden stop due to a plastic bucket that entered the roadway in front of that vehicle. V-2 abrupply put on his brakes to avoid rear ending the uninvolved vehicle. V-1 attempted to move into the right lane to avoid V-2 butwas unable to do so in time and V-1 rear ended V-2 custings had dramane.	940T43011006
17	35567118	11/18/2014	8:00:00 AM	1	PROPERTY DAMAGE	DAYLIGHT	WET	CLEAR	UNSAFE SPEED	WEST	OTHER	V1 was westbound on the Innerloop in the C/Rochester when driver 1 lost control of V1 due to the icy slippery road conditions	940T43011001
18	35569271	11/20/2014	10:20:00 PM	1	PROPERTY DAMAGE AND INJURY	DARK-ROAD LIGHTED	DRY	CLOUDY	REACTION TO OTHER UNINVOLVED VEHICL	WEST	OTHER	and shuck the curb on the right side of the road. Closed V-1 tavelling west bound on the inner loop, is cut off by unknown webicle, OP V-1 loses control and strikes guardrail causing damage to the vehicle. OP V-1 was unable to give a vehicle description of vehicle that cut her off. OP V-1 was transported to	940T43011010
19	35493844	11/27/2014	6:09:00 AM	1	PROPERTY DAMAGE	DARK-ROAD LIGHTED	SNOW/ICE	SNOW	UNSAFE SPEED	WEST	OTHER	Stron Dissolal. Case closed YI WAS WEST BOUND ON THE INNERLOOP NEAR ST PAUL ST N THE CIPROCHESTER. DRIVER I STATED THAT SHE LOST CONTROL OF YO DUE TO THE EVS SNOWLY ROAD CONDITIONS WHICH CAUSED HER TO SLOE NITO THE GUIDE RAIL ON THE LEFT SHOULDER, WHICH THEN PENIN YI AROUND CAUSING VI TO STRIKE THE GUIDE RAIL AGAIN WITH THE REAR PASSENGER BUMPER BEFORE COMING TO REST IN THE RIGHTLAIRE. CLOSED.	940T43011008
20	35489480	11/27/2014	11:43:00 AM	1	PROPERTY DAMAGE	DAYLIGHT	WET	CLOUDY	UNSAFE SPEED	NORTH-EAST	OTHER	V-1 taveling easton the Innerloop, right lane, from I-490 east bound. Due to speed too fast and a bald front driver&aposs: side front tire, V-1 lost control on the wet roadway and struck the concrete barrier on the south side of the roadway. V1 TRAVELING WEST BIOUND IN THE RIGHT LANE ON THE	940T43011001
21	35499990	11/29/2014	4:01:00 AM	1	PROPERTY DAMAGE	DARK-ROAD UNLIGHTED	DRY	CLOUDY	UNSAFE SPEED	WEST	OTHER	INNER LOOP IN THE CITY OF ROCHESTER INTOXICATED PASSENGER STATES THE OPERATOR OF V1 FLED THE SCENE IN AN UNKNOWN DIRECTION. PASSENGER COULD NOT PROVIDE NAME, AGE, CONTRACT NUMBER. OR DESCRIPTION OF THE DRIVER PASSENGER STATED THE DRIVER AND HIM WERE COMING FROM A PARTY WHERE BOTH PARTES HAD BEEN DRINKING ALCOHOLIC BEVERAGES AND THE REASON HE FLED WAS BECAUSE HE BELEVED HE WAS INTOXICATED. PASSENGER STATED V1 LOSES CONTROL DUE TO UNSAFE SPEED AND POSSBUE ALCOHOL INVOLVEMENT NO DAMAGE TO CONCRETE	940T43011008
22	35501879	12/4/2014	9:27:00 AM	1	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	UNSAFE SPEED	NORTH-WEST	OTHER	BARDER NO NUIDIES. 1- Taveling in anothwest direction in the let hand tane on the Inner Loop West to 1490 West. Op of V-1 tooses control of the webtile and tipes of the roadway on the northeast side and strikes a light pole with the rear of the vehicle and then strikes a tree causing said damage to V-1 and causing the light pole to come down. Op of V-1 stated that the was traveling in the let thand lane and there was a wehicle in front of him that suddenly start to slow down and the was unable to slow down in time so he put on the brakes and changed lanes. He stated the put on the brakes at the same time he was changing lanes and the car spun out. Monroe County Department of Environmental Services was notified of the	940T43011002
23	35515866	12/10/2014	6:00:00 PM	1	PROPERTY DAMAGE	DARK-ROAD LIGHTED	SNOW/ICE	SNOW	REACTION TO OTHER UNINVOLVED VEHICL	WEST	OTHER	Doper VI on the ramp from the Inner Loop, merging to west bound 1490. Oper VI or the ramp from the Inner Loop, merging to west bound 1490. Oper VI states she observed a plow fruck very close to her on 1490 and a large amount of snow hen covered her windshield. Oper VI states as she was momentarily unable to see her vehicle struck something and sustained damage. lobserved her vehicle in he middle of the roadway when larned on scene and her front bumper was behind her vehicle on the ground. The appearance of the bumper did not indicated a front impact but that something to the vehicle cought the bumper and tore it off.	490l43022026
24	35548807	12/10/2014	11:41:00 PM	1	PROPERTY DAMAGE	DARK-ROAD LIGHTED	SNOW/ICE	SNOW	UNSAFE SPEED	EAST	OTHER	V-1 east Inner Loop ramp from I-490 E/B Operator lost control of V- 1 and lelf roadway striking light pole causing damage io both pole and V-1. No injury reported. Vehicle removed by John and Son. RGE notified and responded in regards to pole damge.	940T43011002
25	35509613	12/11/2014	2:08:00 PM	1	PROPERTY DAMAGE	DAYLIGHT	SLUSH	CLOUDY	UNSAFE LANE CHANGE	EAST	OTHER	V-1 EAST BOUND 1490. OP V-1 MOVED FROM CENTER RIGHT LANE THROUGH HAZARDOUS MARKINGS AT EXIT RAMP TO MINER LOOPDOWNTOWN. HAZARDOUS MARKING COVERED WITH HEAVY SNOW, V-1 SLD INTO CRASH CUSHION AT END OF GUIDE RAIL CAUSING DAMAGE TO V-1 RIGHT FRONT END AND CRASH CUSHION.	490143022025
26	35519395	12/19/2014	11:40:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	WET	CLOUDY	PASSING OR LANE USAGE IMPROPERLY	WEST	OVERTAKING		
27	35528523	12/24/2014	9:59:00 AM	2	NON- REPORTABLE	DAYLIGHT	WET	RAIN	UNSAFE LANE CHANGE	WEST	OVERTAKING	V-1 W/B ON THE INNER LOOP BETWEEN ST PAUL ST AND STATE STREET EXITS IN THE CITY OF ROCHESTER. V-1 IN THE STREET EXITS IN THE CITY OF ROCHESTER. V-1 IN THE STREAT EXIT LANE TOWARD 4-09 GASTBOUND. V-2 EXITING THE ST PAUL ST OFF. RAMP TO W/B INNER LOOP, MOVES ACROSS CENTER LANE INTO FAR LEFT LANE. DRIVER OF V-2 ACROSS CENTER LANE INTO FAR LEFT LANE. DRIVER OF V-2 AMOVES THAT SHE DO NOT SEE V-1 AS SHE ATTEMPTED TO MOVE INTO THE LANE. V-2 STRIKES V-1 IN THE REAR PASSENGER QUARTERPANEL CAUSING DAMAGE TO SAME. V 2 SUSTAINS DAMAGE TO THE DRIVER SIDE FRONT OLUARTERPANEL AND LIGHT ASSEMBLY. NO INJURIES. NO TOWNS REQUIRED DRIVER OF V-2 SUSUE DITT FOR VIT. 1128A MOVED FROM LANE UNSAFELY. EXCHANGE OF INFORMATION FACILITATED AT THE SCENE. ACCIDENT REPORT COMPLETED AND SUMMITTED C.BL.	Q40T43011005

TE 213 (9/79)						ROUTE NO. OR	CTDEET MANG						
COUNTY:	MONROE		P.I.N.:	NOT APPLICAB	LE		YS 940T) AND F				CASE No.:		
	TOWN		•								FILE:	-	-
	CITY VILLAGE OF	ROCHESTI	ER			AT INTERSECT					BY: DATE:	PSC 5/13/2020	-
					-				RMINUS AT N. UNION ST				-
TIME PERIOD		FROM: 8/1/14	TO: 7/31/19	ENVIRONMENT Use Codes from at right) for these	n MV 104 (shown e categories	Light Conditions: 1. Daylight 2. Dawn 3. Dusk 4. Dark Road Lig 5. Dark Road Ur	ghted	Roadway Surfar 1. Dry 2. Wet 3. Muddy 4. Snowlice 5. Slush 10. Other	ce Condition: Weather: 1. Clear 2. Cloudy 3. Rain 4. Snow 5. SleeVHaWFre 6. Fog/Smog/Sr 10. Other				
No. OF MONTH	S:	6	0	S		ONS					Use Codes from	MV 104 Police Report	
CRASH No.	CASE No.	DATE	TIME	No. of VEHICLES	SEVERITY	LIGHT CONDITIONS	ROADWAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING FACTORS	DIRECTION	TYPE ¹	DESCRIPTION	REFERENCE MARKER
28	35548285	12/30/2014	8:18:00 AM	1	PROPERTY DAMAGE	DAYLIGHT	SNOW/ICE	SNOW	UNSAFE SPEED	WEST	OTHER	VI WAS ON THE EASTBOUND ON RAMP TO 1490 FROM THE WESTBOUND INNERLOOP IN THE CROCHESTER WHEN DRIVER STATED THAT HE LOST CONTROL OF VI ON THE ICY SNOW COVERED ROADWAY WHICH CAUSED VI TO STRKE THE GUIDE RAN ON THE RICHT SHOULDER. SPIN BOD EGGREES, AND THEN SLIDE ACROSS THE RAMP BEFORE STRKING THE LEFT SHOULDER GUIDE RAM. NO DAMAGE WAS DONE TO THE GUIDE RALS. CLOSED.	940T43011001
29	35546007	12/30/2014	3:40:00 PM	1	PROPERTY DAMAGE	DAYLIGHT	DRY	CLOUDY	UNSAFE SPEED	EAST	OTHER	V-1 EB INNER LOOP WHEN OPERATOR STATES SHE TRED TO CHANGE BITO THE REHT LANE WHEN SHE TURNED THE VEHICLE RIGHT THE VEHICLE WINT SHARPLY TO THE LEFT INPACTING THE GUIDE RAIL. V-1 THEN CROSSED THE INNER LOOP IMPACTING AN EARTH EMBANKMENT ON THE SOURT SIDE OF THE INNER LOOP. THE OPERATOR STATED V-1 HAD FAILED INSPECTION FOR A STEERING PROBLEMS ON 12/20/14. DOT NOTFED BY MONROE COUNTY 911 OF THE GUIDE RAIL DAMAGE. NO INJURY	940T43011010
30	35572933	1/16/2015	2:45:00 PM	1	PROPERTY DAMAGE	DAYLIGHT	SLUSH	CLOUDY	UNSAFE SPEED	WEST	OTHER	V-1 WEST BOUND MERGING ONTO INNER LOOP WEST FROM SCIO ST RAMP. V-1 WHILE ACCELERATING LOST TRACTION ON SLUSHYS HOULDER OP V-1 WHILE ATTEMPTED TO CORRECT FISHTAL DROVE OFF NORTH SHOULDER STRIKING SIGN POST. V-1 CONTINUED PAST POST INTO CONCRETE WALL WITH RIGHT FROM TEMBERBUMPER.	940T43011011
31	35579126	1/27/2015	8:45:00 AM	1	PROPERTY DAMAGE	DAYLIGHT	SNOW/ICE	SNOW	UNSAFE SPEED	EAST	OTHER	V-1 EAST BOUND ON INNER LOOP ON SLUSHY/SNOWY ROADWAY. V-1 LOST TRACTION SLIDING INTO NORTH BARRER WITH LEFT FRONT, V-1 DEFLECTED SOUTH OFF BARRER ACROSS BOTH LANES INTO SOUTH BARRIER WITH V-1 & Apply S. RIGHT FRONT. NO OBSERVABLE DAMAGE TO BARRIER.	940T43011004
32	35579121	1/27/2015	10:04:00 AM	1	PROPERTY DAMAGE	DAYLIGHT	SNOW/ICE	CLOUDY	UNSAFE SPEED	EAST	OTHER	VEHICLE#1 WAS EASTBOUND ON THE INNERLOOP. OPERATIOR OF V-1 LOSES CONTROL OF VEHICLE AND STREES BARRIER ON WEST SHOULDER CAUSING DAMAGE TO LEFT FRONT BUMBER OPERATOR OF V-1 ATTEMPTS TO CORRECT VEHICLE BUT IN THE PROCESS LOSES CONTROL ACADA NOS TRIKES BARRIER ON AEST SHOULDER CAUSING DAMAGE TO RIGHT-FRONT PANEL AND RIGHT TAIL-LIGHT.	940T43011004
33	35576003	1/28/2015	1:20:00 AM	1	PROPERTY DAMAGE	Dark-road Lighted	DRY	CLEAR	UNSAFE SPEED	EAST	OTHER	OP V-1 EB NNER LOOP, OP V-1 TRAVELS OF HORTH SHOULDER STRAMEG BARRER & ABM; COMING TO REST IN ROADWAY CBL Ticket Ssued: AA HERNAMDEZ Driver of vehicle number (1) tickets. Ticket Number: M2103ZSDH3 Vloidion: 1180A Ticket Number: M2103ZSDH0 Violation: 1128A Ticket Number: M2103ZS10P Violation: 5911 Tal Ticket Number: M2103ZS143 Vololation: 5901 Ticket Number: M2103ZSTGV Vloidion: 6001A Ticket Number: M2103ZSTGV Violation: 11923.	940T43011013
34	35575958	1/28/2015	4:00:00 AM	1	PROPERTY DAMAGE AND INJURY	DARK-ROAD LIGHTED	DRY	CLOUDY	ALCOHOL INVOLVEMENT	WEST	OTHER	Unit I wesbound on Inner Loop in the City of Nochesler, in he rightlane. Unit I swild the roadway at the intersection of the ramp to Joseph Ave., shiking the guard rail abutment. Damage to enfre fontend of unit I and abutment. DOT notified of damage. East Ave. Auto lowed to kip pound. Ticket Issued: RICARDO J RAMOS Driver of vehicle number (I) lickets. Ticket Number: M2103Z5728 Violation: 11923 Ticket Number: M2103Z58RC Violation: 1128D Ticket Number: M2103Z5926 Violation: 1128A Ticket Number: M2103Z5955 Violation: 11941B Ticket Number: M2103Z5KRC Violation: 1180A.	940T43011011
35	35594961	2/6/2015	8:45:00 AM	1	NON- REPORTABLE	DAYLIGHT	SNOW/ICE	CLOUDY	UNSAFE SPEED	EAST	OTHER	OF V-1 TRAVELING EIB ON NINERLOOP AFTER EXTING OFF INTERSTATE 490 WIB ATEXT 1 (INNINERLOOP) IN THE CITY OF ROCHESTER. DUE TO SLIPPERY CONDITIONS AND EXCESSIVE SPEED, OP V-1 LOST CONTROL SPINNING CLOCKWES OF THE ROADWAY ON TO THE NORTH SHOULDER. V-1 THEN STRUCK A DELINEATOR POST CAUSING DAMAGE TO POST AND V-1. NO INJURIES REPORTED AT SCEINE	940T43011003
36	35610232	2/13/2015	7:45:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	SNOW/ICE	CLOUDY	FOLLOWING TOO CLOSELY	WEST	REAR END	V-1 DIRECTLY BEHIND V.2 ON THE INNER LOOP WEST AT STATE STON ICY ROADWAY. V.2 SLOWING DUE TO SLOWER TRAFFIC AHEAD. V-1 UIMABLE TO AVOID V.2 FOLLOWING TOO CLOSELY FOR CONDITIONS. OP V-1 ATTEMPOTS TO PULL TO LETT DAVID V.2 BUT STRKES V.2 IN LEFT REAR BUMPER WITH V-1 RIGHT FRONT BUMPER.	940T43011004
37	35608499	2/13/2015	2:26:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	UNSAFE LANE CHANGE	WEST	REAR END	V-1 driving West bound on the liner loop gets cut off by uninvolved vehicle in the center lane makes lane change into left lane. V-2 strikes the rear end of v-1 with the front end of v-2 causing minor rear end damage to v-1 and heavy front end damage to v-2.	940T43011006
38	35614639	2/14/2015	3:47:00 PM	1	PROPERTY DAMAGE	DAYLIGHT	SNOW/ICE	CLOUDY	UNSAFE SPEED	EAST	OTHER	VEHICLE#I WAS EASTBOUND ON THE INNERLOOP. OPERATOR OF V-1 LOSES CONTROL OF VEHICLE AND STRIKES SNOWBANK ON SOUTH SHOULDER CAUSING DAMAGE TO FRONT-END.	940T43011012
39	35614107	2/20/2015	8:23:00 AM	1	PROPERTY DAMAGE	DAYLIGHT	SNOW/ICE	SNOW	REACTION TO OTHER UNINVOLVED VEHICL	EAST	OTHER	VI was taveling the tiner Loop E/B in the right lane. The uninvolved vehicle was taveling the Inner Loop E/B in the left lane and cut in front of VI. OP/VI altempted to avoid the uninvolved vehicle and lost control. VI spun out and hit the left side barrier.	940T43011005

TE 213 (9/79)						ROUTE NO. OR	CTDEET NAME						
COUNTY:	MONROE		P.I.N.:	NOT APPLICAB	LE	INNER LOOP (N					CASE No.:		_
	TOWN CITY					AT INTERSECT					FILE: BY:		_
	VILLAGE OF	ROCHESTI	ER						RMINUS AT N. UNION ST		DATE:		-
TIME PERIOD		FROM: 8/1/14	TO: 7/31/19	ENVIRONMENT Use Codes from at right) for these	n MV 104 (shown e categories	Light Conditions: 1. Daylight 2. Dawn 3. Dusk 4. Dark Road Lig 5. Dark Road Un	hted	Roadway Surface 1. Dry 2. Wet 3. Muddy 4. Snowlice 5. Slush 10. Other	ce Condition: Weather: 1. Clear 2. Cloudy 3. Rain 4. Snow 5. Sleet/Hall/Fre 6. Fog/Smog/Sr 10. Other				
No. OF MONTH	S:	6	0	ES		TIONS						MV 104 Police Report	
CRASH No.	CASE No.	DATE	TIME	No. of VEHICLES	SEVERITY	LIGHT CONDITIONS	ROADWAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING FACTORS	DIRECTION	TYPE ¹	DESCRIPTION	REFERENCE MARKER
40	35630543	2/22/2015	7-28:00 AM	2	PROPERTY DAMAGE AND NJURY	DAYLIGHT	WET	CLOUDY	ALCOHOL INVOLVEMENT	EAST	SIDESWIPE	VI WAS TRAVELING EIR ON THE NINEL LOOP WIR ON RAMP FROM EAST MAN STREET IN THE WRONG DIRECTION. V2 WAS TRAVELING WIR ON THE INNER LOOP WIR ON RAMP FROM EAST WAS TRAVELING WIR ON THE INNER LOOP WIR ON RAMP FROM EAST MAIN STREET. OPERATOR OF V2 STATES SHE OBSERVED V1 TRAVELING IN THE WRONG DIRECTION COMING STRAGHT ON AT HER. OPERATOR V2 SWEEVED TO THE RIGHT BUT WAS UNABLE TO AVOID COLLISION WITH V1. OPERATOR OF V1 WAS UNCLEAR WHAT HAPPENED OR WHAT FROAD HE WAS ON. OPERATOR OF V1 WAS SAMESTED FOR DRIVING WHE E NTOWCATED WITNESS 1 NSBET, ANDREW E 340 RUTGERS #050 ROCHESTER NY 14607 7165729522 WITNESS 2 NSBET, NIKKIR 2340 RUTGERS APT505 ROCHESTER NY LOOP TICKED WITNESS 1 NSBET, LOWER WAS UNDER WITNESS W	
41	35650746	3/12/2015	5:14:00 AM	1	PROPERTY DAMAGE	DARK-ROAD LIGHTED	WET	RAIN	UNSAFE SPEED	EAST	OTHER	OP V-1 Faveling EB on the Inner Loop approaching SL Paul Blvd when he loses contol of V-1. OP V-1 was taveling to loo tast for conditions and is unable to regain control of V-1. The puide rail causing heavy damage to the front end of V-1. The guide rail causing heavy damage is to the front end of V-1. The guide rail did not sushin any damage as a result of the contact. OP V-1 contacts OP1 and advises hem than he and been in an accident. OP V-1 then leaves the vehicle at the scene. After several altempts to contact the operator by phone, he finally answers and advises that he would be returning to the scene of the accident within 15 minutes. OP V-1 never returned to the scene and the vehicle was removed from the scene by East-Max Auth and taken to the CROchester Pound. No injuries were reported as a result of his accident.	940T43011007
42	35660684	3/22/2015	9:00:00 AM	1	PROPERTY DAMAGE	DAYLIGHT	SNOW/ICE	SNOW	UNSAFE SPEED	EAST	OTHER	Diver 1 saled that he was east bound on the 1490 East Entrance Ramp from the hiner Loop, lost control on the snow covered road and struck a guard rail. Driver 1 returned to his nearby residence to report the incident because the collision occurred in a hazardous location. There were no injuries, tows, or arrests. There was no damane to the quard rail.	940T43011000
43	35689622	4/16/2015	7:50:00 AM	1	PROPERTY DAMAGE AND INJURY	DAYLIGHT	DRY	CLEAR	UNSAFE LANE CHANGE	EAST	OTHER	V-1 EAST BOUND RIGHT LANE INNER LOOP MOVES INTO AND THROUGH LEFT LANE STRIKING MORTH GUIDE RAIL WITH LEFT FRONT BUMPER. V-1 SPINS APPROX. 180 DEGREES BACK ACROSS BOTH LANES STRIKING A DILINEATOR POST ON SOUTH SHOULDER WITH REAR OF V-1 COMING TO REST FACING WEST ON GRASS SHOULDER. 'OP V-1 HAS DJ PERMIT ISSUED NOVEMBER 2014.	940T43011007
44	35691629	4/16/2015	8:00:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	UNSAFE LANE CHANGE	EAST	OVERTAKING	V-1 AND V-2 E/B INNER LOOP AT THE SCIO EXIT RAMP WHEN OPERATOR OF V-2 WENT TO CHANGE LANES STATING HE DID NOT SEE V-1 SINCE IT WAS IN HIS BLIND SPOT IMPACTING V-1 AND CAUSING DAMAGE TO V-1. NO TOW NO INJURY	940T43011012
45	35704947	4/18/2015	3:40:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY, REACTION TO OTHER UNINVOLVED VEHICLE	WEST	REAR END	OP V-1 taveling behind V-2 approaching the I-490 EastWest spilt. OP V-2 reports that he is slowing down at the interchange to allow an uninvoked vehicle merge in bit is lane. When OP V-2 was slowing down, OP V-1 is not able to slow down in time and collides with the rear of V-2. OP V-1 is forced to the ramp for I-490 East result of the accident and is able to get this vehicle off I-490 at South ave. V-2 was located at the offramp of I-490 WB at Ames St. There were no further. Shat were reported as a result of the accident and both vehicles were lowed from the scene.	
46	35693885	4/20/2015	5:27:00 PM	2	INJURY	DAYLIGHT	WET	RAIN	FOLLOWING TOO CLOSELY	EAST	REAR END	UNIT 1 TRAVELING EASTBOUND ON INNER LOOP RAMP TO E. MAIN ST BEHIND UNIT 2. UNIT 2 DRIVER IS UNIS QUICKLY FOR LINE OF TRAFFE S STOPPED AHEAD OF HER AND UNIT 1 STRUCK UNIT 2 IN THE REAR, CAUSING DAMAGE TO REAR OF UNIT 2 AND FRONT OF UNIT 1. DRIVER OF UNIT 2 COMPLAINED OF MION RICE YAM, AND TRANSPORTED TO ROCHESTER GENERAL HOSPITAL VIA RURAL METRO.	940T43011014
47	35738382	5/13/2015	4:47:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	DRIVER INATTENTION, REACTION TO OTHER UNINVOLVED VEHICLE	WEST	REAR END	V-1 WEST BOUND ON NINER LOOP IN RIGHT LANE DIRECTLY BEHIND V-2 IN HEAVY TRAFFIC. V-2 SLOWED AND STOPPED DUE TO STOPPED TRAFFIC AHEAD. "OP V-1 MOMENTARILY DISTRACTED BY TRAFFIC ON THE STATE ST RAMP FAILED TO OBSERVE V-2 HAD STOPPED AHEAD. V-1 DROVE INTO REAR OF V-2.	940T43011005
48	35746077	6/2/2015	7:35:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	WET	CLOUDY	PASSING TOO CLOSELY	EAST	OVERTAKING	V-1 EAST BOUND INNER LOOP IN LEFT LANE PASSING V-2 DRIVING IN CENTER LANE. V-1 PARTIALLY ENTERS CENTER LANE WHILE PASSING V-2. "V-1 SIDESWIPES V-2 AS V-1 OVERTAKES V-2 AND V-2 IS IN V-1'S BLIND SPOT.	940T43011008
49	35754308	6/5/2015	8:20:00 PM	2	PROPERTY DAMAGE	DARK-ROAD LIGHTED	WET	RAIN	FOLLOWING TOO CLOSELY	EAST	REAR END	OP V-1 EB INNER LOOP. OP V-2 EB INNER LOOP. OP V-2 SLOWS FOR TRAFFIC & IS STRUCK BY V-1 IN ROADWAY. CBA.	940T43011011
50	35769603	6/14/2015	9:48:00 PM	2	INJURY	DARK-ROAD LIGHTED	DRY	CLOUDY	PASSING OR LANE USAGE IMPROPERLY	NORTH	HEAD ON		940T43011005
51	35784784	6/22/2015	9:10:00 AM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	EAST	REAR END	V-1 EB NNER LOOP IN THE LEFT LAME. V-2 EB NNER LOOP IN THE LEFT LAME BEHIND V-1. OPV-1 HAS TO STOP DUE TO HEAVY TRAFFIC. OPV-2 FOLLOWING TOO CLOSELY TO V-1. V-2 STRIKES V-1. E2801.	940T43011004

TE 213 (9/79)						DOUTE NO OR	OTDEET HANG						
COUNTY:	MONROE		P.I.N.:	NOT APPLICAB	LE	ROUTE NO. OR INNER LOOP (N					CASE No.:		_
	TOWN CITY					AT INTERSECT					FILE: BY:		-
	VILLAGE OF	ROCHEST	ER						RMINUS AT N. UNION ST		DATE:		- -
TIME PERIOD		FROM: 8/1/14	TO: 7/31/19	ENVIRONMENT Use Codes from at right) for these	n MV 104 (shown e categories	Light Conditions: 1. Daylight 2. Dawn 3. Dusk 4. Dark Road Light 5. Dark Road Ur	ghted	Roadway Surfar 1. Dry 2. Wet 3. Muddy 4. Snowlice 5. Slush 10. Other	ce Condition: Weather: 1. Clear 2. Cloudy 3. Rain 4. Snow 5. Sleel/Hall/Free 6. Fog/Smog/Sn 10. Other				
No. OF MONTH	S:	6	0	ES		TIONS						MV 104 Police Report	
CRASH No.	CASE No.	DATE	TIME	No. of VEHICLES	SEVERITY	LIGHT CONDITIONS	ROADWAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING FACTORS	DIRECTION	TYPE ¹	DESCRIPTION	REFERENCE MARKER
52	35827955	7/25/2015	11:20:00 AM	1	NON- REPORTABLE	DAYLIGHT	WET	CLOUDY	UNSAFE SPEED	WEST	OTHER	V-1 was traveling west on the hiner loop on ramp to hierstale 490 west. Operator of V-1 takes the curve on the on ramp at an unsafe speed causing operator of V-1 to lose control striking a cement barrier and then coming to rest on the shoulder of hierstale 490 west. V-1 was lowed from the scene, no injuries	490143022026
53	35852427	7/26/2015	1:54:00 AM	2	PROPERTY DAMAGE	DARK-ROAD LIGHTED	DRY	CLEAR	ALCOHOL INVOLVEMENT	WEST	HEAD ON	V-2 traveling in the Eastbound lanes of the hiner Loop, SR-940T, a controlled access highway. Operator V-1 inhoxicated. V-1 enters liner Loop traveling West in the Eastbound lanes. V-1 strikes V-2 head on. Both operators arrested for the above listed charges CLOSED	940T43011008
54	35820883	7/30/2015	5:10:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	FAILURE TO YIELD RIGHT OF WAY	WEST	OVERTAKING	V-1 west on the Inner Loop and was changing lanes to the right when front of V-1 struck left side of V-2 which was in the right lane headed West. Both vehicles sustained minor damage and relocated to MIII St to await Police.	940T43011006
55	35823282	7/31/2015	1:25:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	EAST	REAR END	V-1 taveling east on the innerloop exiting at Sala St, in the offamp lane. V-2 taveling east on the hnerloop, in the offamp lane, exiting at Sala St. Due to following to closely, V-2 struck the rear of V-1 V I Tavels west in the let driving lane or the inner Loop in the City of	940T43011005
56	35847347	8/10/2015	4:08:00 AM	1	PROPERTY DAMAGE	DARK-ROAD LIGHTED	DRY	CLEAR	ALCOHOL INVOLVEMENT	WEST	OTHER	In Taxes westin the self driving line of the Innet Loop in the Lilyof Rochester. OP I'could not explain how the collision occured but only stated she turned, three signation at the scene showed the vehicle skid marks cross from the left lane across the right lane and struck the cement barrier to caled on the right shoulder. After the collision with the cement barrier the vehicle bounced across both lanes and struck the ecement guide rail located on the left shoulder. V1 comes to restfacing west blocking the left lane. OP V1 appeared to be showing the signs of intoxication. An immediation conducted at the accident scene revealed OP V1 to be intoxicated and was subsequently arrested for Driving White intoxicated. Tackes Issued: MaRNAM GOLLOGL Vibrier of vehicle number (1) lickets: Ticket Number: M2104NH182 Violation: 11923 Ticket Number: M2104NH184 Violation: 11840 Ticket Number: M2104NH158 Violation: 11340 Ticket Number: M2104NH158 Violation: 11341 Ticket Nu	940T43011008
57	35852416	8/11/2015	12:45:00 PM	1	PROPERTY DAMAGE	DAYLIGHT	DRY	CLOUDY	DRIVER INATTENTION	EAST	OTHER	V-1 parked on side of the roadway for traffic stop. Upon completion of stop, operator of v-1 advised that he was fee to leave. V-1 starts from parked position and pulls forward to enter roadway. Operator fails to observe guard rail and strikes same causing damage to V-1 and guard rail CLOSED	940T43011012
58	35867656	8/31/2015	8:28:00 PM	1	NON- REPORTABLE	DARK-ROAD LIGHTED	DRY	CLEAR	PAVEMENT DEFECTIVE	EAST	OTHER	Oper V1 East Bound Innerloop, CRochester. Oper V1 states as he was approaching the intersection with East Main Street his rear tire hit a pot hole which caused tire damage.	
59	35875731	9/8/2015	8:30:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	EAST	REAR END		940T43011003
60	35879528	9/11/2015	9:05:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	EAST	REAR END	V-1 AND V-2 EB INNER LOOP CROCHESTER. V-1 WAS STOPPED IN TRAFFIC AND WAS REAR ENDED BY V-2 WHICH ATTEMPTED TO STOP AND TAKE EVASIVE ACTION TO AVOID THE ACCIDENT. NO INJURY NO TOW	940T43011004
61	35889244	9/17/2015	8:24:00 AM	1	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	REACTION TO OTHER UNINVOLVED VEHICLE	WEST	OTHER	OPER YI WESTBOUND INNER LOOP IN THE RIGHT LANE WHEN SHE FAILE DTO OBSERVE TRAFFIC QUICKLY STOP FOR AN UNINVOLVED VEHICLE DISABLED BLOCKING THE RIGHT LANE. OPER, YI TOOK EVASIVE ACTION TO AVOID STRINGS THE VEHICLE IN FRONT OF HER AND SWERVED OFF NORTH SIDE OF ROADWAY STRIKING CONCRETE BARRER WITH FRONT PASSENGER SIDE CORNER AND TIRE. NO INJURIES REPORTED.	940T43011005
62	35906236	9/23/2015	8:52:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	EAST	REAR END	THE OPERATOR OF V-2 STATES SHE WAS SLOWING IN TRAFFIC ABRUPTLY ON THE INNER LOOP EB WEST OF ST PAUL. THE OPERATOR OF V-2 STATES HE SLOWED ABRUPTLY AND DID NOT HAVE ENOUGH TIME TO STOP. V-1 STRUCK V-2 CAUSING VISBLE DAMAGE TO V-1 ONLY.	940T43011005
63	35906219	9/26/2015	4:41:00 AM	1	PROPERTY DAMAGE AND INJURY	DARK-ROAD LIGHTED	DRY	CLEAR	ALCOHOL INVOLVEMENT	SOUTH	OTHER	VI SOUTHBOUND ON INNER LOOP AND WAS TAKING THE ON RAMP ENTERING 1490 WEST IN THE CITYOF ROCHESTER. OPERATIOR OF VI FALLED TO NEGOTIATE A RICHIT HAND TURN AND LOST CONTROL OF THE VI. VI STRUCK THE CONCRETE BARRER LOCATED OFF THE SOUTH SIDE OF THE ROADWAY AT 1490 WEST. OPERATIOR WAS CONSCIOUS AND WAS TRANSPORTED BY AMBULANCE TO STRONG MEMORIAL HOSPITAL. VI WAS TOWNED FROM SCENE BY EXCEL TOWING. Tickels Issued: SHAWN L ADAMS Driver of vehicle number (1) lockes: Tickel Number: 15334THJ6L Violation: 11923 Tickel Number: 15334THJ6L Violation: 11923 Tickel Number: 18334THJ6L Violation: 1923 Tickel Number: M2104TJFXW Violation: 51931 Tickel Number: M2104TJFXW Violation: 51931 Tickel Number: M2104TJFXW Violation: 11924 Tickel Number: M2104TJFXW Violation: 11924 Tickel Number: M2104TJFXW Violation: 11924 Tickel Number: M2104TKG3 Violation: 11924 Tickel Number: M2104TK	490143022026
64	35906232	9/29/2015	5:23:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	WET	RAIN	FOLLOWING TOO CLOSELY	EAST	REAR END	OP V-2 WAS EB ON THE INNER LOOP STOPPED IN HEAVY TRAFFIC. OP V-1 WAS ALSO EB ON THE INNER LOOP AND FOLLOWING TOO CLOSELY. OP V-1 FAILED TO STOP IN TIME AND STRUCK THE REAR OF V-2 - WITNESS 1 BENTON, ANDREA IN 204 PENNELS DR GREECE IN 14626 5853710067	940T43011013
65	35923363	10/9/2015	7:10:00 AM	2	PROPERTY DAMAGE	DAWN	WET	RAIN	PASSING OR LANE USAGE MPROPERLY	EAST	OVERTAKING	OPER 'VI FASTBOUND NINER LOOP IN LET I LANE WHEN LINKKOWN TASCTOR TRALE BY SWERVED OUT OF RIGHT LANE INTO LEFT LANE STRKING VI Bapos S FRONT PASSENGER SED CONER CAUSING DAMAGE. VZ THEN CONTINUED EASTBOUND AND EXTED HIGHWAY. TRALER PLATE SAMP: TRUCK INFO PROVIDED FALLED TO DENTEY TRUCK INFOLVED. NO INJURIES REPORTED AND VI WAS DRIVEN FROM SCENE	940T43011008

TE 213 (9/79)											ı		
COUNTY:	MONROE		PIN-	NOT APPLICAB	I F	ROUTE NO. OR					CASE No.:		
	TOWN		1 .1.14	NOT ATTECAD	LL	INNER LOOP (N	YS 940T) AND R	AMPS			FILE:	PSC 5/13/2020	-
	CITY					AT INTERSECT	ION WITH/OR B	ETWEEN:			BY:	PSC	-
	VILLAGE OF	ROCHESTI	ER			FROM I-490 INT	ERCHANGE TO	INNER LOOP TE	RMINUS AT N. UNION ST		DATE:	5/13/2020	_
TIME PERIOD		FROM: 8/1/14	TO: 7/31/19	ENVIRONMENT Use Codes from at right) for these	MV 104 (shown e categories	Light Conditions: 1. Daylight 2. Dawn 3. Dusk 4. Dark Road Lig 5. Dark Road Un	ghted	Roadway Surface 1. Dry 2. Wet 3. Muddy 4. Snowlice 5. Slush 10. Other	ce Condilion: Weather: 1. Clear 2. Cloudy 3. Rain 4. Snow 5. Slee\/ Hail\/ Free 6. Fog/Smog/Sn 10. Other				
No. OF MONTH	S:	6	0			SNC					¹ Use Codes from	MV 104 Police Report	
CRASH No.	CASE No.	DATE	TIME	No. of VEHICLES	SEVERITY	LIGHT CONDITIONS	ROADWAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING FACTORS	DIRECTION	TYPE ¹	DESCRIPTION	REFERENCE MARKER
66	35921033	10/12/2015	2:50:00 PM	1	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	OBSTRUCTION/DEBRIS	EAST	OTHER	V1 IN LEFT LANE WB ON I-490 AT PLYMOUTH AVE WHEN A METAL SCREW FELL FROM THE RALROAD BRIDGE ONTO V18apos;S WINDSHIELD. METAL SCREW WAS OBSERVED IN THE ROADWAY. NO INJURIES	490143022025
67	35928262	10/16/2015	5:17:00 PM	2	NON- REPORTABLE	DARK-ROAD LIGHTED	WET	RAIN	UNSAFE LANE CHANGE	WEST	OVERTAKING	V-1 traveling west bound on the inner loop in the right lane, attempts to switches lanes do to traffic stopping and side swipes V-	940T43011002
68	35939389	10/19/2015	8:05:00 AM	1	PROPERTY DAMAGE AND INJURY	DAYLIGHT	DRY	CLEAR	GLARE	EAST	OTHER	2 which was in the let lain. No humes No lows, No arress. OPER. V1 & ASTROBOUND 1490 ATTEMPTED TO EXIT LEFT ONTO NINER LOOP WHEN SHE DROVE OUT OF HER LANE NIOT THE SPLIT IN THE ROADWAY DUE TO A HEAVY SUNGLARE. V1 THEN STRUCK THE PERMANENT CRASH CUSHION ATTENUATOR WITH V1 KAPPOS SFRONT END. OPER. V1 STRUCK HER FOREHEAD ON THE WINDSHIELD DUE TO BEING UNRESTRANED. ROCHESTER FIRE AND EMS ONSCENE.	49043022025
69	35967872	11/11/2015	8:20:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	WET	RAIN	UNSAFE SPEED	WEST	OVERTAKING	OPER 11 WESTBOUND ON THE NINER LOOP ONRAMP TO I- 490 WB WHEN SHE LOST CONTROL OF 10 NTHE WET 490 WB WHEN SHE LOST CONTROL OF 10 NTHE WET 490 WB REGENE SPLIT NTO THE 1490 WB REGHT LANE AND 5TRUCK THE REAR END OF V2. V2 WAS FORCED TO SPN 180': OF THE NORTH SIDE OF THE ROADWAY 5TRIKNS THE GUIDERAW. WITH DRIVER SDE WHILE V1 CAME TO REST AGAINST THE ROADSDE CURBING ON THE SOUTH SIDE OF 1490. NO NUIRIES REPORTED AND OPER. V1 WAS FOUND TO POSSESS ONLY A LEARNER': S PERMIT WITHESS LT GENCOL JAMES A 8589999444	490143022026
70	36002608	11/24/2015	5:35:00 PM	2	PROPERTY DAMAGE AND INJURY	DARK-ROAD LIGHTED	DRY	CLEAR	FOLLOWING TOO CLOSELY	WEST	REAR END	VI AND V2 IN RIGHT LANE WB ON THE INNER LOOP IN THE CITY OF ROCHESTER. V2 FAILED TO OBSERVE V1 SLOWING DOWN FOR STOPPED TRAFFIC, SUBSEQUENTLY STRIKING THE REAR OF V1. DRIVER OF V1 TRANSPORTED TO HIGHLAND HOSPITAL VIA MONROE AMBULANCE FOR PRECAUTIONARY REASONS DUE TO BEING 8 MONTHS PRECAUTIONARY REASONS DUE TO BEING 8 MONTHS	940T43011004
71	35991059	11/30/2015	5:21:00 PM	2	PROPERTY DAMAGE	DUSK	DRY	CLEAR	UNSAFE SPEED	WEST	REAR END	OPV1 TRAVELING THE INNERLOOP WB BEHIND OPV2 AS V2 IS STOPPED IN TRAFFIC. SUBSEQUENTLY V1 STRIKES V2.	940T43011005
72	35993086	12/1/2015	4:50:00 PM	2	PROPERTY DAMAGE AND INJURY	DARK-ROAD LIGHTED	WET	CLOUDY	UNSAFE LANE CHANGE	WEST	REAR END	V-1 WEST BOUND INNER LOOP IN LEFT LANE. V-2 WEST BOUND IN RIGHT LANE. V-1 CHANGED LANES INTO RIGHT LANE BEHIND V-2 AS V-2 WAS SLOWING IN HEAVY TRAFFIC. V-1 BRAKED AND SLID INTO REAR BUMPER OF V-2.	940T43011007
73	35997158	12/3/2015	9:33:00 AM	2	NON- REPORTABLE	DAYLIGHT	WET	CLOUDY	FAILURE TO YIELD RIGHT OF WAY	EAST	OVERTAKING	OPERATOR OF VEHICLE #1 STATES HE WAS TRAVELING WEST BOUND ON INTERSTATE 490 HE WAS EXITING THE MITERSTATE AT EXTRA TEXT AT EXTRAINE AS ON THE MITER LOOP WHEN HE SIDE SWIPE VEHICLE #2 WHICH WAS TRAVELING EAST BOUND ON THE INNER LOOP CAUSING MINOR DAMAGE TO VEHICLE #2 REAR RIGHT FENDER AREA.	490143022027
74	36005194	12/8/2015	3:38:00 PM	3	PROPERTY DAMAGE AND INJURY	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	NORTH	OTHER		940T43011014
75	36028727	12/28/2015	10:30:00 AM	1	PROPERTY DAMAGE	DAYLIGHT	SNOW/ICE	SNOW	UNSAFE SPEED	EAST	OTHER	VI WAS EASTBOUND ON THE INNERLOOP IN THE CROCHESTER WHEN DRIVER I STATED HE LOST CONTROL OF VI ON THE CYSLEPPERY ROOMWAY WHICH CAUSED VI TO STRIKE THE CONCRETE BARRIER ON THE LEFT SHOULDER AND THEN BOUNCE OFF AND CROSS BOTH LANES OF TRAFF C AND STIRKE THE CONCRETE BARRIER ON THE RIGHT SHOULDER BEFORE COMING TO REST. NYS DOT WAS NOTIFIED OF THE POSSIBLE DAMAGE TO THE BARRIERS (ON SEPED).	940T43011006
76	36043257	1/5/2016	12:17:00 AM	2	PROPERTY DAMAGE	DARK-ROAD LIGHTED	WET	CLOUDY	UNSAFE SPEED	WEST	REAR END	V-1 traveling west bound on the innerloop was going to fast for slippery icy roadway starts is spin out of control. V-2 was traveling behind V-1 and was unable to avoid stilking V-1 in the rear bumper area as it was spinning. OP V-1 had no ficense. V-2 lost its rear fire and was towed to John and Sons.	
77	36037569	1/5/2016	5:16:00 PM	2	PROPERTY DAMAGE	DARK-ROAD LIGHTED	DRY	CLOUDY	PASSING OR LANE USAGE IMPROPERLY	EAST	REAR END		940T43011006
78	36060850	1/15/2016	9:40:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	WET	CLEAR	PASSING OR LANE USAGE IMPROPERLY	WEST	OVERTAKING	OPV1 TRAVELING THE INNER-LOOP WB PARALLEL TO OPV2. WHILE ATTEMPTING TO CHANGE LANES V1 SIDE SWIPES V2.	940T43011006
79	36053796	1/15/2016	2:16:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	UNSAFE LANE CHANGE	EAST	OVERTAKING	V-1 driving in the left lane East on the inner loop, V-2 driving in the right lane East on the inner loop, V-2 makes a lane change from the right lane to the left lane striking V-1 in the rear passenger side quarter panel with the front driver side quarter panel causing minor damage to both vehicles.	
80	36053802	1/15/2016	5:20:00 PM	1	PROPERTY DAMAGE AND INJURY	DARK-ROAD LIGHTED	DRY	CLOUDY	UNSAFE SPEED	WEST	OTHER	V-1 WEST BOUND ON THE NNER LOOP IN THE CITY OF ROCHESTER. THE OPERATOR STATES HE CHANGED FROM THE RIGHT TO THE LEFT LAME AND WHEN HE DO DIE NOTICED TRAFFIC WAS STOPPED IN THE LEFT LAME THE OPERATOR IMPACTED THE CEMENT BARRIER ATTEMPTING TO AVIOL BEAR ENDING AN UNINVOL VED VEHICLE. THE WITNESS STATED THAT THE OPERATOR OF V-1 APPEARED TO TURNO INFECTIV NITO THE BARRIER FROM THE RIGHT LAME. THE WITNESS STATED THAT THE BARRIER ATTEMPTING TO AVIOL BY A WAS AND THE WITNESS STATED THAT THE OPERATOR OF V-1 STATED TO HIM HE HIT THE BARRIER ATTEMPTING TO AVIOL BY THIS OF THE PROPERS OF THE PROP	940T43011004

TE 213 (9/79)						DOUTE NO. OD	CTDEET NAME				1		
COUNTY:	MONROE		P.I.N.:	NOT APPLICAB		ROUTE NO. OR INNER LOOP (N					CASE No.:		_
	TOWN CITY					AT INTERSECT					FILE: BY:		_
	VILLAGE OF	ROCHESTI	ER						RMINUS AT N. UNION ST		DATE:		- -
TIME PERIOD		FROM: 8/1/14	TO: 7/31/19	ENVIRONMENT Use Codes from at right) for these	AL: MV 104 (shown calegories	Light Conditions:	hted	Roadway Surface 1. Dry 2. Wet 3. Muddy 4. Snow/Ice 5. Slush 10. Other					
No. OF MONTH	S:	6	0	S		IONS					¹ Use Codes from	MV 104 Police Report	
CRASH No.	CASE No.	DATE	TIME	No. of VEHICLES	SEVERITY	LIGHT CONDITIONS	ROADWAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING FACTORS	DIRECTION	TYPE ¹	DESCRIPTION	REFERENCE MARKER
81	36065803	1/24/2016	9:45:00 AM	2	NON- REPORTABLE	DAYLIGHT	WET	CLOUDY	FAILURE TO YIELD RIGHT OF WAY	WEST	OVERTAKING	V-1 and V-2 both entered I-490 West from the Inner Loop and V-1 was in the right lane and V-2 was to the left of V-1 when V-1 was passing V-2 on the right and as the right lane was ending V-1 struck the right side of V-2 with the left side of V-1 as the altempted to merce left both vehicles sustained minor damage.	490143022025
82	36065678	1/25/2016	7:05:00 AM	2	PROPERTY DAMAGE	DAWN	DRY	CLOUDY	FOLLOWING TOO CLOSELY	SOUTH	REAR END	V-1 taveling south on the innerloop from the SI Paul on-ramp, slowing in traffic. V-2 traveling south on the innerloop from the ST. Paul on-ramp, behind V-1. An unknown vehicle stopped in the roadway for unknown reasons, causing traffic to slow abruptly. Due to following too closely. V-2 struck the rear of V-1.	940T43011006
83	36085310	1/29/2016	2:13:00 AM	1	PROPERTY DAMAGE AND INJURY	DARK-ROAD LIGHTED	WET	SNOW	ALCOHOL INVOLVEMENT	WEST	OTHER	THE OPERATOR WAS TRAVILING ON THE INNER LOOP WB IN THE RIGHT LANE AT THE INTERCHANGE OF 1490. THE SUBJECT DROVE STRAGHT THROUGH THE MEDIAN AND STRUCK A GUIDE RAIL. AFTER STRKING THE GUIDE RAIL TROLLED ON THE PASSENGER SIDE AND STRUCK A LIGHT POLE WITH THE FROSH TEND OF THE VEHICLE. THE OPERATOR WAS SUBSEQUENTLY ARRESTED FOR DRIVING WHILE INTOXICATED. Tickes Issued: ANDREW JHOVEY Oriver of vehicle number (1) lickes: Tickel Number: 1E3458TTWG VIOLATOR. TICKEL WITHOUT STREAM TICKEL WINDER: 1E3458TTWG VIOLATOR. TICKEL WITHOUT STREAM TICKEL WINDER: 1E3458TTMG VIOLATOR.	940T43011003
84	36086641	2/5/2016	10:00:00 AM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLOUDY	UNSAFE LANE CHANGE	WEST	OVERTAKING	V-1 and V-2 were headed west on the Inner loop. V-1 moves from lane one to lane two. While moving from lane one to lane two operator of V-1 fails to see V-2 and side swipes V-2. No injuries no tow.	940T43011006
85	36106338	2/22/2016	5:20:00 PM	3	PROPERTY DAMAGE	DAYLIGHT	DRY	CLOUDY	FOLLOWING TOO CLOSELY	WEST	OTHER		940T43011004
86	36130782	2/24/2016	7:00:00 AM	2	PROPERTY DAMAGE	DARK-ROAD UNLIGHTED	WET	RAIN	DRIVER INATTENTION	NORTH	LEFT TURN (AGAINST		940T43011006
87	36124171	3/2/2016	2:21:00 AM	1	PROPERTY DAMAGE	DARK-ROAD LIGHTED	SNOW/ICE	SNOW	ALCOHOL INVOLVEMENT	WEST	OTHER CAR) OTHER	UNIT 1 TRAVELING WESTBOUND ON INNER LOOP IN THE CITY OF ROCHESTER. UNIT 1 ATTEMPTS TO EXIT INNER LOOP AT JOSEPH AWE OF FRAMP. UNIT TARBOPS SPEED UNREASONABLE AND PRUDENT GMEN SNOW COVERED UNREASONABLE AND PRUDENT GMEN SNOW COVERED SADOMAY. UNIT 1 FALS TO NEGOTIATE OF FRAMP SUBSEQUENTLY STRKING BARRER OTHER UTT-sapos. S ISSUEDM2 105DC032 - 3191UM2 105DC023 - 306BM2 105DC03C - 3191UM2 105DC025 - 4011AM2 105DC825 - 4011AM2 105DC82	
88	36131066	3/10/2016	5:00:00 PM	2	NON- REPORTABLE	DAYLIGHT	WET	RAIN	FAILURE TO YIELD RIGHT OF WAY	WEST	OVERTAKING	VIOLATION 11923 THE AN IMPORT MATING TO CAME VIOLATION 51 THE CENTRE LANGE WAS PROBLEDING 1479 CENTRE LANGE WAS PROBLEDING 1479 AT INNER LOOP. VI WAS MERGING ON FROM THE INNER LOOP HEADING WESTBOUND AND ATTEMPTED TO CHANGE LANES NTO THE CENTER LANGE FALING TO WELD THE RIGHT AWAY OF V2 AND SDE SWPED V2 IN THE RIGHT FRONT COLARTER PANEL WITH V1 LET FEAR OLLARTER PANEL. NO INJURIES WERE REPORTED AND NO TOWS WERE REQUESTED. DRIVER OF V1 WAS CITED FOR FALED TO YELD RIGHT WAY.	490143022026
89	36160313	4/3/2016	7:04:00 AM	1	PROPERTY DAMAGE	DAYLIGHT	SNOW/ICE	SNOW	UNSAFE SPEED	WEST	OTHER	V-1 WB hmer Loop traveling at speed not reasonable and prudent. Roads snow covered and slick. V-1 fails to negoliate curve and strikes guide rail. Operator and sole occupant reports no injuries. UTT issued. DOT notified of damage to guide rail. CLOSED	490143022029
90	36160306	4/3/2016	10:03:00 PM	2	PROPERTY DAMAGE	DARK-ROAD LIGHTED	SNOW/ICE	SNOW	FOLLOWING TOO CLOSELY	WEST	REAR END	Diver 2 skied that he was west bound on the inner Loop in the tane for the 1409 West EuR Ramp, sowed for a separate accident ahead and was struck from behind by Vehicle 1. Driver 1 stated that he had entered the timer Loop West Bound from SIPaul, book evasive action to avoid a non involved whicke and struck Vehicle 2. Vehicle 1 was bwed by Excel Towing to Excel Towing. There were no histings to was or arrests.	940T43011006
91	36161152	4/3/2016	10:03:00 PM	2	INJURY	DARK-ROAD LIGHTED	SNOW/ICE	SNOW	PAVEMENT SLIPPERY	WEST	RIGHT ANGLE		940T43011005
92	36214276	4/3/2016	10:03:00 PM	2	PROPERTY DAMAGE	DARK-ROAD LIGHTED	SNOW/ICE	SNOW	PAVEMENT SLIPPERY, REACTION TO OTHER UNINVOLVED VEHICLE	WEST	REAR END	V1 and V2 were both w/b on the 490 Inner Loop. The road was snow covered. V2 had lo slow for a separate accident that happened just in front of it. V1 was unable to slow down behind V2 and struck V2. the collision caused damage to both vehicles. No injuries were reported.	940T43011006
93	36167834	4/5/2016	5:30:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	WEST	REAR END	V1 AND V2 ARE WB ON THE INNERLOOP APPROACHING 490. V2 SLOWS IN RESPONSE TO TRAFFIC. V1, FOLLOWING TOO CLOSELY UNABLE TO STOP IN TIME ATTEMPTS TO AVOID V2 BY SWERVING TO LEFT. V1 STRKES V2 IN DRIVERS REAR BUMPER.	940T43011004
94	36185425	4/25/2016	5:19:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLOUDY	DRIVER INATTENTION	WEST	OVERTAKING	V2 WB Inner Loop in right lane. V-1 merging on b WB Inner Loop from Scib. V-1 Falls b yield to V-2 and side swipes V-2. Operabr V-2 states he observed V-1 fail b yield but could not avoid collision due to an uninvolved vehicle in the left lane. All bartles report no inluries.	940T43011012
95	36199863	4/29/2016	5:30:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLOUDY	FOLLOWING TOO CLOSELY	EAST	REAR END	ISTREST LEGATION UNITED AND AN INVERLOOP WEST OF THE STATE STREET OVERPASS AS SHE SIN RIGHT LAWE AND SLOWING FOR CONCISSION THANFO FOR TO TO A WORKZONE WHEN SHE IS HIT FROM BEHIND BY OPERATOR OF V.2 WHO MAS BEHIND HER AND FALED TO LEAVE SUFFICIENT SPACE TO STOP HIS VEHICLE. E2801	940T43011004

TE 213 (9/79)						DOLLTE NO. OD	CTDEET MAME						
COUNTY:	MONROE		P.I.N.:	NOT APPLICAB	LE	ROUTE NO. OR					CASE No.		
	TOWN		•'			INNER LOOP (N AT INTERSECT					FILE		- =
	CITY VILLAGE OF	ROCHESTI	ER								DATE		=
	•				_				RMINUS AT N. UNION ST				-
TIME PERIOD		FROM: 8/1/14	TO: 7/31/19	ENVIRONMENT Use Codes from at right) for these	n MV 104 (shown e categories	Light Conditions: 1. Daylight 2. Dawn 3. Dusk 4. Dark Road Lig 5. Dark Road Ur	yhted	Roadway Surfar 1. Dry 2. Wet 3. Muddy 4. Snowlice 5. Slush 10. Other	ce Condition: Weather: 1. Clear 2. Cloudy 3. Rain 4. Snow 5. Sleet/Hail/Fre 6. Fog/Smog/Sr 10. Other				
No. OF MONTH	S:	6	0	S		SNOI					¹ Use Codes from	MV 104 Police Report	
CRASH No.	CASE No.	DATE	TIME	No. of VEHICLES	SEVERITY	LIGHT CONDITIONS	ROADWAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING FACTORS	DIRECTION	TYPE ¹	DESCRIPTION V1 WAS TRAVELING EASTBOUND ON INTERSTATE 490 IN THE	REFERENCE MARKER
96	36195808	5/4/2016	8:05:00 AM	1	PROPERTY DAMAGE AND INJURY	DAYLIGHT	DRY	CLEAR	UNSAFE LANE CHANGE	EAST	OTHER	CITY OF ROCHESTER. DUE TO UINSAFE LAINE CHANGE AND SUN GLARE ON WINDSHELD, VI STRUCK THE END OF A CENTER MEDIAW WITH FRONT BUMPER AT THE MERGE OF INTERSTATE 490 FASTBOUND AND INNER LOOP. DRIVER WAS TRANSPORTED BY RURAL METRO AMBULANCE TO STRONG MEMORIAL HOSPITIA. FOR FURTHER MEDICAL EVALUATION. VEHICLE WAS TOWED FROM SCENE BY 454. DRIVER WAS NOT CITED.	490143022025
97	36214337	5/19/2016	8:04:00 AM	2	PROPERTY DAMAGE AND INJURY	DAYLIGHT	DRY	CLEAR	UNSAFE LANE CHANGE	EAST	OVERTAKING	Oper V1, Oper V2 On the ramp to North Plymouth Ave from East Bound I490 CRochester. As a result of an unsafe lane change V1 side swipes V2. Closed.	940T43011000
98	36232908	5/28/2016	11:59:00 AM	1	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	PASSING OR LANE USAGE IMPROPERLY	EAST	OTHER	V-1 was traveling eastbound on I490 and exited onto the Inner Loop. The driver of V-1 was unable to maintain his lane and struck the southern jersey barrier with the passenger side of V-1. V-1 driving East on the Inner loop in the right hand lane. V-2	490143022025
99	36237855	5/31/2016	9:09:00 AM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	EAST	REAR END	driving East on the inner loop behind v-1. V-1 slows for traffic, V-2 strikes the rear bumper of V-1 with the front bumper of V-2 causing minor damage to both vehicles.	940T43011003
100	36252572	6/7/2016	3:32:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	WEST	REAR END	VI WAS TRAVELING WESTBOUND ON THE INNER LOOP JUST EAST OF THE STATE STREET OFF RAWN IN THE CITY OF ROCHESTER. V. WAS ALSO TRAVELING WESTBOUND IN FRONTO F VI. V. 2 STOPPED DUE TO TRAFFIC AND VI DUE TO FLOOR TO FLOOR TO FLOOR VI. V. 2 STOPPED DUE TO TRAFFIC AND VI DUE TO FLOOR VI. V. 2 STOPPED DUE TO TRAFFIC AND VI DUE TO FLOOR VI. V. 2 STOPPED DUE TO TRAFFIC AND VI. DUE TO FLOOR VI. V. 1 THE REAR BUMPER WITH THE FRONT END CAUSING VISBLE DAMAGE TO BOTH VEHICLES. NO NUJURES WERE REPORTED AND NO TOWS REQUESTED. THE INNER LOOP IS A TWO LANE ROADWAY BUT CURRENTLY UNDER CONSTRUCTION AND FROM LANE ROADWAY. THE DRIVER OF VI. VIAS CITED FOR FOLLOWING TO CLOSELY, UNLICENSED, BALD TIRES, NADEQUATE EXHAUST, EXPRED INSPECTION, AND FALURE TO UPDATE DAM WITH ADDRESS CHANGE. TICKES ISSUED: CARLOS JAVIERO RIZE WIFE OF VIEW VIAS CITED TO THE TO THE VIEW VIAS CITED TO THE VIEW VIA VIAS CITED TO THE VIEW VIAS CITED TO THE VIEW VIAS CITED TO THE VIAS CITED TO THE VIAS CITED TO THE VIAS CITED TO THE VIEW VIA VIAS CITED TO THE VIAS CITED TO	940743011005
101	36252036	6/8/2016	2:45:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLOUDY	VIEW OBSTRUCTED/LIMITED	WEST	OVERTAKING	VI AND V2 WERE WESTBOUND ON THE MINERLOOP IN THE CROCHESTER ENTERING A CONSTRUCTION ZONE WHERE THE RICHT LANK MERGES INTO THE LEFT LANE. AS VI WENT TO MERGE INTO THE LEFT LANE VI SDE SWIPED V2. DRIVER I STATED THAT HE DD NOT SEE V2 AND THEN V2. TO A SUDDEN V2 HAD ZPPED UP ALONG SIDE OF HIM. DRIVER 2 STATED THAT VI CAME NTO HER LANE AND SIDE	940T43011004
102	36267555	6/20/2016	1:30:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	UNSAFE LANE CHANGE	WEST	OVERTAKING	SWIPED V2. CLOSED. VI WAS TRAVELING WESTBOUND IN THE FAR LEFT LANE ON INNER LOOP IN THE CITY OF ROCHESTER. V2 WAS ALSO WESTBOUND IN THE FAR RIGHT LANE V1 WAS A PICK-UP TRUCK HOOKED TO A TRAILER AND MADE A UNSAFE LANE CHANGE INTO THE RIGHT LANE AND SIDESWIPE V2 CAUSING VISIBLE DAMAGE. V1 LEFT SCHIPP FROIR TO PATOL ARRAYING. NO INJURIES REPORTED AND NO TOWS REQUISTED.	940T43011008
103	36302319	7/18/2016	1:25:00 PM	2	NON- REPORTABLE	DAYLIGHT	WET	CLOUDY	FOLLOWING TOO CLOSELY	WEST	OVERTAKING	Vehicle 1 westom the Inner Loop behind Vehicle 2 in he let Iane. Operabr of Vehicle 2 stopped for a large puddle of water blocking the let Iane under the North Clinton Ave overpass. Operabr of Vehicle 1 unable to stop in time and took evasive action to the right lane but side swiped the right side of Vehicle 2. No visible damage to Vehicle 1.	040743011008
104	36325736	7/27/2016	5:30:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	WEST	REAR END	Oper V1 and V2 West Bound Innerloop, CRochester. As a result of following too closely, V1 rear ends V2.	940T43011005
105	36327117	8/4/2016	5:13:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	WEST	REAR END	V-1 and V-2 west on hner Loop ramp to RT 490 west. Due to heavily congested traffic consistent for fime of day, V-2 suddenly stops for traffic and V-1 unable to stop in fime strikes the rear of V-2 causing damage to both vehicles. No injuries reported and both wehicles left scene under own power.	
106	36336798	8/8/2016	10:21:00 AM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	WEST	REAR END	V1 AND V2 ARE WB ON THE INNERLOOP APPROACHING STATE ST IN HE LEFT LAME IN A CONSTRUCTION ZONE. V2 SLOWS IN ANTICIPATION OF MERGING TO THE LEFT. V1 FOLLOWING TOO CLOSELY STRIKES THE REAR OF V2. OPV1 LEFT SCENE OF ACCIDENT.	940T43011005
107	36343860	8/12/2016	4:30:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	REACTION TO OTHER UNINVOLVED VEHICL	WEST	OVERTAKING	OPER 'Y WAS WESTBOUND ON THE INNER LOOP IN THE CENTER LANE WHEN AN UNKNOWN UNINVOLVED TRUCK CHANGED LANES NTO PATH OF Y I FROM THE RIGHT LANE. OPER 'YI TOOK EVASUR'S ACTION BY SWERVING INTO THE LEFT LANE FAUNG TO DESERVE 'YI WHO A IREADY OCCUPIED THE LEFT LANE. YI STRUCK SIDE OF YZ CAUSING DAMAGE. NO BUJURES REPORTED AND BOTH YERLICLE SWERFED RIVED BY THE OWNER OF THE OWNER OF THE OWNER OF THE OWNER OWNER.	940T43011011
108	36341937	8/14/2016	2:32:00 AM	1	PROPERTY DAMAGE	DARK-ROAD LIGHTED	DRY	CLOUDY	PASSING OR LANE USAGE IMPROPERLY	WEST	OTHER	-V-1 entering 490 WB form innerloop when looses control in curve, leaves road to the north, and strikes RGE utility pole m162. RGE notified at scene. Operator cited for move from lane unsafely, vehicle towed by John and Son. No injuries. Closed	
109	36356833	8/24/2016	5:15:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	UNSAFE LANE CHANGE	WEST	OVERTAKING	UNIT I TRAVELS WESTBOUND ON 1490 IN THE CITYOF ROCHESTER. UNIT 2 TRAVELS WESTBOUND ON THE INDER LOOP IN THE CITYOF ROCHESTER. UNIT I MERGES FROM LANE UNSAFELY AND SUBSEQUENTLY SIDE SWIPES UNIT 2 WHERE WESTBOUND INNER LOOP MERGES WITH WESTBOUND 1490.	490143022026

TE 213 (9/79)													
COUNTY:	MONROE		DIN	NOT APPLICAB	ı F	ROUTE NO. OR	STREET NAME	:			CASE No.:		
COUNT 1.	TOWN		· Film.	NOT AFFEICAB	LL	INNER LOOP (N	YS 940T) AND R	RAMPS			FILE:		-
	CITY					AT INTERSECT	ION WITH/OR B	ETWEEN:			BY:	PSC	=
	VILLAGE OF	ROCHESTI	ER		_	FROM I-490 INT	FRCHANGE TO	INNER LOOP TE	ERMINUS AT N. UNION ST		DATE:	5/13/2020	=" =
THE DEDICE		50014	70	I CAN HOOLINACAD									
TIME PERIOD		FROM: 8/1/14	TO: 7/31/19	ENVIRONMENT Use Codes from at right) for these	n MV 104 (shown e categories	Light Conditions: 1. Daylight 2. Dawn 3. Dusk 4. Dark Road Lig 5. Dark Road Ur	ghted	Roadway Surfar 1. Dry 2. Wet 3. Muddy 4. Snowlce 5. Slush 10. Other	ce Condition: Weather: 1. Clear 2. Cloudy 3. Rain 4. Snow 5. SleeWHail/Fre 6. Fog/Smog/Sr 10. Other				
No. OF MONTH	S:	6	0			SNO					¹ Use Codes from	MV 104 Police Report	
CRASH No.	CASE No.	DATE	TIME	No. of VEHICLES	SEVERITY	LIGHT CONDITIONS	ROADWAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING FACTORS	DIRECTION	TYPE ¹	DESCRIPTION	REFERENCE MARKER
110	36363296	8/24/2016	6:03:00 PM	2	INJURY	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	WEST	REAR END	V-2 slowing in heavy traffic west bound on the innerloop in The City of Rochester, is struck in rear bumper area by V-1 which was also traveling west bound and was unable to sbp. No injuries, No lows	940T43011004
111	36357658	8/25/2016	10:05:00 AM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	UNSAFE LANE CHANGE	EAST	OVERTAKING	VI WAS TRAVELING EASTBOUND IN THE CENTER LANE ON THE INNER LOOP IN THE CITY OF ROCHESTER. V2 WAS TRAVELING EASTBOUND IN THE FAR RIGHT LANE. DUE TO UNSAFE LANE CHANCE, V1 SIDESWIPED V2 IN THE RIGHT DRIVER SIDE OF THE VEHICLE CAUSING VISBLE DAMAGE. NO BUJURIES WERE REPORTED AND NO TOW WAS REQUESTED. NO DRIVERS WERE CITED. WITNESS I JONES, KM D 30 CHURCH ST ROCHESTER NY 14614 5857943309	940T43011007
112	36374292	9/8/2016	12:10:00 PM	3	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	UNSAFE LANE CHANGE	EAST	OTHER	V2 WAS TRAVELING EASTBOUND ON THE NINER LOOP IN THE CITY OF ROCHESTER AND CAME TO A COMPLETE STOP DUE TO TRAFFIC. V3 WAS LOCATED DIRECTLY SERIND V2 AND ALSO CAME TO A COMPLETE STOP WITH NO INCIDENT. V1 DUE TO UNSAFE SPEED, APPOACH BOTH SAD VEHICLES AND WAS UNABLE TO STOP, STRKING V3 IN THE REAR END CAUSING VISIBLE TOMAGE. V3 WAS THE PUSHED INTO V2 STRKING V2 IN THE REAR END CAUSING VISIBLE DIAMAGE. NO INJURIES WERE PROPRIED, NO TOWS REQUESTED. V1 WAS AT FAULT BUT NOT CITED.	940T43011007
113	36374287	9/8/2016	1:03:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLOUDY	CELL PHONE (HAND HELD)	EAST	REAR END	V-1 driving East on the Inner loop, V-2 driving behind V-1. V-2 slows for traffic, V-2 strikes the rear bumper of V-1 with the front bumper of V-2 causing damage to both vehicles. The driver of V-2 stated that he was looking at the gps on his phone and when he looked up the car in front of him was shopped.	940T43011005
114	36392499	9/14/2016	4:18:00 PM	2	PROPERTY DAMAGE AND INJURY	DAYLIGHT	DRY	CLOUDY	FOLLOWING TOO CLOSELY	WEST	REAR END	VEHICLE-1 WAS WESTBOUND ON THE INNERLOOP WHEN VEHICLE-2 ALSO WESTBOUND STRUCK VEHICLE-1 ON THE REAR BUMPER.	940T43011003
115	36392381	9/19/2016	4:47:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	UNSAFE LANE CHANGE	WEST	OVERTAKING	V-1 driving in the left lane West on the inner loop. V-2 in the center lane altempting to merge into the left lane strikes V-1 in the front passenger side quarter panel with the front drivers side door area causing damage to both vehicles. V-1 drives off the South shoulder striking the cement barrier with the front driver side wheel.	940T43011005
116	36470947	9/20/2016	2:25:00 PM	1	PROPERTY DAMAGE AND INJURY	DAYLIGHT	DRY	CLEAR	UNSAFE SPEED	NORTH-EAST	OTHER		940T43011002
117	36407069	9/21/2016	3:45:00 PM	3	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	WEST	OTHER	OPER V1, V2 AND V3 WEST BOUND INNERLOOP CITY OF ROCHESTER. AS A RESULT OF FOLLOWING TOO CLOSELY V1 FIRST REAR ENDS V2. V2 THEN REAR ENDS V3. UNIT 1 AND UNIT 2 BOTH TRAVEL WESTBOUND IN THE RIGHT	940T43011005
118	36399506	9/26/2016	5:47:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	WET	RAIN	FOLLOWING TOO CLOSELY	WEST	REAR END	LANE ON SR 940T IN THE CITY OF ROCHESTER. DRIVER OF UNIT 2 SLOWS SPEED FOR TRAFFIC CONGESTION AHEAD. DRIVER OF UNIT 1 FOLLOWS UNIT 2 TOO CLOSELY AND FAILS TO SLOW SPEED SUBSEQUENTLY REAR ENDING UNIT 2	940T43011006
119	36425548	10/1/2016	1:54:00 PM	2	PROPERTY DAMAGE AND INJURY	DAYLIGHT	DRY	CLEAR	UNSAFE SPEED	WEST	OVERTAKING	OPERATORS V1 AND V2 WESTBOUND INNERLOOP, CITY OF ROCHESTER WITNESSES STATE PRODE TO THE ACCIDENT Y UNAS OUICKLY PASSING TRAFE (AND MOVE DACK AND FORTH FROM ONE LANE TO ANOTHER IN AN UNSAFE MANNER WHILE CONTINUING TO PASS TRAFE (SA RESULT OF UNSAFE SPEED V1 LOST CONTROL AND FIRST STRUCK A GUIDE RAIL ON THE SOUTH SIDE OF THE ROADWAY V1 THEN SPUN AND STRUCK THE GUIDE RAIL ON THE NORTH SIDE OF THE ROADWAY VIT THEN STRUCK V2 AND CAME TO A REST WITNESS I KAFOREY, RACHEL M 321 MARBLEHEAD DR ROCHESTER NY 14615 5857215249	940T43011007
120	36415147	10/8/2016	6:35:00 AM	1	PROPERTY DAMAGE	DARK-ROAD LIGHTED	WET	RAIN	FELL ASLEEP	EAST	OTHER		940T43011009
121	36419339	10/11/2016	5:25:00 PM	3	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR		WEST	OTHER	V-1, V-2 and V-3 were all traveling westbound in the right driving lane. V-1 and V-2 stopped in congested traffic, the driver of V-3 was following too closely to stop before rear ending V-2. This action caused V-2 to move forward and impact V-1.	940T43011004
122	36427535	10/13/2016	8:27:00 AM	1	NON- REPORTABLE	DAYLIGHT	WET	RAIN	FAILURE TO KEEP RIGHT	WEST	OTHER	OPVI STATES THAT HE WAS TRAVELING THE NINER LOOP WB TO M90 WB IN THE LEFT LANE WHEN THE UNIVOLVED VEHICLE SWITCHED LANES IN FRONT OF HIM. OPVI STATES THAT HE SWERVED TO AVOID A COLLISION AND LOST CONTROL OF VI. VI EXITED THE ROADWAY AND HIT THE CONCRETE BARBER.	490143022026
123	36443726	10/22/2016	2:00:00 AM	1	PROPERTY DAMAGE AND INJURY	DARK-ROAD LIGHTED	WET	RAIN	UNSAFE SPEED	WEST	OTHER	OP VEH STATES SHE WAS WEST ON THE INNER LOOP IN THE CITY OF ROCHESTER, ABOUT TO MERGE ONTO 1490 WEST. OP VEH STATED SHE LOST TRACTION DUE TO WET ROADWAY. VEH 1 STRUCK END OF MEDWIN CAUSING VEH 1 TO OVERTURN ONTO IT&ApposS PASSENGER SIDE COMING TO REST FACING EAST ON 1490 WEST.	

TE 213 (9/79)						DOUTE NO OD	OTDEET HAVE				I		
COUNTY:	MONROE		P.I.N.:	NOT APPLICAB		ROUTE NO. OR INNER LOOP (N					CASE No.:		_
	TOWN CITY					AT INTERSECT					FILE: BY:	PSC	-
	VILLAGE OF	ROCHEST	ER		_				RMINUS AT N. UNION ST		DATE:	5/13/2020	-
TIME PERIOD		FROM: 8/1/14	TO: 7/31/19	ENVIRONMENT Use Codes from at right) for these	n MV 104 (shown e categories	Light Conditions: 1. Daylight 2. Dawn 3. Dusk 4. Dark Road Light 5. Dark Road Ur	yhted	Roadway Surface 1. Dry 2. Wet 3. Muddy 4. Snowlice 5. Slush 10. Other	ce Condition: Weather: 1. Clear 2. Cloudy 3. Rain 4. Snow 5. SleeVHallFre 6. Fog/Snog/Si 10. Other				
No. OF MONTH	S:	6	0	ES		TIONS						MV 104 Police Report	
CRASH No.	CASE No.	DATE	TIME	No. of VEHICLES	SEVERITY	LIGHT CONDITIONS	ROADWAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING FACTORS	DIRECTION	TYPE ¹	DESCRIPTION	REFERENCE MARKER
124	36454939	10/26/2016	3:17:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLOUDY	DRIVER NATTENTION	WEST	OVERTAKING	DRIVER OF VEHICLE 2 STATED THAT HE WAS TRAVELING WE NOT THE NINER LOOP TOWARDS 40 TO GET ONTO 490 WHEN THE DRIVER OF VEHICLE 1 WAS TRYING TO MERGE INTO THE SANIEL LINE TO GET TO 490 WB, WHEN HIS VEHICLE THE STRUCK THE FRONT PASSENGER SIDE OF VEHICLE 2. THIS CAUSED DAMAGE TO VEHICLE 2 SASPOSS FRONT PASSENGER SIDE DRIVER FOR VEHICLE 2 STATED THAT HE WAS ON THE NINER LOOP WB TRYING TO MERGE NOT THE NINER LOOP WB TAYING TO MERGE WHO THE WAS ON THE NINER LOOP WB TAYING TO MERGE WHO THE WAS ON THE NINER LOOP WB TAYING TO MERGE WHO THE WAS ON THE NINER LOOP WB TAYING TO MERGE FOR THE WAS THE WAS THE WAS THE SANIEL SAN	
125	36449104	10/30/2016	8:37:00 PM	1	PROPERTY DAMAGE	DARK-ROAD LIGHTED	WET	CLOUDY	UNSAFE SPEED	EAST	OTHER	UNIT I TRAVELS EASTBOUND ON 1490 IN THE CITY OF ROCHESTER AND TAKES THE DOWNTOWN INNER LOOP EXIT. UNIT I TRAVELS TOO FAST ON WET ROADWAY AND LOSES CONTROL SUBSEQUENTLY STRIKING A CONCRETE WALL.	940T43011002
126	36454958	11/2/2016	8:14:00 PM	2	PROPERTY DAMAGE	DARK-ROAD LIGHTED	WET	RAIN	FOLLOWING TOO CLOSELY	EAST	REAR END	Vehicle: 1 entering 1490 eastfrom the their Loop behind Vehicle 2. When Vehicle 2 sbipped behind an uninvolved vehicle that was slopped in the left lane with a flat fire. Operator of Vehicle 1 was unable to stop in time and attempted to take exastive action by changing lanes but was unable to because of oncoming traffic struck rear of Vehicle 2.	490143022029
127	36466234	11/10/2016	3:48:00 PM	4	PROPERTY DAMAGE AND	DAYLIGHT	DRY	CLEAR		WEST	OTHER		940T43011005
128	36480340	11/18/2016	5:15:00 PM	2	INJURY NON- REPORTABLE	DARK-ROAD LIGHTED	DRY	CLOUDY	FOLLOWING TOO CLOSELY	WEST	REAR END	VEHICLE-1 WAS WESTBOUND ON THE INNERLOOP WHEN VEHICLE-2 ALSO WESTBOUND STRUCK VEHICLE-1 ON THE REAR BUMPER. VEHICLE-2 THEN LEFT SCENE.	940T43011005
129	36483655	11/20/2016	8:37:00 PM	2	PROPERTY DAMAGE	DARK-ROAD LIGHTED	SNOW/ICE	SNOW	FOLLOWING TOO CLOSELY	EAST	REAR END	VEH 1 AND VEH 2 EASTBOUND 1490 AT THE INNER LOOP. VEH 2 SLOWING FOR AN UNINVOLVED MVA AHEAD. VEH 1 STRUCK REAR OF VEH 2 CAUSING DAMAGE TO BOTH VEHICLES.	490143022026
130	36496010	11/20/2016	9:01:00 PM	1	PROPERTY DAMAGE	DARK-ROAD LIGHTED	SNOW/ICE	SNOW	UNSAFE SPEED	EAST	OTHER	VEH 1 EASTBOUND 1490 AT INNER LOOP. VEH 1 LOST CONTROL ON SNOW COVERED ROAD STRKING CONCRETE CAR BARRIER CAUSING DAMAGE TO BOTH VEH 1 AND BARRIER. DRIVER 1 SUSPENDED.	490143022026
131	36496031	11/24/2016	2:10:00 PM	1	PROPERTY DAMAGE AND INJURY	DAYLIGHT	WET	RAIN	UNSAFE SPEED	EAST	OTHER	VEH 1 EASTBOUND INNER LOOP RAMP FROM 1490 EAST. VEH 1 UINSAE SPEED FOR CURVE AND DRIVER 1 LOST CONTROL. VEH 1 STRUCK CONCRETE BARRER AT LEAST TWICE CAUSING SERDUS DAMAGE TO VEH 1. DRIVER 1 TRANSPORTED TO ROCHESTER GENERAL HOSPITAL WITH COMPLANT OF BACK PAIN. DRIVER 1 HOLDS A SUSPENDED LICENSE	490143022029
132	36494111	11/27/2016	2:12:00 AM	2	NON- REPORTABLE	DARK-ROAD LIGHTED	WET	CLOUDY	OUTSIDE CAR DISTRACTION, FOLLOWING TOO CLOSELY	WEST	REAR END	V1 AND V2 TRAVELING WEST ON THE INNER LOOP JUST EAST OF STATE ST. V1 CAME TO A STOP IN THE CENTER LANE! NO AN STATE WE WELLE MERGE ONTO THE INNER LOOP, OPERATOR OF V1 STATED HE WAS WAITING FOR THE OTHER UNINVOLVED VEHICLE SO THAT HE COULD MERGE RIGHT TO GET OFF AT THE STATE ST EXIT. AS V1 WAS STOPPED IN THE LANE, V2 WAS DUMBALE TO AVOID STREMS THE READ OF V1.V1 TORVEN FROM SCENE. V2 TOWED FROM SCENE. NO INJURIES REPORTED.	
133	36509246	12/1/2016	7:46:00 AM	3	PROPERTY DAMAGE	DAYLIGHT	DRY	CLOUDY	FOLLOWING TOO CLOSELY	WEST	OTHER	THE OPERATOR': S OF V-2 AND V-3 BOTH STATE THEY WERE STOPPED IN TRAFFIC ON THE INNER LOOP WB AT I + 400 WHEN THEY WERE STRUCK IN THE RAME NO OF V-1. THE OPERATOR V-1 STATES HE WAS PLAYING WITH HER CAR RADO AND DO NOT REALIZE V-2 AND V-3 WERE STOPPED. V-1 THEN STRUCK V-2 IN THE FEAR END. THE MPACT CAUSE V-2 TO STRIKE V-3. SUBSEQUENT TO THE ACCOBENT I CONDUCTED A CHECK ON ALL OF THE OPERATOR&APOS: LICENESS I TWAS DETERMINED THAT THE LICENSE OF OPERATOR&APOS: LICENESS I TWAS DETERMINED THAT THE LICENSE OF OPERATOR&APOS:	
134	36503288	12/1/2016	8:43:00 PM	2	PROPERTY DAMAGE	DARK-ROAD LIGHTED	DRY	CLOUDY	PASSING OR LANE USAGE IMPROPERLY	WEST	OVERTAKING	V-1 and V-2 both traveling west bound on the innerloop in The City of Rochester. V-1 and V-1 both start to change lanes at the same lime neither operators seeing the other causing a side swipe to both vehicles. No injuries, No tows.	
135	36514048	12/5/2016	8:55:00 AM	2	NON- REPORTABLE	DAYLIGHT	WET	CLOUDY	PASSING OR LANE USAGE IMPROPERLY	WEST	OVERTAKING	Op Veh-2 traveling in the right most lane, west bound on Inner Loop in the CRochester. Op Veh-1 traveling on the Inner loop, west bound, behind Veh-2, passes Veh-2 and shikes same on passenger side door of Veh-2 as they are passing then leaves the scene of the accident.	940T43011004
136	36505230	12/5/2016	8:57:00 AM	2	NON- REPORTABLE	DAYLIGHT	WET	RAIN	DRIVER INATTENTION	SOUTH-WEST	REAR END	Direct 2 salled that he was west bound on the inner loop stopped for a separate motor vehicle accident which had occurred ahead and was struck from behind by Vehicle 1. Driver 1 salled that he was west bound on the inner loop became distracted while attempting to change to the middle lane and struck Vehicle 2. There were no intries bows, or arress. Closed.	940T43011006
137	36508219	12/5/2016	4:09:00 PM	2	NON- REPORTABLE	DUSK	DRY	CLOUDY	PASSING TOO CLOSELY	WEST	OVERTAKING	Driver 1 stated that she altempted to pass Vehicle 2 because she believed that she was in it&aposs blind spot. Driver 1 then shopped abruply for slopped traffic ahead. Driver 2 shed that Vehicle 1 passed Vehicle 2 on the right of the narrowing on ramp and slopped abruply for slopped traffic ahead. Driver 2 was unable to avoid stiking Vehicle 1 due to the abrupt slop and narrowing roadway. Vehicle 2 trailer: TN Registration US70179 VIN 3HSV482CIGT091022. There were no injuries, lows, or arrests.	

TE 213 (9/79)						DOUTE NO OR	OTDEET NAME						
COUNTY:	MONROE		P.I.N.:	NOT APPLICAB	BLE	ROUTE NO. OR					CASE No.:		
	TOWN		•'			INNER LOOP (N					FILE:	PSC	-
	CITY VILLAGE OF	ROCHESTI	ER			AT INTERSECT FROM I-490 INT			RMINUS AT N. UNION ST		DATE:	PSC 5/13/2020	-
TIME PERIOD		FROM: 8/1/14	TO: 7/31/19	ENVIRONMENT Use Codes from at right) for these	n MV 104 (shown e categories	Light Conditions: 1. Daylight 2. Dawn 3. Dusk 4. Dark Road Light 5. Dark Road Ur	yhted	Roadway Surface 1. Dry 2. Wet 3. Muddy 4. Snowlice 5. Slush 10. Other	ce Condition: Weather: 1. Clear 2. Cloudy 3. Rain 4. Snow 5. Sleet/Hall/Fre 6. Fog/Smog/Sr 10. Other				
No. OF MONTH	S:	6	0	S		SNOI					¹ Use Codes from	MV 104 Police Report	
CRASH No.	CASE No.	DATE	TIME	No. of VEHICLES	SEVERITY	LIGHT CONDITIONS	ROADWAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING FACTORS	DIRECTION	TYPE ¹	DESCRIPTION	REFERENCE MARKER
138	36514660	12/9/2016	1:41:00 AM	1	PROPERTY DAMAGE	DARK-ROAD LIGHTED	SNOW/ICE	SNOW	PAVEMENT SLIPPERY	NORTH-EAST	OTHER	VI was taveling northeast altempling to enter innertoop interchange at Phymoth Ave. White negotating a sight left turn onto the ramp, the officer lost control of the vehicle due to snow and ce covered roads. VI began to spin and then struck the curbing. VI left the roadway after stiking the curbing and collided with a guardraf causing the listed damage. The driver of VI was the only occupant and no highly was compliated of or observed by RO. Photos were completed and the vehicle was towed to the drivers house.	940T43011002
139	36519685	12/10/2016	2:09:00 AM	2	PROPERTY DAMAGE	DARK-ROAD LIGHTED	DRY	CLEAR	UNSAFE SPEED	WEST	OVERTAKING		
140	36527563	12/15/2016	10:43:00 AM	1	PROPERTY DAMAGE AND INJURY	DAYLIGHT	SNOW/ICE	SNOW	UNSAFE SPEED	WEST	OTHER	Oper V1 westbound Innerloop, City of Rochester. As a result of unsafe speed and slippery pavement V1 loses control and strikes a cement barrier. Barrier was not damaged.	940T43011005
141	36527578	12/17/2016	6:49:00 AM	2	PROPERTY DAMAGE	DUSK	SNOW/ICE	SNOW	UNSAFE SPEED	EAST	REAR END		940T43011008
142	36538842	12/22/2016	7:27:00 PM	2	PROPERTY DAMAGE AND INJURY	DARK-ROAD LIGHTED	WET	CLEAR	UNSAFE LANE CHANGE	EAST	OVERTAKING	OP V-1 EB NNER LOOP RIGHT LANE. OP V-2 EB NNER LOOP PASSING LANE. OP V-1 ATTEMPTS LANE CHANGE INTO PASSING LANE STRIKING V-2 IN ROADWAY THEN OVERTURNING Amp: COMING TO REST IN ROADWAY, CBA. WITHESS 1 SHATTUCK, STEPHANE M 688 EAST AVE 9A ROCHESTER NY 14607 6073688107	940T43011003
143	36540902	12/25/2016	12:58:00 AM	1	PROPERTY DAMAGE	DARK-ROAD LIGHTED	WET	CLOUDY	UNSAFE SPEED	WEST	OTHER	V-1 traveling WB 490 from the Inner Loop. Operator states she had a diabetic episode and lost control of the vehicle causing V-1 to strike the quide rail. EMS refused at scene.	490143022026
144	36542380	12/26/2016	8:50:00 AM	1	NON- REPORTABLE	DAYLIGHT	SNOW/ICE	RAIN	UNSAFE SPEED	EAST	OTHER	V1 was traveling eastbound on the inner loop onto I-490 in the city of Rochester. V1 lost control due to the slipperyice covered pavement, collided with the barrier and came to rest in the middle of the road.	940T43011002
145	36542382	12/26/2016	8:50:00 AM	1	PROPERTY DAMAGE AND INJURY	DAYLIGHT	SNOW/ICE	RAIN	UNSAFE SPEED	EAST	OTHER	0	940T43011002
146	36542384	12/26/2016	8:50:00 AM	1	PROPERTY DAMAGE	DAYLIGHT	SNOW/ICE	RAIN	UNSAFE SPEED	EAST	OTHER	V1 was traveling eastbound on the inner loop onto I-490 in the city of Rochester. V1 lost control due to the slippenyice covered pavement, collided with the barrier and came to rest.	940T43011002
147	36563817	1/12/2017	11:52:00 PM	1	NON- REPORTABLE	DARK-ROAD LIGHTED	DRY	CLEAR	UNSAFE LANE CHANGE	WEST	OTHER	VI WAS TRAVELING WESTBOUND ON INNER LOOP AT JOSEPH AVENUE OFF RAMP IN THE CITYOF ROCHESTER. DUE TO UNSAFE LANC CHANGE, ALCOHOL INVOLVEMENT AND SPEED NOT REASONABLE AND PRUDENT, VI LOST CONTROL OF VEHICLE AND STUCK THE GUIDERAL WITH FRONT BUMPER OF VEHICLE CAUSING VISBLE DAMAGE. NO NUMBES WERE REPORTED AND VEHICLE WAS TOWED FROM SCENE BY JON AND SON COLLISION TO ROCHESTER CITY POUND. DRIVER OF VI, DUE TO FURTHER NOVESTIGATION WAS SUBSCUENTLY ARRESTED FOR D.W.I., CITED FOR UNSAFE LANC CHANGE AND SPEED NOT REASONABLE AND PRUDENT. Tickets ISSUE! KAILENE E JEFFRES DHEY OYHEICH DEVINION CHANGE AND SPEED NOT MEASONABLE AND PRUDENT. Tickets SUSUE! KAILENE E JEFFRES DHEY OYHEICH MORDE. M.Z. 106,14W/SD VIOLATION. 11923. TICKEN Number: M.Z. 106,14W/SD VIOLATION: 11923.	940T43011011
148	36591514	2/2/2017	12:22:00 PM	1	NON- REPORTABLE	DAYLIGHT	WET	CLOUDY	REACTION TO OTHER UNINVOLVED VEHICLE	WEST	OTHER	OPERATOR OF VEHICLE 1 STATES THAT SHE WAS ON THE WINERLOOP WESTEOUND PERFARRIG TO ENTER THE RAMP TO 1-490 WEST. AN UNINVOL VED VEHICLE CAME ACROSS AND ENTERED VEHICLE 1-18 apos S LANE. OPERATOR OF VEHICLE 1 STATED THAT SHE LOST CONTROL OF VEHICLE AND STRUCK CURB ON SOUTH SHOULDER CAUSING DAMAGE TO RIGHT SUB OF VEHICLE ALONG WITH ALL FOUR TREES.	940T43011002
149	36594612	2/4/2017	11:36:00 AM	1	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	ACCELERATOR DEFECTIVE	WEST	OTHER	Oper V1 westbound innerloop, Cily of Rochester. Oper V1 states as a result of the gas pedal slicking to the floor, he lost control and struck a barrier. No damage to barrier WITNESS 1 BELL, ROBIN M 200 SETHGREEN DR APT 402 ROCHESTER NY 14619 585/991824	940T43011003
150	36607537	2/13/2017	7:50:00 AM	1	PROPERTY DAMAGE	DAYLIGHT	SNOW/ICE	SNOW	UNSAFE SPEED	WEST	OTHER	OPER. V1 WESTBOUND ON THE NNER LOOP IN THE LEFT LANE WHEN SHE FALED TO RECOTTATE THE CURVE ON THE SONG COVERED FROADUMY. V1 SLO INTO THE GUIDERAL IN THE CENTER MEDIAN CAUSING DAMAGE TO THE DRIVER SOE FROM TAIN DEAR FENDERS. NO INJURIES REPORTED AND V1 WAS DRIVEN FROM THE SCENE.	940T43011007
151	36621747	2/27/2017	4:10:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	EAST	REAR END	V-1 following V-2 east on the Rochester City Interloop when V-2 slopped abruptly for traffic ahead. V-1 struck the rear of V-2 causing minor damage to both vehicles.	940T43011014
152	36640823	3/11/2017	8:27:00 PM	2	PROPERTY DAMAGE	DARK-ROAD LIGHTED	SNOW/ICE	SNOW	UNSAFE LANE CHANGE	WEST	OVERTAKING	V-1 driving West on the inner loop in the right lane. V-2 driving in the left lane swened into V-1 striking the rear driver side quarter panelbumper area of V-1 with the front passenger side quarter panel area causing damage to both vehicles. V-2 described as a	940T43011010
153	36646803	3/15/2017	4:59:00 PM	2	NON- REPORTABLE	DAYLIGHT	SNOW/ICE	CLOUDY	UNSAFE LANE CHANGE	WEST	OVERTAKING	red sedan lette scene. VEHICLE: WAS WESTBOUND ON THE INNERLOOP WHEN VEHICLE: ALSO WESTBOUND ENTERS VEHICLE: T\u00e4apos.S LANE AND STRIKES VEHICLE: ON THE LEFT SDE OF PLOW. VEHICLE: THEN LEFT SCENE. VI WAS WESTBOUND ON THE ROCHESTER INNERLOOP IN	940T43011005
154	36646819	3/16/2017	7:42:00 AM	1	NON- REPORTABLE	DAYLIGHT	WET	CLOUDY	UNSAFE SPEED	WEST	OTHER	VT WAS WESTBOUND ON THE ROCHESTER INNERCOOP IN THE right LANE. VT SLOWS FOR TRAFFIC AND LOSES CONTROL STRIKING OVERPASS WALL THEN CROSSES LANES AND STRIKES GUIDERAIL.	940T43011007
155	36646821	3/16/2017	10:40:00 AM	1	NON- REPORTABLE	DAYLIGHT	WET	CLOUDY	UNSAFE LANE CHANGE	EAST	OTHER	V1 EASTBOUND ON THE ROCHESTER INNELOOP IN RIGHT LANE. V1 REACTS TO UNINVOLVED VEHICLE AND MOVES FROM LANE TO RIGHT, STRIKING CONCRETE WALL.	940T43011009

TE 213 (9/79)						ROUTE NO. OR	STDEET NAME						
COUNTY:	MONROE		P.I.N.:	NOT APPLICAB	LE	INNER LOOP (N					CASE No.:		_
	TOWN CITY					AT INTERSECT					FILE:	PSC	-
	VILLAGE OF	ROCHESTI	ER						RMINUS AT N. UNION ST		DATE:		-
TIME PERIOD		FROM:	TO:	ENVIRONMENT	ΓΔΙ ·	Light Conditions:		Roadway Surface					
TIME PERIOD		8/1/14	7/31/19		n MV 104 (shown e categories		yhted	1. Dry 2. Wet 3. Muddy 4. Snowlice 5. Slush 10. Other	1. Clear 2. Cloudy 3. Rain 4. Snow 5. Sleet/Hal/Fre 6. Fog/Smog/Sr 10. Other				
No. OF MONTH	S:	6	0	S		IONS					¹ Use Codes from	MV 104 Police Report	
CRASH No.	CASE No.	DATE	TIME	No. of VEHICLES	SEVERITY	LIGHT CONDITIONS	ROADWAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING FACTORS	DIRECTION	TYPE ¹	DESCRIPTION	REFERENCE MARKER
156	36649408	3/19/2017	11:53:00 PM	3	PROPERTY DAMAGE	DARK-ROAD LIGHTED	WET	CLOUDY	UNSAFE SPEED	WEST	OTHER	V-1, V-2 AND V-3 ALL WESTBOUND ON THE RNER LOOP, OPERATIOR OF V-1 INTOXCATED BY ALCOHOL AND GOING TOO FAST FOR CONDITIONS REAR ENDS V-2. THIS CAUSES V-2 TO SPIN AND STRIKE CENTER MEDIANI. A FTER STRIKING MEDIANI. A PER VISIT OF STRIKING WEDIANI. V-3 WITNESS 1 BUSH, NICHOLE L. STRUCK BY V-3 WITNESS 1 BUSH, NICHOLE L. STRUCK BY V-3 WITNESS 1 BUSH, NICHOLE L.	940T43011004
157	36654577	3/21/2017	6:46:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	WEST	REAR END	V1 AND V2 WERE WESTBOUND ON THE INNERLOOP IN THE CROCHESTER. AS V2 WAS SLOWING DOWN DUE TO HEAVY TRAFFIC V1 COULD NOT SLOW DOWN IN TIME AND STRUCK V2 IN THE REAR. CLOSED.	940T43011004
158	36670088	3/22/2017	5:07:00 PM	3	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	WEST	OTHER	OPER V1, V2 AND V3 WEST BOUND INNERLOOP IN THE CITY OF ROCHESTER. AS A RESULT OF FOLLOWING TOO CLOSELY V1 FIRST REAR ENDS V2. V2 IS THEN PUSHED INTO V3.	940T43011004
159	36663710	3/28/2017	3:25:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLOUDY	FOLLOWING TOO CLOSELY	WEST	REAR END	V-1 west off inner loop merging onto west 490 when V-2 struck rear of V-1. V-2 fled scene , unknown registration to a blue Chevrolet pickup. V-1 sustained minor damage to left rear.	490143022026
160	36673788	4/4/2017	12:43:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	WET	RAIN	UNSAFE SPEED	WEST	OVERTAKING		940T43011006
161	36681012	4/10/2017	5:14:00 PM	3	PROPERTY DAMAGE	DAYLIGHT	DRY	CLOUDY	FOLLOWING TOO CLOSELY	WEST	OTHER	JUNIT J. AND UNIT 3 ALL TRAVEL WESTBOUND ON THE ROCHESTER NURE LOOP RIGHMAN THE CITY OF ROCHESTER. UNIT 3 AND UNIT 2 SLOW THER SPEED FOR TRAFFIC CONGESTION AHEAD. UNIT 1, FOLLOWING UNIT 2 TOO CLOSELY, FALS TO SLOW SPEED AND SUBSCOURTLY REAR ENDS UNIT 2. UNIT 2, AS A RESULT OF BEING REAR ENDED BY UNIT 1, CHITY LIES ON AND SUBSCOURTLY REAR ENDS UNIT 3. THE DRIVET OF BOTH UNIT 1, AND UNIT 2 STATE THAT UNIT 3 HAD VERY MINOR DAMAGE AND THE DRIVER DID NOT REMAIN ON SCENE FOR AN ACCIDENT REPORT	940T43011005
162	36685621	4/11/2017	5:10:00 PM	2	PROPERTY DAMAGE AND INJURY	DAYLIGHT	DRY	CLOUDY	FOLLOWING TOO CLOSELY	WEST	REAR END		940T43011004
163	36685740	4/12/2017	8:27:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLOUDY	UNSAFE LANE CHANGE	WEST	OVERTAKING		940T43011005
164	36694024	4/19/2017	5:28:00 PM	2	NON- REPORTABLE	DAYLIGHT	WET	RAIN	FOLLOWING TOO CLOSELY	WEST	REAR END	Oper V1 and V2 westbound Innerloop, City of Rochester. As a result of following too closely V1 rear ends V2. Closed.	940T43011003
165	36699398	4/25/2017	5:10:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLOUDY	FOLLOWING TOO CLOSELY	WEST	REAR END	V-1 slow moving west bound on innerloop ramp to west 490 when driver was struck from behind. V-2 unable to stop in time struck	
166	36710003	5/2/2017	3:27:00 PM	2	PROPERTY DAMAGE AND INJURY	DAYLIGHT	DRY	CLOUDY	FOLLOWING TOO CLOSELY	WEST	REAR END	the rear of V-1 causing damage to both vehicles. VEHICLE-1 WAS WESTBOUND ON THE INNERLOOP WHEN VEHICLE-2 ALSO WESTBOUND STRUCK VEHICLE-1 ON THE REAR BUMPER.	940T43011004
167	36710011	5/3/2017	4:19:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	UNSAFE LANE CHANGE	WEST	OVERTAKING	Driver 1 saled that he was west bound in the middle lane of the hiner Loop, did not observe Vehicle 2, changed to the lett lane, and struck Vehicle 1. Driver 2 stated that he was west bound in the lett lane of the Inner Loop, Vehicle 1 changed from the middle to the lett lane and struck Vehicle 2. There were no injuries, bws, or arrests.	940T43011006
168	36712606	5/5/2017	4:34:00 PM	2	NON- REPORTABLE	DAYLIGHT	WET	CLOUDY	UNSAFE LANE CHANGE	WEST	OVERTAKING	VEHICLE-1 WAS WESTBOUND ON THE INNERLOOP. VEHICLE- 2 ALSO WESTBOUND CHANGING LANES ENTERED VEHICLE- 18apos; S LANE AND STRUCK VEHICLE-1 ON THE LEFT FRONT PANEL.	940T43011010
169	36716945	5/8/2017	4:20:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	WEST	REAR END	Oper V1 and Oper V2 west bound Innerloop, City of Rochester. As a result of following too closely V1 rear ends V2. Closed.	940T43011004
170	36719951	5/9/2017	7:59:00 AM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	WEST	REAR END	V1 AND V2 TRAVELING WEST ON THE INNER LOOP NEAR STATE ST. V2 SLOWS FOR TRAFFIC AND V1 STRIKES REAR OF V2. BOTH VEHICLES DRIVEN FROM SCENE. NO INJURIES.	940T43011004
171	36721230	5/9/2017	8:06:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLOUDY	UNSAFE LANE CHANGE	WEST	OVERTAKING	V-2 LEFT LANE TRAVELING WB ON THE INNER LOOP, V-1 FAILS TO OBSERVE V-2 AND SIDE SWIPES V-2. ALL PARTIES REPORT NO INJURIES. UNINVOLVED MVA WAS BLOCKING RIGHT LANE AHEAD. ALL PARTIES REPORT NO INJURIES.	940T43011004
172	36716971	5/9/2017	3:21:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY, REACTION TO OTHER	EAST	REAR END		940T43011008
173	36718119	5/10/2017	4:49:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLOUDY	UNSAFE LANE CHANGE	WEST	REAR END	VEHICLE-1 WAS WESTBOUND ON THE INNERLOOP. VEHICLE- 2 WAS ALSO WESTBOUND CHANGING LANES. VEHICLE-2 STRUCK VEHICLE-1 ON THE REAR BUMPER.	940T43011006
174	36719954	5/10/2017	5:25:00 PM	3	PROPERTY DAMAGE AND INJURY	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	WEST	OTHER		940T43011005
175	36725815	5/16/2017	7:58:00 AM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	UNSAFE SPEED	WEST	REAR END	V1 AND V2 WERE WESTBOUND ON THE INNERLOOP IN THE CROCEHSTER. AS V2 WAS SLOWING DOWN DUE TO HEAVY STOP AND GO TRAFFIC, V1 COULD NOT SLOW DOWN IN TIME AND STRUCK V2 IN THE REAR. CLOSED.	940T43011004
176	36745969	5/25/2017	10:54:00 AM	2	NON- REPORTABLE	DAYLIGHT	WET	RAIN	REACTION TO OTHER UNINVOLVED VEHICLE, FOLLOWING TOO CLOSELY	EAST	REAR END	Vehicles 1 and 2 are in the letitane on the ramp to the innerloop and Plymouth Avenue. Vehicle 1 slows abruply and stops unsure what an unknowed noncontact tractor trailer in the right lane was going to do just ahead of thim. Vehicle 2 alempts to steer letit to avoid stiking the rear of vehicle 1. The right front corner of vehicle 2.5 titles the letit roar corner of vehicle 1. Operator V-1 alempt care for vehicle 1. Operator V-1 approaches the exitramp from the Innerloop to SIRT	940T43011002
177	36769750	6/2/2017	11:56:00 PM	1	PROPERTY DAMAGE AND INJURY	DARK-ROAD LIGHTED	DRY	CLEAR	UNSAFE SPEED	SOUTH-WEST	OTHER	Operator V-1 approaches he exitramp from the Innerloop to SIRI 490 Wesbound but last he negoliste burn and crashes bide into grassy area next to road. Operator transported to Strong Memorial Hospital where boods is drawn in suspicion of Driving White Intoxicated. Vehicle towed to City Impound by Exect. Tickets Sesued: GARY O WALKER Driver of Vehicle number (1) lickets. Ticket Number: 122171662 Violetion: 1128A Ticket Number: 12171662 Violetion: 128A Ticket Number: 122171671 Violation: 1308 Ticket Number: 122171671 Violation: 308 Ticket Number: 122171671 Violation: 308 Ticket Number: 122171671 Violation: 5093 Ticket Number: 1221716807 Violation: 11923.	I

TE 213 (9/79)						ROUTE NO. OR	CTDEET NAME						
COUNTY:	MONROE		P.I.N.:	NOT APPLICAB	LE						CASE No.:		
	TOWN		•			INNER LOOP (N					FILE:		- -
	VILLAGE OF	ROCHEST	ER			AT INTERSECT					BY: DATE:		-
	•				-				RMINUS AT N. UNION ST				_
TIME PERIOD		FROM: 8/1/14	TO: 7/31/19	ENVIRONMENT Use Codes from at right) for these	n MV 104 (shown e categories	Light Conditions: 1. Daylight 2. Dawn 3. Dusk 4. Dark Road Lig 5. Dark Road Ur	yhted	Roadway Surfact 1. Dry 2. Wet 3. Muddy 4. Snowlice 5. Slush 10. Other	te Condition: Weather: 1. Clear 2. Cloudy 3. Rain 4. Snow 5. SleeVHallVFree 6. Fog/Smog/Sn 10. Other				
No. OF MONTH	S:	6	0	S		SNOI					¹ Use Codes from	MV 104 Police Report	
CRASH No.	CASE No.	DATE	TIME	No. of VEHICLES	SEVERITY	LIGHT CONDITIONS	ROADWAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING FACTORS	DIRECTION	TYPE ¹	DESCRIPTION	REFERENCE MARKER
178	36773542	6/6/2017	5:17:00 PM	2	NON- REPORTABLE	DAYLIGHT	WET	RAIN	FOLLOWING TOO CLOSELY	SOUTH-WEST	REAR END	V-1 and V-2 both taveling southwest bound on the Inner Loop in the right lane. V-2 has to come be a stop due to uninvolved vehicles that stop in front of her. V-1 is unable to stop in time and V-1 rear ends V-2 causing said damage. Damage appeared to be minor.	940T43011004
179	36767517	6/15/2017	5:24:00 PM	3	NON- REPORTABLE	DAYLIGHT	DRY	CLOUDY	FOLLOWING TOO CLOSELY	WEST	OTHER	OPER V1, V2 AND V3 WEST BOUND INNERLOOP, CITY OF ROCHESTER. AS A RESULT OF FOLLOWING TOO CLOSELY V1 FIRST REAR ENDS V2. V2 THEN REAR ENDS V3.	940T43011005
180	36785731	6/27/2017	5:25:00 PM	2	PROPERTY DAMAGE AND INJURY	DAYLIGHT	DRY	CLOUDY	FOLLOWING TOO CLOSELY	WEST	REAR END	V-1 TRAVELING WB ON THE INNER LOOP IN THE RIGHT LANE BEHIND V-2. V-2 STOPS FOR TRAFFIC STOPPED AHEAD. OP-1 FOLLOWING TOO CLOSELY AT AN UNSAFE SPEED IS UNABLE TO STOP AND REAR FINDS V-2	940T43011004
181	36802838	7/10/2017	10:26:00 PM	2	PROPERTY DAMAGE	DARK-ROAD LIGHTED	WET	CLOUDY	PASSING TOO CLOSELY	EAST	OVERTAKING	TO STOP AND REAR EALDS V.2. VEH 2 PARKED ON RAMP WITH CONE WHILE PERFORMING MAINTENANCE TO OVERHEAD STREET LIGHTS. VEH 1 TRIED TO FIT BETWEEN CURB AND VEH 2. VEH 1 STRUCK THE SIDE OF VEH 2 CAUSING DAMAGE TO BOTH VEHICLES.	
182	36806731	7/13/2017	7:05:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLOUDY	UNSAFE LANE CHANGE	WEST	OVERTAKING	UNIT 1 TRAVELS WB ON THE NNER LOOP IN THE RIGHT LANE IN THE CITY OF ROCHESTER. UNIT 2 TRAVELS WB ON THE MINER LOOP IN THE LEFT LANE IN THE CITY OF ROCHESTER. DRIVER OF UNIT 1 STATES HE WAS MERGING INTO THE LEFT LANE, USING HIS TURN SIGNAL, WHEN HE OBSERVED UNIT 2 SEPEDING PAST HIM. DRIVER OF UNIT 1 SUBSCOUENTLY SIDE SWIPES UNIT 2 WHILE CHANGING LANES. DRIVER OF UNIT 2 STATES SHE WAS TRAVELING WB IN THE LEFT LANE ON THE INNER LOOP AND WAS TRAVELING THE SPEED LIMIT. DRIVER OF UNIT 2 FIRTHER STATES THE DRIVER OF UNIT 1 MERGED INTO HER AND SIDE SWIPED HER VEHICLE.	940T43011004
183	36815734	7/20/2017	11:33:00 AM	2	INJURY	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	WEST	REAR END	VEH 1 AND VEH 2 WESTBOUND INNER LOOP CROCHESTER. VEH 2 SLOWED FOR UNINVOLVED VEHICLE THAT APPEARED AS F IT WOULD IMERGE ATTO VEH 28apps SLAW VEH 1 STRUCK REAR OF VEH 2 CAUSING DAMAGE TO BOTH VEHICLES. DRIVER 2 COMPLAINT OF RIGHT FOOT PAIN BUT REFUSED EMS AT SCENE.	940T43011005
184	36818598	7/22/2017	8:15:00 PM	1	NON- REPORTABLE	DUSK	DRY	CLOUDY	STEERING FAILURE	EAST	OTHER	Driver of V-1 stated his steering was loose as driver was east on Rochester inner loop. V-1 lost steering and shot off right shoulder of inner loop striking a dirt embankment.	940T43011010
185	36827069	7/26/2017	5:32:00 PM	2	PROPERTY DAMAGE AND INJURY	DAYLIGHT	DRY	CLOUDY	FOLLOWING TOO CLOSELY	EAST	REAR END	UNIT JAND UNIT 2 BOTH TRAVEL EB ON THE INNER LOOP IN THE CITYOF ROCHESTER. UNIT 2 SLOWS SPEED FOR TRAFFIC CONGESTION AHEAD. UNIT 1, FOLLOWING UNIT 2 TOO CLOSELY, FAILS TO SLOW SPEED AND SUBSCOUENTLY REAR ENDS UNIT 2. THE PRINTER OF UNIT 1, DESCREED BY THE DRIVER OF UNIT 2. THE PRINTER OF UNIT 1 OF SCREED BY THE DRIVER OF UNIT 2 AS A SQUOBLACK MALE SQUID, FLED FROM THE SCENE ON FOOT IN AN UNKNOWN DIRECTION OF TRAVEL. UNIT 1 HAD IMPROPER PLATES, WAS UNINESSTERED, UNINSURED, AND A DAWN MOUNTY OF THE WIN PRODUCED ON INFORMATION AS TO WHO THE	940T43011013
186	36825894	7/27/2017	12:19:00 PM	1	NON- REPORTABLE	DAYLIGHT	WET	RAIN	PAVEMENT SLIPPERY	SOUTH	OTHER	REGISTERED OWNER IS. V-1 was southbound in the left passing lane on the Inner Loop. V-1 1 encountered a pool of standing water partially obstructing the left passing lane. V-1 hydroplaned into the eastern guard rail.DOT notified of the standing water and damaged guard rail.	
187	36831519	7/31/2017	4:54:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	WEST	REAR END	V1 AND V2 TRAVELING WEST ON THE INNER LOOP. V2 SLOWS FOR TRAFFIC AHEAD AND V1 STRIKES REAR OF V2.	940T43011004
188	36850630	8/14/2017	3:52:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	WEST	REAR END	V1 AND V2 TRAVELING IN THE RIGHT LANE WESTBOUND ON THE INNER LOOP NEAR 1490. V1 FALLED TO OBSERVE V2 BRAKING FOR STOPPED TRAFFIC, SUBSEQUENTLY STRIKING THE REAR OF V2. NO INJURIES	940T43011000
189	36850632	8/15/2017	2:20:00 PM	1	NON- REPORTABLE	DAYLIGHT	WET	RAIN	UNSAFE SPEED	WEST	OTHER	Driver of V1 states it was traveling west bound on the Rochester Inner Loop when it lost control due to flooding water in the roadway. V1 silkes guide rail off the south shoulder of the roadway. NYS DOT notified about the guide rail and flooding in the roadway. Vehicle driven from the scene.	940T43011011
190	36850636	8/15/2017	4:37:00 PM	2	INJURY	DAYLIGHT	WET	CLOUDY	UNSAFE SPEED	WEST	HEAD ON	Diver of V2 states that V1 was west on Rochester Inner Loop when V1 hydroplanes and loses contol V1 strikes he guide rail off the south shoulder which causes her vehicle to spin 180 degrees and strike V2 head on. V2 states that she was traveling west on Rochester Inner Loop when she is re-ended by V2 causing her to spin 90 degrees, V2 then strikes V1 in a T-bone syle collision causing V1 to spin out and strike the concrete barrier on the north shoulder. NYS DOT notfled about the damaged guide	
191	36874616	8/22/2017	8:30:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	UNSAFE LANE CHANGE	EAST	OVERTAKING	Tail and he fooding in the markery I YAND V2 WEER EASTBOUND ON THE INNERLOOP NEAR PLYMOUTH AVE IN THE CROCKESTER. AS V1 WENT TO CHANGE LANES TO GO AROUND V2. V1 SIDE SWPED V2 WITH THE TRAILER AND THEN LEFT THE SCENE OF THE ACCIDENT. DRIVER 2 DID NOT PRIVIDE ANY INFORMATION ON V1 OTHER THAN THAT IT WAS A SMALL RED VEHICLE PULLING A TRAILER AND THAT THE TRAILER WAS WHAT STRIICK HER VEHICLE. CLOSED.	940T43011006
192	36864547	8/22/2017	2:14:00 PM	1	PROPERTY DAMAGE	DAYLIGHT	WET	CLOUDY	UNSAFE SPEED	WEST	OTHER	VEHICLE-1 WAS WESTBOUND ON THE INNERLOOP. DRIVER DRIVES OVER WATER PUDDLE AND LOSES CONTROL OF VEHICLE AND STRIKES GUARD-RAIL ON SOUTH SHOULDER CAUSING DAMAGE TO FRONT-END.	940T43011008
193	36861747	8/22/2017	3:48:00 PM	1	NON- REPORTABLE	DAYLIGHT	WET	RAIN	UNSAFE SPEED	WEST	OTHER	V-1 driving in the left lane West on the Inner loop drives through standing water causing V-1 to hydro plane striking the guide rall in the center median causing minor damage to the front bumper of V- 1.	

TE 213 (9/79)						DOLLTE NO. OD	CTDEET NAME						
COUNTY:	MONROE		P.I.N.:	NOT APPLICAB	LE	ROUTE NO. OR					CASE No.:		
	TOWN		•			INNER LOOP (N					FILE:	PSC 5/13/2020	- -
	CITY VILLAGE OF	ROCHEST	FR			AT INTERSECT					BY:	PSC 5/13/2020	_
	VILLY IOL OI	ROGILET	LIN			FROM I-490 INT	ERCHANGE TO	INNER LOOP TE	RMINUS AT N. UNION ST		Ditte.	3/10/2020	_
TIME PERIOD		FROM: 8/1/14	TO: 7/31/19	ENVIRONMENT Use Codes from at right) for these	n MV 104 (shown e callegories	Light Conditions: 1. Daylight 2. Dawn 3. Dusk 4. Dark Road Lig 5. Dark Road Ur	ghted	Roadway Surfar 1. Dry 2. Wet 3. Muddy 4. Snowlce 5. Slush 10. Other	ce Condition: Weather: 1. Clear 2. Cloudy 3. Rain 4. Snow 5. SleeWhall/Fre 6. Fog/Smog/Sr 10. Other				
No. OF MONTH	S:	6	0	S		ONS					¹ Use Codes from	MV 104 Police Report	
CRASH No.	CASE No.	DATE	TIME	No. of VEHICLES	SEVERITY	LIGHT CONDITIONS	ROADWAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING FACTORS	DIRECTION	TYPE ¹	DESCRIPTION VEH 1 AND VEH 2 EASTBOUND ON THE INNER LOOP	REFERENCE MARKER
194	36866095	8/27/2017	3:10:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	EAST	REAR END	VEH 1 AND VEH 2 EAS BOUNDLOW IN HE WIREL COUP EASTBOUND RAMP FROM 149 O. DRIVER 2 STATES THAT A BLACK HUMMER IN FRONT OF HER STOPPED SUDDENLY, AND SHE HAD TO BRAKE TO AVOID IT. DRIVER IT WAS UNABLE TO STOP IN TIME AND VEH 1 STRUCK VEH 2 CAUSING DAMAGET DOST VEHICLES. BLACK HUMMER WAS UNINVOLVED AND LEFT SCENE. DRIVER 1 HAS A SUSPENDED LICENSE. DRIVER 2 HAS A PERMIT ONLY WITH NO LICENSES DRIVER IN THE VEHICLE WITH HER	940T43011002
195	36872509	8/31/2017	2:14:00 PM	1	PROPERTY DAMAGE AND INJURY	DAYLIGHT	DRY	CLOUDY	UNSAFE LANE CHANGE	WEST	OTHER	VI IS WB ON THE NNERL LOOP IN THE RICHT LANE. VI OPERATOR THEN ATTEMPTS TO CHANGE LANES TO THE LEFT. VI OPERATOR DOES NOT SEE THE UNINVOLVED VEHICLE (WI) THAT SHE IS ABOUT TO HIT. WI OPERATOR THEN HITS HES NORN. VI OPERATOR THEN OUDCKLY VEERS TO THER HITS HIS NORN. VI OPERATOR THEN DIECKLY VEERS TO THER RICHT TO AVOID HITTING VI TO ATTEMPT TO EXIT AT JUSEPH AVE. VI OPERATOR THEN STRIKES AN IMPACT ATTENUATOR AT THE BOTTOM OF THE EXIT RAMP. VI THEN OVERTURNS MULTPLE TIMES AND STRIKES A GUIDE RAIL OVER THE SOUTH SHOULDER. VI THEN COMES TO REST IN THE RICHT LANE. VI TRANSPORTED BY MONROE AMR TO STRONG HOSPITAL. VI TOWED TO JOHN AND SON COLLISION. WITMESS T DEPONZIO, ANTHONYT 6169 CHILL RIGA CENTER RO CHURCHVILLE NY 14428 5855767607 - WITMESS S XESSLER, DONALD A 6 JESSICA LANE SPENCERPORT NY 14559 5853291233	940743011010
196	36879119	9/6/2017	8:00:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLOUDY	FOLLOWING TOO CLOSELY	EAST	REAR END	Vehicle 1 eastbound on the Inner Loop exiting at East Main St behind Vehicle 2 when traffic stopped on the off ramp. Operator of Vehicle 1 stated her foot slipped off the brake pedal and onto the accelerator. Vehicle 1 accelerated into the rear of Vehicle 2.	f
197	36880601	9/6/2017	6:01:00 PM	1	NON- REPORTABLE	DAYLIGHT	WET	RAIN	UNSAFE SPEED	WEST	OTHER	V1 TRAVELING WEST ON THE INNER LOOP IN THE LEFT LANE. DUE TO HEAVY RAIN THERE WAS STANDING WATER IN LEFT LANE. DOER TAND FOR THE WAS STANDING WATER IN TIME TO AVOID STANDING WATER DUE TO OTHER UNINVOLVED VEHICLES IN THE RIGHT LANE V1 TRAVELED THROUGH THE WATER AND LOST CONTROL OF THE VEHICLE STRKING THE SOUTH SHOULDER GUIDE RAIL.	940T43011011
198	36896974	9/12/2017	2:57:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	DRIVER INATTENTION	NORTH	LEFT TURN (AGAINST OTHER CAR)	The direct of VT stated that he was taveling east bound on Auen- SList vest of NP Pymouth Ave in the lane furthest north, which is designated for left hand turns only. As VT continued its travel east he then altempted to perform a left hand turn into the parking lot of SS Allen SL. While attempting to do so V2 was conducting a left hand turn also into the same parking lot. This ultimately resulted in both vehicles colliding. However, the other of VT states hat VZ was also traveling east bound but in the lane just south (right) of his when it conducted the left hand turn. The driver of VT did not report any highrise. No utrither information was given. The driver of VZ stated hat he was traveling east bound in he lane furthest north. As he altempted to conduct a left hand turn into the parking lot of SS Allen S the states that VT came out of no where and collided with the drivers rear wheel. No occupant of VZ reported any highry. No further information was given. Both verlices did	
199	36891576	9/12/2017	5:34:00 PM	4	PROPERTY DAMAGE AND INJURY	DAYLIGHT	DRY	CLEAR	UNSAFE SPEED	WEST	OTHER	obbit in damana. Molibar subilide use broad from the scone. 911 reports 4 or PDAA on the inner loop west bound. I arrived on scene interviewed all parties involved of what occurred, all web libes were travelling west bound on the inner loop. V-4. 3, and V-2 were all slopped in Italië, when V-1 strikes V-2 in rear causing a chain reaction of rear end collision. V-1 and V-2 were bread by ESA West Auto. D-V-1 was Sused ut Risapos for TVB.	940T43011005
200	36897010	9/18/2017	5:48:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLOUDY	FOLLOWING TOO CLOSELY	EAST	REAR END	OP VEH-2 STOPPED IN THE LEFT HAND LANE OF EASTBOUND INNER LOOP IN THE CROCHESTER. OP VEH-1 CHANGING LANES FROM THE RESHIT LANE TO THE LEFT LANE OF EASTBOUND TRAVEL ON THE INNER LOOP, CROCHESTER. DUE TO FOLLOWING TOO CLOSELY, OP VEH-1. STRUCK VEH-2.	940T43011011
201	36897141	9/19/2017	5:13:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	WEST	REAR END		940T43011004
202	36899258	9/21/2017	11:00:00 AM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY, UNSAFE LANE CHANGE	NORTH-EAST	OVERTAKING	V-1 and V-2 both traveling northeast bound on the off ramp from 1- 90 East for Phymouth Ave. V-1 was traveling behind V-2. Op of V 2 Stells hathe was in font of V-1 and he moved into the letitane as soon as he single lear burned into two lanes and V-1 sped up and V-1 struck V-2 causing said damage, op of V-1 stells that she was already in the letit lane when V-2 moved into her lane and V-2 struck V-1 causing said damage. Member is unable to determine who is at Buttl for the cause of the accident.	940T43011002
203	36900455	9/22/2017	4:18:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	EAST	REAR END	OPV1 TRAVELING THE INNER-LOOP EB BEHIND OPV2. AS V2 STOPS FOR TRAFFIC V1 STRIKES V2.	940T43011006
204	36907849	9/28/2017	3:56:00 PM	2	PROPERTY DAMAGE NON-	DAYLIGHT	DRY	CLOUDY	UNSAFE LANE CHANGE FOLLOWING TOO CLOSELY	EAST	OVERTAKING	V-4, V-3 STOPPED IN TRAFFIC WB ON INNER LOOP C/ROCHESTER: V-2 FOLLOWING TOO CLOSELY REAR ENDS	940T43011009
205	36933855 36939425	10/10/2017	3:51:00 PM 4:43:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	WEST SOUTH-WEST	OTHER REAR END	V.3 CAUSING V.3 TO BE PUSHED INTO V.4, V.1 UNABLE TO STOP AND REAR ENDS V.2. OPV.1 STATED THAT SHE WAS TRAVELING WESTBOUND IN THE RISHTED THAT SHE WAS TRAVELING WESTBOUND IN THE RISHT LAND. OF THE INNER LOOP WHEN SHE HAD TO STOP FOR TRAFFE IN HER LAND. WHEN V.1 STOPPED IT WAS STRUCK ON THE BACK END BY V.2. OPV.2 STATED THAT SHE TREID TO STOP BEHIND V.1 BUT WAS UNABLE TO DO SO N TIME TO AVOID STRIKE THE BACK END OF V.1.	940T43011004 940T43011003

TE 213 (9/79)						DOLLTE NO. OD	CTDEET NAME						
COUNTY:	MONROE		P.I.N.:	NOT APPLICAB	LE	ROUTE NO. OR					CASE No.:		
	TOWN		•			INNER LOOP (N					FILE:		-
	CITY VILLAGE OF	ROCHESTI	FD			AT INTERSECT	ION WITH/OR B	ETWEEN:			BY: DATE:	PSC 5/13/2020	=
	TILL TOL OF	ROCHESTI	LIK		-	FROM I-490 INT	ERCHANGE TO	INNER LOOP TE	RMINUS AT N. UNION ST		DATE.	3/13/2020	=
TIME PERIOD		FROM: 8/1/14	TO: 7/31/19	ENVIRONMENT Use Codes from at right) for these	MV 104 (shown e categories	Light Conditions: 1. Daylight 2. Dawn 3. Dusk 4. Dark Road Lig 5. Dark Road Un	hted	Roadway Surfat 1. Dry 2. Wet 3. Muddy 4. Snowlce 5. Slush 10. Other	ce Condition: Weather: 1. Clear 2. Cloudy 3. Rain 4. Snow 5. Sleet/Hall/Fre 6. Fog/Smog/Sr 10. Other				
No. OF MONTH	S:	6	0	S		ONS					¹ Use Codes from	MV 104 Police Report	
CRASH No.	CASE No.	DATE	TIME	No. of VEHICLES	SEVERITY	LIGHT CONDITIONS	ROADWAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING FACTORS	DIRECTION	TYPE ¹	DESCRIPTION	REFERENCE MARKER
207	36950707	10/22/2017	12:15:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	WEST	REAR END	OPV1 TRAVELING THE INNER-LOOP WB BEHIND OPV2. AS V2 STOPS FOR TRAFFIC V1 STRIKES V2.	940T43011014
208	36952991	10/22/2017	3:58:00 PM	2	PROPERTY DAMAGE AND INJURY	DAYLIGHT	DRY	CLEAR	UNSAFE LANE CHANGE	EAST	OVERTAKING	OPV1 TRAVELING EB ON THE INNER-LOOP PARALLEL TO OPV2. SUBSEQUENTLY V1 SIDE SWIPES V2. SHORTLY THEREAFTER OPV1 LEAVES THE SCENE.	940T43011002
209	36953952	10/28/2017	5:32:00 PM	1	NON- REPORTABLE	DUSK	WET	RAIN	UNSAFE SPEED	WEST	OTHER	V-1 was traveling in the right driving lane on the entrance ramp merging not be sebound 1490. The driver of V-1 was driving to fast for the wet roads. The driver of V-1 talled to negotiate a curve and spun around and slid of the north shoulder of the roadway onto the grassy embankment. The driver of V-1 reports that she was cut off by an uninvolved vehicle, but was unable to provide any described not the said vehicle.	
210	36979391	10/28/2017	7:14:00 PM	2	NON- REPORTABLE	DARK-ROAD LIGHTED	WET	RAIN	FOLLOWING TOO CLOSELY	WEST	REAR END	UNIT 1 TRAVELING BEHIND UNIT 2 ON THE INNERLOOP WESTBOUND IN THE CITY OF ROCHESTER. UNIT 1 FALS TO OBSERVE UNIT 2 SLOWING DUE TO WEATHER CONDITIONS AND STRIKES UNIT 2.	940T43011014
211	36957778	10/30/2017	3:45:00 PM	3	NON- REPORTABLE	DAYLIGHT	DRY	CLOUDY	FOLLOWING TOO CLOSELY	SOUTH	OTHER	V-1 diving in the right lane on the inner loop brakes for traffic. V-3 strikes the rear bumper area of V-2 with the front bumper area of V 3 causing V-2 to strike the rear bumper area of V-1 with the front bumper area of V-2 causing damage to all vehicles involved.	940T43011004
212	36988675	11/15/2017	7:50:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLOUDY	FOLLOWING TOO CLOSELY	WEST	REAR END	weh 1 and weh 2 were both with on the inner loop in laine 1 header to the 409 west or ramp. It appears we'h aves slowing or stopping for another accident about 200 fl ahead. Weh 1 was bo close and rear ended weh 1 causing significant damage to the front fower 1. according to the driver of weh 1 he rear ended some sort of suv that didn&apos1look like it had any damage and weh 2 drove away wio and into exchanged. no injuries reported or othseened.	940T43011006
213	36982607	11/15/2017	7:58:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	WEST	REAR END	V-1 WEST ON INNER LOOP SR-940T WHEN HE WAS FOLLOWING TOO CLOSELY TO V-2 WHO MADE A SUDDEN STOP DUE TO TRAFFIC AND STRUCK SAME. NEITHER PARTY INVOLVED REQUESTED AMBULANCE RESPONSE. V-1 TOWED FROM SCENE BY JOHN AND SONS COLLISION.	940T43011004
214	36986034	11/16/2017	7:27:00 AM	4	PROPERTY DAMAGE	DAYLIGHT	WET	CLOUDY	FOLLOWING TOO CLOSELY	EAST	OTHER		
215	36990469	11/18/2017	10:35:00 PM	1	PROPERTY DAMAGE	DARK-ROAD LIGHTED	WET	CLOUDY	UNSAFE SPEED	WEST	OTHER	V-1 West on Inner Loop after entering from Scio St. and driver states she lost control on wet roadway and spun out striking the wall on the North side of the highway lwice, once with front bumper and again with left rear guarter ganet.	940T43011011
216	37038312	12/5/2017	8:00:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	WET	RAIN	FOLLOWING TOO CLOSELY	SOUTH-WEST	REAR END		940T43011004
217	37019746	12/5/2017	8:20:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	WET	RAIN	FOLLOWING TOO CLOSELY	WEST	REAR END	V-1 and V-2 were both traveling westbound in the left lane on The Inner Loop. The driver of V-1 stopped in congested traffic and the driver of V-2 was following too closely to stop before rear ending V-1	
218	37027049	12/7/2017	10:21:00 AM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLOUDY	UNSAFE LANE CHANGE	WEST	OVERTAKING	VEH 1 MERGING FROM INNER LOOP WESTBOUND ONTO INTERSTATE 490 WESTBOUND. VEH 22 WESTBOUND INTERSTATE 490. BOTH DRIVERS CLAM THAT THE OTHER MADE UNSAFE LANE CHANGE AND STRUCK THEIR VEHICLE CAUSING MINOR DAMAGE TO BOTH VEHICLES. NO WITHESSES.	490143022025
219	37021880	12/8/2017	9:47:00 PM	1	PROPERTY DAMAGE	DARK-ROAD LIGHTED	DRY	CLOUDY	UNSAFE SPEED	SOUTH-EAST	OTHER	V-1 rawing southeast bound on the ramp from I-490 East bite hiner Loop East. Op of V-1 losses control of the vehicle and strikes the concrete barrier on the south side of the road, then V-1 confluxes to the north side of the road and overturns onto the passenger side and comes to rest facing the wrong way of travel. There was no damage to the concrete barrier.	940T43011002
220	37033289	12/13/2017	3:40:00 PM	3	PROPERTY DAMAGE AND INJURY	DAYLIGHT	WET	CLEAR	FOLLOWING TOO CLOSELY	EAST	OTHER	V1, V2, AND V3 WERE N THE RICHT LANE EASTBOUND ON THE INTERNITE TO THE NOT THE CHYOF ROCHESTER. V1 FALED TO OBSERVE V2 BRAKING, SUBSEQUENTLY STRIKING THE REAR OF V2. THE MPACT CAUSED V2 TO STRIKE THE REAR OF V3. THE MPACT CAUSED V2 TO STRIKE THE REAR OF V3. THE MPACT CAUSED THE SECOND TH	940143011005
221	37066303	12/14/2017	2:50:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	WEST	REAR END	VI AND V2 WERE TRAVELING IN THE RIGHT LANE WESTBOUND ON THE INNER LOOP AT 1490. VI FAILED TO OBSERVE V2 STOPPED FOR TRAFFIC, SUBSEQUENTLY STRKING THE REAR OF V2. DRIVER OF VI STATED HE WAS LOOKING FOR AN ITEM ON THE PASSENGER SEAT AT THE TIME OF THE COLLISION. NO NUIVIES.	940T43011004
222	37035518	12/16/2017	9:24:00 AM	1	PROPERTY DAMAGE	DAYLIGHT	DRY	CLOUDY	UNSAFE SPEED	EAST	OTHER	V1 OPERATOR IS EB ON THE NINER LOOP WHEN HE STATES AN UNKNOWN OPERATOR IN AN UNKNOWN VEHICLE WAS TALGATING HIM. V1 STATES THAT HE THEN TRED TO SPEED AWAY AND THEN LOST CONTROL OF HIS VEHICLE. V1 THEN STRUCK A LICHT POLE AND CAME TO REST ON AN EMBANKMENT, NO NUIVIEES, REG NOTHED AND RESPONDED TO SCENE FOR THE LIGHT POLE	940T43011002
223	37044413	12/19/2017	5:19:00 PM	2	PROPERTY DAMAGE	DARK-ROAD LIGHTED	DRY	CLOUDY	FOLLOWING TOO CLOSELY	SOUTH-WEST	REAR END	V-1 and V-2 both traveling southwest bound on the Inner Loop . West in the right lane. V-1 was a traveling behind V-2. V-2 has to come to a stop due to uninvolved vehicles that come to a stop in tont of him. V-1 is unable to stop in time and V-1 rear ends V-2 causing said damage. A DMV check of the registration for V-1 vshowed that is was suspended for insurance not in effect. Op of IV. 1 stied that she just of the General Insurance Company but it might not be in effect until the next day. Tickes Issued: CORTIA JOYNEE Driver of Vehicle number () lickest: Ticket Number: 1E1470H560 Violation: 1129A Ticket Number: 1E1470H560 Violation: 5091 Tickets Number: 511470H560 Violation: 5091 Tickets Number: 511470H5	940143011004

TE 213 (9/79)						DOUTE NO OR	OTDEET HANG						
COUNTY:	MONROE		P.I.N.:	NOT APPLICAB	LE	ROUTE NO. OR					CASE No.:		
	TOWN					INNER LOOP (N					FILE:		-
	CITY VILLAGE OF	ROCHESTI	ER			AT INTERSECT			RMINUS AT N. UNION ST		BY: DATE:		-
TIME PERIOD		FROM:	TO:	ENVIRONMENT	TAI:	Light Conditions:		Roadway Surfac					
		8/1/14	7/31/19		n MV 104 (shown e categories		yhted	1. Dry 2. Wet 3. Muddy 4. Snow/Ice 5. Slush 10. Other	1. Clear 2. Cloudy 3. Rain 4. Snow 5. SleeVHaWFre 6. Fog/Smog/Sr 10. Other				
No. OF MONTH	S:	6	0	ES		SNOIL						MV 104 Police Report	
CRASH No.	CASE No.	DATE	TIME	No. of VEHICLES	SEVERITY	LIGHT CONDITIONS	ROADWAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING FACTORS	DIRECTION	TYPE ¹	DESCRIPTION	REFERENCE MARKER
224	37044315	12/20/2017	11:20:00 AM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLOUDY	PASSING TOO CLOSELY	WEST	OVERTAKING	V-1 ENTERING 1-490 WEST RAMP FROM FRONTAGE ST RAMP AT SAME TIME V-2 ENTERING 1-490 WEST RAMP FROM INNER LOOP RAMP. V-1 UPON ENTERING 2 LANE RAMP FROM RIGHT LANE PARTIALLY ENTERED LEFT LANE SIDESWIPING V 2 OCCUPYING LEFT LANE.	
225	37053965	12/23/2017	4:45:00 AM	1	PROPERTY DAMAGE	DARK-ROAD LIGHTED	SNOW/ICE	SLEET/HAIL/F REEZING RAIN	UNSAFE SPEED	WEST	OTHER	UNIT 1 TRAVELING WB ON THE INNER LOOP IN THE CITY OF ROCHESTER. UNIT 1 UNABLE TO MAINTAIN CONTROL OF VEHICLE DUE TO ICY ROADS STRIKES GUIDE RAIL AND COMES TO REST.	940T43011001
226	37053970	12/23/2017	4:50:00 AM	1	PROPERTY DAMAGE	DARK-ROAD LIGHTED	SNOW/ICE	SLEET/HAIL/F REEZING RAIN	UNSAFE SPEED	WEST	OTHER	UNIT 1 TRAVELING WIS ON THE INVERLOOP IN THE CITY OF ROCHESTER. UNIT 1 UNABLE TO MAINTAIN CONTROL OF VEHICLE DUE TO ICY ROADS STRIKES GUIDE RAILS AND COMES TO REST.	940T43011001
227	37076151	1/3/2018	8:14:00 AM	1	PROPERTY DAMAGE	DAYLIGHT	WET	CLEAR	UNSAFE SPEED	EAST	OTHER	V1 OPERATOR IS ED ON THE INNER LOOP IN THE LEFT LANE WHEN HE STATES HE HITS A PATCH OF WHAT HE THOUGHT WAS BLACK ICE. V1 THEN LOSES CONTROL OF HIS VEHICLE AND STRIKES THE GUIDE-RAIL. NO INJURIES. NO TOWS.	940T43011007
228	37072706	1/4/2018	5:23:00 PM	3	PROPERTY DAMAGE	DAYLIGHT	SNOW/ICE	SNOW	UNSAFE SPEED	WEST	OTHER		940T43011006
229	37072710	1/4/2018	5:35:00 PM	2	PROPERTY DAMAGE	DARK-ROAD LIGHTED	SNOW/ICE	SNOW	FOLLOWING TOO CLOSELY	WEST	REAR END		940T43011006
230	37070605	1/5/2018	8:15:00 AM	1	PROPERTY DAMAGE AND INJURY	DAYLIGHT	SNOW/ICE	SNOW	UNSAFE SPEED	WEST	OTHER	V-1 WAS TRAVELING WEST BOUND ON THE INNER LOOP IN THE CITY OF ROCHESTER. V-1 LOST CONTROL OF HI VEHICLE AND STRUCK THE GUARD RAIL CAUSING PROPERTY DAMAGE ONLY TO V-1.	940T43011009
231	37080795	1/7/2018	2:25:00 PM	1	PROPERTY DAMAGE	DAYLIGHT	SNOW/ICE	CLOUDY	REACTION TO OTHER UNINVOLVED VEHICLE	EAST	OTHER	Vehicle T east on the hner Loop in the left lane. Operator stated that an unknown uninvolved pick up cut her off and she hit her brakes and slid off the left side of the roadway strking the guide tail.	940T43011007
232	37080775	1/7/2018	3:02:00 PM	1	PROPERTY DAMAGE	DAYLIGHT	SNOW/ICE	CLOUDY	REACTION TO OTHER UNINVOLVED VEHICLE	NORTH-EAST	OTHER	V-1 Taveling northeast bound on the inter Loop East in the right lane. V-1 goes off he roadway on the south side and strikes a guide rail causing said damage. Op V-1 states that a vehicle that was Taveling in the lett lane cuthim off by moving into his lane in bront of him and he sewered be avoid contact with the other vehicle, causing him to go off of the roadway and strike the guide rail.	940T43011007
233	37101937	1/22/2018	5:48:00 AM	2	NON- REPORTABLE	DARK-ROAD LIGHTED	WET	CLOUDY	UNSAFE LANE CHANGE	EAST	OVERTAKING	There was no damage to pulde rail. YI IS EB ON THE INNER LOOP IN THE LEFT LANE. V2 IS EB ON THE INNER LOOP IN THE RIGHT LANE. V1 OPERATOR STATES HE WENT TO CHANGE LANES FROM THE LEFT TO THE RIGHT AND SIDE-SWIPED V2. NO INJURIES. NO TOWS.	
234	37115665	1/30/2018	8:24:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	SNOW/ICE	SNOW	UNSAFE SPEED, OTHER (VEHICLE)	SOUTH-WEST	REAR END	V-1 and V-2 both traveling southwest bound on the Inner Loop . West in the same law. V-2 was traveling in front of V-1. V-1 rear ends V-2 causing said damage. Op of V-2 staled that his car skepped running all of a sudden and he pulled over to the right as fire as he could. Op of V-2 staled that he was able to get the car started again and just before he was able to of the away, he was rear ended by V-1. Op of V-1 staled that he did not know that V-2 was slopped or broken down because V-2 did not have any	940T43011004
235	37120313	2/1/2018	3:53:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLOUDY	FOLLOWING TOO CLOSELY, REACTION TO OTHER UNINVOLVED VEHICLE	WEST	REAR END	SIDABILIDS OF DAZZED HIDES ON YI AND YA ZHE BOTTH WEN IN THE INNER LOOP IN THE RIGHT LANE. BOTH OPERATORS STATED THAT AN UNKNOWN YEHICLE CUT YI OFF. VZ THEN CAME TO A STOP. YI WAS UNABLE TO STOP AND STRUCK VZ FROM BEHIND. NO INJURIES.	940T43011004
236	37135439	2/9/2018	11:56:00 AM	1	PROPERTY DAMAGE	DAYLIGHT	WET	SNOW	UNSAFE SPEED	EAST	OTHER	V1 WAS EASTBOUND ON THE INNERLOOP NEAR 1490 IN THE CITY OF ROCHESTER WHEN DRIVER 1 LOST CONTROL OF V1, SPUN AROUND 180 DEGREES AND STRUCK THE CONCRETE BARRIER ON THE RIGHT SHOULDER. CLOSED.	
237	37138664	2/9/2018	2:15:00 PM	2	NON- REPORTABLE	DAYLIGHT	SNOW/ICE	SNOW	UNSAFE LANE CHANGE	WEST	OVERTAKING		940T43011003
238	37135437	2/9/2018	5:37:00 PM	1	PROPERTY DAMAGE PROPERTY	DAYLIGHT	WET	SNOW	UNSAFE SPEED	NORTH-WEST	OTHER	OPV1 TRAVELING WB ON THE INNERLOOP. OPV1 LOSES CONTROL OF V1 AND STRIKES THE NORTH BRIDGE ABUTMENT.	940T43011007
239	37156309	2/21/2018	7:00:00 PM	4	DAMAGE AND INJURY	DARK-ROAD LIGHTED	DRY	CLOUDY	FOLLOWING TOO CLOSELY	EAST	OTHER		940T43011013
240	37161016	2/26/2018	9:29:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	UNSAFE LANE CHANGE	WEST	OVERTAKING	OP 1 STATED SHE WAS WEST ON NINER LOOP WHEN V.2 BEGAN CHANGING LANES IN FRONT OF HER, FAILED TO SEE HER AND STRUCK HER VEHICLE. OP 2 STATED HE WAS IN THE RISHT LANE WHEN OP 1 WAS ATTEMPTING TO CHANGE LANES AND DID NOT HAVE ENOUGH ROOM TO DO SO, CAUSING V.1 TO HIT V.2.	940T43011011
241	37167459	3/3/2018	8:07:00 AM	3	PROPERTY DAMAGE	DAYLIGHT	SNOW/ICE	CLOUDY	UNSAFE SPEED	SOUTH	OTHER	V-1, V-2 and V-3 all traveling southbound on the Inner Loop West V-2 was traveling in fontof V-1 and V-3 was traveling behind V-1. Op of V-2 losses control of her vehicle, does a 360, without striking anything and comes to a stop in the lane of the Inner Loop West Op of V-1 is unable to stop in time and the rear passenger side of V-1 strikes the fort off there is off the Inner	940T43011000 f
242	37176994	3/4/2018	7:24:00 PM	1	PROPERTY DAMAGE	DARK-ROAD LIGHTED	SNOW/ICE	CLOUDY	UNSAFE SPEED	EAST	OTHER	V-1 EAST ON NINER LOOP WHEN VEHICLE LOST CONI ROL. DUE TO SNOWINCE ON THE ROAD, OPERATIOR OF V-1 UNABLE TO CORRECT THE VEHICLE DUE TO AN UNSAFE SPEED AND STRUCK THE GUARD RAIL. NO DAMAGED OBSERVED ON THE GUARD RAIL. OPERATIOR DECLINED EMS TO RESPOND TO SCENE. VEHICLE REMOVED FROM SCENE BY EAST AVE AUTO.	940T43011009

TE 213 (9/79)						DOLLTE NO. OD	CTDEET MAME						
COUNTY:	MONROE		P.I.N.:	NOT APPLICAB	LE	ROUTE NO. OR INNER LOOP (N					CASE No.:		
	TOWN										FILE:		- -
	CITY VILLAGE OF	ROCHESTI	ER			AT INTERSECT					DATE:		=
	•				-				RMINUS AT N. UNION ST				_
TIME PERIOD		FROM: 8/1/14	TO: 7/31/19	ENVIRONMENT Use Codes from at right) for these	MV 104 (shown e categories	Light Conditions: 1. Daylight 2. Dawn 3. Dusk 4. Dark Road Lig 5. Dark Road Ur	yhted	Roadway Surfact 1. Dry 2. Wet 3. Muddy 4. Snowlice 5. Slush 10. Other	e Condition: Weather: 1. Clear 2. Cloudy 3. Rain 4. Snow 5. Sleet/Hail/Fre 6. Fog/Smog/Sr 10. Other				
No. OF MONTH	S:	6	0	S		IONS					¹ Use Codes from	MV 104 Police Report	
CRASH No.	CASE No.	DATE	TIME	No. of VEHICLES	SEVERITY	LIGHT CONDITIONS	ROADWAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING FACTORS	DIRECTION	TYPE ¹	DESCRIPTION	REFERENCE MARKER
243	37176997	3/4/2018	7:38:00 PM	1	PROPERTY DAMAGE	DARK-ROAD LIGHTED	SNOW/ICE	CLOUDY	UNSAFE SPEED	EAST	OTHER	VI WAS IN THE LEFT LANE EASTROUND ON THE INNER LOOP NEAR SCIO STREET. DRIVER OF VI BEGAN BRAKING FOR EMERGENCY LIGHTS DUE TO A PREVIOUS MOTOR VEHICLE ACCOENT FOR ICY ROAD CONDITIONS. VI SUBSEQUENTLY LEFT THE NORTH SHOULDER AND STRUCK THE GUIDE RAIL. NYS DOT NOTIFIED. NO INJURIES.	940T43011012
244	37174792	3/5/2018	9:43:00 AM	1	PROPERTY DAMAGE	DAYLIGHT	DRY	CLOUDY	REACTION TO OTHER UNINVOLVED VEHICLE	WEST	OTHER	IN WAS WESTBOUND ON THE NINERLOOP IN THE CITY OF AND CAUSED BRIVER IN UNINVOLVED VEHICLE CUTY IO FF AND CAUSED DRIVER I TO LOSE CONTROL OF VI, SLIDE ACROSS THE RIGHT LANE AND STRIKE LIGHT POLE MD4 WHICH WAS ON THE RIGHT SHOULDER OF THE ROAD. RGE WAS CONTACTED ABOUT THE LIGHT POLE. NO INFORMATION WAS PROVIDED ABOUT THE UNINVOLVED VEHICLE. CLOSED.	490143022029
245	37175140	3/7/2018	3:41:00 PM	3	PROPERTY DAMAGE	DAYLIGHT	WET	RAIN	FOLLOWING TOO CLOSELY	SOUTH-WEST	OTHER	V-1, V-2 and V-3 all traveling southwest bound on the linner Loop West in the right lane. V-2 was staveling in fort of V-1 and V-3 was taveling behind V-1. Op of V-2 has to slow down due to uninvolved vehicles in fort of him that starf to slow down. Op of V-1 is unable to Slow down in time and V-1 rear ends V-2 causing said damage. Op of V-3 is also unable to slow down in time and V-3 rear ends V-1 causing said damage, Op of V-3 let the scene. There was no oble or of their information for V-3.	940T43011006
246	37185479	3/14/2018	7:02:00 AM	1	PROPERTY DAMAGE AND INJURY	DARK-ROAD LIGHTED	SNOW/ICE	SNOW	UNSAFE SPEED	WEST	OTHER	VI WAS WESTBOUND ON THE NIVERLOOP IN THE CITY OF ROCHESTER WHEN DRIVER I LOST CONTROL OF VI ON THE SNOW COVERED ROADWAY AND STRUCK THE CONCRETE BARRER ON THE RIGHT SHOULDER. NY DOT NOTIFIED OF THE POSSIBLE DAMAGE DONE TO THE CONCRETE BARRIER. CLOSED.	940T43011009
247	37188609	3/14/2018	8:01:00 AM	1	PROPERTY DAMAGE	DAYLIGHT	SNOW/ICE	SNOW	UNSAFE SPEED	EAST	OTHER	V1 WAS EASTBOUND ON THE INNERLOOP IN THE CITY OF ROCHESTER WHEN DRIVER 1 LOST CONTROL OF V1 ON THE SNOW COVERED ROADS AND STRUCK THE GUIDE RAIL ON THE LEFT SHOULDER. NY DOT NOTIFIED OF THE POSSIBLE DAMAGE DONE TO THE GUIDE RAIL. CLOSED.	940T43011001
248	37185476	3/14/2018	8:16:00 AM	1	PROPERTY DAMAGE	DAYLIGHT	SNOW/ICE	SNOW	UNSAFE SPEED	WEST	OTHER	V-1 driving in the right lane of the inner loop Westbound. V-1 drives onto the North shoulder striking the guide rail with the front bumper of V-1 causing heavy front end damage.	940T43011007
249	37185477	3/14/2018	3:49:00 PM	2	PROPERTY DAMAGE AND INJURY	DAYLIGHT	WET	CLOUDY	FOLLOWING TOO CLOSELY	WEST	REAR END	V-1 SLOWING IN TRAFFIC ON THE NINER LOOP WESTBOUND IN THE CITY OF ROCHESTER. OPERATOR OF V-2 STATES HE SEEN THAT TRAFFIC WAS STOPPED AIREAD OF HIM AND ATTEMPTED TO STOP BUT COULD NOT AND SLID ON THE PAVEMENT MPACTING THE REAR END OF V-1 WHILE HE WAS WESTBOUND ON THE NINER LOOP. OPERATOR OF V-1 COMPLANED OF NECK PAIN AND WAS CHECKED OUT BY AN AMBULANCE AT HER OWN REQUEST. SHE WAS NOT TRANSPORTED FOR MEDICAL ASSISTANCE.	940T43011003
250	37216080	3/31/2018	2:49:00 PM	1	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	BRAKES DEFECTIVE	SOUTH-EAST	OTHER	V-1 Eveling southeast bound on the ramp from I-490 East to the Inner Loop East when V-1 stikes the concrete barrier on the south shoulder of the roadway. Op of V-1 stated that when he entered the curve in the road, the brakes stopped working and the engine stopped running causing thim to stike the concrete barrier. There was no damage to the concrete barrier.	1
251	37236395	4/15/2018	6:15:00 AM	1	PROPERTY DAMAGE	DAWN	SNOW/ICE	SLEET/HAIL/F REEZING RAIN	UNSAFE SPEED	EAST	OTHER	V-1 east on Innerloop exit ramp to 490 east when vehicle lost control on slippery road surface. V-1 struck guide rail with left front causing damage to V-1.	940T43011001
252	37236400	4/15/2018	6:15:00 AM	1	PROPERTY DAMAGE	DAWN	SNOW/ICE	SLEET/HAIL/F REEZING RAIN	UNSAFE SPEED	EAST	OTHER	V-1 east bound on innerloop exit to 490 east lost control on slippery pavement. V-1 struck right guide rail with right front causing dame to V-1 and rail.	940T43011001
253	37236403	4/15/2018	6:26:00 AM	1	PROPERTY DAMAGE	DAYLIGHT	SNOW/ICE	SLEET/HAIL/F REEZING RAIN	UNSAFE SPEED	EAST	OTHER	VI WAS TRAVELING EASTBOUND ON THE 1490 RAMP FROM THE INNER LOOP WHEN VI BEGAN TO BRAKE FOR A MOTOR VEHICLE ACCIDENT AHEAD DRIVER OF VI WAS UNABLE TO STOP AND SUBSEQUENTLY WENT OFF THE NORTH SHOULDER, STRIKING A CEMENT JERSEY BARRIER. NYS DOT NOTIFED, NO NUURES.	490143022024
254	37247978	4/22/2018	2:10:00 PM	2	PROPERTY DAMAGE AND INJURY	DAYLIGHT	DRY	CLEAR	UNSAFE SPEED	WEST	REAR END	V-1 TRAVELING W/B ON THE INNER LOOP IN THE RIGHT LANE BEHIND V-2. V-2 STOPS FOR STOPPED TRAFFIC AHEAD. OP-1 FOLLOWING TOO CLOSELY AT AN UNSAFE SPEED THEN REAR ENDS V-2.	940T43011005
255	37252314	4/25/2018	5:15:00 PM	3	PROPERTY DAMAGE AND INJURY	DAYLIGHT	WET	RAIN	FOLLOWING TOO CLOSELY	SOUTH-WEST	OTHER	Op Veh-2 and Op Veh-3 stopped in tallic in he right hand weshound lane of the hner Loop in the City of Rochester. Op of Veh 1 started in the right westbound lane of the hner Loop in the City of Rochester. Op Veh-1 changed lanes from the right lane to the left lane and an unimoled vehicle also change lanes into the left lane. Op Veh-1 took evasive action to avoid shiring the unimoled vehicle. Due to following too closely and the lack of driving experience, Op Veh-1 struck Veh-2 causing a chain reaction with Veh-2 strivin Veh-3.	940T43011005
256	37262622	4/28/2018	10:30:00 PM	2	NON- REPORTABLE	DARK-ROAD LIGHTED	DRY	CLOUDY	FOLLOWING TOO CLOSELY	WEST	REAR END	V2 slowed and stopped for traffic ahead. V1 was following too closely and struck the rear of V2 with the front of V1. No damage	
257	37273418	5/8/2018	4:40:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	WEST	REAR END	evident roadside. VI AND V2 WERE TRAVELING IN THE RIGHT LANE WESTBOUND ON THE INNER LOOP IN THE CITY OF ROCHESTER. DRIVER OF V1 FAILED TO OBSERVE V2 BRAKING, SUBSEQUENTLY STRIKING THE REAR OF V2. NO INJURIES.	940T43011003
258	37279220	5/12/2018	4:17:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	FAILURE TO YIELD RIGHT OF WAY	NORTH-WEST	OVERTAKING	V-1 TRAVELING NORTHWEST ON INNER LOOP IN THE CITY OF ROCHESTER IN CENTER LANE WHEN V-2 CHANGES LANE AND STRKES PASSENGER REAR WHEEL OF V-1 WITH FRONT LEFT PORTION OF V-2 CAUSING DAMAGE TO V-2. NO INJURIES REPORTED.	940T43011012

TE 213 (9/79)						DOUTE NO OD	OTDEET HANG						
COUNTY:	MONROE		P.I.N.:	NOT APPLICAB	LE	ROUTE NO. OR INNER LOOP (N					CASE No.:		
	TOWN		•			· ·					FILE:	PSC	-
	CITY VILLAGE OF	ROCHEST	ER			AT INTERSECT			RMINUS AT N. UNION ST		Ы.	PSC 5/13/2020	-
TIME PERIOD		FROM:	TO:	ENVIRONMENT		Light Conditions:		Roadway Surfac					
		8/1/14	7/31/19	Use Codes from at right) for these		1. Daylight 2. Dawn 3. Dusk 4. Dark Road Lig 5. Dark Road Ur		1. Dry 2. Wet 3. Muddy 4. Snowlce 5. Slush 10. Other	1. Clear 2. Cloudy 3. Rain 4. Snow 5. SleeVHaWFre 6. Fog/Smog/Sn 10. Other				
No. OF MONTH	S:	6	0	ES		TIONS						MV 104 Police Report	
CRASH No.	CASE No.	DATE	TIME	No. of VEHICLES	SEVERITY	LIGHT CONDITIONS	ROADWAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING FACTORS	DIRECTION	TYPE ¹	DESCRIPTION	REFERENCE MARKER
259	37303872	5/25/2018	9:58:00 AM	1	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	DRUGS (ILLEGAL)	SOUTH	OTHER	V-1 traveling South on Inner Loop ramp to Interstate 490 East in the City of Rochester when driver of V-1 strikes concrete barrier located on West shoulder of ramp. No injuries reported.	940T43011002
260	37337237	6/6/2018	7:21:00 AM	2	PROPERTY DAMAGE AND INJURY	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	EAST	REAR END		940T43011004
261	37328541	6/12/2018	2:19:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	UNSAFE LANE CHANGE	EAST	OVERTAKING	V1 AND V2 WERE EASTBOUND ON THE INNERLOOP IN THE CITYOF ROCHESTER WHEN V1 TRED TO CHANGE LANES FROM THE RIGHT LANE TO THE LEFT LANE AND SIDE SWPED V2. DRIVER 1 STATED THAT HE THOUGHT HE CLEARED V2. CLOSED.	940T43011011
262	37338768	6/19/2018	4:20:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLOUDY	UNSAFE LANE CHANGE	WEST	OVERTAKING	Vehicle 1 and vehicle 2 traveling weston the inner loop in the city of Rochester. Vehicle 1 attempts to change lanes into the path of vehicle 2. Vehicle 1 strikes vehicle 2.No injury or low. Driver 1 issued a UTT.	940T43011006
263	37353159	6/27/2018	5:10:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	WET	RAIN	FOLLOWING TOO CLOSELY	EAST	REAR END	UNIT 1 TRAVELING BEHIND UNIT 2 ON THE INNERLOOP EB IN THE CITY OF ROCHESTER UNIT 1 FAILS TO OBSERVE UNIT 2 SLOWING DUE TO TRAFFIC. UNIT 1 UNABLE TO REACT IN TIME STRKES UNIT 2. Vehicle 1 Taveling east on the inner loop in the city of Rochester.	940T43011013
264	37361205	7/3/2018	12:45:00 PM	1	PROPERTY DAMAGE	DAYLIGHT	DRY	CLOUDY	REACTION TO OTHER UNINVOLVED VEHICLE	EAST	OTHER	An uninvolved vehicle was traveling east on the on ramp and veered across the driving lane into the passing lane, into the part of vehicle 1. Vehicle swerved to the north to avoid being struck by the vehicle, striking the guider all in the process. The uninvolved vehicle let the scene No injuries, tow or UTTs. DOT notified of dramane.	940T43011006
265	37377353	7/10/2018	1:47:00 PM	3	PROPERTY DAMAGE AND INJURY	DAYLIGHT	DRY	CLEAR		WEST	OTHER	ugilinos.	940T43011003
266	37382870	7/16/2018	2:05:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	UNSAFE LANE CHANGE	SOUTH-WEST	OVERTAKING	V-1 and V-2 both traveling southwest bound on the hner Loop West V-1 was traveling in the right lane and V-2 was traveling in the center lane. Op of V-1 alempts to move into the center lane and does not see V-2 and V-1 strikes V-2 causing said damage. Damage to V-1 was minor and there appeared to be no damage to V-2.	940T43011006
267	37393372	7/20/2018	7:03:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	PASSING OR LANE USAGE IMPROPERLY	WEST	OVERTAKING	Driver of V-2 stales that she was on the Inner Loop getting on to 490 west when she was thit by V-1. She stales V-1 fled the scene and confinued to Child St where she followed V-1. Both V-1 and V 2 slopped on 490 east bound east of Child St. Interviewed driver of V-2 and says V-2 thit V-1 but did not provide any defails.	
268	37398268	7/25/2018	11:43:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	WET	CLOUDY	UNSAFE LANE CHANGE	WEST	OVERTAKING	V-1 and V-2 both traveling westbound on the Inner Loop - West. V-1 was traveling in the middle lane and V-2 was traveling in the left lane. Op of V-1 attempts to change lanes into the left lane and does not see V-2 and V-1 strikes V-2 causing said damage.	940T43011011
269	37451157	7/30/2018	3:44:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLOUDY	PASSING OR LANE USAGE IMPROPERLY	NORTH	OVERTAKING	V-1 traveling north on Inner Loop from I490 in the City of Rochester is twing NY Reg BK2735. V-2 also traveling north on Inner Loop from I490. Driver of V-1 stakes that he did not led or see anything, he stated he was slowing for the light at SI Paul when the maroon vehicle pulled up in front of he tuck and sopped Driver of V-2 stakes V-1 crossed over the line and made contact with her car and kept driving. She stated she pulled ahead of the truck and stopped to prevent him from leaving the scene. Investigation was conducted at the Inner Loop of farmp at SI Paul where V-2 stayped V-1. OV-2, loobserved at the sculf mas for the driver side near the front and rear fire wheel wells. Driver of V-2 stated here sculf was from the accident. ON V-1, lidd into tokesive any damage or paint transfer from the maroon car. When I issued both drivers the Information Exchange From the driver of V-2 stated she had pain in the rock and wanted if mentioned. Stated she would go to the hospital later. I contacted EMS to respond to the scene. Ambidance (NY 1210cV) arrived and stated everything was within normal range. The driver of V-2 was offered transportation to the hospital by EMT but the driver of V-2 declined and signed of the hospital by EMT but the driver of V-2 declined and signed of	940T43011007
270	37423284	8/7/2018	12:10:00 PM	1	PROPERTY DAMAGE	DAYLIGHT	DRY	CLOUDY	REACTION TO OTHER UNINVOLVED VEHICLE	WEST	OTHER	VI WAS WESTBOUND ON THE NINERLOOP IN THE CITY OF ROCHESTER WHEN DRIVER I STATED THAT AN UNINVOLVED VEHICLE WAS ENTERING THE INNERLOOP FROM THE SCIO ST ON RAMP, SWERVED NITO HIS LANE AND CAUSED VI TO SWERVE OUT OF CONTROL AND STRIKE THE CENTER MEDIAN OF THE INNERLOOP. THE UNINVOLVED VEHICLE NEVER MADE ANY CONTRACT WITH VI AND CONTINUED DRIVING WESTBOUND ON THE INNERLOOP. THE ONLY DESCRIPTION OF THAT VEHICLE WAS THAT IT WAS A BLUE SEDAN. IN'S DOT NOTIFED OF THE POSSIBLE DAMAGE DONE TO THE CENTER MEDIAN. CLOSED.	940T43011010
271	37423203	8/7/2018	12:54:00 PM	1	PROPERTY DAMAGE	DAYLIGHT	WET	CLOUDY	OBSTRUCTION/DEBRIS	WEST	OTHER	VEH 1 WESTBOUND NNER LOOP, PART OF THE ROADWAY WAS FLOODED DUE TO HEAVY RAIN ON A BLIND CURVE. DRIVER TO SEET THE FLOODING UNTIL HER CAR WAS IN IT AND UNABLE TO AVOID IT BECAUSE OF OTHER TRAFFIC. VEHICLE STRUCK THE WATER AND THEN STRUCK THE SUDDEN RAIN THE SOUTH CURRANT PAIL CAUSED BANAGE TO VEH 1 AND GUARD RAIL. PATROL OBSERVED THE FLOODING AND ALSO OBSERVED THAT IT WOULD HAVE BEEN IMPOSSIBLE TO AVOID WITH LANES OCCUPED BY OTHER TRAFFIC.	940T43011007
272	37446532	8/22/2018	8:08:00 PM	2	PROPERTY DAMAGE	DUSK	DRY	CLEAR	UNSAFE SPEED	SOUTH	REAR END	VI was stopping in taffic for a DV that was on the inner loop in the vicinly of the 1490 Westramp. V2 was taveling behind VI in the same area. Op. 2 failed to brake when VI was braking, subsequently stiking VI rear bumper area with the font bumper area of V2. Damage to same. No low needed. No injuries reported.	940T43011003

TE 213 (9/79)						ROUTE NO. OR	STDEET NAME	;.					
COUNTY:	MONROE		P.I.N.:	NOT APPLICAB	BLE						CASE No.:		
	TOWN		•			INNER LOOP (N					FILE:		_
	CITY VILLAGE OF	ROCHESTI	- D			AT INTERSECT	ION WITH/OR B	ETWEEN:			BY:		_
	VILLAGE UF	KUCHESTI	EK		=	FROM I-490 INT	ERCHANGE TO	INNER LOOP TE	RMINUS AT N. UNION ST		DATE:	5/13/2020	_
TIME PERIOD		FROM: 8/1/14	TO: 7/31/19	ENVIRONMENT Use Codes from at right) for these	n MV 104 (shown e categories	Light Conditions: 1. Daylight 2. Dawn 3. Dusk 4. Dark Road Lig 5. Dark Road Un	ghted	Roadway Surfar 1. Dry 2. Wet 3. Muddy 4. Snowlice 5. Slush 10. Other	ce Condition: Weather: 1. Clear 2. Cloudy 3. Rain 4. Snow 5. SleeWHall/Fre 6. Fog/Smog/Sr 10. Other				
No. OF MONTH	S:	6	0	S		IONS					¹ Use Codes from	MV 104 Police Report	
CRASH No.	CASE No.	DATE	TIME	No. of VEHICLES	SEVERITY	LIGHT CONDITIONS	ROADWAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING FACTORS	DIRECTION	TYPE ¹	DESCRIPTION	REFERENCE MARKER
273	37452514	8/27/2018	12:20:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLOUDY	FOLLOWING TOO CLOSELY	WEST	REAR END	Vehicle 1 on the on ramp from East Main St to the hiner Loop wesbound behind Vehicle 2. Operabr of Vehicle 1 staked he looked at a vehicle on the rights shoulder and did not notice Vehicle 2 had slowed and stopped. Vehicle 1 unable to stop in time and struck the rear of Vehicle 2. On the above date and time tresponded to the 85 Alen St for the	è
274	37465861	8/28/2018	4:23:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	PASSING OR LANE USAGE IMPROPERLY	EAST	RIGHT ANGLE	Hitland Run report. I met with and spoke to the driver of V2. He stated he was driving East on the one Way on Allent St. He stated as he was pulling into the entrance for 85 Allen St Men of the driver of V1 crashed into the driver and passenger side door of his car. Driver of V2 stated the driver of V1 he move of II. Thad a MNSO check the address for the RIO of V1. The RIO father stated Deta no longer lived there. He would not prove a phone number or new address for the r. Driver of V2 was not hurt. He car was not bowd. There was heavy damage to the driver side door and passenger side door on V2.	
275	37456099	8/30/2018	8:45:00 AM	3	PROPERTY DAMAGE	DAYLIGHT	WET	RAIN	FOLLOWING TOO CLOSELY	EAST	OTHER	VEH 1, VEH 2, VEH 3 EASTBOUND ON THE INNER LOOP, FED X TRUCK BECAME DISABLED BLOCKING THE RIGHT LANE. VEH 3 STOPPED TO AVOID THE DISABLED VEHICLE. VEH 1 STRUCK THE REAR OF VEH 3 CAUSING DAMAGE TO BOTH VEHICLES. VEH 2 STRUCK THE REAR OF VEH 1 CAUSING DAMAGE TO VEH 1 AND VEH 2.	940T43011004
276	37459173	9/3/2018	1:09:00 PM	1	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	TIRE FAILURE/INADEQUATE	EAST	OTHER	V1 east on liner Loop to S. Plymouth Avenue in the City of Rochester. Front drivers tire on V1 popped causing driver of V1 to lose control and strike curb. Driver stated he in uninjured. V1 towed from scene by Hardings Towing company.	
277	37463212	9/5/2018	12:10:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	UNSAFE LANE CHANGE	WEST	OVERTAKING	V.2 WEST ON THE NIVER LOOP IN THE FAR LEFT LANE WHEN Y.1 BEGAIN CHANNICH CAINES AND STRUCK V.2 V.2 UNABLE TO AVOID THE COLLISION. OP.1 STATED TRAFFIC AHEAD OF HIM BEGAIN TO SLOW DOWN SO HE QUICKLY CHANGED LANES AND DID NOT SEE V.2 WEXT TO HIM. OP.1 AND OP.2 DECLINED EMS TO RESPOND TO THE SCENE, BOTH VEHICLES DRIVEN FROM THE SCENE.	940T43011005
278	37465476	9/6/2018	2:33:00 PM	1	PROPERTY DAMAGE AND INJURY	DAYLIGHT	DRY	CLOUDY	REACTION TO OTHER UNINVOLVED VEHICL	EAST	OTHER	Driver 1 stated that he was east bound on the 1490 East Exit Ramp to the hiner Loop East Bound in the left lane, an uninvolved vehicle ahead stopped abruptly. Driver 1 slowed to avoid shiking the uninvolved vehicle, lost control, overfurned onto the right side of the motorcycle, and slid along the roadway into the right lane of the	490143022025
279	37470980	9/8/2018	9:20:00 PM	1	PROPERTY DAMAGE	DARK-ROAD LIGHTED	DRY	CLOUDY	DRUGS (ILLEGAL)	WEST	OTHER	construction zone. Which was Wilb on he hiner Loop and went to get off at Joseph Ave. V1 struck he crash cushion lost control and hen struck he inner Loop wall on he Joseph Ave off ramp. No other vehicles involved. No injuries were reported. Damage to the crash cushion and wall (DOT notified by admin channel). Driver V1 was impared by druggs and alzohol. Tickets Issued: JASON D DOCKUM Driver of vehicle number (1) lickets: Ticket Number. WS178NKCON Violation: 11924A Ticket Number: WS178NKCHO Violation: 11926.	940T43011009
280	37473284	9/11/2018	8:05:00 AM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLOUDY	FOLLOWING TOO CLOSELY	EAST	REAR END	Ticket Number: WM178NKKSK Violation: 11924: V2 was taveling eb on the inner loop entering the on ramp @ main st V1 was behing V2 when V1 front hit V2':s rear causing minor damage to both vehicles, no one was injured.	490143022029
281	37475823	9/12/2018	4:40:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLOUDY	FAILURE TO YIELD RIGHT OF WAY	WEST	OVERTAKING	V1 haveling weston inner Loop in the City of Rochester. Driver of V1 stated he was altempling to merge into left lane and failed to observe V2 which was traveling west in left lane. V1 struck front passenger side of V2 causing damage to both. No injuries	940T43011006
282	37477899	9/12/2018	5:20:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLOUDY	FAILURE TO YIELD RIGHT OF WAY	WEST	OVERTAKING	reported. No twis needed. Both V1 and V2 driven from scene. V1 haveling in let liane, west on the on ramp b inner Loop WB from St. Paul Both. V2 in right liane of the on ramp b inner Loop WB from St. Paul. Operator of V2 stated that he was attempting by assay V1 to merge into single lane. Bailing to yeld to V1, causing the rear drivers side quarter panel of V2 to strike the front passenger side bumper of V1. No injuries reported. No tows needed. Both V1, and V2 driven from scene.	940T43011007
283	37490789	9/19/2018	4:57:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLOUDY	FOLLOWING TOO CLOSELY	SOUTH-WEST	REAR END	V-1 and V-2 both traveling southwest bound on the Inner Loop West in the right lane. V-1 was traveling behind V-2. Op of V-2 had to come to a stop due to uninvolved vehicles that came to a stop in front of him. Op of V-1 is unable to stop in time and V-1	940T43011004
284	37492425	9/19/2018	6:44:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLOUDY	UNSAFE LANE CHANGE	SOUTH-EAST	OVERTAKING	rear ends V-2 causino said damane. V-1 and V-2 both haveling southeast bound on the ramp from I- 490 East to the hiner loop East. V-1 was taveling in the right lane and V-2 was taveling in the left lane. V-2 suddenly moves the right lane and cuts in front of V-1 and V-2 stikes V-1 causing a placard to break off of the front bumper of V-1. V-2 did not stop and confinued earsbound on the Inner Loop. Op of V-1 described V-2 as a newer silver Chevy Monte Carlo with a while male driver. I checked the area for V-2 with negative results. Diver 1 sized that he was west bound on the linner Loop in the	490143022025
285	37490711	9/19/2018	10:30:00 PM	2	PROPERTY DAMAGE	DARK-ROAD LIGHTED	DRY	CLEAR	UNSAFE LANE CHANGE	WEST	REAR END	Other 1 stated that he was west bound on the Inner Loop in the right lane bowards 1490 West, began to change to the leit lane due to the west bound ramp being closed and shuck Vehicle 2. Oriver 1 stated that he had not been able to avoid Vehicle 2 because it had crested a fill at what the hought was a high rate of speed. Officer 2 stated that he was west bound on the Inner Loop in the left lane, Vehicle 1 changed from the right to the left ane, Diver 3 steered to the left but was unable to avoid stiking Vehicle 1.	940T43011003
286	37502797	9/28/2018	2:21:00 PM	3	PROPERTY DAMAGE AND INJURY	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	WEST	OTHER		940T43011004

TE 213 (9/79)						DOLLTE NO. OD	CTDEET MAME						
COUNTY:	MONROE		P.I.N.:	NOT APPLICAB	LE	ROUTE NO. OR					CASE No.:		
	TOWN		•			INNER LOOP (N					FILE:	PSC 5/13/2020	-
	CITY VILLAGE OF	ROCHESTI	FR			AT INTERSECT					BY:	PSC 5/13/2020	-
									RMINUS AT N. UNION ST				-
TIME PERIOD		FROM: 8/1/14	TO: 7/31/19	ENVIRONMENT Use Codes from at right) for these	n MV 104 (shown e categories	Light Conditions: 1. Daylight 2. Dawn 3. Dusk 4. Dark Road Lig 5. Dark Road Ur	ghted	Roadway Surfar 1. Dry 2. Wet 3. Muddy 4. Snowlice 5. Slush 10. Other	te Condition: Weather: 1. Clear 2. Cloudy 3. Rain 4. Snow 5. SleevHail/Fre 6. Fog/Smog/Sr 10. Other				
No. OF MONTH	S:	6	0	S		SNOI					¹ Use Codes from	MV 104 Police Report	
CRASH No.	CASE No.	DATE	TIME	No. of VEHICLES	SEVERITY	LIGHT CONDITIONS	ROADWAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING FACTORS	DIRECTION	TYPE ¹	DESCRIPTION Vehicle 2 was traveling weston the inner loop when the operator	REFERENCE MARKER
287	37509189	10/2/2018	3:45:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	WET	RAIN	FOLLOWING TOO CLOSELY	WEST	REAR END	slowed in Taille. Vehicle 1 was westbound on he inner loop behind V2. The operator of V1 failed to observe V2 slowing and struck the rear of V2. There were no injuries. V2 was driven from the scene, while V1 was towed from the scene by John and Son Towing.	940T43011005
288	37519417	10/4/2018	2:30:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	WEST	REAR END	UNIT 1 TRAVELING WESTBOUND BEHIND UNIT 2 ON THE INNER LOOP IN THE CITY OF ROCHESTER. UNIT 1 FALLS TO OBSERVE UNIT 2 SLOWING AND IS UNABLE TO REACT IN TIME STRIKING UNIT 2. V1 and V2 Taveling east on State Route 940T- Inner Loop. V1	
289	37519414	10/8/2018	1:34:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	UNSAFE LANE CHANGE	EAST	REAR END	attempts to change lanes at an unsafe speed causing V1 to stike the bumper of V2's trailer. V1 towed by Excel towing, no injuries.	940T43011000
290	37522372	10/10/2018	3:10:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	UNSAFE SPEED	WEST	REAR END	V1 AND V2 WERE WESTBOUND ON THE INNERLOOP IN THE CITY OF ROCHESTER. AS V2 WAS SLOWING DOWN DUE TO HEAVY TRAFFIC, V1 COULD NOT SLOW DOWN IN TIME AND STRUCK V2 IN THE REAR. CLOSED.	940T43011005
291	37532746	10/10/2018	5:03:00 PM	3	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	UNSAFE SPEED	WEST	OTHER	V1, V2, AND V3 WERE WESTBOUND ON 1490 N THE CITY OF ROCHESTER. AS V2 AND V3 WERE SLOWING DOWN DUE TO STOP AND GO TRAFFIC, V1 COULD NOT SLOW DOWN IN TIME AND STRUCK V2 WHICH THEN CAUSED V2 TO STRKE V3. V1 TRAILE RIP TO 1931C 2 MGALINAN AGGREGATES LLC 2150AKWOOD AVE TROY NY 12182 CLOSED.	940143011005
292	37524680	10/11/2018	8:18:00 AM	2	NON- REPORTABLE	DAYLIGHT	WET	RAIN	PASSING OR LANE USAGE IMPROPERLY	SOUTH-WEST	OVERTAKING	V1 travelling Southwest on Inner Loop, City of Rochester, County of Monroe, State of New York. Driver merging into traffic and fails to observe V2 travelling same direction striking same. No injuries, both vehicles driven from the scene.	940T43011005
293	37525811	10/12/2018	6:28:00 PM	2	PROPERTY DAMAGE AND INJURY	DARK-ROAD LIGHTED	DRY	CLEAR	FOLLOWING TOO CLOSELY	WEST	REAR END	V-2 slowing in taffic to allow uninvolved vehicle to merge when V-1 operating behind V-2 Weston Inner Loop falls to slow and strikes rear of V-1 causing damage to each vehicle. Driver of V-1 complained of general neck and back pain and was transported to Unity Hospital by AMR. Each vehicle was lowed by East Ave Auto.	940T43011011
294	37526349	10/13/2018	9:17:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	WET	CLOUDY	FOLLOWING TOO CLOSELY, REACTION TO OTHER UNINVOLVED VEHICLE	NORTH-EAST	REAR END	App. **P Tarra v-z born ravening normeast bound on the tamp from F-V-2 bars to me the as sudden shop due to an uninvolved which that came to a sudden shop in front of thim. Op of V-1 was unable to stop in firme and V-1 rear ends V-2 causing said damage. Op of V-1 stated that V-2 and the uninvolved vehicle were having a road rage incident of I-490 before they got onto the ramp and when they gloton the tramp she could no honger see the uninvolved vehicle and did not know it was still in font of V-2 and that it slammed on the trakes. Op of V-2 stated that twill be on I-490 East he was behind the uninvolved vehicle and the operator of that vehicle brake checked him a couple of times so he passed the uninvolved vehicle. Op V-2 stated that the uninvolved vehicle assed him before they got onto the ramp and when they were on the ramp the uninvolved vehicle sammed on the trakes for no reason. Op of V-2 stated that the uninvolved vehicle was going to do hat so he was ready for I and was able to come to a stip without hilling he uninvolved vehicle. Op V-2 stated nather uninvolved vehicle was going to do hat so he was ready for I and was able to come to a stip without hilling he uninvolved vehicle. Op V-2 had no palse information	940T43011004
295	37552603	10/23/2018	12:59:00 PM	2	NON- REPORTABLE	DAYLIGHT	WET	RAIN	UNSAFE LANE CHANGE	WEST	OVERTAKING	and the unique before the state of the state	
296	37545603	10/24/2018	8:15:00 AM	3	PROPERTY DAMAGE	DAYLIGHT	WET	RAIN	FOLLOWING TOO CLOSELY	WEST	OTHER	V-1 TRAVELING WESTBOUND ON STATE ROUTE 940T FAILED TO OBSERVE V-2 STOPPED IN TRAFFIC. V-1 REAR ENDED V-2 CAUSING V-2 TO STRIKE V-3.	940T43011005
297	37545615	10/24/2018	8:17:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	WET	RAIN	FOLLOWING TOO CLOSELY	WEST	REAR END		940T43011004
298	37565981	10/30/2018	5:28:00 PM	3	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	SOUTH-WEST	OTHER		940T43011004
299	37570128	11/6/2018	3:18:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	WET	CLEAR	FOLLOWING TOO CLOSELY	SOUTH-WEST	REAR END	V-1 and V-2 both traveling southwest bound on the Inner Loop- West in he right lane. V-1 was traveling behind V-2. OP of V-2 has to come to a stop due to uninvolved vehicles that come to a stop in font of her. V-1 is unable to stop in time and V-1 rear ends V-2 causing said damage. V-1 left he scene. Op of V-2 was able to get the license plate of V-1 and described the other of V-1. Due to the information given I was able to locate V-1 and the driver.	
300	37575890	11/8/2018	7:32:00 AM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	UNSAFE LANE CHANGE	WEST	OVERTAKING	V1 AND V2 WERE WESTBOUND ON THE INNERLOOP NEAR STATE ST IN THE CITY OF ROCHESTER WHEN V1 TRIED TO CHANGE LANES FROM THE RIGHT LANE TO THE LEFT LANE, DID NOT SEE V2, AND STRUCK V2. CLOSED.	940T43011004
301	37587889	11/11/2018	10:34:00 PM	1	PROPERTY DAMAGE AND INJURY	DARK-ROAD LIGHTED	DRY	CLOUDY	BRAKES DEFECTIVE	WEST	OTHER	Arrived on scene and interviewed the driver of V-1 who shaled that she was taveling west on the Inner Loop. She staked she tired to slow down and lost control, stating the car began to shake and was not able to control the car. Staked she tired to stop but could not and drove in the median. Howked at the car and the damage is limited to the font of the vehicle and suggest the vehicle impacted the guard rail at a right angle. There was some impact damage to the quard rail.	940T43011009
302	37581823	11/13/2018	4:15:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	WET	SNOW	FOLLOWING TOO CLOSELY	WEST	REAR END	VEH 1 AND VEH 2 WESTBOUND ROCHESTER INNER LOOP. DRIVER 1 STATES SHE WAS USING PHONE GPS, IT FELL AND WHEN SHE LOOKED DOWN SHE STRUCK VEH 2 CAUSING DAMAGE TO BOTH VEHICLES.	940T43011003

TE 213 (9/79)													
COUNTY:	MONROE		P.I.N.:	NOT APPLICAB		ROUTE NO. OR					CASE No.:		
	TOWN					INNER LOOP (N	YS 940T) AND R	RAMPS			FILE	PSC 5/13/2020	- -
	CITY					AT INTERSECT	ION WITH/OR B	ETWEEN:			BY:	PSC	_
	VILLAGE OF	ROCHESTE	ER			FROM I-490 INT	ERCHANGE TO	INNER LOOP TE	RMINUS AT N. UNION ST		DATE:	5/13/2020	_
TIME PERIOD		FROM: 8/1/14	TO: 7/31/119	ENVIRONMENT Use Codes from at right) for these	MV 104 (shown e categories	Light Conditions: 1. Daylight 2. Dawn 3. Dusk 4. Dark Road Lig 5. Dark Road Un	yhted	Roadway Surfar 1. Dry 2. Wet 3. Muddy 4. Snowlice 5. Slush 10. Other	ce Condition: Weather: 1. Clear 2. Cloudy 3. Rain 4. Snow 5. Slee\/!Hall/Fre 6. Fog/Smog/St 10. Other				
No. OF MONTH	S:	6	0	S		ONS					¹ Use Codes from	MV 104 Police Report	
CRASH No.	CASE No.	DATE	TIME	No. of VEHICLES	SEVERITY	LIGHT CONDITIONS	ROADWAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING FACTORS	DIRECTION	TYPE ¹	DESCRIPTION	REFERENCE MARKER
303	37590522	11/13/2018	11:15:00 PM	1	PROPERTY DAMAGE	DARK-ROAD LIGHTED	WET	CLOUDY	UNSAFE SPEED	WEST	OTHER	V-1 West on Inner Loop when Operator V-1 states that she lost control on icy pavement and went off the right side of the roadway and struck the concrete wall Located off the North shoulder.	940T43011006
304	37603240	11/24/2018	4:40:00 PM	1	NON- REPORTABLE	DARK-ROAD LIGHTED	WET	RAIN	UNSAFE SPEED	NORTH-WEST	OTHER	V-1 Paveling northwestbound on the ramp from the hner Loop West onto I-490 West when Op of V-1 loses control of her vehicle. V-1 goes of the roadway into the large rock covered median on the southwest side of the road and strikes a concrete barrier causing said damage. There was no damage to the concrete barrier.	490143022026
305	37608258	11/26/2018	12:17:00 PM	1	PROPERTY DAMAGE	DAYLIGHT	WET	RAIN	UNSAFE SPEED	WEST	OTHER	V-1 driving on I 490 West from the inner loop drives off the roadway striking the earth embankment on the North shoulder with the front bumper area of V-1 causing damage.	490143022026
306	37616340	11/29/2018	2:01:00 PM	1	PROPERTY DAMAGE	DAYLIGHT	WET	CLOUDY	UNSAFE SPEED	EAST	OTHER		940T43011016
307	37637379	12/1/2018	12:25:00 AM	1	PROPERTY DAMAGE	DARK-ROAD LIGHTED	DRY	CLOUDY	ALCOHOL INVOLVEMENT	WEST	OTHER	V-1 West on the Inner Loop when operator fails to negotate a left- hand curee. V-1 exits the roadway by the South, shifts the guide rail hen crosses he road and comes to rest off the North side of the roadway up an earth embankment. Three people were identified as occupants of V-1 all denied being the other and two of them refused to provide heir names or any ID. One, claiming to be Jasmine Earthon was transported to Stong Hospital for back / nerk pain by AMR.	940T43011007
308	37637358	12/10/2018	8:52:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLOUDY	UNSAFE LANE CHANGE	WEST	OVERTAKING	STATE ST N THE CITY OF PROCHESTER. AN UNINVOLVED VEHICLE ALLOWED VI TO THE MOST WITO THE RIGHT LANE AHEAD OF IT AND AS VI TRED TO CHANGE LANES FROM THE RIGHT LANE. INTO THE LEFT LANE VI STRUCK. V.2. DRIVER 25 TASTED THAT HE COULD NOT SEE VI MOVE INTO HIS LANE DUE TO THE UNINVOLVED VEHICLE BLOCKING HIS VISSON. (CLOSE).	940T43011006
309	37637322	12/10/2018	5:07:00 PM	3	PROPERTY DAMAGE AND INJURY	DARK-ROAD LIGHTED	DRY	CLEAR	FOLLOWING TOO CLOSELY	WEST	OTHER	V1, V2, and V3 all traveling west bound in the Inner Loop in the City of Rochester. V1 following too closely fails to observe V2 and V3 stopped in traffic and rear ends V2 causing V2 to rear end V3. No tows.	940T43011003
310	37640739	12/10/2018	5:48:00 PM	4	PROPERTY DAMAGE AND INJURY	DARK-ROAD LIGHTED	DRY	CLOUDY	FOLLOWING TOO CLOSELY	EAST	OTHER		940T43011004
311	37640741	12/12/2018	5:21:00 PM	2	PROPERTY DAMAGE	DARK-ROAD LIGHTED	DRY	CLOUDY	FOLLOWING TOO CLOSELY	SOUTH-EAST	REAR END	V-1 and V-2 both traveling southeast bound on the Inner Loop- East, in the left lane. V-1 was traveling in front of V-2. V-1 has be come to a stop due to uninvolved vehicles that come to a stop in front of him. V-2 unable to stop in time and V-2 rear ends V-1 causing said damage. V-2 left the scene of the accident. Op of V- 1 described V-2 as an older style Camaro. No further information and Op of V-1 was unable to get the license plate. I checked the area with neadow results.	940T43011013
312	37646229	12/12/2018	5:30:00 PM	2	PROPERTY DAMAGE	DARK-ROAD LIGHTED	DRY	CLOUDY	FOLLOWING TOO CLOSELY	WEST	REAR END	V1 AND V2 WERE TRAVELING WESTBOUND ON THE INNER LOOP NEAR STATE ST. THE DRIVER OF V1 FALED TO OBSERVE V2 STOPPING, SUBSEQUENTLY STRIKING THE REAR OF V2. NO INJURIES.	940T43011005
313	37637333	12/12/2018	5:45:00 PM	2	PROPERTY DAMAGE	DARK-ROAD LIGHTED	DRY	CLOUDY	FOLLOWING TOO CLOSELY	SOUTH-EAST	REAR END	V-1 and V-2 both traveling southeast bound on the Inner Loop - East, in the left thand lane. V-1 was traveling behind V-2. V-2 has to come to a stop due to uninvolved vehicles that come to a stop in front of him. V-1 unable to stop in time and V-1 rear ends V-2 causing said damage.	940T43011013
314	37638058	12/13/2018	5:48:00 PM	3	PROPERTY DAMAGE AND INJURY	DARK-ROAD LIGHTED	DRY	CLEAR	FOLLOWING TOO CLOSELY	WEST	OTHER		940T43011006
315	37656907	12/16/2018	5:40:00 PM	2	PROPERTY DAMAGE	DARK-ROAD LIGHTED	WET	CLOUDY	UNSAFE SPEED	NORTH-EAST	REAR END		940T43011002
316	37642331	12/16/2018	6:08:00 PM	1	PROPERTY DAMAGE	Dark-Road Lighted	WET	CLOUDY	STEERING FAILURE	NORTH-EAST	OTHER	OP VEH-I ENTERING INITER LOOP FROM EASTBOUND 1490 IN THE CITYOP ROCHESTER. DUE TO STEERING FAULURE. OP VEH-I LOST CONTROL OF VEH-I AND STRUCK THE CURB CAUSING DAWAGE TO THE UNDER CARRIAGE. OP VEH-I ADVISED THE VEHICLE SHUT OFF AND HE EXPERIENCED AN ELECTRICAL ISSUE WHERE HIS STEERING BECAME HARD TO TURN	940T43011002
317	37646239	12/17/2018	4:34:00 PM	2	NON- REPORTABLE	DARK-ROAD LIGHTED	WET	SNOW	UNSAFE LANE CHANGE	WEST	OVERTAKING	V-1 ATTEMPTING TO CHANGE LANES FROM THE LEFT TO THE RICHT LANE WHEN 0P-1 STATED HE BELLEVED HE HAD ENOUGH ROOM WHEN Y-2 BEGAN TO SPEED UP NOT LETTING HIM CHANGE LANES IN A SAFE MANNER CAUSING HIM TO STRIKE THE MIRROR OF V-2. OILLY DAMAGE TO V-1 YELLOW HAZABO LIGHT ON REAR OF BUS, V-2 SDE MIRROR DAMAGEO. NO BUJURES REPORTED ON EITHER V-1 OR V-2. BOTH VEHICLES DRIVEN FROM THE SCENE. NYS DOT CONTACTED TO REPORT THE SCHOOL BUS ACCIDENT. BOTH VEHICLES DRIVEN FROM THE SCHOOL BUS ACCIDENT. BOTH VEHICLES DRIVEN FROM THE SCENE.	940T43011004
318	37646240	12/18/2018	7:17:00 AM	3	PROPERTY DAMAGE	DAWN	DRY	CLOUDY	FOLLOWING TOO CLOSELY	EAST	OTHER	V-1 EAST ON THE INNER LOOP WHEN TRAFFIC AHEAD OF HIM BECAN SLOWING DOWN, V-1 FOLLOWING TOO CLOSE TO V-2 AND SUBSEQUENTLY STRUCK SAME. AFTER V-1 STRUCK V-2, V-2 WAS PUSHED INTO THE BUMPER OF V-3 CAUSING MINIMAL DAMAGE. NO NUTURES REPORTED, EMS DECLINED, V-1 REMOVED FROM SCENE VAI JOHN AND SON COLLISION V-2 AND V-3 RIBEPT FROM SCENE VAI JOHN AND SON COLLISION V-2 AND V-3 RIBEPT FROM SCENE VAI JOHN AND SON COLLISION V-2 AND V-3 RIBEPT FROM SCENE VAI JOHN AND SON COLLISION V-2 AND V-3 RIBEPT FROM SCENE VAI JOHN AND SON COLLISION V-2 AND V-3 RIBEPT FROM SCENE VAI JOHN AND SON COLLISION V-2 AND V-3 RIBEPT FROM SCENE VAI JOHN AND SON COLLISION V-2 AND V-3 RIBEPT FROM SCENE VAI JOHN AND SON COLLISION V-2 AND V-3 RIBEPT FROM SCENE V-3 AND V-3	
319	37651791	12/19/2018	6:04:00 PM	2	PROPERTY DAMAGE	DARK-ROAD LIGHTED	DRY	CLEAR	FOLLOWING TOO CLOSELY	EAST	REAR END	THE PARTY OF THE P	940T43011013

TE 213 (9/79)						DOLLTE NO. OD	STREET NAME						
COUNTY:	MONROE		P.I.N.:	: NOT APPLICAE	BLE						CASE No.:		
	TOWN		•				IYS 940T) AND F				FILE:		-
	CITY VILLAGE OF	ROCHEST	FD			AT INTERSECT	ION WITH/OR B	BETWEEN:			BY: DATE:		-
	TILL TOL OF				=	FROM I-490 INT	ERCHANGE TO		ERMINUS AT N. UNION ST		DATE	3/13/2020	-
TIME PERIOD		FROM: 8/1/14	TO: 7/31/19	ENVIRONMEN Use Codes from at right) for these	n MV 104 (shown e categories	Light Conditions 1. Daylight 2. Dawn 3. Dusk 4. Dark Road Lig 5. Dark Road Ur	ghted	Roadway Surfa 1. Dry 2. Wet 3. Muddy 4. Snowlice 5. Slush 10. Other	ce Condition: Weather: 1. Clear 2. Cloudy 3. Rain 4. Snow 5. Slee\text{VHail/Fre} 6. Fog\Smog\Sr 10. Other				
No. OF MONTH	IS:	6	0	S		SNOI					¹ Use Codes from	MV 104 Police Report	
CRASH No.	CASE No.	DATE	TIME	No. of VEHICLES	SEVERITY	LIGHT CONDITIONS	ROADWAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING FACTORS	DIRECTION	TYPE ¹	DESCRIPTION	REFERENCE MARKER
320	37651802	12/20/2018	5:29:00 PM	4	PROPERTY DAMAGE	DARK-ROAD LIGHTED	DRY	CLOUDY	FOLLOWING TOO CLOSELY	SOUTH-WEST	OTHER	VI south weston Inner Loop WB, SR 940T, in the Ciliyot Rochester, Trailie was slowing down on Sale Highway. VI following bo closely to V2, which was slowing down in taffe, striking the rear of same causing damage: subsequently, causing V2 to stike the rear of V3, and V3 to stike the rear of V4, all causing damage. No injuries reported on scene by all drivers. Passenger of V4 stated she was not injuried. No lows needed. All publishes driven from scene.	940T43011004
321	37673155	1/5/2019	4:27:00 PM	2	PROPERTY DAMAGE	DARK-ROAD LIGHTED	DRY	CLOUDY	UNSAFE LANE CHANGE	EAST	OVERTAKING	Driver 1 saled that she was east bound in the lettaine, Verhicle 2 changed into her lane and shuck Verhicle 1. Driver 2 stated that she was east bound in the right lane, Verhicle 1 changed into her lane and shuck Verhicle 2. Verhicle 1 was towed to the City of Rochester Auto Pound because Driver 1 could not provide proof of insurance.	490143022025
322	37690556	1/14/2019	5:12:00 PM	3	PROPERTY DAMAGE	DARK-ROAD LIGHTED	DRY	CLOUDY	FOLLOWING TOO CLOSELY	WEST	OTHER		940T43011004
323	37696565	1/19/2019	9:30:00 PM	1	PROPERTY DAMAGE	DARK-ROAD LIGHTED	SNOW/ICE	SNOW	FOLLOWING TOO CLOSELY	WEST	OTHER	V-1 west on the innerloop in the city of Rochester following a DOT plow truck. Driver of V-1 stated it looked like the plow truck was taking the exit of the innerloop but swerved back into the right lane which caused driver of V-1 to hit her brakes. V-1 lost control and struck guide rail end causing damage to V-1.	940T43011008
324	37718833	1/30/2019	10:23:00 AM	1	PROPERTY DAMAGE	DAYLIGHT	SNOW/ICE	CLOUDY	UNSAFE SPEED	WEST	OTHER		940T43011001
325	37738882	2/11/2019	4:14:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLOUDY	FOLLOWING TOO CLOSELY	SOUTH-WEST	REAR END	Vehicle 1 traveling in the West Bound right lane of the Rochester Interloop behind Vehicle 2. Vehicle 2 slows for traffic ahead of her and the Operator of Vehicle 1 does not realize that she had slowed down and strikes the rear of Vehicle 2.	940T43011004
326	37745805	2/15/2019	10:53:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	WET	RAIN	PASSING OR LANE USAGE IMPROPERLY	EAST	OVERTAKING	V-1 AND V-2 TRAVELING SIDE BY SIDE IN AN EASTERLY DIRECTION ON INNER LOOP IN THE CITY OF ROCHESTER. DRIVER OF V-1 AND DRIVER OF V-2 BOTH CLAIM OTHER VEHICLE DRETED INTO LANE. NO INJURIES REPORTED. V-1 WESTOR THE INDEX LO	940T43011007
327	37757548	2/23/2019	7:30:00 PM	1	PROPERTY DAMAGE	DARK-ROAD LIGHTED	WET	CLOUDY	ALCOHOL INVOLVEMENT	WEST	OTHER	hand curve and strikes the barrier at the exit ramp to Joseph Ave and then continues Wesbound with two fall tires and heavy front and damage before being shopped by the police at IMI St and Alen St. The barrier at that ramp already had extensive damage from several previous collisions. The operator of V-1 was determined to be intoxicated and was arrested for DMI. Tickets ISSUEd: SNAYSIG RUIZ-GONZALEZ Driver of vehicle number (1) tickets. Ticket Number: P16098GDJB Violation: 11923 Ticket Number: P16098GCJX Violation: 11924 Ticket Number: P16098GCJX Violation: P16098GCJX Violation: P16098GCJX Violation: P16098GCJX Violati	940T43011011
328	37764265	2/24/2019	11:17:00 PM	1	PROPERTY	DARK-ROAD	WET	RAIN	UNSAFE SPEED	EAST	OTHER	V-1 traveling eastbound on Interstate 490 off ramp lost control of vehicle striking barrier. No apparent damage to barrier.Out of	490143022027
					DAMAGE PROPERTY	LIGHTED			5011 0111110 TOO 01 0051 V			State Insurance State Farmpolicy number 4898416-A22-22A .	
329	37769526	2/27/2019	4:20:00 PM	2	DAMAGE	DAYLIGHT	SNOW/ICE	SNOW	FOLLOWING TOO CLOSELY	WEST	REAR END	Unit 1 and Unit 2 are westbound on the Innerloop. Unit 2 is	940T43011006
330	37767560	2/28/2019	4:05:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	WEST	REAR END	stopping in traffic and Unit 1 rear ends Unit 2. Unit 1 is Towed by	940T43011005
331	37786350	3/6/2019	3:36:00 PM	1	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	UNSAFE LANE CHANGE	WEST	OTHER	V-1 WEST ON THE INNERLOOP WHEN OP-1 CHANGED LANES UNSAFELY DUE TO ANOTHER CARS ACTIONS, AND STRUCK THE END OF THE GUARDRAIL. NO APPARENT DAMAGE TO THE GUARDRAIL OBSERVED. V-1 DRIVEN FROM THE SCENE.	940T43011010
332	37807390	3/15/2019	4:38:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	WEST	REAR END	V-1 traveling West on Inner Loop in the City of Rochester fails to slow in time and strikes rear of V-2 causing minor damage. No	940T43011004
333	37824058	4/4/2019	4:57:00 PM	2	PROPERTY DAMAGE AND INJURY	DAYLIGHT	DRY	CLEAR	DRIVER INATTENTION	WEST	REAR END	injuries reported.	940T43011004
334	37835494	4/12/2019	9:55:00 AM	1	PROPERTY DAMAGE AND INJURY	DAYLIGHT	DRY	CLOUDY	DRIVER INATTENTION	WEST	OTHER	Vehicle 1 traveling weston the Inner Loop in the City of Rochester. Driver 1 sales he looks down and drifts north off he roadway striking the crash barrier hald whites he Inner Loop and the exit for S. Paul Bird. Vehicle 1 then crosses the westbound lanes of the Inner Loop and Sirkse he guider alon the south side. Driver 1 complains of hip and neck pain and is transported by ambulance to Strong Memorial Hospital WITNESS 1 MCARTHUR. SCDTI- 475 SUPPER HOLLEY ROAD HOLLEY NOT 4470 5857387603	940T43011011
335	37836007	4/12/2019	4:41:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	WET	RAIN	FOLLOWING TOO CLOSELY	WEST	REAR END	V-1 WEST ON THE INNER LOOP WHEN TRAFFIC AHEAD OF HIM BEGAN SLOWING DOWN, V-1 FOLLOWING TOO CLOSELY TO V-2 AND STRUCK SAME. OP-1 AND OP-2 DECLINED EMS TO RESPOND TO THE SCENE. BOTH VEHICLES DRIVEN FROM THE SCENE.	940T43011004
336	37840247	4/14/2019	8:43:00 PM	2	PROPERTY DAMAGE	DARK-ROAD LIGHTED	WET	CLOUDY	FOLLOWING TOO CLOSELY	WEST	OVERTAKING	V-2 WEST ON THE NNER LOOP WHEN V-1 CAME UP BEHIND HER VEHICLE AND ATTEMPTED 10 PASS ON THE RIGHT HAND SIDE STRIKING THE REAR BUMPER OF V-2. V-1 THEN MMEDIATELY BACKED UP ON THE HIGHWAY BEFORE CONTINUING ON THE NINER LOOP ON POLATE INFORMATION AVAILABLE PER OP-2. V-1 FLED THE SCENE NO DIRECTION OF TRAVEL V-2 UNINJURED, EMS REFUSED. V-2 DRIVEN FEROM THE SCROWN TH	940T43011006
337	37840251	4/14/2019	8:43:00 PM	2	PROPERTY DAMAGE	DARK-ROAD LIGHTED	WET	CLOUDY	PASSING OR LANE USAGE IMPROPERLY	WEST	OVERTAKING	V1 was weston the Inner Loop when V2, an unknown red weblice, altempted to pass V1 on the right V2 sideswiped the passenger side of V1 causing damage to same. V2 fled the scene. Scene consistent with a hit and run accident. No injuries reported. V1 driven from scene.	940T43011006

TE 213 (9/79)						ROUTE NO. OR	CTDEET NAME						
COUNTY:	MONROE		P.I.N.:	NOT APPLICAB	LE	INNER LOOP (N					CASE No.:		_
	TOWN CITY					AT INTERSECT					FILE:	DSC	-
	VILLAGE OF	ROCHESTI	ER						RMINUS AT N. UNION ST		DATE:	PSC 5/13/2020	-
TIME PERIOD		FROM:	TO:	ENVIRONMENT	Δ1 ·	Light Conditions:		Roadway Surfa					
TIME PERIOD		8/1/14	7/31/19		MV 104 (shown e calegories		yhted	1. Dry 2. Wet 3. Muddy 4. Snowlice 5. Slush 10. Other	1. Clear 2. Cloudy 3. Rain 4. Snow 5. Sleet/Hall/Fre 6. Fog/Smog/Sn 10. Other				
No. OF MONTH	S:	6	0	S		SNOI					¹ Use Codes from	MV 104 Police Report	
CRASH No.	CASE No.	DATE	TIME	No. of VEHICLES	SEVERITY	LIGHT CONDITIONS	ROADWAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING FACTORS	DIRECTION	TYPE ¹	DESCRIPTION	REFERENCE MARKER
338	37848712	4/19/2019	6:50:00 PM	2	PROPERTY DAMAGE	DUSK	WET	RAIN	FOLLOWING TOO CLOSELY	EAST	REAR END	Driver 1 states he driving eastbound and due to the slippery roads was unable to stop in time and he rear ended Unit 2 who was stopping in 1 raffic. Driver 1 states Unit 2 left the scene. Driver 1 states he does not have any identifiable information on the vehicle other than it&aooss a while sedan.	940T43011013
339	37848441	4/22/2019	8:55:00 AM	3	PROPERTY DAMAGE	DAYLIGHT	DRY	CLOUDY	FOLLOWING TOO CLOSELY	EAST	OTHER		940T43011009
340	37853730	4/24/2019	2:34:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	WEST	REAR END	VI AND V2 WERE WESTBOUND ON THE NWERLOOP IN THE CITYOF ROCHESTER. AS V2 WAS SLOWING DOWN DUE TO A DISABLED VEHICLE PARTHALLY BLOCKING THE RIGHT LANE, VI COULD NOT SLOW DOWN IN TIME AND STRUCK V2 IN THE REAR. CLOSED. VI and V2 Taveling weston the Inner Loop in the rightlane when	940T43011003
341	37853737	4/24/2019	5:21:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	WEST	REAR END	V2 slows for traffic. V1 unable to avoid striking the rear of V2 and strikes same. Both vehicles driven from scene. No injuries reported.	940T43011005
342	37868661	5/6/2019	4:43:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	UNSAFE LANE CHANGE	EAST	OVERTAKING	VI and V2 are traveling eashbound on the Inner Loop in the CI Rochester within he area of Scio St. Op. 1 attempted to make a lane change from the lattlane to the right lane, falling to see V2 tavelling in the right lane. Subsequently, V1 struck V2 front driver side quarter panel area with the rear passenger side quarter panel area of V2. Damage to same. No tows needed. No injuries recorded.	940T43011006
343	37876103	5/10/2019	6:30:00 PM	1	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	PAVEMENT DEFECTIVE	EAST	OTHER	V1 traveling eastbound on the inner loop in the C/ Rochester in wichity of East Ave. While traveling in the right lane, Op. 1 struck a large pot hole that was unavoidable in the lane causing damage to the front driver side litre of V1. No injuries reported. V1 did sustain damage to the litre and rim area.	940T43011013
344	37881545	5/14/2019	7:50:00 AM	2	PROPERTY DAMAGE AND INJURY	DAYLIGHT	WET	RAIN	UNSAFE SPEED	WEST	REAR END		940T43011002
345	37883818	5/14/2019	3:56:00 PM	4	PROPERTY DAMAGE AND INJURY	DAYLIGHT	DRY	CLOUDY	UNSAFE SPEED	WEST	OTHER		940T43011004
346	37886337	5/16/2019	9:03:00 PM	2	PROPERTY DAMAGE	DARK-ROAD LIGHTED	WET	CLOUDY	FOLLOWING TOO CLOSELY	WEST	REAR END		940T43011004
347	37886346	5/16/2019	9:03:00 PM	2	NON- REPORTABLE	DARK-ROAD LIGHTED	WET	CLEAR	UNSAFE LANE CHANGE	WEST	REAR END	V-1 CHANGING LANES UNSAFELY ON INNER LOOP WEST IN THE CITY OF ROCHESTER. V-1 CHANGES LANES AND STRIKES V-2 CAUSING DAMAGE TO EACH VEHICLE. NO INJURIES REPORTED.	940T43011005
348	37941211	5/16/2019	9:03:00 PM	4	PROPERTY DAMAGE AND NURY	DARK-ROAD LIGHTED	WET	CLOUDY	REACTION TO OTHER UNINVOLVED VEHICLE, OTHER (VEHICLE)	WEST	OTHER	V-1 WEST ON THE NINER LOOP WHEN OP-1 OBSERVED 2 VEHICLE SPARED ON THE SHOULDER V-2 AND V3 WERE PARKED PARTIALLY OCCUPYING THE RIGHT LANE OF TRAVEL WESTBOUND ON THE NINERLOOP DUE TO BEING MYOLVED IN A PREVIOUS MAY. V-4 AND ANOTHER VEHICLE UNINVOLVED IN THIS MAY WERE PARKED PARTIALLY OCCUPYING THE RIGHT LANE OF TRAVEL WESTBOUND ON THE NINERLOOP. OP-1 COULD NOT GO TO THE LEFT, DROVE V-1 SENT INTO THE CONCRETE BARRER. V-1 SLID ALONG THE SHOULDER AND STRUCK V-3 ON THE FRONT PASSENGER SIDE CORNER BEFORE COMING TO A REST AFTER STRIKING V-4, UPON INVESTIGATION OF THE ACCIDENT V-1 COULD NOT GO TO THE LEFT DUE TO ANOTHER MOTORCYCLE NEXT TO HIM GOING TO THE LEFT TO AVOID THE VEHICLES. OP-1 TRANSPORTED TO STRONG MOSPITAL IN CRITICAL/STABLE CONDITION LOWER LEFT LEF MUJEY. NO OTHER NUJINES REPORTED FROM V-2, V-3 AND V-4, V-1 AND V-2 TOWED FROM THE SCREW VE ACCIDENT V-4 V-1 AND V-2 TOWED FROM THE SCREW VE ACCIDENT OWNING. V-1 HAS PROGRESSIVE INSURANCE, UNKNOWN COMPANY CODE - WITNESS I BROWN, RASHONDA D 52 PORTLAND OR ROCHESTER TY H-4621 SSE20884647	940743011004
349	37893077	5/18/2019	7:45:00 AM	3	PROPERTY DAMAGE AND INJURY	DAYLIGHT	DRY	CLEAR	OTHER (VEHICLE)	WEST	OTHER	V1, V2, V3 WERE WESTBOUND ON THE INNERL OOP IN THE CITYOF ROCHESTER. V1 BECAME DISABLE IN THE LEFT LANE AND CAME TO A COMPLETE STOP. V2 APPROACHED AND CAME TO A STOP BEHIND V1 WITHOUT MAKING CONTACT. V3 COULD NOT STOP IN TIME, STRUCK V2 IN THE REAR WHICH CAUSED V2 TO STRIKE V1. DRIVER 1 STATED THAT SHE DID NOT KNOW WHY HER VEHICLE BECAME DRSABLED. (C) SED.	940T43011004
350	37909001	5/30/2019	9:00:00 AM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLOUDY	UNSAFE LANE CHANGE	EAST	OVERTAKING	Vehicle 1 Taveling east on the Rochester Inner Loop in the right lane. Vehicle 2 traveling in the left lane eastbound on the Rochester Inner loop. Vehicle 1 altempts to change lanes and does not see Vehicle 2. As Vehicle 1 changes lanes, it side swites Vehicle 2.	940T43011006
351	37918818	6/3/2019	4:26:00 PM	1	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	FAILURE TO KEEP RIGHT	WEST	OTHER	Driver 1 stated that he was west bound on the Inner Loop in the left lane, unknown vehicles swerved from the right to left lane ahead, Driver 1 look evasive action to avoid a collision and struck the median.	940T43011004
352	37910619	6/3/2019	4:38:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	EAST	REAR END	V-1 slowing in traffic and unable to slow in time for V-2 stopped in traffic. V-1 strikes rear of V-2 causing damage. No injuries reported.	940T43011002
353	37926903	6/13/2019	4:05:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	WET	RAIN	FOLLOWING TOO CLOSELY	WEST	REAR END	Vehicle 1 west on the Inner Loop behind Vehicle 2 when Iraffic slowed and slopped. Operator of Vehicle 1 was following too closely and was unable to stop in time and struck the rear of Vehicle 2.	940T43011006
354	37930739	6/14/2019	2:35:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	WEST	REAR END	VI AND V2 WERE WESTBOUND ON THE MINERLOOP IN THE CITYOF ROCHESTER. AS V2 WAS SLOWING DOWN DUE TO A SEPARATE ACCIDENT WHICH HAD OCCURRED DRECTLY IN FRONT OF BOTH VEHICLES ON THE INMERLOOP, V1 WAS FOLLOWING TOO CLOSELY TO V2 AND STRUCK V2 IN THE REAR. CLOSED.	940T43011003

TE 213 (9/79)

TE 213 (9/79)													
						ROUTE NO. OR	STREET NAME						
COUNTY:	MONROE		P.I.N.	NOT APPLICAB	LE	INNER LOOP (N	YS 940T) AND R	AMPS			CASE No.:		_
	TOWN										FILE:		
	CITY VILLAGE OF	DOOUTOT				AT INTERSECT	ION WITH/OR B	ETWEEN:			BY:	PSC	
	VILLAGE OF	ROCHEST	ER			FROM I-490 INT	ERCHANGE TO	INNER LOOP TE	RMINUS AT N. UNION ST		DATE:	5/13/2020	
TIME PERIOD		FROM:	TO:	ENVIRONMENT	AL:	Light Conditions:		Roadway Surfac	e Condition: Weather:				
		8/1/14	7/31/19	Use Codes from at right) for these	MV 104 (shown	Daylight Dawn		1. Dry 2. Wet	1. Clear 2. Cloudy				
		0/1/14	1131119	attigity tot trese		3. Dusk		3. Muddy	3. Rain				
						 Dark Road Lig Dark Road Un 		Snow/Ice Slush	4. Snow 5. Sleet/Hail/Fre	o zina Doin			
						5. Daik Rudu Uli	iligineu	10. Other	6. Fog/Smog/Sr				
									10. Other				
No. OF MONTH	IS:	6	0	S		ONS					Use Codes from I	MV 104 Police Report	
				of VEHICLES		LIGHT CONDITIONS	_ z			DIRECTION	TYPE ¹	DESCRIPTION	REFERENCE
CRASH No.	CASE No.	DATE	TIME	₽	SEVERITY	1 00	ROADWAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING				MARKER
				No. o	SEVE	HSIT	ROA SURF CON	WEA	FACTORS				
												V1, V2 WERE WESTBOUND ON THE INNERLOOP IN THE CITY OF ROCHESTER. AS V2 WAS SLOWING DOWN DUE TO	
355	37930778	6/14/2019	2:35:00 PM	2	PROPERTY	DAYLIGHT	DRY	CLOUDY	FOLLOWING TOO CLOSELY	WEST	REAR END	HEAVY STOP AND GO TRAFFIC, V1 WAS FOLLOWING TOO	940T43011004
333	3/930//0	0/14/2019	2:35:00 PW	2	DAMAGE	DATEIGHT	DKT	CLOUDT	TOLLOWING TOO CLOSELT	WEST		CLOSELY AND STRUCK V2 IN THE REAR CAUSING V1 TO BOUNCE OFF OF V2 AND STRIKE THE CENTER MEDIAN.	940143011004
												CLOSED.	
356	37945467	6/23/2019	7:05:00 AM	2	PROPERTY	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	EAST	REAR END	V-2 stopped in traffic on Inner Loop East in the City of Rochester. V-1 fails to slow and strikes rear of V-2 causing damage. No	940T43011006
555	07710107	0/20/2017	7.00.007411	-	DAMAGE	DATE	Ditt	OLD III		LAD.		injuries reported.	710110011000
												V-1 and V-2 both traveling southwest bound on the Inner Loop - West in the right lane. V-1 was traveling behind V-2. Op of V-2	
357	37951198	6/26/2019	8:57:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	SOUTH-WEST	REAR END	has to come to a stop due to uninvolved vehicles that come to a	940T43011006
												stop in front of him. Op of V-1 is unable to stop in time and V-1 rear ends V-2 causing said damage.	
358	37970837	7/9/2019	5:45:00 PM	2	PROPERTY	DAYLIGHT	DRY	CLEAR	OTHER (VEHICLE)	WEST	REAR END		940T43011002
358	3/9/083/	//9/2019	5:45:00 PM	2	DAMAGE AND INJURY	DAYLIGHT	DKY	CLEAR	OTHER (VEHICLE)	WEST	KEAK END		940143011002
												VEH 1 AND VEH 2 WESTBOUND ROCHESTER INNER LOOP. DRIVER 1 STATES THAT HE DID NOT SEE VEH 2 WHEN HE	
359	37973610	7/13/2019	9:33:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	UNSAFE LANE CHANGE	WEST		LOOKED TO CHANGE LANES. WHEN VEH 1 CHANGED LANES	940T43011006
					DAINAGE							VEH 1 STRUCK VEH 2 CAUSING DAMAGE TO BOTH VEHICLES:	
												V-1, V-2 and V-3 all traveling southwest bound on the Inner Loop -	
												West in the center lane. V-1 was traveling behind V-2 and V-2 was traveling V-3. Op of V-3 comes to a stop due to uninvolved	
360	37983376	7/16/2019	7:51:00 AM	3	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	SOUTH-WEST	OTHER	vehicles that come to a stop in front of him. Op of V-2 starts	940T43011006
					D. III.NOL							slowing down behind V-3. Op of V-1 is unable to stop in time and V-1 rear ends V-2 which pushes V-2 into V-3 causing said	
												damage to all vehicles.	

TE 213 (9/79)

CASE No.	TE 213 (9/79)													
THE FEMOL	COUNTY:	MONROE		P.I.N.:	NOT APPLICATE	BLE						CASE No.:		
THE FEMOL		TOWN		•								FILE:		_
THE FEMOL							AT INTERSEC	TION WITH/OR	BETWEEN:			BY	PSC	_
No. OF MANIFEST 100		VILLAGE OF	ROCHESTER				SEE MAP					DATE	5/13/2020	-
No. OF MANIFEST 100	TIME PERIOD		FROM:	TO:	ENVIRONMEN	TAL:	Light Conditions		Roadway Surfac	e Condition: Weather:				
CONSISTING CON					Use Codes from	MV 104 (shown	1. Daylight 2. Dawn 3. Dusk 4. Dark Road Li	ghted	1. Dry 2. Wet 3. Muddy 4. Snow/Ice 5. Slush	1. Clear 2. Cloudy 3. Rain 4. Snow 5. Sleel/Hail/Fre 6. Fog/Smog/Sr				
## PAPER CASE No. DATE TIME 19	No. OF MONTH	HS:		50	10					To. Oilei		*Use Codes from	MV 104 Police Report	
1 SSPENSE 99,0014 125100PM 2 2 MONTH PROPERTIES DANCE TO DRY CLOUDY DIRECT MONTH PAST SEARCH DISCONNECT SEA HONOLOGISTS AND WAS INMANASE OF CREATING THE CONTINUE OF THE SEARCH SEA HONOLOGISTS AND WAS INMANASE OF CREATING THE CHARGE MINE OF CREATING THE C					No. of VEHICLE!	SEVERITY	CONDITIONS	ROADWAY SURFACE CONDITION	WEATHER		DIRECTION			REFERENCE MARKER
2 336477 88/2914 5-460 PM 2 900 PM 2 90	1	35397522	8/3/2014	12:51:00 PM	2		DAYLIGHT	DRY	CLOUDY	DRIVER INATTENTION	NORTH-EAST	REAR END	DRIVEWAY OF 74 LYNDHURST ST AND WAS UNAWARE OF V2 PULLING OUT OF THE DRIVEWAY. V1 DID REAR END V2.	
\$ 1554956 \$90,001 \$12,000,000 \$2,000,000 \$1,	2	35360127	8/6/2014	5:46:00 PM	2	REPORTABLE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	NORTH	REAR END	AN UNINVOLVED TRUCK CUT INFRONT OF V2 CAUSING HER TO STOP. VI WAS READY FOR THE SUDDEN STOP	4
4 SSS4155 811/2014 100300 AM 2 DAMACE AND DAVLEHT DRY CLEAR DRIVER REPFERENCE SOUTH ROHTH FAILURE STATES TO MORPHITED SHELL DISKS SQUENE CLEAR STATES TO MORPHITE SHELL DISKS SQUENE CLEAR STATES TO MORPHITE SHELL DISKS SQUENE CLEAR STATES TO MORPHITE SHELL DISKS SATES STATES DAVING AND ALL DISKS STATES TO MORPHITE SHELL DISKS SATES SATES DAVING MULLION STATES STATES TO MORPH TO STATES STATES SATES DAVING MULLION STATES STATES TO MORPH THE STATES SATES DAVING MULLION STATES STATES SATES SATES DAVING MULLION STATES SATES S	3	35429856	8/9/2014	12:00:00 AM	2	DAMAGE	UNKNOWN	UNKNOWN	UNKNOWN	UNKNOWN	UNKNOWN	UNKNOWN		
S 35382731 8162014 8.600 PM 2 RAURY DARK ROAD LICHTED WET RAIN FAILURE TO YELD RIGHT OF WAY WAY FOR THE PROPERTY OF WAS ARRESTED BY OWN SEASTED ON ALLENS TENOR AS ED TRAFFE SSIGNAL DOT WEINELS ENTERED THE WEINE FROM THE PROPERTY OF WAS ARRESTED OF WAS ARRESTED ON ALLENS THE PROPERTY OF WAS ARRESTED ON ALL ALLENS THE PROPERTY OF WAS ARRESTED ON ALLENS THE PROPERTY OF	4	35364155	8/11/2014	10:03:00 AM	2	DAMAGE AND	DAYLIGHT	DRY	CLEAR	DRIVER INEXPERIENCE	SOUTH	RIGHT ANGLE		
SOUTH LAVE VY MIS TRAVELING WID DOWN CUMBERANDS SURFIX BERNOW TO AND IN THE SECOND LAME SOUTH OF THE NORTH CURB. THE LEGHT AT THE NTERSECTION WAS GERE HAND BOTH CARS WERE APPROACHING THE MITERSCEND AT JOSEPHI AVE. SUDDENLY, YI MADE A REGITTURIS FROM THE PART LEFT LAME TO GO DIRRITHON JOSEPHI AVE. SUDDENLY, PART A REGITTURIS FROM THE PART LEFT LAME TO GO DIRRITHON JOSEPHI AVE. SUDDENLY, PART LAWE A REGITTURIS FROM REPORTABLE DRY CLEAR ALCOHOL INVOLVEMENT NORTH-WEST ALCOHOL INVOLVEMENT NORTH-WEST CARD REGITTURIN AND SLAMMED ON THE BRATES, WILLE HONINGN IS BOMD HE ASSO TORNED IS WHERE TO THE REGIT AT A BOMD HE ASSO TORNED IS WHERE TO THE REGIT AT A BOMD HE ASSO TORNED IS WHERE TO THE REGIT AT A BOMD HE ASSO TORNED IS WHERE TO THE PART HE AND BOMD HE ASSO TORNED IS WHERE TO THE PART HE AND BOMD HE ASSO TORNED IS WHERE TO THE PART HE AND BOMD HE ASSO TORNED IS WHERE TO THE PART HE AND BOMD HE ASSO TORNED IS WHERE TO THE PART HE AND BOMD HE ASSO TORNED IS WHERE TO THE PART HE AND BOMD HE ASSO TORNED IS WHERE THE PART HE AND BOMD HE ASSO TORNED IS WHERE THE PART HE AND BOMD HE ASSO TORNED IS WHERE THE PART HE AND BOMD HE ASSO TORNED IS WHERE THE PART HE AND BOMD HE ASSO TORNED IS WHERE THE PART HE PART HE AND BOMD HE ASSO TORNED IS WHERE THE PART HE AND BOMD HE ASSO TORNED IS WHERE THE PART HE AND BOMD HE ASSO TORNED IS WHERE THE PART HE AND WAS CURRENTLY STORDED THE BERT HERE TO SIGNAL AT THE INTERSECTION OF ASST MAN STREET HERE AND WAS CURRENTLY STORDED AND THE PART HERE TO THE PART HERE AND WAS	5	35368731	8/16/2014	8:40:00 PM	2	INJURY		WET	RAIN		NORTH	RIGHT ANGLE	APPROACHING ALLEN ST FACING A RED TRAFFIC SIGNAL. VC OPERATED BY DU ANS EASTBOUND ON ALLEN ST FACING A GREEN TRAFFIC SIGNAL. BOTH VEHICLES ENTERED THE INTERSECTION AND VI STRUCK V2. DZ WAS TAKEN TO STRONG FOR BACK AND NECK PAIN BY RURAL METRO AMBULANCE. ALL OTHERS NIVOLVED DD NOT REPORT NUITIES. BOTH VEHICLES WERE CFBD.	
MESTBOUND ON EAST MAN STREET AND WAS CURRENTLY STOPPED AT THE RED TRAFFC SIGNAL AT THE INTERSECTION OF EAST MAN STRUMON STREET. THE TRAFFC SIGNAL CHANGED TO GREEN AND VI PROCEED TO CONTINUE WESTBOUND ON EAST MAN STREET. THE TRAFFC SIGNAL CHANGED TO GREEN AND VI PROCEED TO CONTINUE WESTBOUND ON EAST MAN NOT STREET. AT THE SAME TIME VZ WAS N THE PROCESS OF CROSSING EAST AMAN STREET AT TRAVELING NORTHBOUND AT THE SAME INTERSECTION. VI DD NOT SEE FROM CORPS. THE CROSSWALK UNITE. THE SECOND AND DD NOT HAVE ENOUGH TIME TO STOP STRIKKING VZ MINOR DAMAGE WAS CAUSED TO THE FRONT END OF VI AND VZ SUFFERED A BUMP TO THE HEAD. VZ WAS TRANSPORTED BY RURAL METRO AMBULANCE 73TO STRONG HOSPITAL FOR COMPLANT OF PAIN. NO OTHER NUIRIES WERE REPORTED AT THE SCENE. WITHOUT STATE CORP. THE LEFT OF VI WHEN SHE OBSERVED THE ACCORDINATION OF THE SCENE WITHOUT STATE OF VI WHEN SHE OBSERVED THE ACCORDINATION OF THE STATE OF VI WHEN SHE OBSERVED THE ACCORDINATION OF THE STATE OF VI WHEN SHE OBSERVED THE ACCORDINATION OF THE STATE OF VI WHEN SHE OBSERVED THE ACCORDINATION OF THE STATE OF VI WHEN SHE OBSERVED THE ACCORDINATION OF THE STATE OF VI WHEN SHE OBSERVED THE ACCORDINATION OF THE STATE OF VI WHEN SHE OBSERVED THE ACCORDINATION OF THE STATE OF VI WHEN SHE OBSERVED THE ACCORDINATION OF THE STATE OF VI WHEN SHE OBSERVED THE ACCORDINATION OF THE STATE OF VI WHEN SHE OBSERVED THE ACCORDINATION OF THE STATE OF VI WHEN SHE OBSERVED THE ACCORDINATION OF THE STATE OF VI WHEN SHE OBSERVED THE ACCORDINATION OF THE STATE OF VI WHEN SHE OBSERVED THE ACCORDINATION OF THE STATE OF VI WHEN SHE OBSERVED THE ACCORDINATION OF THE STATE OF VI WHEN SHE OBSERVED THE ACCORDINATION OF THE STATE OF VI WHEN SHE OBSERVED THE ACCORDINATION OF THE STATE OF VI WHEN SHE OBSERVED THE ACCORDINATION OF THE STATE OF VI WHEN SHE OBSERVED THE ACCORDINATION OF THE STATE OF THE STATE OF VI WHEN SHE OBSERVED TO STRONG HOSE OF THE STATE OF VI WHEN S	6	35370076	8/17/2014	1:17:00 AM	2			DRY	CLEAR	ALCOHOL INVOLVEMENT	NORTH-WEST	(WITH OTHER	Y WAS TRAVELING WE ON CUMBERCHAND 3 IN THE PAR SOUTH LAME V.WAS TRAVELING WED DOWN CUMBERAND, SUCHTLY BEHIND VI AND IN THE SECOND LANE SOUTH OF THE NORTH CURBER THE LIGHT AT THE INTERSECTION WAS GREEN AND BOTH CARS WERE APPROACHING THE INTERSECTION AT JOSEPH AVE. SUDDENLY, VI MADE A RIGHT LIGHT FROM THE FAR LEFT LANE TO GO NORTH ON JOSEPH AVE. CROSSING OVER MULTIPLE LANSE OF TRAFFIC. V.S. AWY IN APPROACHING AND SLAMMED ON THE BRAKES, WHILE HONKING HIS HORN, HE ALSO TURNED HIS WHEEL TO THE RIGHT IN AN HORN, HE ALSO TURNED HIS WHEEL TO THE RIGHT IN AN HORN, HE ALSO TURNED HIS WHEEL TO THE RIGHT IN AN HORN, HE ALSO TURNED HIS WHEEL TO THE RIGHT IN AN HORN, HE ALSO TURNED HIS WHEEL TO THE RIGHT IN AN HORN, HE ALSO TURNED HIS WHEEL TO THE RIGHT IN AN HORN, HE ALSO TURNED HIS WHEEL TO THE RIGHT IN AN HORN, HE ALSO TURNED HIS WHEEL TO THE RIGHT IN AN HORN, HE ALSO TURNED HIS WHEEL TO THE RIGHT IN AN HORN, HE ALSO THE RIGHT IN AN HORN HIS WHEEL TO THE RIGHT IN AN HORN HIS WHEEL TO THE RIGHT IN AN HORN HIS WHEEL TO THE RIGHT IN AN HORN HIS WHEEL THE ROWN. THE PARK HE TO THE RIGHT IN AN HORN HIS WHEEL THE ROWN. THE OFFICE DAMAGE TO THE RIGHT FROM THE RIGHT IN AN HORN HIS WHEEL THE ROWN THE OFFI OWN DIVING OF WIGHT HIS WITH THE PARK HIS WHITE THE PARK HIS WHITE THE PARK HIS WHEN HIS WITH HIS WHEN HIS WHEN HIS WHEN HIS WITH HIS WHEN HIS WHEN HIS WHEN HIS WHEN HIS WITH HIS WHEN HIS WHEN HIS WHEN HIS WITH HIS WHEN HIS WITH HIS WHEN HIS WHEN HIS WITH HIS WITH HIS WHEN HIS WHEN HIS WITH HIS WITH HIS WHEN HIS WITH H	
9 26/70/24 9/27/2014 12/00/00 AM 2 NON- HINVAICHAN HINVAICHAN HINVAICHAN HINVAICHAN HINVAICHAN HINVAICHAN HINVAICHAN	7	35380339	8/26/2014	4:46:00 PM	1	NURY	DAYLIGHT	DRY	CLEAR	PEDESTRIAN'S	WEST	OTHER	WESTBOUND ON EAST MAN STREET AND WAS CURRENTLY STOPPED AT THE REP TRAFFE SIGNAL AT THE INTERSECTION OF EAST MANN ST/N. LINDON STREET. THE TRAFFE SIGNAL CHANCED TO GREEN AND IT PROCEED TO CONTINUE WESTBOUND ON EAST MAN STREET. AT THE SAME TIME V2 WAS IN THE PROCESS OF CROSSING EAST MAN STREET AT TRAVELING NORTHBOUND AT THE SAME INTERSECTION. V1 DID NOT SEE V2 OUT IN THE CROSSWALK UNIT. THE LAST SECOND AND DE NOT HE CROSSWALK UNIT. THE LAST SECOND AND DE NOT HE CROSSWALK UNIT. THE LAST SECOND AND DE NOT SEE V2 OUT IN THE CROSSWALK UNIT. THE LAST PRINKING V2 MINOR DAMAGE WAS CAUSED TO THE FRONT END OF V1 AND V2 SUFFERED A BUMP TO THE HEAD. V2 WAS TRANSPORTED BY RUBLAL METRO MUSIC STRANSPORTED BY RUBLAL METRO MUSIC STRANSPORTED BY RUBLAL METRO MUSIC STRANSPORTED OF THE MUSIC STRANSPORTED STREAM SOURCES WERE REPORTED AT THE SCENE. WITHESS STATED THAT SHE WAS IN THE NEXT LAME OVER TO THE LEFT OF V1 MEN SHE SHEST NET THE SCENE.	
	8	35478436	8/27/2014	12:00:00 AM	3	NON- REPORTABLE	UNKNOWN	UNKNOWN	UNKNOWN	UNKNOWN	UNKNOWN	UNKNOWN	DATE OF THE PROPERTY OF THE PR	

TE 213 (9/79)								-					
	MONROE		P.I.N.:	NOT APPLICAL	BLE	ROUTE NO. OF ADJACENT RO.					CASE No.:		
	TOWN CITY					AT INTERSECT					FILE: BY:	PSC 5/13/2020	-
	VILLAGE OF	ROCHESTER			-	SEE MAP					DATE:	5/13/2020	-
TIME PERIOD		FROM: 8/1/14	TO: 7/31/19	ENVIRONMEN Use Codes from at right) for these	n MV 104 (shown e categories	Light Conditions: 1. Daylight 2. Dawn 3. Dusk 4. Dark Road Lig 5. Dark Road Ur	ghted	Roadway Surfact 1. Dry 2. Wet 3. Muddy 4. Snow/Ice 5. Slush 10. Other	ce Condition: Weather: 1. Clear 2. Cloudy 3. Rain 4. Snow 5. Sleet/Hail/Fre 6. Fog/Smog/Sr 10. Other				
No. OF MONTH	IS:	(0	CLES		10				DIDECTION		MV 104 Police Report	DEFEDENCE
CRASH No.	CASE No.	DATE	TIME	No. of VEHICLES	SEVERITY	LIGHT	ROADWAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING FACTORS	DIRECTION	TYPE1	DESCRIPTION	REFERENCE MARKER
9	35391927	8/27/2014	12:15:00 PM	3	PROPERTY DAMAGE AND NUURY	DAYLIGHT	DRY	CLEAR	AGGRESSIVE DRIVINGIROAD RAGE	NORTH	OTHER	IRESPONDED TO THE AFOREMENTIONED MOTOR VEHICLE ACCIDENT. THROUGH INVESTIGATION IT WAS DETERMINED THAT (VEHICLE 1) WHICH WAS A STOLEN VEHICLE DENREM BY (DRINER 1) AND OCCUPED BY PASSENGER 1) WAS DRIWING AT AN UNDETERMINED HIGH RATE OF SPEED IN A RECKLESS MANNER NORTHBOUND ON IN CLINTON ANE. (DRIVER 1) ADMITTED TO NVESTIGATOR FERGUSON THAT HE DD NOT STOP FOR A RED LEHAT AND THAT THE BRAKES OF (VEHICLE 1) DD NOT WORK TO BE ABLE TO AVOID COLLOING WITH OFFICE AND HAT WHE AND THAT WE STROWN ON WESTBOUND ON CUMBERLAND ST, WHICH IS A ONE WAY STREET. VEHICLE 2) WHICH HAS DRIWN WE STBOUND ON CUMBERLAND ST, WHICH IS A ONE WAY STREET OFFICE THROUGH THE NITERSECTION OF IN. CLINTON AVECUMBERLAND ST, (VEHICLE 1) WHIT THE PASSENGER SIDE DOOR COLLIDED WITH (VEHICLE 2) JABOOS SFRONT BUMPER, CAUSING EXTENSIVE DAMAGE TO FROM TSUMPER AND HOOD OF (VEHICLE 2). VEHICLE 1) THEN PROCEEDED STRAIGHT INTO AND SIDE SWEPD WITH (VEHICLE THROUGH THE NITERS SEED OF THE VEHICLE TO THE DRIVERS SIDE REPORT AND READ OF (VEHICLE 2) AND THE REAR WHELE AXEL. (VEHICLE 1) THEN SPUN AND THE REAR WHELE AXEL. (VEHICLE 1) THEN SPUN AND THE REAR WHELE AXEL. (VEHICLE 1) THEN SPUN AND THE REAR WHELE AXEL. (VEHICLE 1) THEN SPUN AND THE REAR WHELE AXEL. (VEHICLE 1) THEN SPUN AND THE REAR WHELE AXEL. (VEHICLE 1) THEN SPUN AND THE REAR WHELE AXEL. (VEHICLE 1) THEN SPUN AND THE REAR WHELE AXEL. (VEHICLE 1) THEN SPUN AND THE REAR WHELE AXEL (VEHICLE 1) THEN SPUN AND THE REAR WHELE AXEL (VEHICLE 1) THEN SPUN AND THE REAR WHELE AXEL (VEHICLE 1) THEN SPUN AND THE REAR WHELE AXEL (VEHICLE 1) THEN SPUN AND THE REAR WHELE AXEL (VEHICLE 1) THEN SPUN AND THE REAR WHELE AXEL (VEHICLE 1) THEN SPUN AND THE REAR WHELE AXEL (VEHICLE 1) THEN SPUN AND THE REAR WHELE AXEL (VEHICLE 1) THEN SPUN AND THE REAR WHELE AXEL (VEHICLE 1) THEN SPUN AND THE REAR WHELE AXEL (VEHICLE 1) THE SPUN AND THE REAR WHELE AXEL (VEHICLE 1) THE SPUN AND THE REAR WHELE AXEL (VEHICLE 1) THE SPUN OF SOME PAN WAS ALSO TRANSPORTED TO STRONG HOSSITIAL BY RURAL METRO 12714 WITH A COMPLANT OF SOME PAN WAS ALSO T	
10	35384166	8/28/2014	10:30:00 PM	2	NON- REPORTABLE	DARK-ROAD LIGHTED	DRY	CLEAR	PASSING OR LANE USAGE IMPROPERLY	NORTH-WEST	RIGHT TURN (WITH OTHER CAR)	OPER VIWEST BOUND IN LEFT LANE, EAST MAIN STREET, CIRCOHESTER, OPER VZ WEST BOUND IN RIGHT LANE, EAST MAIN STREET, CIRCOHESTER, AS THE VEHICLE APPROACHED THE INTERSECTION WITH THE RAMP TO THE INNERLOOP, VI IMPROPERLY TURNED BIGHT EROM THE LEFT LANE AND STRIKES VZ.	
11	35391919	8/31/2014	2:55:00 AM	2	PROPERTY DAMAGE AND INJURY	DARK-ROAD LIGHTED	DRY	CLEAR	ALCOHOL INVOLVEMENT	WEST	HEAD ON	0	
12	35397452	9/9/2014	12:49:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	BACKING UNSAFELY	NORTH-EAST	REAR END	DRIVER OF VEHICLE 1 STATED THAT SHE WAS TRAVELING SOUTHEAST ON N UNION ST. SHE STATED THAT SHE STOPPED WITH THE FRONTEND OF THE VEHICLE IN THE INTERSECTION OF E MAIN ST AFTER THE TRAFFIC SIGNAL TURNED RED. DRIVER OF VEHICLE 1 STATED THAT SHE BACKED UP THE VEHICLE AND MPACTED THE FRONT OF VEHICLE 2. DRIVER OF VEHICLE 2. STATED THAT SHE WAS BEHIND VEHICLE 1. PRIOR TO THE MPACT AND AT A COMPLETE STOP FOR A RED TRAFFIC LIGHT.	
13	35414091	9/10/2014	10:05:00 PM	2	NON- REPORTABLE	DARK-ROAD LIGHTED	WET	CLOUDY	TRAFFIC CONTROL DEVICES DISREGARDED	EAST	RIGHT ANGLE	VEH 2 WAS NIB ON STATE ST WITH A GREEN TRAFFIC SIGNAL. VEH 1 WAS 6/B ON ALLEN ST TOWARDS THE NINER LOOP WITH A RED TRAFFIC SIGNAL. VEH 1 STRUCK VEH 2 IN THE LEFT FRONT AND CONTINUED ON	
14	35412287	9/17/2014	12:45:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLOUDY	TRAFFIC CONTROL DEVICES DISREGARDED	NORTH	RIGHT ANGLE	AND HAD THE GREEN LIGHT TO PROCEED WHEN VZ FALED TO STOP AT RED LIGHT ON CUMBERLAND ST WESTBOUND AND ONCE N THE NITERSECTION WAS STRUCK BY VI IN THE FRONT DRIVERS SIDE OF HER VEHICLE. A WITNESS WAS LICATED WHO WAS A COUPLE CARS BEHIND VI AND CONFIRMED THAT VI HAD GREEN LIGHT TO PROCEED. NO NUMBERS TO EITHER PARTY. DRIVER OF VZ WAS CITED FOR PASSING RED LIGHT. WITNESS 00T MACCONNELL, JACOB J 4	
15	35408478	9/18/2014	3:00:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLOUDY	PASSING OR LANE USAGE IMPROPERLY	EAST	OVERTAKING	WHICH IS A ONE WAY, TWO LANE STREET IN THE EAST BOUND DIRECTION. VEH 1 WAS N THE LEFT MOST LANE WHILE VEH 2 WAS N THE LEFT MOST LANE. WHILE VEH 2 WAS N THE KENTH MOST LANE. VEH 2 WAS GOING STRACHT THROUGH THE METRESCE TON WHILE VEH 1 ATTEMPTED TO MAKE A RIGHT TURN FROM THE LEFT LANE ON TO STATE STREET. VEH 1 TURNED INTO THE PATH OF VEH 2 CAUSING DAMAGE TO BOTH VEHS. ON THE PATH OF VEH 2 CAUSING DAMAGE TO BOTH VEHS.	
16	35418051	9/19/2014	6:58:00 AM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	DRIVER INATTENTION	EAST	OVERTAKING	ON THE ABOVE UNIT A MOUT IME, INES-POUNDED ITO THE WITERSECTION OF ST. PAUL AND CUMBERLAND ST. FOR THE REPORT OF A VEHICLE ACCIDENT. IMET DRIVED OF (VI) AND HE SAD THAT HE WAS DRIVING EAST DRIVED NOTO CUMBERLAND ST. FROM THE INTERLOOP AND WAS TRAVELING IN THE MIDDLE RIGHT LANE OF THE FOUR LANE ROADWAY. HE SAD THAT WHILE IN MOTION THE DRIVER OF (VZ) SDESWIPED HIS VEHICLE AND LEFT A SWALL MARK ON THE RIGHT SDE OF HIS CAR. ITHEN SPOKE TO (VZ) WHO SAD (VI) HAD CUT HER OFF ON CUMBERLAND ST. CAUSING THE SDESWIPE. THERE WAS LONG SCRAPES ON THE LEFT SIDE OF (VZ)SARDOS SCAR. (W) JOE MCCOY (2.21-67) OF ROCHESTER, WITNESSED THE TWO VEHICLES COLLIDE. HE DID IN OT SEE WHAT LAME THE VEHICLES WARE IN PRIOR TO THE MAY.	

TE	213	(9/79)

TE 213 (9/79)													
COUNTY:	MONROE		PIN	NOT APPLICATE	BI F	ROUTE NO. OF					CASE No.:		
	TOWN		•			ADJACENT RO					FILE:		-
	CITY VILLAGE OF	ROCHESTER				AT INTERSECT	TION WITH/OR	BETWEEN:			BY: DATE:		-
	VILLY TOL OT				•	SEE MAP					D/TIC.	0/10/2020	-
TIME PERIOD		FROM: 8/1/14	TO: 7/31/19	ENVIRONMEN Use Codes from at right) for these	MV 104 (shown e categories	Light Conditions: 1. Daylight 2. Dawn 3. Dusk 4. Dark Road Light 5. Dark Road Ur		Roadway Surfa 1. Dry 2. Wet 3. Muddy 4. Snow/Ice 5. Slush 10. Other	ce Condition: Weather: 1. Clear 2. Cloudy 3. Rain 4. Snow 5. SleeVHall/Fre 6. Fog/Smog/Sn 10. Other				
No. OF MONTH	IS:	(60	S					10. 0010		¹ Use Codes from	MV 104 Police Report	
CRASH No.	CASE No.	DATE	TIME	No. of VEHICLES	SEVERITY	CONDITIONS	ROADWAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING FACTORS	DIRECTION	TYPE ¹	DESCRIPTION	REFERENCE MARKER
17	35418052	9/27/2014	11:09:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	DRIVER INATTENTION	NORTH	RIGHT ANGLE	ON THE ABOVE DATE AND TIME I RESPONDED TO THE ABOVE LOCATION FOR THE CALL OF AN IMAN WHEN I ARRIVED ON SCENE I SPOKE WITH BOTH PARTIES WHO BOTH INFORMED ME THAT (VI) HAD BEEN HEADING NORTHESTIN ON NORTH ST. (V2) WAS STOPPED AT THE STOP SIGN HEADING WEST ON CUMBERLAND ST. (V2) THEN PROCEEDED INTO THE INTERSECTION. (VI) THEN MPACTED ON THE REAR LEFT CUJART ERPÄNEL OF (V2). BOTH PARTIES STATED THEY DID NOT HAVE ANY NUILIES AND EXCHANGED IN FORMATION. (V2) DID STATE THAT SHE &QUOLVANS NOT PAYMOR STATE THAT SHE &QUOLVANS NOT PAYMOR ATTENTIONAGOUS WHEN SHE METER DITHE	
18	35422544	9/28/2014	8:42:00 PM	2	PROPERTY DAMAGE	DARK-ROAD LIGHTED	DRY	CLEAR	TRAFFIC CONTROL DEVICES DISREGARDED	EAST	RIGHT ANGLE	VI WAS TRAVELING EAST ON UNIVERSITY AV AND STATES THAT SHE IS NOT SUBE IF SHE HAD THE GREEN LIGHT OR NOT . V2 STATES HE CLEARLY HAD THE GREEN LIGHT AND WAS TRAVELING NORTH ON N UNION ST. VI ENTERED THE INTERSECTION AND STRUCK THE LEFT	
19	35439754	9/30/2014	8:55:00 AM	5	PROPERTY DAMAGE AND INJURY	DAYLIGHT	DRY	CLEAR	BRAKES DEFECTIVE	WEST	OTHER	VEH WAS TRAVELING WIS ON E MAIN ST IN THE INNER MOST LANK. EVEN WAS IN THE CENTER LANK HEADING MIS ONE MAIN ST, VEH2 ATTEMPTED TO GET INTO THE RIGHT LANKE WHEN VEH1 STRUCK HER PASSENGER SIDE BUMPER CAUSING DAMAGE. AS VEH1 ATTEMPTED TO AVIOD VEH2, HE SLAMMED ON THE BRAKES CAUSING HIS BRAKE LINE TO BREAK. VEH1 HENTERED THE CENTER LANE AND REAR ENDED VEH38appo.S REAR BUMPER CAUSING DAMAGE. VEH3 THEN STRUCK VEH4appo.S REAR BUMPER WITH HER FRONT BUMPER CAUSING DAMAGE. WHEN THEN STRUCK VEH5Appo.S REAR BUMPER WITH HER FRONT BUMPER CAUSING DAMAGE. WHEN THEN STRUCK VEH5Appo.S REAR BUMPER WITH HER FRONT BUMPER CAUSING DAMAGE. WHEN STRUCK VEH5Appo.S REAR BUMPER WITH HER FRONT BUMPER CAUSING DAMAGE. WHEN STRUCK VEH5APPO.	
20	35446683	10/1/2014	7:43:00 AM	1	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	DRIVER NATTENTION	NORTH	OTHER	AND CUMBERLAND ST. UPON ARRIVAL ISPOKE TO (M) WHO SAID THAT HE WATCHED (Y)) DRIVE HIS DUMP TRUCK FROM THE SOUTHEAST CORNER OF THE THERE SA LIGHTPOLE ON THE SOUTHEAST SED OF THE MIEERS ECTION HEADING NORTHBOUND ON JOSEPH AVE. HERE SA A LIGHTPOLE ON THE SOUTHWEST SDE OF THE MIEERS CTION, WHICH HAS A WIRE THAT EXTENDENDS DIAGONALLY ACROSS THE WITERSECTION TO THE NORTHBAST SIDE OF THE STREET. ON THIS WIRE IS A TRAFFIC LIGHT. (M) SAD (M) DROVE THROUGH THE MORTHBAST SIDE OF THE STREET. ON THIS WIRE IS A TRAFFIC LIGHT. (M) SAD (M) DROVE THROUGH THE MERSECTION WITH THE BED OF THE DUMP TRUCK EXTENDED UPWARDS. (VI) SAPONS TRUCK CAUGHT THE WERE PULLIND GOWN THE LIGHT POLE AND THE TRAFFIC SIGNAL. (VI) CONTINUED TO DRIVE NORTHBOUND WITHOUT STOPPING. (VI) RETURNED TO THE SCENE OF THE ACCIDENT AFTER POLICE ARRIVAL (VI) STATED THAT CLEAVE ANY WAYS. OFF. MITCHELL ADMINISTERED STANDARD FIELD SORRIETY TESTS TO (VI). RE GARRINGD ON SCENA PING BUT CONTINUED TO LEAVE ANY WAYS. OFF. MITCHELL ADMINISTERED STANDARD FIELD SORRIETY TESTS TO (VI). REG ARRIVED ON SCENA AND REMOVED THE FALEN LICHTPOLE FROM THE WITERSECTION.	
21	35422581	10/4/2014	11:52:00 AM	2	NON- REPORTABLE	DAYLIGHT	WET	CLOUDY	FALURE TO YIELD RIGHT OF WAY	WEST	LEFT TURN (AGAINST OTHER CAR)	WERKENURCH FERRELENSTAILES THAN SINE WISS TRAVELING WEST BOUND ON CUMBER LAND ST WHEN VEHICLE F2 PULL OUT OF APARKING SPOT IN FRONT OF HER VEHICLE CAUSING HER TO STRIKE WENICLE 2 ON THE LEFT FEAR BUMPER AREA, OPERATOR OF VEHICLE STATES THAT SHE WAS PULLING OUT OF A PARKING SOTO WHEN VEHICLE 91 CAMES PEEDIND WEST BOUND ON CUMBERLAND ST STRIKING HER VEHICLE. WITNESS	
22	35426660	10/4/2014	7:44:00 PM	1	PROPERTY DAMAGE	DARK-ROAD LIGHTED	DRY	CLOUDY	PEDESTRIAN'S ERROR/CONFUSION	NORTH	OTHER	7F.7002	
23	35457426	10/7/2014	1:47:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	DRIVER NATTENTION	NORTH	REAR END	DWINER OF VZ STATES SHE WAS TRAVELING NIBOUND ON STATE ST APPROACHING ALLEN TO, ROWER VZ STATES THAT SHE SAWTHE TRAFFIC SIGNAL WAS YELLOW AND BEGAN TO SLOW DOWN PREPARING TO STOP FOR THE RED LICHT DRIVER OF VZ STATES WHEN SHE STOPPED FOR THE RED LICHT SHE WAS STRUCK FROM BEHIND BY VI. DRIVER OF V STATES SHE WAS TRAVELING NIBOUND ON STATE ST BEHIND VZ. DRIVER OF VI STATES SVZ DID ON STATE ST BEHIND VZ. DRIVER OF VI STATES SVZ STOPPED KIND OF COULK IN FRONT OF HER, AND SHE DID THAVE ROUGHT THE TO TRACT CAUSING HER TO STRIKE VZ. NO INJURES REPORTED VI HAS SIGNIFICANT DAMAGE TO THE RONT END. VZ HAS DAMAGE TO THE REAR END. AND THE COLLISION CAUSED VZ EMAILIST SYSTEM TO FALL HANGING ON THE GROUND. BOTH VI AND VX DRES OF PROME FOR THE SCENE	,
24	35429460	10/11/2014	11:05:00 AM	2	PROPERTY	DAYLIGHT	DRY	CLOUDY	PASSING OR LANE USAGE	NORTH-WEST	OVERTAKING	PART AND AND THE SCENE	
				1	DAMAGE			1	IMPROPERLY			ı	

A	TE 213 (9/79)													
1000 1000	COUNTY:			P.I.N.:	NOT APPLICATE	BLE						CASE No.:		
Processor Proc												FILE: BY:	PSC	-
Company Comp			ROCHESTER	!								DATE	5/13/2020	•
CONTINUE	TIME PERIOD				Use Codes from	n MV 104 (shown e categories	1. Daylight 2. Dawn 3. Dusk 4. Dark Road Lig	ghted	1. Dry 2. Wet 3. Muddy 4. Snow/Ice 5. Slush	1. Clear 2. Cloudy 3. Rain 4. Snow 5. Slee¥Hail/Fre 6. Fog/Smog/Sr				
100 100	No. OF MONTH	IS:	(60	ES					TO. OBIG		¹ Use Codes from	MV 104 Police Report	
20 201200 1092014 7480 80 2 8074014 2004 5 8075	CRASH No.	CASE No.	DATE	TIME		SEVERITY	CONDITIONS	ROADWAY SURFACE CONDITION	WEATHER		DIRECTION	TYPE ¹	DESCRIPTION	REFERENCE MARKER
20	25	35434209	10/12/2014	7:48:00 AM	2				CLEAR	DRIVER INATTENTION	SOUTH-WEST	(AGAINST	THECENTER LANE APPRACHMOTHE INTERSECTION OF NO LOTTON AVE VEH VAWS ALSO TRAVELING WIS HIT NENTER TURNING LANE APPROACHING THE INTERSECTION OF N CLINTON AVE. AS VEH2 ATTEMPTED TO MAKE A LEFT TURN ONTO N CLINTON AVE. HAS OFFOM THE CENTER LANE VEH1 STIELD, VEH2 ATTEMPTED TO MAKE A LEFT TURN ONTO N CLINTON AVE ALSO FROM THE CENTER LANE VEH1 STRUCK VEH28, 2005. PASSENGER SIDE PEAR QUARTER PANIEL CAUSING DAMAGE. VEH1 SUSTAINED DAMAGE. THE DRIVER OF VEH1 STATED THAT SHE DID NOT SEE ANY ROAD MAKENINGS BECAUSE THE ROAD WAS FRESHLY PAVED.	
27	26	35439763	10/21/2014	5:48:00 PM	2		DUSK	WET	RAIN	FOLLOWING TOO CLOSELY	SOUTH	REAR END	PAUL ST, VI WAS TRAVELING SVB BEHIND IT. VI STRUCK THE REAR OF V2 WITH ITS FRONT END. DRIVER OF VI STATED THAT SHE DID NOT SEE THE VEHICLE BECAUSE HER WINDSHIELD HAD FOGGED OVER. NO INJURIES	
28 39-5947 1902/0014 12:05:00 PM 2 1 NOSE ROAD 28 39-5947 1902/0014 12:05:00 PM 2 2 REPORTANCE 29 39-5947 1902/0014 12:05:00 PM 2 2 REPORTANCE 20 39-5947 1902/0014	27	35465523	10/24/2014	10:12:00 AM	2		DAYLIGHT	DRY	CLEAR		WEST	RIGHT ANGLE	DEDODTEN	
### PROPRIEST OF THE STORY IN COLUMN TO THE AUTHOR TO SHAPE STORY AND THE AUTHOR THROUGH THROUGH THE AUTHOR THROUGH	28	35457427	10/24/2014	12:05:00 PM	2	NON-	DAYLIGHT	DRY	CLEAR	FAILURE TO YIELD RIGHT OF	SOUTH	OVERTAKING	INNER LOOP, FACING SIR ON UNIVERSITY AVE AT E MAN ST. VI MISON IN LEFT TURN ONLY LAWE. VZ WAS IN A STRAIGHT OR LEFT TURN LANE. VI ATTEMPTED TO CONTINUE TO GO STRAIGHT. SIR ON UNIVERSITY AVE., WHILE V2 ATTEMPTED TO MAKE A LEFT TURN ONTO E MAIN ST. TO HEAD EIR ON E MAIN ST. VI STRUCK V2 IN THE LEFT EREA OF THE VEHICLE, CAUSING DAMAGE TO THE AREA. VI SUSTAINED DAMAGE TO RIGHT FRONT OF THE VEHICLE, WHERE IT MADE CONTACT WITH V2. NO VAURIES WERE REPORTED FROM EITHER DRIVER, BOTH	
30 3548537 1051/2014 8:2000 PM 2 NON- REPORTABLE LAGRED WET RAIN UNSAFE LABLE CHANGE WEST OWER MAN, 14 DRIVER DEFINITION OF WEAR AND STRUCK THE REPORT ASSURABLE SIDE OF HIS VEHICLE OF V.2 STATES AS HE PULLED TO THE ROAD HIS OFFICIAL OF V.2 STATES AS HE PULLED TO THE ROAD HIS OFFICIAL OF V.2 STATES AS HE PULLED TO THE ROAD HIS OFFICIAL OF V.2 STATES AS HE PULLED TO THE ROAD HIS OFFICIAL OF V.2 STATES AS HE PULLED TO THE ROAD HIS OFFICIAL OF V.2 STATES AS HE PULLED TO THE ROAD HIS OFFICIAL OF V.2 STATES AS HE OFFI AND STATES HIS OFFI AS HE PULLED TO THE ROAD HIS OFFI AND STATES HIS OFFI AS HE PULLED TO THE ROAD HIS OFFI AS HE PULL DOWN	29	35452224	10/27/2014	2:58:00 AM	2			DRY	CLOUDY	UNSAFE SPEED	NORTH	REAR END	APPROACHING A RED TRAFFIC SCINAL AT THE INTERSECTION OF N UNION ST AND UNIVERSITY AVE. VI WAS TRAVELING BEHIND V2. THE DRIVER OF VI CLAMED THAT WHEN V2 STOPPED AT THE SIGNAL SHE TRIED TO APPLY HER BRAKES, BUT SHE WAS WEARING HIGH HEL SHOES AND CLAMED THAT BECAUSE OF THEM HER FOOR SUPPED OFF OF THE BRAKE PEDAL, CAUSING THE FOORT OF HER VHICLE TO COLLIDE WITH THE REAR OF	
11/1/2014 651:00 PM 2 NON-REPORTABLE LIGHTED WET RAN EARLY FALURE TO WELD RICHT OWN FALURE FROM THE NORTH OWN FALURE FRO	30	35456537	10/31/2014	8:20:00 PM	2			WET	RAIN	UNSAFE LANE CHANGE	WEST	OVERTAKING	OVER E MAN ST. V-1 DRIFTED NTO HS LAME AND STRUCK THE FROM PASSENGER SIDE OF HIS VEHICLE. OP OF V-2 STATES AS HE PULLED TO THE RIGHT SHOULDER OF THE ROAD THE OPERATOR OF V1 STOPPED HER CAR IN THE LANE AND EATED HE VEHICLE HE FURTHER STATES THE OP OF V-1 WAS NOT ACTING IN A NORMAL STATE OF MIND. BOTH OPERATOR LOCKED AT THERE CARS. AS THE OPERATOR OF V-2 ENTERED HIS VEHICLE TO WRITE DOWN INFORMATION, V-	
PAUL AND CUMBERLAND FOR A REPORT OF AN MYA. JEON ARRING, 15 POPKET TO(2) WHO TOLD ME Agoad; JON ARAPINE, 15 POPKET TO(2) WHO TOLD ME Agoad; JON ARAPINE, 15 POPKET TO(2) WHO TOLD ME Agoad; JON ARAPINE, 15 POPKET TO(2) TOLD ME THAT HE WAS RINGHED, SIKE GOING SOUTHBOUND ON ST PAUL ST WHEN VIO). A "11/2/2014" JEON CHES ME, CON WEST WANT TO PRESS ANY CHARGES. I WAS AN DIDIT AND RAN THE LIGHT. I AM N'THE WAS RINGH, IT AM WHEN VIO). A "11/2/2014" JEON CHES ME, CON WEST WAS TO THAT HE WAS RINGH THIN WHEN HE WAS RINGH WEST WORLD WEST WAS DRINGH WEST WAS DRINGH WEST WITH WHEN VIO). A "11/2/2014" JEON CHES ME, CON WEST WHO WAS DRINGH OF WAS DRINGH WEST WHO WAS DRINGH WHO WAS DRINGH WEST WHO WAS DRINGH WHO WAS DRINGH WHO WAS DRINGH WEST WHO WAS DRINGH	31	35458278	11/1/2014	6:51:00 PM	2			WET	RAIN	FAILURE TO YIELD RIGHT OF	NORTH	RIGHT ANGLE	(VI) WAS TRAVELING NIB ON N. CLINTON. (V2) WAS TRAVELING SID ON N. CLINTON AVE. (V2) ATTEMPTED A LEFT HAND TURN TO GO EIB ON THE INNER LOOP WHILE (V1) WAS GOING STRENHT THROUGH THE INTERSECTION. PER (02) HE WAS ATTEMPTING A EIB TURN ONTO THE INNER LOOP. HE STATED HE HAD A GREEN LIGHT BUT NOT A GREEN ARROW WHILE MAKING THE TURN. DURNG THE TURN (V1) THEN CAME THROUGH THE INTERSECTION STRIKING (V2). PER (01) SHE WAS GOING BOOM ON CLINTON AVE. (01) HAD THE GREEN LIGHT, WHILE GOING THROUGH THE INTERSECTION (V2). ATTEMPTED A LEFT HAND TURN IN FRONT OF (V1). CAUSING (V1) OSTRIKE IT. BOTH PARTEE STATED	
33 35490387 11/5/2014 8.16-00 PM 2 PROPERTY DAMK-ROAD LICHTED DRY CLOUDY FOLLOWING TOO CLOSELY NORTH REAR END AND WAS REAR BEIDED DAWKS ITSTATED THAT SHE DID NOT KNOW THAT VEH 2 WAS GOING TO TURN AND STRUKY THE BECKE FEEL OF COMBERLAND ST. VEH 2 WAS GOING TO TURN AND STRUKY THE BECKE FEEL OF COMBERLAND ST. VEH 2 WAS GOING TO TURN AND STRUKY THE BECKE FEEL OF COMBERLAND ST. VEH 2 WAS GOING TO TURN AND STRUKY THE BECKE FEEL OF COMBERLAND ST. VEH 2 WAS GOING TO TURN AND STRUKY THE BECKE FEEL OF COMBERLAND ST. VEH 2 WAS GOING TO TURN AND STRUKY THE BECKE FEEL OF COMBERLAND ST. VEH 2 WAS GOING TO TURN AND STRUKY THE BECKE FEEL OF COMBERLAND ST. VEH 2 WAS GOING TO TURN AND STRUKY THE BECKE FEEL OF COMBERLAND ST. VEH 2 WAS GOING TO TURN AND STRUKY THE BECKE FEEL OF COMBERLAND ST. VEH 2 WAS GOING TO TURN AND STRUKY THE BECKE FEEL OF COMBERLAND ST. VEH 2 WAS GOING TO TURN AND STRUKY THE BECKE FEEL OF COMBERLAND ST. VEH 2 WAS GOING TO TURN AND STRUKY THE BECKE FEEL OF COMBERLAND ST. VEH 2 WAS GOING TO TURN AND STRUKY THE BECKE FEEL OF COMBERLAND ST. VEH 2 WAS GOING TO TURN AND STRUKY THE BECKE FEEL OF COMBERLAND ST. VEH 2 WAS GOING TO TURN AND STRUKY THE BECKE FEEL OF COMBERLAND ST. VEH 2 WAS GOING TO TURN AND STRUKY THE BECKE FEEL OF COMBERLAND ST. VEH 2 WAS GOING TO TURN AND STRUKY THE BECKE FEEL OF COMBERLAND ST. VEH 2 WAS GOING TO TURN AND STRUKY THE BECKE FEEL OF COMBERLAND ST. VEH 2 WAS GOING TO TURN AND STRUKY THE BECKE FEEL OF COMBERLAND ST. VEH 2 WAS GOING TO TURN AND STRUKY THE BECKE FEEL OF COMBERLAND ST. VEH 2 WAS GOING TO TURN AND STRUKY THE BECKE FEEL OF COMBERLAND ST. VEH 2 WAS GOING TO TURN AND STRUKY THE BECKE FEEL OF COMBERLAND ST. VEH 2 WAS GOING TO TURN AND STRUKY THE BECKE FEEL OF COMBERLAND ST. VEH 2 WAS GOING TO TURN AND STRUKY THE BECKE FEEL OF COMBERLAND ST. VEH 2 WAS GOING TO TURN AND STRUKY THE BECKE FEEL OF COMBERLAND ST. VEH 2 WAS GOING TO TURN AND STRUKY THE BECKE FEEL OF COMBERLAND ST. VEH 2 WAS GOING TO TURN AND ST. VEH 2 WAS GOING TO TURN AND ST. VEH 2 WAS GOING TO TURN AND ST. VEH 2 WAS	32	35479756	11/3/2014	4:16:00 PM	1	INJURY	DUSK	DRY	CLOUDY	FAILURE TO YIELD RIGHT OF	WEST	OTHER	PAUL AND CUMBERLAND FOR A REPORT OF AN MVA. UPPON ARRIVAL I. SPOKET OF (AV) BHO TOLD ME. AGURED ON BARDOS. T WANT TO PRESS ANY CHARGES. I WAS AN DIOT AND RAW THE LIGHT. I. AM IN THE WORNOR. IT BARDOS. TO MAY FAULT AGUNE (CY) TOLD ME THAT HE WAS RIDING HIS BIKE GOING SOUTHBOUND ON ST FAUL ST WHEN (VI). WHO WAS DRIVING WESTBOUND, HIT HIM WHELE HE WAS RIDING HIS BIKE. (VZ) WAS TRANSPORTED TO RICH BY DRIVING AND COMPUNION AND COMPLAINT OF PAND DRIVING HIS BIKE. (VZ) WAS TRANSPORTED TO RICH BY DRIVING HIS BIKE. (VZ) WAS TRANSPORTED TO RICH BY DRIVING HIS BIKE. (VZ) WAS TRANSPORTED TO RICH BY DRIVING HIS BIKE. (VZ) WAS TRANSPORTED TO RICH BY DRIVING HIS BIKE. (VZ) WAS TRANSPORTED TO RICH BY DRIVING WITH THE GREEN LIGHT WHEN (VZ) CAME OUT OF NOWHERE. (W) SAW (VI) STRIKE. (VZ) AND PULLED OVER AND WAITED WITH (VI) AND (VZ) FOR POLICE. OF FECE OLILING TOOK PHOTOGRAPH'S (SEE	
34 35479733 11/6/2014 12:30:00 PM 2 PROPERTY DAMAGE DAYLIGHT WET RAIN FOLLOWING TOO CLOSELY WEST REAR END STOPPED IN TRAFFIC AT THE ST PAUL INTERSECTION. WENT REAR END WE	33	35490387	11/5/2014	8:16:00 PM	2			DRY	CLOUDY	FOLLOWING TOO CLOSELY	NORTH	REAR END	VEH 2 WAS SLOWING TO TURN ON TO CUMBERLAND ST AND WAS REAR ENDED. DRIVER 1 STATED THAT SHE DID NOT KNOW THAT VEH 2 WAS GOING TO TURN AND	
I I INTERES	34	35479733	11/6/2014	12:30:00 PM	2		DAYLIGHT	WET	RAIN	FOLLOWING TOO CLOSELY	WEST	REAR END	STOPPED IN TRAFFIC AT THE ST PAUL INTERSECTION.	

TE 213 (9/79)						1							
COUNTY: I	MONROE		P.I.N.:	NOT APPLICAE	BLE	ROUTE NO. OF					CASE No.:		
	FOWN					ADJACENT RO					FILE		- -
	CITY VILLAGE OF	ROCHESTER				AT INTERSECT	TION WITH/OR	BETWEEN:			DATE:	PSC 5/13/2020	-
	•					SEE MAP							_
TIME PERIOD		FROM: 8/1/14	TO: 7/31/19	ENVIRONMEN Use Codes from at right) for these	MV 104 (shown	Light Conditions: 1. Daylight 2. Dawn 3. Dusk 4. Dark Road Lig 5. Dark Road Ur	ghted	Roadway Surfact 1. Dry 2. Wet 3. Muddy 4. Snow/Ice 5. Slush 10. Other	ce Condition: Weather: 1. Clear 2. Cloudy 3. Rain 4. Snow 5. Sleet/Hail/Fre 6. Fog/Smog/Sr 10. Other				
No. OF MONTH	S:	ć	50	ES							¹ Use Codes from	MV 104 Police Report	
CRASH No.	CASE No.	DATE	TIME	No. of VEHICLES	SEVERITY	CONDITIONS	ROADWAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING FACTORS	DIRECTION	TYPE ¹	DESCRIPTION ONE THE ABOVE DATE AND TIME VEAND V2 WERE	REFERENCE MARKER
35	35468211	11/6/2014	3:10:00 PM	2	NON- REPORTABLE	DAYLIGHT	WET	RAIN	FOLLOWING TOO CLOSELY	EAST	REAR END	ONE THE ABOUTE DATE AND TIME OF YAMID VEWERS. SITTING AT A RED LICHT FACING WIS ON CUMBERLAND SI AT ST PAUL STREET WAITING TO CONTINUE WIS, WHEN VEH 1 DID STRIKE VEH 2. VEH STATED THAT HIS FOOT SUPPED OF THE BRAKE AND THE VEH SLOMLY ROLLED MTOVER 1.7 MOIN LIPIES PEPORTED ON SCENE STROVER 1.7 MOIN LIPIES PEPORTED ON SCENE S	Г
36	35465525	11/10/2014	2:50:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	PASSING OR LANE USAGE MPROPERLY	SOUTH	OVERTAKING	DEMORE VI STATES THAT HE WAS STARTING FROM THE LEFT TURN LANGE AGENT TO MAKE A LEFT TURN TO E.B. CUMBERLAND. DRIVER VI FURTHER STATED THAT HE HEARD HIS MIRKOR GET HIT AND REALIZED THAT VIZ MUST HAME STRUCK HIM. DRIVER VI STATED THAT HE DIDNBappost T SEE THE COLLISION OF THE VI AND VZ. THE MIRROR OF VI WAS PUSHED IN MAINIVERTHAT IT WAS BACK TOWARD THE PASSENGER SDE WINDOW WITH THE MARCH TO THE PROMISE THAT THE ADDIDATION OF THE VI AND ADMAGE TO THE PASSENGER SDE WINDOW WITH THE VISTOR THE VI	
37	35479760	11/13/2014	8:15:00 AM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	DRIVER INATTENTION	SOUTH-WEST	OVERTAKING	VEHICLE TWAS DRIVING SOUTH ON NORTH'S I, IN THE LEFT LANE OF TRAFFIC. VEHICLE 2 WAS DRIVING SOUTH ON NORTH ST, IN THE RISHT LANE OF TRAFFIC. BOTH VEHICLES TURNED RIGHT ONTO CUMBERLAND ST, AND AS THEY MADE THE TURN, VEHICLE 1 SDESWIPED NEWLY 15 2.	
38	35472911	11/15/2014	7:38:00 PM	2	PROPERTY DAMAGE	DARK-ROAD LIGHTED	WET	SNOW	TURNING IMPROPER	EAST	OVERTAKING	THE OPERATOR OF V-2 WAS STOPPED AT A RED LIGHT IN THE LEFT LANE AT THE INTERSECTION OF CUMBERLAND ST AND N CLINTON AVE. THE OPERATOR V-1 STATES SHE WAS APPROACHING THE INTERSECTION IN THE RIGHT LANE AS THE LIGHT WAS CHANGING TO GREEN. OP OF V-	
39	35479767	11/18/2014	7:30:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	SNOWICE	SNOW	PAVEMENT SLIPPERY	WEST	REAR END	IZ WAS STOPPED AT THE RED LIGHT. VI ATTEMPTED TO STOP BUT SLID ON THE ICE DOWN THE SLIGHT GRADE AND STRUCK VZ. NO INJURES. THE SLIGHT GRADE WAS PURE ICE AND SEVERAL VEHICLES WERE SLDING WHILE WE WERE ONSCENE	
40	35481121	11/18/2014	9:03:00 AM	3	PROPERTY DAMAGE AND INJURY	DAYLIGHT	SNOW/ICE	SNOW	VIEW OBSTRUCTED/LIMITED	SOUTH	OTHER		
41	35487745	11/21/2014	4:06:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	TRAFFIC CONTROL DEVICES DISREGARDED	NORTH	RIGHT ANGLE	INTELE 2 WAS WINING AT A RED LISH IT ACKNOWN DISCOMERICAND S. IV WAS TRANKING WIS ON JOSEPH AVE. BOTH VEHICLES ENTERED THE INTERSECTION AND VI STRUCK V2 WITH ITS FRONT LEFT IN THE FRONT END OF V2. DRIVES OF VI STATED THAT HE HAD THE YELLOW LIGHT AND ENTERED THE INTERSECTION. DRIVEN OF V2 STATED THAT SHE WAS WAITING AT A RED LIGHT AND WHEN THE LIGHT TURNED GREEN SHE ENTERED THE INTERSECTION. NO CAMERAS IN THE LORT TURNED GREEN SHE	
42	35627867	12/1/2014	12:00:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLOUDY	UNKNOWN	NORTH	UNKNOWN	BOTH AT AND AS MEKE HEADING NOKTHROOND ON 21	
43	35568508	12/9/2014	4:31:00 PM	2	NON- REPORTABLE	DUSK	DRY	CLEAR	UNSAFE LANE CHANGE	NORTH	OVERTAKING	PAUL BLVD APPROACHING THE LIGHT AT CUMBERLAND ST. BOTH VEHICLES WERE IN A LANE DESIGNATED TO GO STRAIGHT. WHEN BOTH VEHICLES ENTERED THE	
44	35511428	12/14/2014	3:27:00 PM	2	NON- REPORTABLE	DAYLIGHT	WET	RAIN	TRAFFIC CONTROL DEVICES DISREGARDED	SOUTH	RIGHT ANGLE	UNIVERSITY AVE., AND HAD THE GREEN LIGHT. VI WAS	
45	35511424	12/14/2014	7:35:00 PM	1	NJURY	DARK-ROAD LIGHTED	WET	RAIN	FALURE TO YIELD RIGHT OF WAY	SOUTH	OTHER	OF WAS TRAVELING SOUTH ON THE WINER LOOP AND HAVE A GREEN LIST AT THE WITERS ECTION OF E MAIN THAT HE WITERS ECTION OF E MAIN THAT PROCEEDED TO ENTER THE WITERSECTION, STILL TRAVELING SOUTH, WHEN VAIPEDESTRAIN, STEPPED OUT IN FRONT OF HIS VEHICLE. VAWAS ATTEMPTING TO CROSS THE WITERSECTION AND WAS HEADING EAST ON EMAIN ST. VI HAD THE RICHTO WAY. V.Z CROSSED FRONT OF VI ACANST THE TRAFFIC SIGNAL IT IS NOTEWORTHY THAT V.Z APPEARED TO BE HIGHLY WITERSECTION OF WAS VICENOR OF WAS VICEN	
46	35531607	12/17/2014	4:35:00 PM	2	PROPERTY DAMAGE	DARK-ROAD LIGHTED	WET	SNOW	FAILURE TO YIELD RIGHT OF WAY	NORTH	RIGHT ANGLE	17737). DUTH VI AND VZ WERE GIVEN ACCIDEN	

TE 213 (9/79) ROUTE NO. OR STREET NAME MONRO P.I.N.: NOT APPLICABLE CASE No ADJACENT ROADWAY NETWORK TOWN FILE: CITY AT INTERSECTION WITH/OR BETWEEN: BY PSC VILLAGE OF ROCHESTER DATE: 5/13/2020 SEE MAP TIME PERIOD FROM NVIRONMENTAL 1. Dry 2. Wet 3. Muddy 1. Clear 2. Cloudy 3. Rain se Codes from MV 104 (shown right) for these categories 1. Daylight 8/1/14 7/31/19 4. Snow/lo 5. Dark Road Unlighted 5. Slush 5. Sleel/Hail/Freezing Rain 10. Other 6. Fog/Smog/Smoke lo. OF MONTHS 60 Ise Codes from MV 104 Police Report of VEHICLES DIRECTION DESCRIPTION REFERENCE CRASH No CASE No DATE TIME APPARENT CONTRIBUTING FACTORS WESTBOUND ON CUMBERLAND STREET. VEHICLE 1 ALS WESTBOUND ON CUMBERLAND AND DID NOT NOTICE THAT TRAFFIC HAD STOPPED IN FRONT OF HER. VI THAT I RAPPED HAD STOPPED HAT ROWN OF THEK, VI FRONT END STRUCK REAR END OF V2 WHICH CAUSED FRONT OF V2 TO STRIKE THE REAR END OF V3. V3 DRIVE GOT OUT OF VEHICLE AND STATED THAT SHE DID NOT NON 47 35523490 12/19/2014 10:53:00 AM DAYLIGHT DRY CLOUDY DRIVER INATTENTION WEST OTHER IAVE ANY DAMAGE SO LEFT LOCATION BEFORE POLICE ARRIVAL, MINOR DAMAGE TO V2 FRONT AND REAR RUMPER AREA ALONG WITH THE HOOD, MINOR TO NO EMICLE TWAS TRAVELING SOUTH ON STPAUL ST FHICLE 2 WAS TRAVELING NORTH THROUGH THE ITERSECTION OF ST PAUL AND CUMBERLAND PROPERTY EAST VEHICLE 2 HAD A GREEN LIGHT. VEHICLE 1 MADE A EFT TURN FROM ST PAUL, ONTO CUMBERLAND ST 48 35557500 12/31/2014 9:45:00 AM DAYLIGHT DRY CLEAR DRIVER INATTENTION RIGHT ANGLE EASTBOUND) AND STRUCK VEHICLE 2 IN THE OTH VEHICLE WERE TRAVELING WEST ON CUMBERLAND ST. VEH #1 WAS IN THE CENTER LANE AN NON-DARK-ROAL FHICLE #2 WAS IN THE RIGHT LANE. DRIVER 2 STATED 49 35557617 1/5/2015 5-49-00 PM DRY CLOUDY UNSAFE LANE CHANGE WEST OVERTAKING HAT VEH #1 MERGED INTO HER LANE AND STRUCK HER EHICLE. DRIVER 1 STATED THAT HE DID NOT SEE THE PORTABL LIGHTED JEHICLE AND THERE WAS A RUND SPOT ON THE ABOVE DATE AND TIME VEH1 WAS TRAVELLING ON THE ABOVE DATE AND TIME VEHT WAS TAXVELLING TEE ON CUMBERLAND ST. VEH 2 WAS APPROACHING THE TRAFFIC SIGNAL AT ST PAUL ON CUMBERLAND ST, THAT WAS YELLOW AND COMING TO A COMPLETE STOP. VEH WAS APPROACHING THE TRAFFIC SIGNAL IN THE FAR EFT LANE BUT REALIZED IT WAS A TURN ONLY LANE NON DARK-ROAF EFITANE BUT REALIZED IT WAS A TURN ONLY LANE ND SWITCHED TO THE CENTER LANE. AS VEHT WAS WITCHING LANES FROM FAR LEFT TO CENTER SHE HOUGHT THAT VEH 2 WAS GOING TO GO THROUGH THE 50 35549424 1/9/2015 8:54:00 PM DRY CLOUDY FOLLOWING TOO CLOSELY EAST REAR END EPORTARI. LIGHTED ELLOW LIGHT. WHEN VEH 2 STOPPED VEH1 TRIED TO TOP BEST SHE COULD TO AVOID HITTING THE BACK OF EH 2 BLIT DID STRIKE THE CENTER BACK OF VEH2 IURIES REPORTED AT THE SCENE, NO CAMERAS IN I) WAS TRAVELING WEST ON UNIVERSITY AVE BEHIN V2). (V2) WAS STOPPED IN TRAFFIC FACING WEST ON PROPERTY 51 35555646 1/13/2015 5:04:00 PM DUSK WFT CLEAR DRIVER INATTENTION WEST REAR END INIVERSITY AVE IN FRONT OF (V1). (V1) CONTINUED ON INIVERSITY AVE AND STRUCK (V2). THE DRIVER OF (V1) DAMAGE TATES HE WASN&ARDS T PAYING ATTENTION EH 1 AND VEH 2 WERE BOTH TRAVELING SOUTH ON PROPERTY STATE STREET. VEH 2 ATTEMPTED TO STOP WHEN THE FOLLOWING TOO CLOSELY 52 35557648 1/14/2015 4:15:00 PM 2 DAYLIGHT WET CLEAR SOUTH REAR END DAMAGE IGHT TURNED YELLOW AT ALLEN ST AND WAS REAR ENDED BY VEH 1. NO INJURIES NO WITNESS IT IGHT LANE. DRIVER 2 STATED THAT SHE WAS TTEMPTING TO FIND THE UPS STORE IN THE AREA AND AS LOST. SHE SLOWED DOWN TO LOOK AT THE STREE NON DARK-ROAD FOLLOWING TOO CLOSELY 35564159 REAR END 53 1/16/2015 7:23:00 PM WET CLOUDY NORTH SIGNS AND WAS REAR ENDED. DRIVER 1 STATED THAT REPORTABLE LIGHTED FH #2 HAD HER LEFT TURN SIGNAL ON AND HE BELIEVED THE VEHICLE WAS GOING TO TURN LEFT. THE CAR THEN SUDDENLY STOPPED IN FRONT OF HIM AND JE STOLICK IT. AVE EAST TO WEST ON THE NORTH SIDE OF E MAIN ST. PEDESTRIAN STATED AS SHE WAS CROSSING AN INKNOWN VEHICLE/DRIVER STRUCK HER COMING FROM A UNKNOWN VEIRLECTION ON HER LEFT SIDE MAKING HER GO UP ONTO THE HOOD. PEDESTAN STATED WHEN IT HAPPENED SHE HEARD YELLING TOWARD HER AS IF IT WAS HER FAULT. PEDESTRIAN STATED (VI) DROVE AILURE TO YIELD RIGHT OF 54 INJURY NORTH OTHER AWAY AND 911 WAS CALLED. PEDESTRIAN STATED SHE 35572012 1/20/2015 2:15:00 PM DAYLIGHT DRY CLEAR DID NOT GET A GOOD ENOUGH LOOK AT THE VEHICLE TO GET A LICENSE PLATE. PEDESTRIAN TRANSPORTED TO STRONG FOR COMPLAINT OF PAIN. PEDESTRIAN STATEI SHE WAS STRUCK ON THE LEFT SIDE OF HER BODY BUT IAD SOME PAIN ON THE RIGHT SIDE OF HER BODY. RO CONTACTED CITY CAMERA ROOM AND THERE IS NO OOTAGE OF THE INCIDENT. NO WITNESSES IN AREA OSED RUSINESS ON BOTH SIDES OF STREET VE EAST TO WEST ON THE NORTH SIDE OF E MAIN ST PEDESTRIAN STATED AS SHE WAS CROSSING AN NKNOWN VEHICLE/DRIVER STRUCK HER COMING FROM UNKNOWN DIRECTION ON HER LEFT SIDE MAKING HER SO UP ONTO THE HOOD. PEDESTIAN STATED WHEN IT IAPPENED SHE HEARD YELLING TOWARD HER AS IF IT WAS HER FAULT. PEDESTRIAN STATED (VI) DROVE AILURE TO YIELD RIGHT OF 55 INJURY 35575121 2:15:00 PM DAYLIGHT CLEAR NORTH OTHER AWAY AND 911 WAS CALLED. PEDESTRIAN STATED SHE 1/20/2015 DRY DID NOT GET A GOOD ENOUGH LOOK AT THE VEHICLE TO GET A LICENSE PLATE. PEDESTRIAN TRANSPORTED TO TRONG FOR COMPLAINT OF PAIN. PEDESTRIAN STATE
HE WAS STRUCK ON THE LEFT SIDE OF HER BODY BUT AD SOME PAIN ON THE RIGHT SIDE OF HER BODY. RO ONTACTED CITY CAMERA ROOM AND THERE IS NO OOTAGE OF THE INCIDENT. NO WITNESSES IN AREA CENTER LANE. THE TRAFFIC LIGHT AT ST PAUL ST WAS ENTER LAWE. THE TRAFFIC LIGHT AT ST PAUL ST WAS ED AND THERE WAS A LONG LINE OF CARS WAITING OR THE LIGHT. DRIVER 2 STATED THAT SHE WAS TOPPED AND THEN STARTED TO INCH FORWARD WITH 3:48:00 PN 56 35582070 DAYLIGHT CLEAR WEST REAR END 1/23/2015 DRY RAFFIC AND WAS REAR ENDED. DRIVER 1 STATED THAT

UNKNOWN

NORTH-EAST

CLEAR

DDODEDT

DAMAGE

57

35623127

1/25/2015

1:45:00 PM

HE SAW VEH #2 START TO GO SO HE HIT THE GAS. HE
STATED HE DIDN'T EVEN SEE VEH #2'S BRAKE

TE 213 (9/79)													
COUNTY:	MONROE		PIN	: NOT APPLICA	BLE		R STREET NAM				CASE No.:		
	TOWN						ADWAY NETW				FILE:		-
	CITY VILLAGE OF	ROCHESTER			_	SEE MAP	TION WITH/OR	BETWEEN:			BY: DATE:	130	- -
TIME PERIOD		FROM: 8/1/14	TO: 7/31/19	ENVIRONMEN Use Codes from at right) for these	n MV 104 (shown e categories	Light Conditions. 1. Daylight 2. Dawn 3. Dusk 4. Dark Road Li 5. Dark Road U	ghted	Roadway Surfa 1. Dry 2. Wet 3. Muddy 4. Snow/Ice 5. Slush 10. Other	1. Clear 2. Cloudy 3. Rain 4. Snow 5. SleeVHail/Fre 6. Fog/Smog/Sr				
No. OF MONTH	HS:	- 6	0						10. Other		*Use Codes from	MV 104 Police Report	
CRASH No.	CASE No.	DATE	TIME	No. of VEHICLES	SEVERITY	CONDITIONS	ROADWAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING FACTORS	DIRECTION	TYPE ¹	DESCRIPTION	REFERENCE MARKER
58	35577791	1/27/2015	1:05:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	SNOW/ICE	CLEAR	DRIVER INATTENTION	WEST	RIGHT ANGLE	WEHICLE TWAS TRAVELING WESTBOUND ON CUMBERLAND STAND AFTER STOPPING AT THE STOP SIGN PROCEEDED WESTBOUND STRIKING VEHICLE 2. DRIVER OF VEHICLE 1 STATED THAT SHE LOOKED NORTH THEN SOUTH, FHOUGHT IT WAS CLEAR AND DROVE FOWARD AND DID NOT SEE VEHICLE 2 UNTIL. SHE	
59	35594924	2/2/2015	8:45:00 AM	2	NON- REPORTABLE	DAYLIGHT	SNOW/ICE	SNOW	PAVEMENT SLIPPERY	NORTH	RIGHT ANGLE	SYPHICKE'S NO UN JUSEPH AVE APPROACHING A REU LICHT AT THE NTERSECTION OF CUMBERLAND ST VEH 2004 SE BON CUMBERLAND ST AND WAS ED PROACHING A GREEN LIGHT AT THE JUSEPH AVE INTERSECTION. WENT FALED TO STOP AT THE RED LIGHT DUE TO SHOW AND ICE COVERED ROADWAY AND STRUCK VEHZ AS SELECTION OF THE REPORT OF THE REPORT OF THE RESECTION.	
60	35595470	2/2/2015	4:58:00 PM	2	NON- REPORTABLE	DUSK	SNOW/ICE	SNOW	PAVEMENT SLIPPERY	NORTH	REAR END	BOTH VEHICLES WERE NORTH ON N CLINTON AVE. DRIVER 1 STATED THAT SHE TRIED TO HIT THE BRAKES AND SLID IN THE SNOW, DRIVER 2 WAS WAITING FOR THE LIGHT AND GOT READ ENDED. WIS STOPPED AT TRAFFIC CONTROL DEVICE IN TURN	
61	35584314	2/3/2015	12:00:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	WET	CLOUDY	PASSING OR LANE USAGE IMPROPERLY	WEST	REAR END	LEFT ONLY LANE AND VZ IS IN MIDDLE LANE FACING WESTBOUND ON CUMBERLAND AT THE INTERSECTION OF SAINT PAUL BLYD. VZ PROCEEDS TO TRAVEL WESTBOUND AND SUBSEQUENTLY SIDE SWIPES V1. NO NUMBER OF THE PROPERTY OF T	
62	35594927	2/5/2015	11:38:00 AM	1	PROPERTY DAMAGE	DAYLIGHT	SNOW/ICE	SNOW	TRAFFIC CONTROL DEVICES DISREGARDED	NORTH	OTHER	WHILE IS A TRACTORTIFALER. TRALER HAS A STATE OF MAN FEGISTATION LEGNS PHATE 2550033. WIN 1JASZDX-1872564. VEHICLE I WAS TRAVELING NORTH ON ST PAUL ST. VEHICLE I WAS TRAVELING NORTH ON ST PAUL ST. VEHICLE I ATTEMPTED TO DRIVE UNDER THE CSX RALROAD BRDGE JUST NORTH OF THE CUMBERLAND ST NITESSECTION, AND THE ROOF OF VEHICLE I STRUCK THE BRDGE. CSX RALROAD PERSONNEL NOTIFED AND RESPONDED - TOOK PHOTOS PERSONNEL NOTIFED AND RESPONDED - TOOK PHOTOS ON HAD REPORT. THERE IS A STANDARDIZED TRAFFIC CONTROL DEVICE: VELLOW HEEGHT RESTRICTION SIGN APPROMMATELY SOFETS SUTHOF THE BRDGE CA POSTED FOR NORTHBOUND TRAFFIC. THIS SIGN POSTS THE HEEGHT RESTRICTION FOR THE BRDGE CA 118 appossäquot. IT IS CLEAR AND UNOBSTRUCTED. NSURANCE FOR THE TRACTOR IS WITH GREAT WEST FERSIAL TIME GOVERNEY MOURES.	
63	35621981	2/5/2015	11:36:00 PM	2	NON- REPORTABLE	DARK-ROAD LIGHTED	SNOWICE	SNOW	UNKNOWN	NORTH	RIGHT ANGLE	WAS TRAVELING EASTBOUND ON ALLEN ST. THERE WAS A TRAFFIC LIGHT AT THE INTERSECTION INDICATING WHICH CAR HAD THE RIGHT OF WAY, BOTH CARS ENTERSED THE MITERSECTION STRIKING EACH OTHER. AFTER SPEAKING WITH BOTH MOTORSTS, BOTH STATED THAT THEY HAD THE GREEN LIGHT AND PROCEEDED MITO THE WITERSECTION, BOTH MOTORST STATED THAT THEY WERE STRUCK BY THE OTHER MOTORIST SAFED THAT THEY WERE STRUCK BY THE OTHER MOTORIST SAFED THAT THEY WERE STRUCK BY THE OTHER MOTORIST SAFED THAT THEY WERE STRUCK BY THE OTHER MOTORIST OF VI. IDDIO DESERVE DAMAGE ON BOTH OF THE VEHICLES, TOMOVERE, THE ODMAGE DO NOT NOICATE WHICH VEHICLE WAS THE STRIKING VEHICLE WOE OF DOTAGE OF THE RED LIGHT CAMERAS AT THE NET WHICH VEHICLE WAS THE STRIKING VEHICLE VEHICLE WAS THE	
64	35623935	2/13/2015	9:05:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	SNOW/ICE	CLOUDY	UNSAFE SPEED	WEST	REAR END	OFER THE WINER EOOF ON THE BEHIND V2 WHO WAS STOPPEN IN THAFFE. VI SLOON SNOW COVERED ROADWAY INTO REAR END OF V2 CAUSING EXTENSIVE DAMAGE TO BOTH VEHICLES. NO INJURIES REPORTED LAND V2 WAS DOMEN LEPTIM SCENE.	
65	35613326	2/15/2015	5:57:00 PM	2	NON- REPORTABLE	DARK-ROAD LIGHTED	SNOW/ICE	SNOW	PAVEMENT SLIPPERY	WEST	REAR END	THE RED LIGHT AT THE ALLEN ST, AND STATE ST MITERSECTION, WIZ REAR ENDED HIS VEHICLE. OPERATOR AT STATES THAT AS SHE WAS APPROACHING THE RED LIGHT, SHE ATTEMPTED TO STOP, BUT COULD NOT STOP DUE THE ROAD BEING ICY, AND STRUCK THE REAR OF WIZ. OPERATOR AZ COMPLIANTED OF NECK PAIN, AND WAS ACTUALLY BACK BOARDED WITH HIS NECK SECURED, BUT REFUSED TO BE TRANSPORTED TO THE HOSPITAL, AND SIGNED OFF, AND WAS	;
66	35670632	2/18/2015	7:54:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	WET	CLEAR	FOLLOWING TOO CLOSELY	SOUTH	REAR END	VEHTAND VEHT 2 SOUTHBOUND ON STATE STATALLEN ST, BOTH IN CENTER LANE. VEH 2 STOPPED AT A RED LIGHT, VEH 1 DIRECTLY BEHIND VEH 2. VEH 1 REAR- ENDED VEH 2 CAUSING MOCERATE DAMAGE TO VEH 1 AND MINOR DAMAGET TO VEH 1 WENT WAS TRANSCHING MORTH ON STATE STATALLEN	
67	35613340	2/18/2015	3:10:00 PM	2	NON- REPORTABLE	DAYLIGHT	SNOW/ICE	SNOW	FAILURE TO YIELD RIGHT OF WAY	NORTH	RIGHT ANGLE	VEH 1 WAS TRAVELING NORTH ON STATE STATE ALLEN ST. VEH 2 WAS TRAVELING EAST ON ALLEN STAT STATE. THE 2 VEH&appos S STRUCK EACH OTHER AND CAUSED DAMAGE TO BOTH VEHS. BOTH SAID THEY HAD THE GREEN LIGHT. NO WITHESS NO INJUIES. BOTH ARE SAYING THEY HAD A GREEN MICHT.	
68	35622431	2/19/2015	7:30:00 PM	2	PROPERTY DAMAGE	DARK-ROAD LIGHTED	SNOW/ICE	SNOW	PAVEMENT SLIPPERY	EAST	REAR END	AND A MOVE DATE MAD YEAR AND THE TAX STORDED TO THE ABOVE LOCATION FOR THE MAY ATT AND RUN. ISPOKE TO (D.2) WHO STATED SHE WAS STOPPED IN TRAFFIC WHILE TRAVELING EAST ON E. MAINS TA THE INNER LOCOP. (D.2) STATES AN JUNKNOWN COLOR, MAKE OR MODEL VAN REAR ENDED HER VEHICLE. THEN DROVE ANWAY EAST ON E. MAND THE AREA. NO PLATE IN FORMATION CATHERED. (D.2) WAS ABLE PULL HER VEHICLE INTO THE FAST TRAC PARKING LOT IN CASE PLATE VALUE OF THE MAD THE	

ΤE	213	(9/79)

MANAGEMENT MAN	TE 213 (9/79)								_					
Part	COUNTY:	MONROE		P.I.N.:	NOT APPLICAE	BLE						CASE No.:		
Property												FILE		_
Property			DOGUECTED				AT INTERSECT	TION WITH/OR	BETWEEN:			BY	PSC	_
1		VILLAGE OF	ROUNESTER			-	SEE MAP					DATE	3/13/2020	-
1	TIME PERIOD				Use Codes from	MV 104 (shown	1. Daylight 2. Dawn 3. Dusk 4. Dark Road Lig	ghted	1. Dry 2. Wet 3. Muddy 4. Snow/Ice 5. Slush	1. Clear 2. Cloudy 3. Rain 4. Snow 5. Sleel/Hail/Fre				
Column C							1		TO. ORIGI		1	1		
1906 1907 1908						VERITY	SHT	ADWAY RFACE INDITION	SATHER		DIRECTION			REFERENCE MARKER
10 20,000 20,000 115,000 AM 2 20,000 115,000 AM 2 20,000 20,000 AM 2 2	69	35617717	2/19/2015	11:35:00 PM		NON-	DARK-ROAD				EAST	REAR END	MAIN STREET AT THE INTERSECTION OF UNIVERESTLY AVENUE. TRAVELING EAST VI MOS TRAVELING EAST ON CAST MAIN STREET BEHIND V2, DUE TO BEING TOO CLOSE TO V2 AND ON TOY PAMEMENT, VI MAS UNABLE TC STOP IN TIME. THE FROM I CENTER OF VI STRUCK THE REAR CENTER OF V2, CAUSING MINOR DAMAGE TO BOTH CHECKS. THE VAULUE OF WHICH MAS UNKNOWN AT THE	ł
200 200	70	35628582	3/1/2015	11:52:00 AM	2	DAMAGE AND	DAYLIGHT	WET	SNOW		NORTH-EAST	HEAD ON	TURNING LANE. OPV2 TRAVELING SB ON SCIO ST APPROACHING THE INTERSECTION OF DELEVAN ST. OPV1 FAILS TO YIELD TO V2'S RIGHT A WAY AND MAKES A	
2	71	35637125	3/3/2015	4:08:00 PM	2		DAYLIGHT	SNOWICE	SNOW	FOLLOWING TOO CLOSELY	NORTH	REAR END	NORTH ON STATE ST AT ALLEN ST. VI OPERATED BY D1 ATTEMPTED TO STOP AT THE INTERSECTION WHILE TRAVELING NORTH HOWEVER DUE TO SLPPERY ROAD CONDITIONS FROM SNOW AND FOLLOWING TOO CLOSELY	,
15 15 15 15 15 15 15 15	72	35640257	3/4/2015	8:48:00 AM	2		DAYLIGHT	SNOW/ICE	CLEAR	UNKNOWN	WEST	OVERTAKING	PARKED ALONG THE CURB ON LYNDHURST ST FACING WB. VEH1 ATTEMPTED TO PASS VEH2 AT WHICH POINT HE STRUCK VEH2&apos. S DRIVER SIDE REAR BUMPER AND REAR VIEW MIRROR CAUSING DAMAGE. VEH1 LEFT	
74 3563809 3402015 9000 AM 2 REPORTABLE DAYLGHT SNOWICE CLOUDY UNKNOWN WEST OVERTAKING (MORHEST ST, FACING WEST, VEHT TAWKEING WEST) REPORTABLE DAYLGHT SNOWICE CLOUDY UNKNOWN WEST OVERTAKING (MORHEST ST, FACING WEST, VEHT TAWKEING WEST) REPORTABLE DAYLGHT WEST OVER DRIVEN STREET STOPPED AT THE RED LIGHT AT NORTH CLITICAL PROJECT OF THE RED LIGHT AT NORTH CLITICAL PROJECT STREET SA ONE WAY WEST BOUND, DENER 2 STATED THAT WEST OVER DRIVEN STREET STOPPED AT THE RED LIGHT AT NORTH CLITICAL PROJECT STREET SA ONE WAY WEST BOUND, DENER 2 STATED THAT WEST STREET SA ONE WAY WEST BOUND, DENER 2 STATED THAT WEST STREET SA ONE WAY WEST BOUND, DENER 2 STATED THAT WEST STATED STREET SA ONE WAY WEST BOUND, DENER 2 STATED THAT WEST STATED STREET SA ONE WAY WEST BOUND, DENER 2 STATED THAT WEST STATED STREET SA ONE WAY WEST BOUND, DENER 2 STATED THAT WE WAS STREET SA ONE WAY WEST BOUND, DENER 2 STATED THAT WE WAY STREET SA ONE WAY WEST BOUND, DENER 2 STATED THAT WE WAS STREET SA ONE WAY WEST BOUND, DENER 2 STATED THAT WE WAS STREET SA ONE WAY WEST BOUND, DENER 2 STATED THAT WE WAY STREET SA ONE WAY WEST BOUND, DENER 2 STATED THAT WE WAY STREET SA ONE WAY WEST BOUND, DENER 2 STATED THAT WE WAY STREET SA ONE WAY WEST BOUND, DENER 2 STATED THAT WE WAY STREET SA ONE WAY WEST BOUND, DENER 2 STATED THAT WE WAY STREET SA ONE WAY WEST BOUND, DENER 2 STATED THAT WE WAY STREET SA ONE WAY WEST BOUND, DENER 2 STATED THAT WE WAY STREET SA ONE WAY WEST BOUND, DENER 2 STATED THAT WE WAY STREET SA ONE WAY WE STREET SA ONE WAY W	73	35637016	3/4/2015	5:34:00 PM	2		DUSK	WET	CLOUDY		EAST	OVERTAKING	NB 5T, PAUL ST FROM THE MSDE LEFT TURN ONLY LAME. V2 WAS TURNING LEFT FROM E/B CUMBERLAND ST TO NB 5T. PAUL ST FROM THE CENTER LAME WHICH ALLOWS VEHICLES TO TURN LEFT OR TO CONTINUE STRAIGHT. PAWEMENT MARKINGS DO NOT CLEARLY DELWEATE LANES THROUGH THE INTERSECTION. AS V. AND V2 MADE THE LEFT TURN A COLLISION OCCURED COULD NOT BE DETERMINED WHICH VEHICLE MOVED NTO THE RIGHT OF WAY OF THE OTHER. NO NUJURES REPORTED OR OBSERVED. METHER IN OR DRIVER OF V. OSSERVED ANY DAMAGE TO V2. VI HAD MINOR DAMAGE TO THE FRONT PASSESNERS BY	1
TO SECURIS A COURSE DA COMPRESAND STAND NORTH CLICATION AREAN LESS WEST BOUND ON COMPRESAND STATE THAT SHE WAS REST BOUND ON COMPRESAND STATE THAT SHE WAS RED AND WHEN THE LIGHT WAS RED AND WHEN THE WAS RED AND WHEN THE WAS IN THE CENTER AND COMPRESANDED STATES THAT WHENCE IT AND THE REPORT THAT WHENCE IT AND THE WAS IN THE CENTER AND COMPRESANDED WHEN THE WAS IN THE CENTE	74	35638039	3/6/2015	9:00:00 AM	2		DAYLIGHT	SNOW/ICE	CLOUDY	UNKNOWN	WEST	OVERTAKING	LYNDHURST ST, FACING WEST. VEH1, TRAVELING WEST ON LYNDHURST ST., STRUCK VEH 2 AND FLED THE	
76 35647472 377/2015 9.25.00 AM 2 NON- REPORTABLE DAYLIGHT WET CLOUDY FOLLOWING TOO CLOSELY WEST REAR END GOBY. WEH YAWS TURNING RIGHT FROM E. MAIN ST. ONTO THE NICER COOP AND STORPED TO ALLOW CROSS TRAFFIC TO GOBY. WENT WAS BERIND YEEL, 24 AND STRUCK VIEW TRAFFIC TO ALLOW CROSS TRAFFIC TO GOBY. WENT WAS BERIND YEEL, 24 AND STRUCK VIEW TRAFFIC TO ALLOW CROSS TRAFFIC TO GOBY. WENT WAS BERIND YEEL, 24 AND STRUCK VIEW TRAFFIC TO ALLOW CROSS TRAFFIC TO GOBY. WENT WAS BERIND YEEL, 24 AND STRUCK VIEW TRAFFIC TO ALLOW CROSS TRAFFIC THAT SHE TO ALLOW CROSS TRAFFIC T	75	35637014	3/6/2015	12:42:00 PM	2		DAYLIGHT	WET	CLEAR		WEST	(AGAINST	THAT OCCURRED AT CUMBERLAND ST AND NORTH CLINTON AVENUE JUPON ARRAMS, LSPOKE TO DRIVER 2 WHO STATED THAT SHE WAS WEST BOUND ON CUMBERLAND STREET STOPPED AT THE RED LIGHT AT NORTH CLINTON AND CUMBERLAND. CUMBERLAND STREET IS A ONE WAY WEST BOUND. DRIVER 2 STATED HATT THE LIGHT WAS RED AND WHEN THE LIGHT TURNED GREEN, SHE STATED TO TRAVEL WESTBOUND WHEN VEHICLE TURNED LETF (SOUTHBOUND) NTO HER VEHICLE. VEHICLE I MPACTED VEHICLE 2 IN THE ROOT PASSENGER SDE QUIASTREPANELITIES AREA. DRIVER OF VEHICLE 1 STATED THAT HE WAS IN THE CENTER LANG ON CUMBERLAND STREET. HE STATES THAT THE LIGHT WAS GREEN AND HE WAS TRYING TO GET IN THE LEFT LANE TO TURNELEFT ONTO NORTH CLINTON AVENUE. DRIVER 1 STATES THAT VEHICLE 2 CAME UP OULCKLY ON HIS DRIVERS SIDE AND WHEN HE WENT TO TURNE LEFT SHE STRICLE 2 CAME UP OULCKLY ON HIS DRIVERS SIDE AND WHEN HE WENT TO TURNE LEFT SHE STENCE ARE.	
77 35649828 3/9/2015 4:00:00 PM 2 NON- REPORTABLE DAYLIGHT UNKNOWN UNK	76	35647472	3/7/2015	9:25:00 AM	2		DAYLIGHT	WET	CLOUDY	FOLLOWING TOO CLOSELY	WEST	REAR END	VEH2 WAS TURNING RIGHT FROM E. MAIN ST. ONTO THE INNER LOOP AND STOPPED TO ALLOW CROSS TRAFFIC TO GO BY. VEH 1 WAS BEHIND VEH. 2 AND STRUCK VEH. 2	
78 35644628 3/10/2015 3:15:00 PM 2 PROPERTY DAMAGE DAYLIGHT WET CLOUDY TRAFFIC CONTROL DEVICES DISREGARDED NORTH RESETTION HAD SHE CROSSED THE NORTH AND WAS RIGHT AND WAS	77	35649828	3/9/2015	4:00:00 PM	2		DAYLIGHT	UNKNOWN	UNKNOWN	UNKNOWN	UNKNOWN	OTHER	SONIC ON THE TRACKS. SOMEHOW, VI TRAVELED BACKWARDS AND STRUCK VZ CAUSING MINOR DAMAGE. THE DAMAGE WAS TO THE GRILL OF VZ. VI LEFT AND DZ REPORTED THIS TO DELTA SONIC WHO WILL BE PROCESSING DZ'S CLAIM. DELTA SONIC ADVISED	
70 35A40003 3/12/2015 7-45-00 AM 2 PROPERTY DAYLICHT DDY CLEAD LINKNOWN SOLITH OVERTAKING	78	35644628	3/10/2015	3:15:00 PM	2		DAYLIGHT	WET	CLOUDY		NORTH	RIGHT ANGLE	LEFT MOST LANE. WEH #2 WAS TRAVELING EAST ON CUMBERLAND S IN THE CENTER LANE. DRIVER 2 STATED THAT SHE HAD A GREEN LICHT AND WAS STRUCK BY VEH #1 AS SHE CROSSED THE NTERSECTION. HER CART HER STRUCK THE CORNER OF THE GUARD RAL. DRIVER 1 STATED THAT SHE DID NOT KNOW WHAT COLOR LICHT SHE HAD. SHE HIT VEH #2	2
	79	35649003	3/13/2015	7:45:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	UNKNOWN	SOUTH	OVERTAKING	AND HED CAD THEN MENT BLTO A POLE	†

TE 213 (9/79)											ı		
COUNTY:	MONROE		P.I.N.:	NOT APPLICATE	BLE	ROUTE NO. OF ADJACENT RO					CASE No.:		_
	TOWN CITY					AT INTERSECT					FILE: BY:	PSC 5/13/2020	-
	VILLAGE OF	ROCHESTER			-	SEE MAP					DATE:	5/13/2020	-
TIME PERIOD		FROM: 8/1/14	TO: 7/31/19	ENVIRONMEN Use Codes from at right) for these	MV 104 (shown e categories	Light Conditions: 1. Daylight 2. Dawn 3. Dusk 4. Dark Road Lig 5. Dark Road Ur	ghted	Roadway Surface 1. Dry 2. Wet 3. Muddy 4. Snow/Ice 5. Slush 10. Other	ce Condition: Weather: 1. Clear 2. Cloudy 3. Rain 4. Snow 5. Sleet/Hail/Fre 6. Fog/Smog/Sr 10. Other				
No. OF MONTH	HS:	(50	ES					IU. Olici			MV 104 Police Report	
CRASH No.	CASE No.	DATE	TIME	No. of VEHICLES	SEVERITY	CONDITIONS	ROADWAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING FACTORS	DIRECTION	TYPE ¹	DESCRIPTION VI WAS TRAVELING SOUTH ON NURTH CLINTON AVENUE,	REFERENCE MARKER
90	35647437	3/15/2015	12:40:00 AM	1	PROPERTY DAMAGE	DARK-ROAD LIGHTED	DRY	CLEAR	OBSTRUCTIONIDEBRIS	SOUTH	OTHER	AND AS IT APPRACHED THE INTERSECTION OF CUMBERLAND STREET, THE DEWER NOTICED THAT THERE WAS A LARGE PILE OF SNOWTHAT WAS OBSTRUCTING THE MAJORITY OF HIS LANE OF TRAFFIC. DUE TO VEHICLES TRAVELINE NORTH IN THE MONOMING LANE, THE DRIVER OF VI WAS FORCED TO DRIVE ONTO THE SODEWARG. ON THE SOUTHWAS TO CONTRO OF THE HE DRIVER OF VI WAS FORCED TO DRIVE ONTO THE SODEWARG. AS ABLE TO BRING VI TO A COMPLETE STOP, HOWEVER, THE FRONT RIGHT OF VI STRUCK A CITY OF ROCHESTER OWNED FIRE HYDRANT ON THE SDEWALK, SHEARING IT OF FAT THE BASE AND DAMAGING VI, TOTAIN OTHE CASE OF THE CONTROL OF THE SOUTH OF THE SHORT OF THE STRUCK AND THE CHARGE OF THE STRUCK AND THE SOUTH OF THE STRUCK AND THE CHARGE OF THE STRUCK AND THE STRUCK AND THE CHARGE OF THE SCRIP OF THE STRUCK AND	
81	35658657	3/20/2015	9:12:00 AM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	WEST	REAR END	OPANISTPWINE CHARPEING MICROMEREAND ST, VZ WAS IN FRONT OF YI. UPON APPROACH OF ST PAUL ST THE LIGHT TURNED RED. VZ BEGAN TO SLOW DOOM, YI WAS FOLLOWING TOO CLOSELY AND STRUCK VZ. NO NJURIES. MINOR DAMAGE TO BOTH VEHICLES. NO TOW NAMEDED.	
82	35665633	3/25/2015	4:21:00 PM	2	INJURY	DAYLIGHT	WET	RAIN	TRAFFIC CONTROL DEVICES DISREGARDED	SOUTH	RIGHT ANGLE	(IV) WAS TRAVELING SOUTHBOUND ON STATE ST. AT ALLEN ST. (20) MAS TRAVELING WESTBOUND ON ALLEN ST AT STATE ST. THE DRIVER OF (V2) STATED SHE HAD A GREEN LIGHT AND AS SHE WENT THROUGH THE MYERSECTION SHE WAS STRUCK BY (V1). THE DRIVER OF (V1) SAD THAT HE WAS TRAVELING SOUTHBOUND THROUGH THE METRESECTION WITH A GREEN LIGHT AND WAS STRUCK BY (V2). (W) STATED THAT (V2) HAD THE GREEN LIGHT AND THAT (V1) RAN THE RED LIGHT. THE DRIVER OF (V3) HAD ON VISIBLE MIJKES BUT COMPLANED OF NECK PAIN AND WAS TRANSPORTED TO STRONG FOR THE SAME. WITHSES SOI GAYDRIN, SHEA	
83	35665630	3/26/2015	12:00:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	WET	RAIN	PASSING OR LANE USAGE IMPROPERLY	SOUTH-EAST	OVERTAKING	VEH. TWAS TRAVELING EAST BOUNDLOVE. HAMMS TAND THEM MAKING A RICHIT TURN ONLO UNINCESSITY AVE. WHEN WITH ITS RICHIT CUARTEEPANLE. STRUCK THE FROWIT LEFT GUARTEEPANLE OF WHI. 2 WHICH WAS ALSO MAKING A RICHIT TURN ONTO UNIVERSITY AVE. OPER. OF WEH. 1 STATE O HATTHET TURN WAS TED AND SHE DID NOT NOTICED STRKING VEH. 2. NO NUIDRES	
84	35665631	3/27/2015	9:35:00 AM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLOUDY	FOLLOWING TOO CLOSELY	EAST	REAR END	WEH TAMD VEH. WERE STOPPED AT THE RED LIGHT. THE INTERSECTION OF LAMAN ST, @OUNDERSITY AVE. WHAT WAITING TO MAKE A RIGHT TURN ONTO UNINVERSITY AVE. VEH. 1 WITH ITS RIGHT FROM TEND, STRUCK THE REAR CENTIER OF VEH. 2 OPER. OF VEH. 1 STATED THAT THE LIGHT WAS RED BUT THEN THE GREEN ARROW TURN GREEN FOR THE RIGHT TURN AND THAT VEH. 2 STARTED TO TURN AND STOPPED ABRUPTLY CAUSING HIM TO HIT THE VEHICLE. OPER OF VEH. 2 STATED THAT SHE WAS WAITING AT THE LIGHT AND WAS LOOKING TO HER LEFT BECAUSE CARS WERE STALL COMMOS FROM THE LEFT BECAUSE CARS WERE STALL COMMOS FROM THE LEFT BECAUSE CARS WERE STALL COMMOS FROM THE LEFT AND INVERSE LOOKED UP TO SEE "THE LIGHT HAD TURNED GREEN WHEN VEH. 1 HIT HER PROM THE REAR. WON WINDINGS PROOFED TO A THE SEEPER OF MININESSEE.	
85	35678260	3/30/2015	4:19:00 PM	2	NON- REPORTABLE	DAYLIGHT	WET	CLEAR	FALURE TO KEEP RIGHT	NORTH	HEAD ON	NO MURRES REPORTED A THE SCENE OR WITNESSES WAND DESCRIPTION TO MEND AND THE SCENE OR WITNESSES WAND DESCRIPTION TO WAND STOPED ON IN UNION STATE EMAN ST FACING SEWHEN WIWAS WE ON E MAIN ST. TIRED TO TURN LEFT ONTO IN UNION ST. VI. SWERVED TO AVOID HITTING WAND NISTED STRUCK VZ. VI. THEN BECKED UP AND PULLED AWAY NO ON IN UNION ST. NO PLATE RECORDED AND THE CITY CAMERA AT IN UNION ST. AND WELD ST WAS NOT WORKING. WE SAD THAT THE STRENKS WEHCE WAS A SMALLER GRAY 40SD POSSBLY A TOYAL BUT AND THE WITNESS WHO DID NOT WAIT FOR POLICE TO ARRIVE CALLED IN THE MINA AND SAD IT WAS A GREEN A CLIEB. A WITNESS ON MAILS WAND SAD THAT WAS DEAD AND AND WELL WAS A GREEN A CLIEB. A WITNESS ON MAILS WAND SAD THAT WAS A GREEN A CLIEB. A WITNESS ON MAILS WAS A GREEN A CLIEB. A WITNESS ON MAILS WAS A GREEN A CLIEB. A WITNESS ON MAILS WAS BELLD WAS A WELL WAS A WELL WAS A WELL.	
86	35688235	3/31/2015	9:44:00 PM	2	PROPERTY DAMAGE	DARK-ROAD LIGHTED	DRY	CLEAR	DRIVER INATTENTION, PASSENGER DISTRACTION	NORTH	OVERTAKING	TOWARDS CUMBERLAND ST. VEH 2 WAS ALSO DRIVING MIB. VEH 1 ATTEMPTED TO GO AROUND VEH 2 TO GET TO THE LIGHT. THIS CAUSED VEH 1 TO SIDESWIPE VEH 2. DAMAGE WAS FOUND ON THE PASSENGER SIDE OF VEH I CONSISTANT WITH A SIDESWIPING MOTION TO VEH 2. VEH 2 HAD DAMAGE ON THE DRIVER'S SIDE MIRROR AS	
87	35698563	4/4/2015	11:30:00 AM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	DRIVER INATTENTION, PASSING OR LANE USAGE IMPROPERLY	EAST	OVERTAKING	WELL AS CRONAT LETT FEINER AREA WHEN HAWS IN THE MODEL LANE OF THREE LANES OF TRAFFIC ON CUMBERLAND ST, TRAVELING EASTBOUND. WHEN YAWS IN THE LEFT LANE, NEXT TO WEH I, EASTBOUND ON CUMBERLAND ST. THE LEFT LANE IS A LEFT TURN ONLY LANE, THERE IS A CLEARLY MARKED, UMOSSTRUCTED TRAFFIC CONTROL SIGN INDICATING THIS AT THE INTERSECTION. THE MODEL LANE IS A LEFT TURN OS TRAGHT AHEAD, AS NOICATED BY A CLEARLY MARKED LUNGSTRUCTED TRAFFIC CONTROL SIGN AT THE INTERSECTION. WEH 2 WENT STRAIGHT ON CUMBERLAND, THROUGH THE ST PAUL INTERSECTION. WEH TURNED LEFT FROM CUMBERLAND ST, WEH TURNED LEFT FROM CUMBERLAND ST, ATTEMPTING TO GO IN BIS T PAUL WHI STRUCK WEH 2 IN	

TE	213	(9/79)

TE 213 (9/79)													
COUNTY:	MONROE		DIN	NOT ADDITIONS	n E	ROUTE NO. OR STREET NAME:							
	TOWN		F.J.N.:	NOT APPLICAE		ADJACENT RO	ADWAY NETWO	ORK			FILE:	PSC 5/13/2020	-
	CITY					AT INTERSECT	TION WITH/OR	BETWEEN:			BY:	PSC	-
	VILLAGE OF	ROCHESTER	!		•	SEE MAP					DATE	5/13/2020	-
TIME PERIOD		FROM:	TO:	ENVIRONMEN		Light Conditions:		Roadway Surface					
		8/1/14	7/31/19	Use Codes from at right) for these	MV 104 (shown categories	Daylight Dawn		1. Dry 2. Wet	1. Clear 2. Cloudy				
						Dusk Dark Road Lig		Muddy Snow/lce	3. Rain 4. Snow				
						5. Dark Road Ur		5. Slush	Sleet/Hail/Fre				
								10. Other	6. Fog/Smog/Sr 10. Other	noke			
No. OF MONTH	IS:		50	ES								MV 104 Police Report	
				of VEHICLES	≽	CONDITIONS	WA Y CE TION	8		DIRECTION	TYPE ¹	DESCRIPTION	REFERENCE MARKER
CRASH No.	CASE No.	DATE	TIME	No. of \	SEVERITY	IGHT	ROADWAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING FACTORS				
				Z	S	30	S S O	>	TACTORS			VI WAS WIB ON COMBERLAND APPROACHING JUSEPH AVE INTERSECTION. DRIVER STATES THAT LIGHT AT	
												INTERSECTION WAS GREEN FOR W/B TRAFFIC. V2 WAS	
88	35698538	4/5/2015	10:00:00 AM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	DRIVER INATTENTION	WEST	RIGHT ANGLE	N/B ON JOSEPH AVE AND APPROACHING CUMBERLAND ST INTERSECTION. DRIVER STATES THAT LIGHT AT	
												INTERSECTION WAS GREEN FOR N/B TRAFFIC. BOTH VEHICLES DROVE INTO INTERSECTION AND V1 STRUCK	
89	35682164	4/7/2015	2:10:00 PM	2	PROPERTY	DAYLIGHT	DRY	CLOUDY	TRAFFIC CONTROL DEVICES	WEST	RIGHT ANGLE	ND	
89	35082164	4///2015	2:10:00 PM	2	DAMAGE	DAYLIGHT	DRY	CLOUDY	DISREGARDED	WEST	RIGHT ANGLE	V-1 north on Joseph Ave., V-2 east on Cumberland St. V-2 had	
					PROPERTY				FAILURE TO YIELD RIGHT OF			green signal and proceeded through intersection when V-1 also entered intersection and struck V-2 causing damage to both	
90	35684208	4/7/2015	2:44:00 PM	2	DAMAGE	DAYLIGHT	DRY	CLOUDY	WAY	NORTH	RIGHT ANGLE	vehicles. Operator V-1 states that he had the red light when he	
												entered the intersection and braked too late striking V-2. no injuries vencted all vehicles left scene under syn nower supped in main.	
												at the red light at st paul st. while waiting in traffic veh 1 which was also w/b rear ended veh 2 causing damage to the rear of veh 2.	
												veh 1 ten backed up and drove around veh 2 and sped away w/b	
91	35683813	4/7/2015	5:36:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLOUDY	FOLLOWING TOO CLOSELY	WEST	REAR END	onto the inner loop to rt 490. the occupants of veh 2 describe veh 1 has a gold toyota 4 dr driven by a female with blonde hair. the	
												occupants are sure veh 1 had a gold nys plate but were not able to get the plate number or any other details for veh 1. there are no	
												cameras at the intersection and no witnesses. no injuries reported	
92	35690686	4/14/2015	7:44:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLOUDY	FAILURE TO YIELD RIGHT OF WAY	NORTH	OVERTAKING		
					DAMAGE				10.11			VEHICLE 2 WAS TRAVELING EAST ON EAST MAIN STREET AND PROCEEDING STRAIGHT AHEAD WHILE IN THE LEFT	
												LANE. VEHICLE 1 WAS ALSO TRAVELING EAST ON EAST	
											RIGHT TURN	MAIN STREET, AND HAD SIGNALED TO CHANGE LANES FROM THE LEFT TO THE RIGHT. THE DRIVER OF VEHICLE	
93	35698658	4/14/2015	1:47:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	DRIVER INATTENTION	EAST	(WITH OTHER	1 WAS NOT PAYING ATTENTION AND DID NOT SEE VEHICLE 2, AND ATTEMPTED TO EXECUTE THE LANE	
											CAR)	CHANGE, AT WHICH POINT THE FRONT RIGHT OF VEHICLE	
												1 STRUCK THE REAR LEFT OF VEHICLE 2 CAUSING DAMAGE TO BOTH VEHICLES, THE VALUE OF WHICH WAS	
												UNKNOWN AT THE TIME THAT THIS INCIDENT WAS REPORTED. NO INJURIES REPORTED. NEITHER VEHICLE.	
94	35693881	4/16/2015	3:58:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	NORTH	REAR END		
95	35703324	4/23/2015	8:25:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	SNOW/ICE	SNOW	TRAFFIC CONTROL DEVICES DISREGARDED	SOUTH	RIGHT ANGLE		
												VEHICLE 2 WAS NORTH ON N CLINTON AV GOING THROUGH THE INTERSECTION WITH CUMBERLAND ST.	
96	35700478	4/27/2015	7:10:00 AM	2	PROPERTY	DAYLIGHT	DRY	CLOUDY	TRAFFIC CONTROL DEVICES	WEST	RIGHT ANGLE	WHEN VEHICLE 1 WHICH WAS WEST ON CUMBERLAND ST FAILED TO STOP FOR THE RED LIGHT. THUS ENTERING	
,,,	30700170	WE/12010	7.10.007101	_	DAMAGE	bitteom	Dit.	020001	DISREGARDED		NOTT FAVOLE	THE INTERSECTION AND HITTING THE REAR RIGHT	
					HOH							BUMPER OF VEHICLE 2 CAUSING DAMAGE.THE DRIVER	
97	35733056	5/1/2015	3:28:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	BACKING UNSAFELY	EAST	REAR END	VI WAS BACKING OUT OF A PARKING SPOT WHEN HE HIT V2 LEFT SIDE DOOR WHICH WAS PARKED	
98	35732500	5/2/2015	4:00:00 PM	2	NON-	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	NORTH	REAR END	VEH 2 WAS STOPPED AT A REDLIGHT ON STATE ST AT ALLEN ST FACING NORTH. VEH 1 FAILED TO STOP AND	
,,,	50752550	32,2010	1.00.001 W	-	REPORTABLE	bitteom	DIC.	OLLYIN		NOICH	KEAK END	STRUCK VEH 2 IN THE REAR CAUSING DAM TO BOTH VEHS. NO WITNESS NO IN JUJES	
]		both veh 1 and veh 2 were e/b from the innerloop and crossed n clinton ave approaching joseph ave. veh 2 was in the curbside left	
												turn only lane to turn left, n/b on joseph ave. veh 2 was in the center lane which can go straight or turn left. as veh 2 was making	
99	35709098	5/3/2015	2:30:00 PM	2	NON-	DAYLIGHT	DRY	CLEAR	UNSAFE LANE CHANGE	NORTH-EAST	OVERTAKING	the left turn, veh 1 also attempted to turn left into veh 2's lane	
					REPORTABLE							and struck the passenger side door of veh 2 with the drivers side fender of veh 1. veh 2 pulled over but veh 1 fled n/b on joseph out	
												of sight of veh 2. the only description of veh 1 is a 2 door light blue mazda operated by an asian looking male of unkown age. no	
												injuries observed or reported. only minor damage to veh 2. VEH 2 WAS STOPPED AT THE RED LIGHT ON JOSEPH AVE	
100	35724930	5/4/2015	2:55:00 PM	2	NON-	DAYLIGHT	DRY	CLEAR	DRIVER INATTENTION	SOUTH	REAR END	FACING S/B AT CUMBERLAND ST. VEH 1 WAS SLOWING TO)
					REPORTABLE							STOP IN TRAFFIC AT THE RED LIGHT BUT STRUCK THE REAR OF VEH 2	
101	35820141	5/7/2015	5:40:00 PM	2	PROPERTY DAMAGE	UNKNOWN	UNKNOWN	UNKNOWN	UNKNOWN	UNKNOWN	LEFT TURN (WITH OTHER		
										1	CAR)	V-1 Norm on Joseph Ave inrough green light at intersection with	
					PROPERTY				TRAFFIC CONTROL DEVICES			Cumberland St. when Westbound V-2 enters intersection from East directly into path of V-1. V-1 strikes driver side door of V-2 with	
102	35735214	5/9/2015	6:20:00 PM	2	DAMAGE	DAYLIGHT	DRY	CLEAR	DISREGARDED	NORTH	RIGHT ANGLE	front bumper of V-1 causing extensive front end damage. V-2 then flees the scene before speaking to anyone in V-1. Attempts to	
												locate the driver of V-2 were unsuccessful. The PO Box listed is	
												VEH 2 WAS PARKED ALONG THE SOUTH CURB IN FRONT OF 209 CUMBERLAND STREET FACING E/B UNOCCUPIED	
103	35770001	5/21/2015	4:20:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	DRIVER INATTENTION	EAST	REAR END	FROM 0700HRS - 1600HRS. SOMETIME DURING THAT TIME	
					KEFORTABLE							VEH 1 STRUCK THE REAR OF VEH 2 CAUSING DAMAGE. VEH 1 LEFT THE SCENE PRIOR TO OWNER OF VEH 2	
			<u> </u>	L	<u> </u>	L	l	L	1	1		RECOMING AWARE OF WHAT HAPPENED	1

TE	213	(9/79)

TE 213 (9/79)											ı			
COUNTY:	MONROE		P.I.N.:	NOT APPLICATE	BLE	ROUTE NO. OI				CASE No.:				
	TOWN		•				ADWAY NETW				FILE		-	
	VILLAGE OF	ROCHESTER				AT INTERSECT	TION WITH/OR	BETWEEN:			DATE:		-	
TIME PERIOD		FROM: 8/1/14	TO: 7/31/19	ENVIRONMEN Use Codes from at right) for these	MV 104 (shown	SEE MAP Light Conditions 1. Daylight 2. Dawn 3. Dusk 4. Dark Road Li 5. Dark Road U	ghted	Roadway Surfact 1. Dry 2. Wet 3. Muddy 4. Snow/lce 5. Slush 10. Other	1. Clear 2. Cloudy 3. Rain 4. Snow 5. SleeVHail/Fre 6. Fog/Smog/Sr					
No. OF MONTH	IS:		50					10. Other			*Use Codes from	MV 104 Police Report		
CRASH No.	CASE No.	DATE	TIME	No. of VEHICLES	SEVERITY	LIGHT	ROADWAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING FACTORS	DIRECTION	TYPE ¹	DESCRIPTION	REFERENCE MARKER	
104	35736688	5/25/2015	10-43:00 PM	2	PROPERTY DAMAGE	DARK-ROAD LIGHTED	WET	RAIN	PAVEMENT SLIPPERY, REACTION TO OTHER UNINVOLVED VEHICLE	WEST	REAR END	ON 52/31, AT APPROX. 231 HIRS, INES-INNUBLD TO THE FASTITAC GAS STATION AT 57.2 MAN ST. UPON ARRIVAL, ISPOKE TO (D) AND (D2). (D2) SAD SHE WAS TAVELLING WESTEOUND ON E. MANN ST AND ADD COME TO THE INTERSECTION OF E. MANN ST AND SCIO ST. (D2) SAD SHE WAS NOTHER MODEL AND OF E. MANN ST AWHEN THE CAR IN FRONT OF HER MADE A QUICK LAWE CHANGE. (D2) SAD SHE HAD TO MAKE A SHARP MOVEMENT INTO THE NEXT LAWE TO THE RESTAT. (D2) THEN SAD SHE FELT THE COLLISTON OF HER VEHICLE AND (V1). (D1) HAD A SIMILAR ACCOUNT OF THE MODEL (D1) SAD HE WAS TRAVELLING WESTEOUND IN THE RICHT LAWE OF E. MANN ST. (D1) SAD HE WAS TRAVELLING WESTEOUND IN THE RICHT LAWE OF E. MANN ST. (D1) SAD HE WAS MOVING TO HIS LAWE. TRED TO STOP BUT WAS MOVING TO HIS LAWE. THED TO STOP BUT WAS MOVING TO HIS LAWE. THE DTO STOP BUT WAS MOVING TO HIS LAWE. THE DTO STOP BUT WAS MOVING TO HIS LAWE. THE DTO STOP BUT WAS MOT ABLE TO STOP IN TIME. THE DRIVERABORS SDEFORM TO SUPPLY SASSEMBER SDEFORM TO SARD STANDERS OF THE ASSEMBER SDEFORM TO SARD THE ASSEMBER SDEFORM TO SARD THE ASSEMBER SDEFORM TO THE ASSEMBER SDEFORM TO THE ASSEMBER SDEFORM TO THE ASSEMBER SDEFORM TO THE ASSEMBER SDEFORM TEMPORADORS STOP TO THE ASSEMBER SDEFORM TO THE ASSEMBER SDEFORM TEMPORADORS STOP THE ASSEMBER SDEFORM TO THE ASSEMBER SDEFORM TO THE ASSEMBER SDEFORM TO THE ASSEMBER SDEFORM THE ASSEMBER SDEFORM THE ASSEMBER SDEFORM TO THE ASSEMBER SDEFORM THE		
105	35744394	5/27/2015	3:11:00 AM	2	NON- REPORTABLE	DARK-ROAD LIGHTED	DRY	CLOUDY	UNSAFE LANE CHANGE	WEST	OVERTAKING	BEAD RIMBER OF AVI. MAN BUILDIES BERDORTEN FABS. BOTH VEHICLE WERE TRAVELING WIS ON EM AMA ST. VI. WAS IN THE CENTER LANE AND VZ WAS IN THE RICHT UT LANE. VI STATES HE WAS GOING TO CHANGE LANES FROM THE CENTER LANE TO THE OUTER RICHT LANE WHE DOONS O, VI. DID NOT PEROPERLY CHECK HIS RICHT SIDE MIRROR AND MADE THE LANE CHANGE TO HIS RICHT SIDE MIRROR AND MADE THE LANE CHANGE TO HIS RICHT SIDE MIRROR AND MADE THE LANE CHANGE RICHT LOSS HOW TO AND ANGE TO THE RICHTICENTER AREA. VZ HAD MINOR DAMAGE TO THE LEFT DOOR AREA ONLY, VI. IS AN AMBULANCE FOR RURAL METRO AMUBULANCE SERVICE; RICE 768. NO MUINIES COSSESSED OR COMPANIED OF. BOTH		
106	35744398	5/28/2015	11:49:00 AM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	WEST	REAR END	TO WAS STOPPED AT THE RED LIGHT FACING WESTBOUND ON EAST MAIN STREET WHEN VI DID COLLIDE WITH V2 FROM BEHIND NO INJURIES REPORTED MINOR DAMAGE		
107	35749664	6/1/2015	9:13:00 AM	2	INJURY	DAYLIGHT	WET	RAIN	FOLLOWING TOO CLOSELY	SOUTH	REAR END	White #2 Stopped in Halfe for the consultation workers southbound on Siles Unken vehicle is shout he rear of veh #2. Driver #1 did not speak English and was difficult to communicate with, but she did she hat she hit vehicle #2. Both passengers from het #2 were laken to Storagh brogalist complaining of head of back pair. Mijor damane is hoft websites:		
108	35761678	6/1/2015	12:31:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	WET	RAIN	PASSING OR LANE USAGE IMPROPERLY	NORTH	OVERTAKING	traveling northbound on University Av. Vehicle #1 attempted to go		
109	35750221	6/2/2015	5:04:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	BACKING UNSAFELY	WEST	REAR END	4.1 traveling west bound on hydrhust st in the olly of nothester, comes to a stop at the intersection of lyndhust st and north st. vs. raveling west bound comes to a stop behind v1 at the intersection, the operator of v1.1 then decides to back up unaware that v2 is stopped behind into v1.1 makes contict with v2 causing minor damage, both vehicles come to rest at the intersection.		
110	35766171	6/9/2015	1:05:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	FAILURE TO YIELD RIGHT OF WAY	WEST	RIGHT ANGLE			
111	35754241	6/9/2015	5:14:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLOUDY	PASSING OR LANE USAGE IMPROPERLY	WEST	OVERTAKING	AND COLLIDED WITH THEM. WI WAS TRAVELING WIB BEHIND THE INVOLVED VEHICLES AND STATED THAT IT APPEARED THAT VEH 1 MOVED OUT OF ITS LANE OF TRAVEL TO THE RIGHT AND STRUCK VEH 2. NO INJURY REPORTED OR OBSERVED. WITHESS 001 BUSS, LORI 53		
112	35758196	6/10/2015	2:53:00 PM	2	NON- REPORTABLE	DAYLIGHT	WET	RAIN	DRIVER INATTENTION	NORTH	RIGHT ANGLE	WH 2 AND THEM DID STRIKE THE DRIVE RRAPPORS SIDE FRONT FENDER OF VEH 2 CAUSING DAMAGE TO THE FENDER, DRIVERAPORS SIDE TIRE, AND WHEEL AXLE VEH THEM BACKED UP AND FLED THE SCENE HEADING NIS ON STATE STREET. (M) DESCRIBES THE VEHICLE AS A GREENISH, TEAL COLORGE HOMDAZ DOCUPED BY AFFO BRIVER AND WIS FROM TS CAT PASSENGER. NO PLATE WAS OBTANED. NEGATIVE ON ANY CAMERAS IN HIE AREA, PHOTOS TAKEN OF DAMAGE TO VHE 2. NO NUIVERS REPORTED, VEH 2 TOWED BY PERSONAL TOW. NO FURTHER SOLVABILITY FACTORS PRESENT.		
113	35794088	6/14/2015	11:21:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLOUDY	DRIVER INATTENTION	NORTH	RIGHT ANGLE	VEHICLE 1 WAS NORTH ON ST PAUL ST AT CUMBERLAND ST. WHEN IT FALLED TO STOP FOR THE RED LIGHT. THUS ENTERING THE INTERSECTION AND HITTING VEHICLE 2 WHICH WAS WEST ON CUMBERLAND ST. VEHICLE 2 DID HAVE A CREEN LIGHT		

ROUTE NO. OR STREET NAME MONRO P.I.N.: NOT APPLICABLE CASE No ADJACENT ROADWAY NETWORK TOWN FILE: CITY AT INTERSECTION WITH/OR BETWEEN: BY: PSC VILLAGE OF ROCHESTER DATE: 5/13/2020 SEE MAP TIME PERIOD FROM TO ENVIRONMENTAL se Codes from MV 104 (shown 1. Daylight right) for these categories 2. Dawn 3. Dusk 1. Dry 2. Wet 3. Muddy 1. Clear 2. Cloudy 3. Rain 8/1/14 7/31/19 4. Snow/lo 5. Dark Road Unlighted 5. Slush 5. Sleel/Hail/Freezing Rain 10. Other 6. Fog/Smog/Smoke lo. OF MONTHS 60 Jse Codes from MV 104 Police Report of VEHICLES DIRECTION DESCRIPTION REFERENCE ROAD WAY SURFACE SONDITION CRASH No CASE No DATE TIME APPARENT CONTRIBUTING FACTORS eh1 attempted to make a right turn and turned the vehicle to wide art alempeu to invake a night unit and united use verticle to will susing the vehicle to slightly sideswipe veh2. Veh1 continued up e road until veh2 caught up to her and called officers. Veh1 stat te didn't realize she struck veh2. Minor damage to both PROPERTY 35804138 4:58:00 PM DRIVER INATTENTION EAST 114 DAYLIGHT DRY CLEAR OVERTAKING DAMAGE ehicles and no injuries reported. - WITNESS 1 VAZQUEZ, JUAI INKNOWN ROCHESTER NY 14619 7167717321 V2 was s/b Inner Loop exit ramp with a green traffic light to continue s/b University Av. While in the intersection of Inner Loop exit ramp and E Main St, V2 was struck by V1, which was w/b E es state east and west bound traffic was stopp want 3. "witessess supper with a red traffic light. V1 could only be described as newer mode black sedan with a male driver, possibly a passenger, and last seen w/b E Main St. V2 damage to left front quarter panel, left fo door, left rear door and left rear quarter panel. V1 reportedly had NON RAFFIC CONTROL DEVICE: 6/22/2015 115 35779852 4:19:00 PM DAYLIGHT DRY CLEAR WEST RIGHT ANGLE ont end damage with the front bumper hanging off of the vehicle. Not injuries repote to it observer. V zwas ower by 43.2 biter shop. - WITNESS 1 MELVIN, PATTI 6 KAY AV ROCHESTER On the above date and time I responded to the above location for the MVA involving a bicyclist that was struck. Upon arrival I spoke to the bicyclist who stated he did not need medical attention and that he was uninjured due to (V1) hitting him (D1) states she was name was unique out or (V) finally limit (V) sates sie was aveiling North on University Ave crossing over the E. Main St ntersection on to the Inner Loop when the bicyclist crossed in fro if her vehicle. (D1) and (W) state there was a large semi-truck in the left lane next to (V1) which made it difficult to see the bicyclist NON AILURE TO YIELD RIGHT OF 116 35774411 6/23/2015 5:36:00 PM DAYLIGHT DRY CLEAR NORTH OTHER REPORTABLE going through the intersection. The bicyclist was traveling the rong way against traffic and disobeyed the traffic control device for e pedestrian crosswalk. No fickets were issued. No need for a ow truck No injuries. - WITNESS 1 RIEFLIN, CHAD M 352 /eh #1 was west on Cumberland St. Veh #2 was north on los Ave. Driver 1 stated that she was stopped for a red light. The light wee. Divise I stated that a rise was subject to a feet things in the light in the light in med green so she starled to proceed through the intersection and priver 2 blew a red light hit her. Driver 2 stated that he had a gree ght and veh #1 struck him. There were no cameras to confirm who had the red light and no witnesses. Passenger #1 stated that PROPERTY RAFFIC CONTROL DEVICES 117 35797789 7/7/2015 12:01:00 PM 2 DAYLIGHT DRY CLOUDY WEST RIGHT ANGLE DAMAGE DISREGARDED new had the green light also, eh 2 was driving w/b on cumberland st then turning n/b onto senh ave in the extreme north lane of cumberland st. veh 1 was AILURE TO YIELD RIGHT OF NON-NORTH-WEST OVERTAKING 118 35797802 7/9/2015 8:10:00 PM DAYLIGHT DRY CLOUDY so driving in the same described direction as yeb 2 but in the REPORTABLI quot middle lane on cumberland st. this lane is not a turning lar weh 1 made the same n/h turn onto insenh ave and struck weh 1. V1 traveling w/b on Cumberland St which is 3 lanes, w/b only wil guardrail on the south side. In the area of 250 Cumberland, the a guardiant rise stands and a guardian state of any office and a guardian state of the foot and rear left corners of his car, coming to rest blocking the right two lanes of travel. A asserby called 911 and told me that a male was passed out in th PROPERTY DARK-ROAL passency called 911 along the trial a maner was passed out in the car with his arm hanging out of the window. Marks on the guardist matched the damage to the car. The driver and sole occupant of the car was arrested for Aggravated DWI. Tickets Issued: GOLDEN A MILLER Driver of vehicle number (1) lickets: Ticket 119 35822617 7/19/2015 2:01:00 AM DRY CLEAR ALCOHOL INVOLVEMENT WEST OTHER DAMAGE LIGHTED umber: DZ9A4L4DF0 Violation: 1180A Ticket Number DZ9A4L4DP7 Violation: 11923 Ticket Number: DZ9A4L4DSB olation: 11922 Ticket Number: DZ9A4L4DTF Violatio ST AT CUMBERLAND ST. WHEN VEHICLE 1 ALSO ON ST PROPERT AUL ST COMING UP TO THE RED LIGHT AT 120 35813048 7/20/2015 1:21:00 PM DAYLIGHT DRY CLOUDY DRIVER INATTENTION SOUTH REAR END DAMAGE CUMBERLAND ST. WHEN IT FAILED TO COME TO A STOP BEFORE HITTING VEHICLE 2'S REAR BUMPER CAUSING SLIGHT DAMAGE HICLE 1 CAME INTO VEHICLE 2' S LANE HITTING PROPERTY ACCELERATOR DEFECTIVE 121 35813053 7/24/2015 8:20:00 AM DAYLIGHT DRY CLEAR WEST OVERTAKING TS REAR RIGHT QUARTER PANEL CAUSING DAMAGE. DAMAGE OTH CARS STOPPED AND EXCHANGED INFO. HOWEVER HE DRIVER OF VEHICLE 2 LATER THOUGHT IT BEST TO AVE A DEDODT I TRAVELING WEST ON ALLEN STREET WAS UNABLE T FOLLOWING TOO CLOSELY 122 35820879 7/24/2015 10:20:00 PM 2 INJURY DRY CLEAR WEST REAR END TOP AND STRIKES V-2 IN REAR BUMPER AREA CAUSING LIGHTED INOR DAMAGE. NO TOWS, NO ARREST pervisor Soto told me that an RTS bus. V2 was hit at the supervisor solo and the trial air K13 bids, V2 was filter the intersection of E. Main St. and N. Union St. I then spoke to the driver of V2 who told me that he was traveling West in the right lane owly with traffic when V1, who was traveling in the left hand lane vestbound, scraped her passenger side mirror on the driver side of V2. V1 then fled West on E. Main St. Soto took pictures and a or V2. Y interfined west of it. Wall is 1,500 block picules and a registration was able to be taken of the vehicle, bbu1195. It came back to a 1989 Chevrolet suburban from Brockport Ny,I then Had MCSO check the registered owner&apos:s address for the vehicle OVERTAKING 123 35837595 DAYLIGHT REPORTABLE IMPROPERLY n question. They located the registered owner who had the drive ntact me. I spoke with the driver of v1 and she told me that she onlact mile: I spoke with the larvier of vir and a lare with mile that was travelling west in traffic at the above location. She stated that the does not usually drive v1 and that she also does not drive in the city often so she was nervous, she told me she heard a scrap of the city often so she was nervous. but did not see any damage to her mirror so she assumed there vas no accident, she then went home and was contacted by the gistered owner. It appears that v1 did not maintain her lane ar as distracted while driving causing the accident. v1 was given RIGHT TURN (WITH OTHER PROPERTY 35860188 8:27:00 PM 2 UNKNOWN UNKNOW UNKNOWN 124 7/26/2015 UNKNOWN DAMAGE CAR) 1 was driving n/b on scio st. veh 2 was driving s/b on scio PASSING OR LANE USAGE ne area of scio stand lyndhurst st the drivers side mirrors of each 125 REPORTABL chicle struck the other, veh 1 left the scene, veh 2 had the mirror ed out and did crack DDODEDT DRIVER INATTENTION

DRY

DAMAGE

CLEAR

TE 213 (9/79)

126

35822632

7/29/2015

2:55:00 PM

TE 213 (9/79) ROUTE NO. OR STREET NAME MONRO P.I.N.: NOT APPLICABLE CASE No ADJACENT ROADWAY NETWORK TOWN FILE: CITY AT INTERSECTION WITH/OR BETWEEN: BY: PSC VILLAGE OF ROCHESTER DATE: 5/13/2020 SEE MAP ENVIRONMENTAL TIME PERIOD FROM TO Roadway Surface Condition se Codes from MV 104 (shown 1. Daylight right) for these categories 2. Dawn 3. Dusk 1. Dry 2. Wet 3. Muddy 1. Clear 2. Cloudy 3. Rain 8/1/14 7/31/19 4. Snow/lo 4. Snow 5. Sleet/Hail/Freezing Rain 5. Dark Road Unlighted 5. Slush 10. Other 6. Fog/Smog/Smoke lo. OF MONTHS 60 Jse Codes from MV 104 Police Report of VEHICLES IGHT DIRECTION DESCRIPTION REFERENCE SOADWAY SURFACE CONDITION DATE CRASH No CASE No TIME APPARENT CONTRIBUTING FACTORS is a Police venicle owned and operated by the RC olice Department and was traveling north on St Paul St enterin he intersection of Cumberland St. At the time, V2 was facing a deady green light and had the right of way on St Paul St. As V2 was driving through the intersection, V1 was traveling west on Cumberland St and entering the intersection with St Paul St. Whil V1 was entering the intersection, the vehicle faced a steady red ght. V1 then struck the front passenger side wheel of V2 with &apos:s front driver side bumper causing damage to both whicles. Damage was also caused to the front passenger side numper of V2. Driver of V1 (Thomas) stated he thought he had a een light. The driver told Sqt. Kennedy that he was not wearing s seat helt and R/o did not observe a seat helt on Thomas whe is sear bell and it or but in discissed a sear bell of infinitials with the car was first approached by officers. Thomas also lold Sgl kennedy that he was eafing a sandwich white driving. R/o local kild markings on street which were caused by V1's tires. DARK-ROAF TRAFFIC CONTROL DEVICES 127 35826865 8/1/2015 3:48:00 AM INJURY DRY CLEAR WEST RIGHT ANGLE LIGHTED hey started prior to V1 entering the intersection and ended at the Iney started prior to VI entering the intersection and ended at the point of impact. Thomas had the complaint of pain to his head and back. R/o did not observed any obvious injuries to Thomas. Rural Meto #776 transported Thomas to Strong Memorial Hospital for precaudinary reason. Police photographs were taken of the accident scene. It appeared that the inspection sticker on VI had N. R. M. R. een issued to another vehicle and was replaced on V1. No DMV ord of an inspection sticker could be found for V1. Office oseph Bonacci was operating V2 (RPD Fleet #141362 - P-85) and states he faced a green traffic light as he entered the ntersection. The DOT camera at this intersection was facing awa om the intersection towards N Clinton Av at the time of the 128 35828717 8/4/2015 9:37:00 AM 2 DAYLIGHT DRY CLEAR UNKNOWN NORTH-EAST OVERTAKING 35852418 8/11/2019 2:22:00 PM AMAGE AN DAYLIGHT DRY CLOUDY DRIVER INATTENTION WEST OTHER 130 35854445 8/13/2015 8:51:00 PM 2 INJURY DRY CLEAR FOLLOWING TOO CLOSELY WEST REAR END LIGHTED GREEN LIGHT AT THE INTERSECTION OF ST PAUL ST. WHEN VEHICLE 2 WHICH WAS NORTH ON ST PAUL ST WHEN VERILLE ZWINLEN WAS NORTH ON STAULS IT.

FIFER ENTERING THE SAME INTERSECTION WHEN IT

FIAD THE GREEN LIGHT, IT'S DRIVER REALIZED HE

COULD&Apos;NT GO STRAIGHT DUE TO CONSTRUCTION PROPERTY OTHER (VEHICLE), FAILURE 12:05:00 PM 131 35845728 8/14/2015 2 DAYLIGHT DRY CLOUDY WEST RIGHT ANGLE DAMAGE TO YIELD RIGHT OF WAY HE TRIED TO MAKE A U-TURN THUS TURNING RIGHT INTO FWAS at the light of cumberiand strand st paul st. (v1) after go through the intersection of the above listed intersection and to go through the intersection of the above islead intersection and struck (v2). (v1) had damage to the front of the vehicle, (v2) had damage to the right front door. I was unable to speak with (d1) as he was taken by ambulance to strong hospilal with complaint of neck pain. I did speak to (p1) wh was the front seat passanger of (v1). per (p1), (v1) was traveling whon cumberland st. (v1) was slopped at the traffic light of with our cumberland st. (v1) was supped at the trainit light (v1) cumberland st and st. paul st. the light turned green and (v1) altempted to go through the intersecting, at this point (v1) shuck (v2). I then spoke with (d2). (d2) stated that (v2) was traveling nil on st paul st when he noticed that the lane was closed due to RAFFIC CONTROL DEVICES 132 35873244 8/14/2015 4:56:00 PM 2 INJURY DAYLIGHT DRY CLOUDY WEST RIGHT ANGLE DISREGARDED onstruction, per (d2) the light for him was vellow and he tempted to be at the red and make a e/b turn onto central ave to mempine to be a first real and make a rebruint on central aver a world the construction. at this point (v1) struck (v2) there were no vihesses. There was no compliant of pain nor visible injuries by d2) or (p1). both vehicles did not need to be towed. (d1) was V-2 stopped at intersection facing West on Cumberland St. with r r-2 subpeed at miles section recting west on Cumbertain 3.5 wint is glitt. V-2 receiving green light for East/West traffic and enters ntersection. V-1 travelling North on St. Paul at an unreasonable peed. V-1 fails to stop at a steady red signal for North/South traffi and strikes V-2 in the intersection. V-1 leaves the scene prior to atrol arrival. Patrol later located V-1 and the operator of V-1 at th patrol arrival. Patrol later located V-1 and the operator of V-1 at the registered owners address. V-1 signed a supporting deposition admilling to operating V-1 and being involved in the incident. V-1 issued UTT&aposs. No injuries reported. Tickets Issued: ALFRED IIITA/MAS Driver of vehicle number (i) lickets: Ticket Number: 1E224P87FB Volcation; 5111A Ticket Number: RAFFIC CONTROL DEVICES PROPERTY DARK-ROAD 133 35852265 8/18/2015 12:40:00 AM DRY CLOUDY NORTH RIGHT ANGLE DAMAGE LIGHTED DISREGARDED 1E224PB8HP Violation: 6001A Ticket Number: 1E224PB8KL lation: 1180A Ticket Number: 1F224PB8I 9 Violation: 1111A1 1111D1 Ticket N PROPER1 134 35854457 8/18/2015 10:35:00 AM DAMAGE AND DAYLIGHT DRY CLEAR TURNING IMPROPER NORTH-WES (AGAINST eh1 was west on cumberland st in the middle lane of three lane NON-135 36938013 8/21/2015 6:55:00 AM 2 DAYLIGHT DRY CLEAR DRIVER INATTENTION WEST OVERTAKING eh2 was west on cumberland in the right lane of three lanes, as REPORTABLE e vehicles were side by side, they collided. 2 was stopped at the red light in traffic at the above address facin NON-DARK-ROAD /b. v1 was behind v2 coming up to the stopped traffic, v1 then 136 35873251 8/22/2015 8:47:00 PM 2 DRY CLEAR FOLLOWING TOO CLOSELY WEST REAR END REPORTABL LIGHTED ruck v2 causing minor damage to both vehicle. no tows neede d no injuries renorted on scene.
iver of V1 states he was e/b Cumberland St at N Clinton Ave order or vi sales ne was ein Cuminel and stativ Climon Ave with a green takelic light. Driver of VI stales as he went fitrough th ntersection, he was struck by V2. Driver of V2 stales she had een w/b Cumberland St, made the left turn on to St Paul St and stopped for a red traffic light at Cumberland St and St Paul St. NON UNKNOWN 137 35857469 8/24/2015 7:42:00 PM 2 DUSK DRY CLEAR EAST RIGHT ANGLE river of V2 states her traffic light turned green, she entered the REPORTABLE tersection and struck V1. It is unknown which driver actually had e green traffic light. I watched the traffic light for two cycles and it ppeared to be working properly. V1 damage to the left rear

138

35869057

8/27/2015

10:36:00 AM

2

DAYLIGHT

DAMAGE

DRY

CLOUDY

UNSAFE LANE CHANGE

WEST

OVERTAKING

umper. V2 damage to the front center and front right bumper. o injuries complained of or observed. Both vehicles cfbo. both TE 213 (9/79) ROUTE NO. OR STREET NAME MONRO P.I.N.: NOT APPLICABLE CASE No ADJACENT ROADWAY NETWORK TOWN FILE: CITY AT INTERSECTION WITH/OR BETWEEN: BY: PSC VILLAGE OF ROCHESTER DATE: 5/13/2020 SEE MAP TIME PERIOD FROM TO ENVIRONMENTAL Roadway Surface Condition se Codes from MV 104 (shown 1. Daylight tright) for these categories 2. Dawn 3. Dusk 1. Dry 2. Wet 3. Muddy 1. Clear 2. Cloudy 3. Rain 8/1/14 7/31/19 4. Snow/lo 4. Snow 5. Dark Road Unlighted 5. Slush 5. Sleel/Hail/Freezing Rain 10. Other 6. Fog/Smog/Smoke lo. OF MONTHS 60 Jse Codes from MV 104 Police Report of VEHICLES DIRECTION DESCRIPTION REFERENCE GHT ROADWAY SURFACE SONDITION CRASH No CASE No DATE TIME APPARENT CONTRIBUTING FACTORS CUMBERLAND ST VEHICLE 1 WHICH WAS WEST ON YNDHURST ST. FAILED TO STOP FOR THE STOP SIGN A IORTH ST. THUS GOING RIGHT INTO VEHICLE 2'S NORTH 31. THUS GOING KIGHT INTO VERILLEZ AZAIDAS, PATH ON NORTH ST. BOTH DRIVERS AND THE PASSAGEF IN VEHICLE 2 WERE TRANSPORTED TO THE HOSPITAL WITH MINOR INJURIES. THE DRIVER OF VEHICLE 1 WAS PROPERTY AILURE TO YIELD RIGHT OF 139 35881817 9/10/2015 11:27:00 AM AMAGE AN INJURY DAYLIGHT DRY CLOUDY WEST RIGHT ANGLE TICKETED FOR FAILING TO STOP FOR SIGN.BOTH EHICLES WERE TOWED DUE TO DAMAGE. - WITNESS 1 CUNNINGHAM, DANIELLE 33 MARKET ST #5 BROCKPORT Was traveling S/B on N. Clinton Ave when it went through the red light and struck V2. V2 was going firrough the intersection a green light, traveling E/B on Cumberland St when it was s The driver and passenger of V2 both had injuries and were PROPERTY 140 35912266 9/14/2015 9:15:00 AM AMAGE ANI INJURY DAYLIGHT DRY CLEAR DRIVER INATTENTION SOUTH RIGHT ANGLE nsnorted to Strong via ambulance. V2 was tower EXIT RAMP AT A RED LIGHT AT THE INTERSECTION OF E MAIN ST, V1 WAS TRAVELING S/B ON THE INNER LOOP EXIT RAMP. V1 STRUCK V2 WITH ITS FRONT END IN THE EATLANDER OF V.2. AFTER STRIKING THE VI FLED THE SCENE. OFFICER MATTOX (#2324) OBSERVED THE ACCIDENT AND VI FLEEING THE SCENE. HE WAS ABLE TO KEEP EYES ON THE VEHICLE AND LOCATE IT AT THE ORNER OF PITKIN ST AND CHARLOTTE ST. THERE, VI NON. DARK-ROAF VAS STILL OCCUPPIED BY THE DRIVER AND TWO 9/14/2015 141 35896132 9:12:00 PM DRY CLEAR FOLLOWING TOO CLOSELY SOUTH REAR END REPORTABLE PASSENGERS. IT IS TO BE NOTED THAT THE WAS NO NSURANCE CARD LOCATED IN THE VEHICLE AND THE RIVER COULD NOT PROVIDE ONE.THERE WAS NO INJURES REPORTED AND CITY CAMERAS IN THE AREA GGT, WERSTER RESPONDED TO THE SCENE. Tickets GI. WEBSTER RESPONDED TO THE SCENE. TILKES sued: MARQUIN M GORDON Driver of vehicle number (1) kels: Ticket Number: 8K9Q4S9FSX Violation: 1163B Ticket umber: 8K9Q4S9FL9 Violation: 1180A Ticket Number: BK9Q4S9FFG Violation: 6001A Ticket Number: 8K9Q4S9H1S umberland St at St Paul St with a green traffic light. The far lef ne, a left turn only lane, was blocked by orange barrels due to ad construction. V2 was in the second lane from the left. Tha ne is marked as a left turn or continue straight lane. V1 was in RAFFIC CONTROL DEVICES NORTH-EAST LEFT TURN NON e third lane from the left. This lane is marked as a right turn or 142 35888282 9/16/2015 4:04:00 PM 2 DAYLIGHT DRY CLEAR (AGAINST ne mutularie from the ene. This same is marked as a right full of onthine straight lane. V2 confinued straight (e/b) on Cumberland St. V1 attempted to make a left turn from his lane (straight or right and struck V2 in the intersection. V1 damage to the front left PEPORTARI I DISREGARDED OTHER CAR) imper and front left quarter panel. V2 damage to the right front or, right rear door, and right rear quarter pa ported or observed. Both vehicles CFBO. Both drivers pro OTH VEHICLE 1 AND VEHICLE 2 WERE NORTH. WHE PROPERTY EHICLE 2 WAS SLOWING FOR TRAFFIC. VEHICLE 1 REAR REAR END 143 35896123 9/17/2015 7:01:00 PM 2 DUSK DRY CLEAR DRIVER INATTENTION NORTH DAMAGE NDED VEHICLE 2 CAUSING SLIGHT DAMAGE TO BOTH outh on Clinton Avenue making a left onto Cumberland. Both AILURE TO YIELD RIGHT OF PROPERTY DARK-ROAL ehicles entered the intersection at same time at which point 144 35912276 9/22/2015 8:07:00 PM 2 DRY CLEAR SOUTH-EAST RIGHT ANGLE DAMAGE LIGHTED WAY ehicle 1 crashed into vehicle 2. Drivers of both vehicles claime herfore he uehirle at fault was unable to be determined while 1 was facing southbound in center lane of university) ave a main st facing a red light. Vehile 2 was adjacent to vehile 1 in southbound left lane of university ave at Main st. Both vehicles received a green light. Both vehicles attempted to turn eastbound n main st. During left turn, vehicles made contact with each other PROPERT 145 35900492 9/26/2015 9:38:00 AM 2 DAYLIGHT DRY CLEAR UNKNOWN SOUTH-EAST OVERTAKING ausing damage to both vehicles. Driver of vehicle 1 states it was DAMAGE adaining an alarmate to well are a driver of vehicle 2 driver states it was ehicle 2&apos.s fault and driver of vehicle 2 driver states it was ehicles 1&apos.s fault. Witness states vehicle 1 took turn too harp causing accident. Vehicles cared for by owners. Fault cou tot be determined as there was no markings to assist drivers in laving in lanes. No injuries. · WTNESS 1 DIMENTO, eh 1 was traveling north on the one way st., union st, in the rost lane. veh 2 was also north but in the middle lane. veh 1 DRIVER INATTENTION OVERTAKING 146 35904524 9/29/2015 8:19:00 PM 2 WET RAIN NORTH tempted to make a left turn on to university from the right most REPORTABLI LIGHTED ne into the path of veh 2 sideswiping it. op 1 admitted her RAVELING WEST BOUND ON EAST MAIN STREET SHE RAVELING WEST BOUNDON CAST MAIN STREET, SHE STOP AT THE RED LIGHT WHEN VEHICLE #1 REAR ENDED HER VEHICLE CAUSING DAMAGE TO THE REAR RIGHT BUMPER AND FENDER AREA. OPERATOR OF 147 35907839 10/1/2019 9:07:00 AM DAYLIGHT DRY CLEAR FOLLOWING TOO CLOSELY WEST EHICLE #1 STATES THAT HE WAS TRAVELING WEST DAMAGE SOUND ON EAST MAIN STREET SAW VEHICLE #2 STOP AT THE LIGHT HE STEP ON HIS BRAKES HIS
VEHICLE DID NOT STOP IN TIME AND HE REAR ENDED
VEHICLE #2 CAUSING DAMAGE TO VEHICLE #2 RIGHT NON-EPORTABL 1 operated by d1 rear ends v2 operated by d2 while they are bot

148

149

35907848

10/3/2019

5:10:00 PM

2

INJURY

DAYLIGHT

WET

DRY

RAIN

CLOUDY

FOLLOWING TOO CLOSEL'

NORTH

REAR END

opping at a red light at state st/allen st. no injures. vehicles cfbo hen (p) says that he was struck by (v1), driver of (v1) says that h as cameras on his vehicle and says that when he initially was

acking out (p) walked up and kicked the back of his vehicle then rew himself to the ground. (p) was transported to rgh with

TE 213 (9/79) ROUTE NO. OR STREET NAME MONRO P.I.N.: NOT APPLICABLE CASE No ADJACENT ROADWAY NETWORK TOWN FILE: CITY AT INTERSECTION WITH/OR BETWEEN: BY: PSC VILLAGE OF ROCHESTER DATE: 5/13/2020 SEE MAP TIME PERIOD FROM TO NVIRONMENTAL Roadway Surface Condition Daylight
 Daylight
 Dawn
 Dusk 1. Dry 2. Wet 3. Muddy 1. Clear 2. Cloudy 3. Rain se Codes from MV 104 (shown right) for these categories 8/1/14 7/31/19 4. Snow/lo 5. Dark Road Unlighted 5. Slush 5. Sleet/Hail/Freezing Rain 10. Other 6. Fog/Smog/Smoke lo. OF MONTHS 60 Ise Codes from MV 104 Police Report of VEHICLES DIRECTION DESCRIPTION REFERENCE CRASH No CASE No DATE TIME APPARENT CONTRIBUTING FACTORS EHICLE 2 AND VEHICLE 1 WERE WEST ON CUMBERLAND ST. WHEN AT NICLINTON AV BOTH VEHICLES WERE IN TH AR LEET LANE BOTH VEHICLES WERE TRYING TO MAKE AR LEFT LANE. BUTH VEHICLES WERE TRYING TO MAKE LLEFT TURN ONTO N CLUTTON AV. WHEN THE CARS IN FRONT OF VEHICLE 2 STOPPED FOR TRAFFIC THAT WAS ALSO TURNING LEFT. VEHICLE 1 REAR ENDED VEHICLE 2 NON 9:11:00 AM DRIVER INATTENTION WEST 150 10/13/2015 DAYLIGHT CLOUDY CAUSING SLIGHT DAMAGE. THERE WAS NO DAMAGE TO HICLE 1 AND NEITHER DRIVER WAS INJURIED. WITH A GREEN LIGHT. VEH 1 WAS AT A RED LIGHT FACING NORTH ON STATE AT ALLEN ST. AN UN INVOLVED VEH TO HER LEFT MOVED FORWARD LEADING HER TO BELIEVE THAT HER LIGHT HAD TURNED GREEN. SHE STARTED FORWARD INTO THE INTERSECTION WHILE STILL HAWNO THE RED LIGHT STRIKING VEH 2 CAUSING DAM AGE TO NON AILURE TO YIELD RIGHT OF RIGHT ANGLE 151 10/13/2015 4:16:00 PM DAYLIGHT DRY CLEAR NORTH BOTH VEHS. THERE IS ONE INDEPENDANT WITNESS OCCUMENTED. NO INJUIES - WITNESS 1 SULLIVAN 1) and (V2) were both traveling N/B on N Union St. (V1) wa hind (V2). (V2) began making a left had turn onto Lyndhurst S NON PASSING OR LANE USAGE nd (V1) attempted to pass it on the right. As (V1) drove around /2) it struck the rear right corner of (V2) causing damage to both 152 35959470 10/16/2015 4:08:00 PM DAYLIGHT WFT RAIN NORTH OVERTAKING EPORTABL IMPROPERLY bicles. No injuries reported. Photos taken... PREVAILURE OF VEHICLE #2 STATES THAT SHE WAS FRAVELING SOUTH BOUND ON UNIVERSITY AVE IN THE LEFT LANE, SHE MADE A RIGHT FROM THE LEFT LANE DID NOT SEE VEHICLE #1 TRAVELING SOUTH BOUND ON RIGHT TURN PROPERTY AILURE TO YIELD RIGHT OF INIVERSITY AVE IN THE RIGHT LANE CAUSING VEHILE I 153 36005908 10/18/2015 11:42:00 AM DAYLIGHT DRY CLOUDY SOUTH (WITH OTHER INVERSIT AVE IN THE RIGHT LAWE CAUSING VEHILE!

FIRIKE HER VEHICLE RIGHT REAR DOOR. OPERATOR OI

EHICLE #1 STATES THAT VEHICLE MADE A RIGHT TURN

ROM THE LEFT LANE IN FRONT OF HIS VEHICLE DAMAGE CAR) CAUSING HIS VEHICLE TO STRIKE VEHICLE #2 RIGHT T was driving s/b on n.clinton ave and making an e/b turn ont LEFT TURN NON-DARK-ROAD FAILURE TO YIELD RIGHT OF imberland st. V2 was driving n/b on n.clinton ave across imberland st. both vehicles had green lights. V1 ran into the 154 35935916 10/19/2015 8:00:00 PM 2 DRY CLEAR SOUTH EPORTAR LIGHTED OTHER CAR on left end of v2. Minor damage only. No injuries to report IEAD SOUTH ON N CLINTON. HE DID NOT MAKE THE PROPERTY GHT AND THEN ATTMEPTED TO BACK UP TO GET OUT 155 35934540 10/20/2015 9:28:00 AM DAYLIGHT WET CLOUDY BACKING UNSAFELY EAST REAR END DAMAGE THE INTERSECTION IN DOING SO HE STRUCK VEHICL VEHICLE 2 WAS JUST SITTING IN TRAFFIC WAITING FOR HE LIGHT IT THE ADOVE GAIE AND GIVE TRESPORE on the above date and time responded to the above address to in MVA. There the driver of V1 told me she was in the left lane raveling West on E. Main St. When she entered the intersection a . Union St. she misjudged the distance to V2 and her passenge NON-DRIVER INATTENTION OVERTAKING 156 35939263 10/26/2015 6:01:00 PM DUSK DRY CLEAR WEST nirror struck V2's driver side mirror causing it to break. I EPORTABLI nen spoke to the driver id V2 who lold me he was traveling West on E. Main in the right lane when V1's passenger mirror druck his driver side mirror. V2's mirror was cracked with 2 Stated while Waiting for the traffic light to change green V1 re NONded V2. D1 stated he was lost and could not find the highway FOLLOWING TOO CLOSELY 10/27/2015 DAYLIGHT CLEAR SOUTH REAR END 157 35939266 7:56:00 AM DRY to injuries reported at the scene. Both vehicles were cared by EPORTABLE - WITNESS 1 JORDAN, EDWIN V 632 PENNSYI VANI TERISEE 2 WAS 300 FFON TO NOTE 3 AT COMBERGATION ST SLOWING TO STOP FOR TRAFFIC. WHEN VEHICLE 1 ALSO SOUTH ON NORTH ST REAR ENDED VEHICLE 2 CAUSING SLIGHT DAMAGE. BOTH VEHICLES STOPPED TO NON-REPORTABLI DRIVER INATTENTION 158 2 DAYLIGHT SOUTH REAR END 35942907 10/28/2015 7:57:00 AM WET RAIN HECK THE DAMAGE AND EXCHANGE INFO. HOWEVER HE DRIVER OF VEHICLE 1 GOT BACK IN HER CAR AND FET THE SCENE THE DRIVER OF VEHICLE 2 FOLLOWED REPORT OF A MOTOR VEHICLE ACCIDENT. RO SPOKE WITH (V2) WHO STATED THAT AT ABOUT 1040 HOURS HE WITH (V2) WHO STATED THAT AT ABOUT TOWN HOURS HE WAS FACING NORTH ON UNIVERISTY AT E MAIN STREET STOPPED AT THE RED LIGHT. (V2) STATED THAT HE WA STRUCK FROM BEHIND BY (V1) WHO WAS ATTEMPTING CLEAR DRIVER INEXPERIENCE SOUTH REAR END 159 35978927 11/1/2019 10:40:00 AM DAYLIGHT DRY CHANGE LANES FROM THE MIDDLE LANE INTO THE IGHT TURNING LANE. THERE WERE NO INJURIES REPORTED BY FITHER PARTY AT THE TIME OF THIS EPORT AND NEITHER VEHICLE REQUIRED A TOW FROM WAS IN THE LEFT TURNING LANE EXTING IZ WAS IN THE LET I TOKNING JANCE EXTING THE VITERLOOP ONTO EAST MAIN STREET TO HEAD E/B ON EAST MAIN STREET AND VI WAS IN THE CENTER LANE VEXT TO VZ. BOTH VEHICLES PROCEEDED TO MAKE LEFT TURNS ONTO EAST MAIN STREET AND THIS IS WHEN EACH DRIVER STATES THE OTHER SWERVED INTO THE OTHER&ADDS:S LANE AND THUS CAUSED THE THE UTTERSAPPUSS LAIVE AND THUS CAUSED THE ACCIDENT. NO NUMERIES REPORTED. V1&apps;S
REGISTRATION WAS SUSPENDED FOR NO INSURANCE AND NONE COULD BE PROVIDED BY THE DRIVER OF V1 PASSING OR LANE USAGE IMPROPERLY NON-EPORTABLI 35954079 SOUTH-EAST OVERTAKING OR THE REGISTERED OWNER. DRIVER OF V1 LEFT WITH REGISTERED OWNER IN ANOTHER VEHICLE PRIOR TO RA COMPLETING ACCIDENT INVESTIGATION. TRAFFIC CITATIONS WERE ISSUED TO DRIVER OF V1 AT A LATER DATE. Tickets Issued: RASHUNN L SMITH Driver of vehicle

number (1) fickets: Ticket Number: W9U54ZGHBJ Violation: 509 Ticket Number: W9U54ZGHPJ Violation: 3191U Ticket Number:

TE	212	(0/70)

TE 213 (9/79)													
COUNTY:	MONROE		P.I.N.:	NOT APPLICA	BLE	ROUTE NO. OF					CASE No.:		
	TOWN		•			ADJACENT RO					FILE	PSC 5/13/2020	-
	CITY VILLAGE OF	ROCHESTER				AT INTERSECT	TION WITH/OR	BETWEEN:			DATE	PSC 5/13/2020	-
TIME PERIOD		FROM: TO: ENVIRONMENTAL: Use Codes from MV 104 (s at right) for these categories				SEE MAP Light Conditions: 1. Daylight 2. Dawn 3. Dusk 4. Dark Road Lig 5. Dark Road Ur	ghted	Roadway Surface 1. Dry 2. Wet 3. Muddy 4. Snow/Ice 5. Slush 10. Other	te Condition: Weather: 1. Clear 2. Cloudy 3. Rain 4. Snow 5. Sleet/Hall/Fre 6. Fog/Smog/Sr 10. Other				
No. OF MONTH	HS:	(50	S							¹ Use Codes from	MV 104 Police Report	
CRASH No.	CASE No.	DATE	TIME	No. of VEHICLES	SEVERITY	CONDITIONS	ROADWAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING FACTORS	DIRECTION	TYPE ¹	DESCRIPTION	REFERENCE MARKER
161	35959905	11/4/2015	2:05:00 PM	2	NON- REPORTABLE	DAYLIGHT	UNKNOWN	UNKNOWN	TURNING IMPROPER	SOUTH-WEST	OVERTAKING	us casto potice z upgs and in energipticals. See exponent unit lives a round Zipm and she was going to out concerning thild support. She was slopped at the light on cumberland stat st paul st and in the lane next to her to her right was a red pick up that was browing a whith eatile. 2d said they her began to turn led ontso paul st and v1 sideswiped v2 with the white trailer. d2 said that v1 was in a lane that was not a brring lane. after the crash, v1 confinence on st pauls v2 v2 turned right ofton andrews st because she had court, after court, d2 called her insurance who lold her to	
162	35964899	11/12/2015	9:23:00 PM	1	NON- REPORTABLE	DARK-ROAD LIGHTED	WET	RAIN	TURNING IMPROPER	SOUTH	OTHER	Officer make a settum or cumbertand St to head south on clinton Av. Driver drove up on the sidewalk and struck a fire hydrant, breaking it off at the ground level. The sidewalk in this portion of the road is lowered, for access to a parking lot and the roadway is at an angle. The driver claimed the rain combined with the darkness make it dilificall has see he mad.	
163	35997094	11/18/2015	6:15:00 PM	2	PROPERTY DAMAGE AND	DARK-ROAD LIGHTED	DRY	CLOUDY	TRAFFIC CONTROL DEVICES DISREGARDED	NORTH	RIGHT ANGLE		
164	35977660	11/20/2015	9:39:00 AM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLOUDY	FOLLOWING TOO CLOSELY	WEST	REAR END	VZ WAS STUPPEU IN TRAFFIC FACING WIB ON CUMBERLAND ST AT WESTCOTT. VI WAS TRAVELING WIB ON CUBMERLAND AND FALED TO STOP, REAR ENDING VZ CAUSING MINOR DAMAGE. VI DID LEAVE THE SCENE, HOWEVER DE GOTORECT NY-FTEP950. THIS CAR WAS BROADCAST BUT COMES BACK OUT OF TOWN AND UNABLE TO LOCATE OR RECORDED THE STAFF THE STEAM OF THE STAFF THE ST	
165	35976851	11/21/2015	12:45:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLOUDY	FOLLOWING TOO CLOSELY	NORTH	REAR END	IN SIGNATURE IS THE STORM CHAPLE OF THE STORM OF THE STOR	
166	35984239	11/23/2015	11:52:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	SNOW/ICE	CLOUDY	PAVEMENT SLIPPERY	NORTH	REAR END	VERICLE 2 AND VERICLE I WERE BUT IN OKT HOW NORTH ST. WHEN VERICLE 2 WAS SLOWING TO STOP FOR TRAFFIC. VEHICLE 1 TRIED TO STOP AS WELL BUT HIT A PATCH OF SNOWICE THUS SLIDING INTO THE BACK OF VEHICLE 2 CAUSING DAMACE TO ROTH VEHICLE 5.	
167	35997113	11/30/2015	7:26:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLOUDY	DRIVER INATTENTION	EAST	OVERTAKING	WEHICLE 2 WAS IN THE LEFT TANK HEADING FAST ON CUMBERLAND ST AT N CLINTON AV. WHEN VEHICLE 1 ALSO EAST ON CUMBERLAND ST IN THE RIGHT LANE. TRIED TO MAKE A LANE CHANGE INTO THE LEFT LANE HITTING VEHICLE 2&opos. S PASSENGER SIDE CAUSING DAMAGE	
168	35997168	12/1/2015	4:20:00 PM	2	NON- REPORTABLE	DUSK	WET	CLEAR	DRIVER INATTENTION	NORTH	OTHER	The driver of V1 sheld she was driving North on Sales st. She sheld she was not sure if the Taffic light was greated when she went through the intersection of Sales St and Allein St. Driver of V1 struck V2 as V1 drove through the intersection. Driver of V2 sheld she was driving East on Allein St. She shalled she had the Green light and drove brough the intersection of Allein St and Sales St. V2 drove brough the intersection and V1 struck the car. V1 had damage to the front bumper. V2 had damage the passenger side front door. Neither vehicle was towed and no one was injured.	
169	36030881	12/2/2015	9:02:00 PM	2	PROPERTY DAMAGE AND INJURY	DARK-ROAD LIGHTED	DRY	CLEAR	FAILURE TO YIELD RIGHT OF WAY	WEST	RIGHT ANGLE	VT was taveling who on Lyndhurst st.coming to the intersection of lyndhurst and north st. Vaws taveling nb on north st. VT, who had the stop sign, failed to yeld to v2 strking v2 as she entered the intersection, both passengers had complaint of pain and were stransported to strong hospital (rig #5 7679, 7619). Both cars	
170	36000727	12/6/2015	2:02:00 AM	2	NON- REPORTABLE	DARK-ROAD LIGHTED	DRY	CLEAR	ALCOHOL INVOLVEMENT	EAST	OVERTAKING	Vehicle #2 was taveling Eastbound of the inner loop when Vehicle #1, also taveling Eastbound switched lanes and bruck Vehicle #2 causing above said damage. During the course of the investigation. Driver of Vehicle #1 attempted to leave the scene, causing RO to pull the driver over East of the intersection of the MVA. Driver of Vehicle #1 was arrested for DVM WITNESS 1 COLLETTI, AARON 185 EXCHANCE BLVD ROCHESTER NY 1841 48584/28901 Sex5429801 Ticket Susued. ABSENCE STEVENSON Driver of vehicle number (1) tickets. Ticket Number: 7980532KIAV Volation: 11923 Ticket Number: 7980532KIAV Volation: 11941 Bit Licket Number: 798053XIAV Volation: 11941 Bit Li	
171	36000731	12/6/2015	7:08:00 AM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLOUDY	FALURE TO YIELD RIGHT OF WAY	EAST	OVERTAKING	DEPENDING OF VERIFICE 22 STATES THAT THE WAS TRAVELING EAST BOUND ON UNIVERSITY AVE, HE WAS NFRONT OF VERIFICE #1 THE TWO LANES BECOME ONE LANE, HE MERGE INTO THE ONE LANE WHEN VEHICLE #1 STRUCK HIS VEHICLE LEFT REAR QUARTER PANEL AND DOOR AREA OPERATOR OF VEHICLE #1 STATES THAT HE WAS ALSO TRAVELING EAST BOUND ON UNIVERSITY AVE. WHEN VEHICLE #2 MERGE INTERONT OF HIS VEHICLE #3 STATES THAT HE WAS ALSO TRAVELING EAST BOUND ON UNIVERSITY AVE. WHEN VEHICLE #3 MERGE INTERONT OF HIS	
172	36002536	12/7/2015	10:00:00 AM	2	PROPERTY DAMAGE AND	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	NORTH	REAR END		
173	36005190	12/8/2015	2:20:00 PM	2	INJURY	DAYLIGHT	DRY	CLEAR	OTHER (VEHICLE)	EAST	REAR END	On 12/08/2015 at about 1420 hours, V1 and V2 were both e/b E Main Stal University Ave stopped at a red traffic light. V2 was intort of V1. Driver of V1 states he had been stopped, but had so stopped of of the break pedd, causing V1 br ord into V2. Passenger of V2 complained of pain to her elbow, which , she stated was subsiding. Passenger of V2 refused medical. No other injuries were reported or descrived. Driver of V2 reduces the ear emmor scalf marks to her ear bumper. Driver of V2 noded there are scrakehs to the top of the rear bumper which were there prior to the acident. Driver of V1 states there is no damage to his collection. Both whitevs were given an Acident Exchange. Sign. Both vehicles V1 was so on so also and V2 was sho no so to six V1 was stiff the safe V1 was 50 on so so shall V2 was 50 on so so six V1 was 50 on so so shall V2 was 50 on so so six V1 was 50 on so six V1 was	
174	36003798	12/8/2015	4:28:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	FAILURE TO YIELD RIGHT OF WAY	SOUTH	LEFT TURN (AGAINST OTHER CAR)	straight firrough the intersection and v2 was making a left hand lurn. when v2 started her left hand lurn she struck the left rear of v1 with the font left of v2. no injuries reported. both drivers id&apos.d bu valid mostil.	

ROUTE NO. OR STREET NAME MONRO P.I.N.: NOT APPLICABLE CASE No ADJACENT ROADWAY NETWORK TOWN FILE: CITY AT INTERSECTION WITH/OR BETWEEN: BY: PSC VILLAGE OF ROCHESTER DATE: 5/13/2020 SEE MAP FROM NVIRONMENTAL TIME PERIOD TO se Codes from MV 104 (shown 1. Daylight right) for these categories 2. Dawn 3. Dusk 1. Dry 2. Wet 3. Muddy 1. Clear 2. Cloudy 3. Rain 8/1/14 7/31/19 4. Snow/lo 4. Snow 5. Sleet/Hail/Freezing Rain 5. Dark Road Unlighted 5. Slush 10. Other 6. Fog/Smog/Smoke lo. OF MONTHS 60 Jse Codes from MV 104 Police Report of VEHICLES DIRECTION DESCRIPTION REFERENCE SOADWAY URFACE ONDITION CRASH No CASE No DATE TIME APPARENT CONTRIBUTING FACTORS HICLE LAND VEHICLE 2 WERE BOTH WEST ON CUMBERLAND ST. WHEN AT THE LIGHT WITH JOSEPH AV OTH VEHICLES WERE MAKING A RIGHT TURN. VEHICLE SLOWED WHILE MAKING THE TURN AND VEHICLE 1 NON 10:12:00 AM DAYLIGHT DRIVER INATTENTION 36038923 CLEAR WEST REAR END REAR ENDED VEHICLE 2. THUS CAUSING DAMAGE TO OTTHE VEHICLE'S Innertoop crossing over twain star continue on niversity Ave heading southbound in lane 1 of traffic with a steat een light. Vehicle 1 was slopped on Main stat a solid red light a the intersection of University ave in curb lane of westbound Main safe.

affic. Vehicle 1 decided to turn right on red at the light to head builbound on University ave. Vehicle 1's intended goal as to turn into the curb lane of southbound University Ave. RIGHT TURN NON AILURE TO YIELD RIGHT OF 176 36014904 12/14/2015 9:30:00 AM DAYLIGHT DRY CLEAR SOUTH-EAST hicle 1 did not negotiate turn correctly and entered lane one of outhbound University Ave and struck vehicle 2 as he went rough the intersection. Minor damage to both vehicles. No Vehicle 1 (v1) and Vehicle 2 (v2) were both driving east on numberland st approaching a green light. The light turned from green to yellow and (v2) stopped before the light reached red. (v1 hich was behind (v2), struck (v2) because (v1) was following to dosely. (v1) initially pulled over, but when (v2) called the police v1) fled the scene without exchanging information. Officers onducted an investigation at (v1) home where the vehicle was NON DARK-ROAF 177 36072602 12/18/2015 2-27-00 AM DRY CLEAR FOLLOWING TOO CLOSELY WEST REAR END LIGHTED cated and found to have minor front bumper damage, consiste with the minor damage to the rear bumper of (v2). The residents v1) address were not cooperative with investigation and it was unable to be determined who was driving (v1).
weh 1 and veh 2 were both traveling e/b on cumberland st. veh are occupying the inside left turn only(n/b) lane, veh 2 was the hiddle lane that has the option of turning left(n/b) or confinuing traight, veh 1 continued straight forward and veh 2 made a left NON-DARK-ROAL PASSING OR LANE USAGE 178 36030886 12/18/2015 6:48:00 PM DRY CLEAR FAST OVERTAKING REPORTABLE LIGHTED IMPROPERLY PROPERT 179 36028628 12/27/2015 9:02:00 AM 2 DAYLIGHT WET RAIN FOLLOWING TOO CLOSELY SOUTH REAR END DAMAGE In 12/27/2015 at about 1711 hours V2 was e/h Cumberland S on 122/12013 at about 1711 floors v2 was enr Cumberlant os stopped at the red traffic light at N Climbon Ave stopped at the left lane. V1 was e/b Cumberland St at N Climbon Ave stopped at the red traffi light at N Climbon Ave in the center lane. When the traffic light med green, V2 began to proceed straight through the LEFT TURN tersection, which is not prohibited. Driver of V1 states he though NON DARK-ROAD uesscuori, which is not pointwise. Drive of V i states he bodgin e left lane was a left turn only lane and began to make a left turn om the centre lane, striking V2 in the intersection. Driver of V1 build not find any damage to (V1). Front right passenger of V1 tales she thought only the mirrors of both vehicles made contact. 180 36030901 12/28/2015 5:11:00 PM DRY CLOUDY TURNING IMPROPER NORTH-FAST (AGAINST OTHER CAR) REPORTABL LIGHTED river of (V2) states she did not see damage to her vehicle, but anted a police report. Both vehicles cared for by owner. No wanted a police report. Both vehicles cared for by owner. No migries reported or observed. Both drives provided an Acident On January 1st, 2016 at approx. 0217 hours VI was traveling northbound on State Street with a circular green light giving him th hight of way. V2 was traveling westbound on Allen Street with a circular red fight. V2 stated that he was distracted by the people inside of his vehicle that were having an argument. V2 stated that the ran through the red light and caused the accident. V1 stated nat because of the blind corner he did not see V2 until it was to la had because of the bind to content the bind seer Vz. Unlin threats to and did strike Vz. V1 would not have been able to see V2 pproaching the intersection due to the blind view of Allen Street and there for would not be able to predict or anticipate V2&apos: pproach. V2 also admitted to consuming alcohol prior do the /IEW OBSTRUCTED/LIMITED PROPERTY DARK-ROAD cident. V2 did submit to a roadside prescreen which did show 181 36114747 1/1/2016 2:17:00 AM DRY CLEAR TRAFFIC CONTROL DEVICES NORTH RIGHT ANGLE inducin. V2 dui soutin de l'acesse préseree inventir du sirovi he presence of alcohol in V2's system. V2 stated that he led from the scene because he did not have a valid driver&apos icense and that V2 knew that it was suspended. Lt. Colletti did DAMAGE LIGHTED DISREGARDED observe V2 flee from the scene in his vehicle and did initiate a traffic stop at the intersection of White St. and N. Plymouth Ave. V. was issued multiple V&.T traffic ficket violations and was issued an appearnce ficket for January 14, 2016 at 0930 hours. Tickets Issued: TIMOTHY D COLLINS Driver of vehicle number (2) fickets: Ticket Number: VM0155TNLF Violation: 5111A Ticket ımber: VM0155TNB0 Violation: 5091 Ticket Number: VM0155TNMQ Violation: 6001A Ticket Number: VM0155TNLF Violation: 1110A Ticket Number: W9U556C4M6 Violation: 1163D V1 was fleeing from W1 who is a police officer with the Rochester Volice Department operating in uniform in a marked patrol vehicle with emergency lights and sirens activated (261 Fleet # 151300). It had left the scene of a personal injury accident that occurred a 60 Murray St (CR # 15-000790). V1 had fied Northbound on Murray St, Eastbound on Lyell Ave, Southbound on State St and RAFFIC CONTROL DEVICES DARK-ROAL 182 36040425 1/1/2016 8:14:00 PM 2 AMAGE AND DRY CLOUDY SOUTH RIGHT ANGLE roceeded through multiple solid red signals on State St before LIGHTED DISREGARDED INJURY triking V2 on State Stat Allen St. - WITNESS 1 LINDAUER. JEREMY 185 EXCHANGE BLVD ROCHESTER NY 14614 5854289810 Tickels Issued: EDMUND C REYNOLDS Driver ehicle number (1) tickets: Ticket Number: S5KQ55X90J olation: 3752A1 Ticket Number: S5KQ55X8RN Violation: 1212 cket Number: S5KQ55X7H7 Violation: 1111D1 Ticket Number h1 was travel w on cumberland st when he attempted to make right turn into the parking lot heading nw. veh2 was parked facing PROPERTY 1/4/2016 10:40:00 AM DAYLIGHT SNOW/ICE CLEAR DRIVER INATTENTION NORTH-WEST REAR END 183 36045007 vb in the parking lot. veh1 struck veh2's rear driver side DAMAGE mper causing minor damage. veh1 sustained damage to his of center bond and humper HICLE TAND VEHICLE 2 WERE BUTH EAST ON IERIALE I AND VERLLE ZWERE BOTH EAST OW JUMBERLAND ST. VEHICLE ZWAS IN THE LEFT LANE ND VEHICLE 1 WAS IN THE RIGHT LANE. VEHICLE 2 WAS JAKING A LEFT TURN ONTO N CLINTON AV. WHEN PROPERTY PASSING OR LANE USAGE 1/11/2016 12:13:00 PM 2 DAYLIGHT DRY CLEAR NORTH EHICLE 1 ALSO TRIED TO MAKE A LEFT TURN FROM THI 184 36075939 AMAGE AND (AGAINST OTHER CAR) IMPROPERLY INJURY RIGHT LANE. THUS TURNING IN FRONT OF VEHICLE 2 ND THEY MADE CONTACT WITH EACH OTHER, CAUSING AMAGE TO BOTH VEHICLES AND VEHICLE 28:

TE 213 (9/79)

TE 213 (9/79) ROUTE NO. OR STREET NAME MONRO P.I.N.: NOT APPLICABLE CASE No ADJACENT ROADWAY NETWORK TOWN FILE: CITY AT INTERSECTION WITH/OR BETWEEN: BY: PSC VILLAGE OF ROCHESTER DATE: 5/13/2020 SEE MAP NVIRONMENTAL TIME PERIOD FROM TO Roadway Surface Condition Daylight
 Daylight
 Dawn
 Dusk 1. Dry 2. Wet 3. Muddy 1. Clear 2. Cloudy 3. Rain se Codes from MV 104 (shown right) for these categories 8/1/14 7/31/19 4. Snow/lo 4. Snow 5. Sleet/Hail/Freezing Rain 5. Dark Road Unlighted 5. Slush 10. Other 6. Fog/Smog/Smoke lo. OF MONTHS 60 Ise Codes from MV 104 Police Report of VEHICLES DIRECTION DESCRIPTION REFERENCE ROADWAY SURFACE SONDITION CASE No CRASH No DATE TIME APPARENT CONTRIBUTING FACTORS oth Unit One and Unit Two were EB starting in traffic at cumberland st/ N.Clinton when Unit One rear ended Unit Two 36052119 1/12/2016 1:04:00 PM DAYLIGHT FOLLOWING TOO CLOSELY EAST 185 2 WE1 CLEAR REAR END finor damage, no injuries. 1 states that V1 operated by d1 was rear ended by v2 operated y unknown d2 on state st approaching its intersection with allen st 1 stated that v2 then fled the scene. I attempted to locate v2 or d2 NON DARK-ROA 36130774 1/15/2016 5:16:00 PM FOLLOWING TOO CLOSELY 186 CLOUDY SOUTH REAR END LIGHTED II the r/o of v2&apos s address with pegalive results /EHICLE 2 WAS WEST ON CUMBERLAND ST WITH A REEN LIGHT AT THE INTERSECTION WITH JOSEPH AV PROPERTY RAFFIC CONTROL DEVICES 12:06:00 PM WHEN VEHICLE 1 WHICH WAS NORTH ON JOSEPH AV RAY THE RED LIGHT AT CUMBERLAND ST. THUS GOING INTO 187 36075944 1/16/2016 DAYLIGHT DRY CLOUDY NORTH RIGHT ANGLE DISREGARDED THE PATH OF VEHICLE 2. Veh 2 was traveling north on Scio St. and was stopping at the rec ight at the intersection of Lyndhurst St. Veh.2 slid to the right due to ign at one lines section to Eyndrium's 2. Veriez sind one ingit index he icy pavement. Veh.1 was haveling behind Veh. 2 also North on Scio St. Veh.1 altempted to stop but also slid to the right due to the cy pavement and struck Veh. 2. Veh.1 also struck the curb with its NON 188 36064132 1/21/2016 9:30:00 AM DAYLIGHT SNOW/ICE SNOW PAVEMENT SLIPPERY NORTH OVERTAKING EPORTABL oht front fre causing damage to the rim. eh 1 and veh 2 were at the cumberland st and n. clinton ave ntersection awaiting a green light to make a n/b turn onto n. clinto NON DARK-ROAL PASSING OR LANE USAGE e, veh 1 was positioned in the southern lane on cu 189 36073211 1/23/2016 6:42:00 PM WFT CLOUDY NORTH-FAST OVERTAKING and veh 2 was in the northern lane, as veh 2 made the n/b turn teh 1 attempted to pass veh 2 and crashed into the front right REPORTABL LIGHTED IMPROPERLY o veh 2 O V2 WERE BOTH TRAVELING EASTBOUND ON MAIN ST. V2 WAS IN THE TURNING LANE, AND V1 NON DARK-ROAD TTEMPTED TO MOVE INTO THE TURNING LANE 190 36072609 1/24/2016 3:19:00 AM DRY CLOUDY UNSAFE LANE CHANGE FAST OVERTAKING REPORTABLE LIGHTED ESUILTING IN THE LEFT SIDE OF V1 STRIKING THE RIGH IDE OF V2. THE DRIVER OF V1 CLAIMED SHE DID NOT F V2 was traveling WB on E. Main Street in the middle lane of trat V1 was exiting the driveway to Delta Sonic located at 718 E. Main St. Driver of V1 stated that an uninvolved vehicle had stopped to ke her out of the business driveway. Driver 1 Stated that it appeared as if V2 had attempted to merge lanes into the most northern lane of E. Main st. When V1 was exiting Delta Sonic, she did hit V2 in FAILURE TO YIELD RIGHT OF NON ne passenger front door causing damage. Damage to V1 SOUTH-WEST RIGHT ANGLE 191 36067512 1/25/2016 4:51:00 PM DAYLIGHT WET CLEAR passing in low local causing durings. Damlags or VY mosisled of the driver side headlight/bumper. Driver of V2 stated at she had been traveling in the middle lane, going straight, and dn&apost see V1 until it was loo late and there was nothing she REPORTABLI VAY, DRIVER INEXPERIENCE could do because she was in the middle lane and there was traffic on her other side. Driver 2 stated she had not been attempting to ange lanes. No injuries to any party. Driver of V2 was cited for unlicensed operation for having a VAIID permit only with no On 01/30/2016 I met with the driver of V1. Driver of V1 was able larify the accident. Driver of V2 was e/b Cumberland St at N Clinton Ave in the left lane. Driver of VI was elb Cumberland St at N Clinton Ave in the center lane. Both vehicles were stopped at a red light. When the light turned green, allowing elb Cumberland St taffic to move, driver of VI states V2 "hesitated" and VI ulled forward into the intersection and began a left turn to head n N Clinton Ave. Driver of V2 pulled forward into V1. Driver of V2 i Callioni Ave. Direc in V2 pulses accessed into V1. Direct in V2 and been planning to head e/b Cumberland St b Joseph Ave, an en make a left turn on to Joseph Ave to head n/b. The letersection of e/b Cumberland St at N Clinton Ave is on the south de of the inner loop and has three e/b lanes. About 100 feet eas NON-DARK-ROAL TURNING IMPROPER 192 36069076 1/26/2016 6:07:00 PM DRY CLOUDY NORTH-WEST (AGAINST f that intersection is the intersection of Cumberland St and Joseph REPORTABLE LIGHTED what intersection is the linesection to Cultifushard state and Joseph Wee. There is no signage at the intersection of Cumberland Ste/b at N Clinton Ave denoting which turns are or are not permitted. The traffic control signs at Cumberland Ste/b at Joseph Ave has OTHER CAR)

PROPERT

DAMAGE

EPORTABL

DAYLIGHT

DAYLIGHT

WET

DRY

SNOW

CLOUDY

WEST

WEST

IMPROPERLY

AILURE TO YIELD RIGHT OF

WAY

OVERTAKING

REAR END

4:17:00 PN

4:15:00 PM

193

194

36073851

36084483

1/29/2016

1/31/2016

TE 213 (9/79)													
COUNTY:	MONROE		P.I.N.:	NOT APPLICATE	BLE		R STREET NAM			CASE No.: FILE: BY: PSC DATE: 5/13/2020			
	TOWN		-				ADWAY NETW				FILE:		
	CITY VILLAGE OF	ROCHESTER				AT INTERSECT	TION WITH/OR	BETWEEN:			BY:	PSC 5/13/2020	-
TIME PERIOD		FROM: 8/1/14	TO: 7/31/19	ENVIRONMEN Use Codes from at right) for these	MV 104 (shown categories	SEE MAP Light Conditions: 1. Daylight 2. Dawn 3. Dusk 4. Dark Road Lig 5. Dark Road Ur	ghted	Roadway Surface 1. Dry 2. Wet 3. Muddy 4. Snow/Ice 5. Slush 10. Other	ce Condition: Weather: 1. Clear 2. Cloudy 3. Rain 4. Snow 5. SleetHallFre 6. Fog/Smog/Sr 10. Other				-
No. OF MONTH	IS:		60	S					IU. Olner		¹Use Codes from	MV 104 Police Report	
CRASH No.	CASE No.	DATE	TIME	No. of VEHICLES	SEVERITY	CONDITIONS	ROADWAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING FACTORS	DIRECTION		DESCRIPTION	REFERENCE MARKER
195	36109197	2/7/2016	12:01:00 AM	2	PROPERTY DAMAGE	DARK-ROAD LIGHTED	UNKNOWN	UNKNOWN	BACKING UNSAFELY	NORTH-EAST	RIGHT ANGLE	THE PARKED FAUNCS SIZE AT CAS PUMM FAIL OF ASADOS FAST TRACEAGORS. WEH BACKS UP STRIKHIGU SEHZ AND THEN FLEES NIB ON N. UNION ST. INSURANCE FOR VEHZ IS & ADDOS ANTIONAL CENTERAL INSURANCE, CODE OF ASADOS ON SIZE OF THE STRIKE OF THE SIZE OF T	
196	36090454	2/8/2016	11:45:00 AM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLOUDY	OTHER (VEHICLE)	NORTH	REAR END	DISKEPEN-KSALLE'YE (TAL'OB'FIAS'HE WAS STOPPEU AT THE LIGHT ON JOSEPH AVE, AT CUMBERLAND ST, WHEN HIS VEHICLE WAS STRUCK FROM BEHIND BY VEHICLE I. VEHICLE 2 WAS FACING NO BAT THE LIGHT. VEHICLE 2 SUSTAINED VERY MINOR DAMAGE. BOTH THE DRIVER OF VEHICLE 2 AND HIS PASSENGER COMPLAINED OF VERY MINOR BACK PAIN, AND BOTH FRUSED AND AMBULANCE. DRIVER OF VEHICLE ONLY HAD A VALID NYS PERMIT, AND THE PASSENGER ONLY HAD A VALID NYS PERMIT, AND THE PASSENGER ONLY HAD A VALID NON NYS DRAWER OF VEHICLE 2 SUSUED A UTT FOR UNILCENSED OPERATOR DRIVER OF VEHICLE 2 STATED THAT SHE WEN'T TO STOP, BUT DO NOT HIT HER BRAKES IN TIME, WHICH CAUSED HER TO STRIKE VEHICLE 2 WHICH WAS STOPPED AT THE LIGHT. DRIVER OF VEHICLE 1 WAS STRAYELING BON JOSEPH AVE. DRIVER OF VEHICLE 1 STATED SHE NOR HER DRIVER OF V	
197	36098418	2/11/2016	11:10:00 AM	2	NON- REPORTABLE	DAYLIGHT	SNOW/ICE	SNOW	DRIVER INATTENTION	NORTH	REAR END	PASSEMER MAS NOT BUILDED VERY WINDER DAMAGE TO VEHICLE? WAS NORTHBURDED VIES PER MAGE TO STOPPED AT A RED LIGHT AT THE INTERSECTION OF CUMBERLAND ST. VEHICLE 2 APPROACHED THIS NTERSECTION, NORTHBURDID ON JOSEPH AVENUE, AND FALED TO STOP. VEHICLE 1 STRUCK VEHICLE 2 IN THE DEED.	
198	36095820	2/11/2016	4:48:00 PM	4	NON- REPORTABLE	DAYLIGHT	SNOW/ICE	SNOW	VIEW OBSTRUCTED/LIMITED	NORTH	RIGHT ANGLE	The accident occurred in a Police Vehicle owned and operated by the Rochester Police department while responding to an emergency. the RPD fleet number for (x2) is 1213 and was being operated by officer Bostick with Officer Hasper as the forst parasepases of (x2). VI was traveling NIB on north s1 in the far east lane of traffic. (x2) was sioning SIB on North S1 attempting to make a EIB turn on by Johnthus S1. Pre (x2) There was a large volume of traffic. Fat was shopped in both north-south direction. There was an unimbored Fuck traveling NIB flat was shopped in taffic that left a gap for (x2) to make the EIB turn onto Lyndhurst st, the unimobred fluck traveling NIB flat was shopped in taffic that left a gap for (x2) to make the EIB turn onto Lyndhurst st, (v1) passed the unimobred vehicle in the right lane and struck (x2), there were no unimoted vehicle in the right lane and struck (x2), there were no injuries not concluded of pairs by any profiles involved. (v1), when we have the value for the water norund. (£1) was found to not have a valet NYS.	
199	36094290	2/12/2016	7:50:00 AM	2	NON- REPORTABLE	DAYLIGHT	SNOW/ICE	CLOUDY	PAVEMENT SLIPPERY	NORTH	REAR END	behind veh. 2 and attempted to stop but slid on the icy pavement	
200	36102277	2/14/2016	10:29:00 AM	1	PROPERTY	DAYLIGHT	SNOW/ICE	CLEAR	TURNING IMPROPER	EAST	OTHER	and struck veh. 2.	
201	36115375	2/14/2016	3:00:00 PM	1	DAMAGE PROPERTY	UNKNOWN	UNKNOWN	UNKNOWN	UNKNOWN	UNKNOWN	OTHER		
202	36102294	2/16/2016	12:54:00 PM	2	DAMAGE PROPERTY	DAYLIGHT	SNOW/ICE	SNOW	PAVEMENT SLIPPERY	NORTH	RIGHT ANGLE		
203	36101298	2/17/2016	3:42:00 PM	2	NON- REPORTABLE	DAYLIGHT	WET	SNOW	FAILURE TO YIELD RIGHT OF WAY	SOUTH		A was a reasing southcould in the right utiling pare to fit. Custom SI to fur we shound onto Cumberland SI. VI was also I series outhbound in he lane to he let of V2. VI then entered the right furn lane and did not see V2. VI stuck the driver side door with her passenger side door caving damage to he same. The operator of VI admitted that she did not see V2 before she changed lanes. The Operator of V2 currently has a suspended drivers license. The operator of VI was issued a UTIT for failure to yield. The operator of V2 was Sued a UTIT for interested V2 was Sued a UTIT on interested.	
204	36121240	2/18/2016	10:00:00 PM	2	PROPERTY DAMAGE	DARK-ROAD LIGHTED	WET	CLOUDY	DRIVER INATTENTION	SOUTH	RIGHT ANGLE	WAY. VI WAS UNABLE TO STOP IN TIME AT THE INTERSECTION OF UNINERSITY AVE AND STRUCK V2 AS V2 WAS TRAVELING WEST ON UNIVERSITY AVE. DRIWER OF V2 SAID SHE WAS CONFUSED WITH THE STREET DIDECTION AFTER SHELLET A BUISDIESS NEADRY	
205	36104604	2/20/2016	1:51:00 PM	2	NON- REPORTABLE	DAYLIGHT	WET	CLEAR	TURNING IMPROPER	EAST	LEFT TURN (AGAINST OTHER CAR)	On the above date and time, Vz was eth Cumberland SI approaching he intersection of Cumberland SI and SI Paul SI in the center lane. The center lane is marked both on the roadway and with a sign for vehicles in that lane to 1 vavel straight or make a right turn. VI was in the left lane even by Cumberland SI approaching SI Paul SI. That lane is marked on the roadway for straight (eth) or left turn, rib). There of VZ states he achiedath St sur Singlat to turn in the View of VZ states he achiedath St sur Singlat burn let on to SI Paul SI (n/ti), began his left turn and struck VI, who was traveling eith Druchy the intersection. No highlies reported or discovered. VI of damage to high front quarter panel. VZ damage to left front quarter panel and left front door. Bish drivers of some an Accident Exchannes Silla. Both vehicles were cared for for	
206	36110904	2/24/2016	3:03:00 PM	2	NON- REPORTABLE	DAYLIGHT	WET	RAIN	TRAFFIC CONTROL DEVICES DISREGARDED	SOUTH	LEFT TURN (AGAINST OTHER CAR)	given an Accident Exchanne Silo. Both vehicles were cared for by 0x0024/2016 at board 1930 haven police were dispatched to E Main S1 and University Ave for the reported MVA. Driver of V1 states she was not henred top of 18 map at E Main S(SIB) in the let late. The left lane is marked with signs for a left turn (eb E Main S) only. Driver of V2 states she was on them Loop Off Examp (sh) at EM mil Si in the centre frame. The centre lane is marked with signs for left turn (eb E Main S) on stagistic late in the sign of the stage of the sign of t	

TE 213 (9/79) ROUTE NO. OR STREET NAME MONRO P.I.N.: NOT APPLICABLE CASE No ADJACENT ROADWAY NETWORK TOWN FILE: CITY AT INTERSECTION WITH/OR BETWEEN: BY: PSC VILLAGE OF ROCHESTER DATE: 5/13/2020 SEE MAP FROM NVIRONMENTAL TIME PERIOD TO Roadway Surface Condition Daylight
 Daylight
 Dawn
 Dusk 1. Dry 2. Wet 3. Muddy 1. Clear 2. Cloudy 3. Rain se Codes from MV 104 (shown right) for these categories 8/1/14 7/31/19 4. Snow/lo 4. Snow 5. Sleet/Hail/Freezing Rain 5. Dark Road Unlighted 5. Slush 10. Other 6. Fog/Smog/Smoke lo. OF MONTHS 60 Ise Codes from MV 104 Police Report of VEHICLES DIRECTION DESCRIPTION REFERENCE ROADWAY SURFACE SONDITION CRASH No CASE No DATE TIME APPARENT CONTRIBUTING FACTORS HICLE 2 WAS AT THE LIGHT ON CUMBERLAND ST OSEPH AV HEADING WEST. WHEN THE LIGHT TURNED FREEN VEHICLE 2 STARTED TO GO. THATS WHEN DDODEDTY 36112871 9:10:00 AM DRIVER INATTENTION DAYLIGHT CLOUDY WEST REAR END DAMAGE REEN VEHICLE 2 STARTED TO GO. THATS WHEN EHICLE 1 REAR ENDED VEHICLE 2 CAUSING DAMAGE TO op. I met with the driver of V1. He stated he was driving West or ie inter-loop in the right lane. He stated he realized he et in the lane for 490 East. As the driver of V1 went to change nes, he struck V2. Driver of V2 stated he was driving West on the ter-loop. He stated he was in the lane for 490 East bound wher NON PASSING OR LANE LISAGE 208 36129673 3/4/2016 2:35:00 PM DAYLIGHT DRY CLEAR WEST OVERTAKING ne driver of V1 changed lanes and struck his car. V1 had damag to the left front hubcap and just above the fire. V2 had damage to e right front fire hubcap. No one was injured and neither vehicle INJURY DAYLIGHT CLEAR DRIVER INATTENTION NORTH REAR END 36124989 DRY 209 On 3/5/16 at about 1208hrs I responded to the area of 672 E Ma I for the reported MVA that had occurred around 1137hrs. Upor rival I spoke to driver 1 and driver 2, Driver 1 was backing out of parking spot at the gas station as driver 2 was walking to his chicle parked at the gas pumps just behind vehicle 1. Driver 1 NON VIEW OBSTRUCTED/LIMITED 210 36134813 3/5/2016 11:37:00 AM 2 DAYLIGHT DRY CLOUDY SOUTH REAR END aving his view partially obstructed by pedestrians in the parking le REPORTABLI lid strike the front of vehicle 2 with the rear of vehicle 1. I was inable to observe any significant damage to either vehicle but triver 2 was adamant of filling a police report. No reported injurie none complained or observed. Driver 1 and Driver 2 were issued ccident exchange slip that was completed by Ofc. K. Graham veniuse 2 was in Court to lane or invession in a lant on E. in anni si approaching the intersection of University Ave. Vehicle 1 was directly behind vehicle 2 in same direction in curb lane of E Mair approaching University ave. Eastbound traffic then received a FOLLOWING TOO CLOSELY 211 36130794 3/8/2016 8:18:00 AM 2 DAYLIGHT DRY CLEAR WEST REAR END ady red light at that intersection . Vehicle 2 then applied there EPORTABLI rakes and slowed to a stop and vehicle 1 attempted to apply rakes but was following to closely and ran into the rear of vehicle. Minor damage to both vehicles. No injuries. Vehicles cared for 2 DAYLIGHT DRY DRIVER INATTENTION RIGHT ANGLE 212 36134827 3/11/2016 4:45:00 PM CLEAR SOUTH DAMAGE AND INJURY ND OF THE DAMP FROM ER INNER LOOP TO STIDALL ST THE CITY OF ROCHESTER. DRIVER OF UNIT 1 DECIDE E WANTED TO CHANGE FROM THE LEFT LANE TO THE 213 8:30:00 PM DRY CLOUDY BACKING UNSAFELY WEST 36133493 3/12/2016 MIDDLE LANE AND BACKED UP, NOT SEEING UNIT 2, WHO REPORTABLE LIGHTED WAS STOPPED IN TRAFFIC BEHIND UNIT 1. DRIVER OF INIT 1 STRUCK LINIT 2 IN THE FRONT END. CALISING AMAGE TO FRONT OF UNIT 2 AND REAR OF UNIT 2. NO hile on patrol in the area, i observed a light pole down in the ro n the area of 135 delevan st. furhter up the road at the intersection f scio and delevan st. the above listed vehicle had come to rest is such and delevant so, in a douver issent venture had come to test against a quartfail. The vehicle has severe front end damage with it hag deployment but the vehicle was unoccupied, fire responde of the scene for fluids, officers checked the ros address with PROPERTY UNSAFE SPEED EAST DAMAGE LIGHTED egative results, photos were taken (see tech sheet) The vehicle s towed from the scene due to damage. Area hospitals were necked for persons with injuries with negative results. The drive vas E/B on Delevan when they went onto the curb, striking a ightpole which had a stop sign and one way sign attached. no mage to the guard rail, neighborhood check negative n 03/18/16 at 1456 hours I responded to the intersection of SI St and Allen St for the report of a MVA. I met with and spoke to the Iriver of V2. She stated she was stopped on State St at the light, acing South. Driver of v2 stated the light was red but the next affic light furned green and the driver of V1 rear ended her.

Driver of V2 stated the driver of v1 could not stay and wait for polic
and gave her, her contact information. I contacted the driver of V1 FOLLOWING TOO CLOSELY EPORTABL y telephone (585230-4204). The women I spoke to stated she as the driver and did rear end V2. I was able to get her information for this report. Driver of V1 stated she was not hurt an the had heavy front end damage. Driver of V1 phone hung up. I was not able to get a hold of her again. V2 had minor damage to he rear bumper. Driver of V2 was not injured and her car was On 03/18/2016 at about 1505 hours, police were dispatched to Joseph Ave at the Inner Loop for a reported MVA. Driver of V2 lates she was stopped second car in line at a red traffic light n/b loseph Ave on the bridge over the Inner Loop when she was truck in the rear by V1. Driver of V1 states he was n/b Joseph uuk in uite real by Vir. Divies div Visales le was in USusepin we when the Iraffic light at Jospeh Ave and Cumberland St was etting ready to turn yellow. Driver of V1 states he speeded up a le to make the light before it turned red. Driver of V1 went 3/18/2016 216 36142641 3:05:00 PM DAYLIGHT WET RAIN UNSAFE SPEED NORTH REAR END rough the intersection, but was unable to stop in time before triking V2 at the next traffic light. Driver of V1 states V1 slid on w wavement. No injuries were reported or observed. V2 damage in he left rear bumper. V1 damage to the right front bumper, right ont headlight, hood and right front quarter panel. Both vehicles rere cared for by their driver. Both drivers were provided an EHICLE 1 WAS IN THE FAR LEFT LANE ON CUMBERLAT IT HEADING EAST. THAT LANE HAS A LEFT TURN ONLY SIGN. VEHICLE 2 WAS IN THE CENTER LANE ALSO ON CUMBERLAND ST HEADING EAST. THE CENTER LANE PROPERTY AS A SIGN THAT STATES LEFT TURN OR STRAIGHT DARK-ROAF PASSING OR LANE USAGE HEAD. VEHICLE 2 WAS MAKING A LEFT TURN FROM UMBERLAND ST TO ST PAUL ST. WHEN VEHICLE 1HIT 217 36149727 7:27:00 AM AMAGE ANI INJURY EAST RIGHT ANGLE 3/23/2016 WET RAIN IMPROPERLY HE DRIVERSIDE OF VEHICLE 2 CAUSING DAMAGE. THE PASSENGER IN VEHICLE 1 COMPLAINED OF BACK PAIN

UT REFUSED MEDICAL. THE DRIVER OF VEHICLE 2

ROUTE NO. OR STREET NAME MONRO P.I.N.: NOT APPLICABLE CASE No ADJACENT ROADWAY NETWORK TOWN FILE: CITY AT INTERSECTION WITH/OR BETWEEN: BY: PSC VILLAGE OF ROCHESTER DATE: 5/13/2020 SEE MAP TIME PERIOD FROM TO NVIRONMENTAL 1. Dry 2. Wet 3. Muddy 1. Clear 2. Cloudy 3. Rain se Codes from MV 104 (shown right) for these categories 1. Daylight 8/1/14 7/31/19 4. Snow/lo 4. Snow 5. Dark Road Unlighted 5. Slush 5. Sleel/Hail/Freezing Rain 10. Other 6. Fog/Smog/Smoke lo. OF MONTHS 60 Ise Codes from MV 104 Police Report of VEHICLES DIRECTION DESCRIPTION REFERENCE SOAD WAY URFACE ONDITION CRASH No CASE No DATE TIME APPARENT CONTRIBUTING FACTORS WAS IN FRONT OF V2. GOING THROUGH CAR WASH WHILE INSIDE OF CAR WASH, VI BACKED UNSAFELY AND HIT V2. DRIVER OF VI SAID TRACK THAT MOVES CARS FORWARD IN CAR WASH MALFUNCTIONED AND THAT V2 NON 36155511 BACKING UNSAFELY NORTH 5:42:00 PN DAYLIGHT CEPT MOVING FORWARD WHILE HIS CAR WAS STUCK AND HAT IS HOW CARS HIT FACH OTHER I Was raveling normbound benind V2 on Scio St. V2 stopped 1 rn westbound onto Lyndhurst St. The operator of V1 stated that e dropped his bottle of juice on the driver side floorboard. The perator of V1 said that he took his eyes off of the road to retriev te bottle. The operator of V1 stated that he looked back up and NON 219 36164688 3/29/2016 7:10:00 PM DAYLIGHT DRY CLEAR DRIVER INATTENTION NORTH REAR END ouldn't stop before V1 struck the rear bumper area with h ont bumper causing damage to the same. There were no injurie PTWESTBOOND ON THE INNER LOOP AT E. MAIN ST. PEDESTRIAN CROSSING THE INTERSECTION ON E. MAIN ST AT THE INNER LOOP (ELECTRONIC CROSS WALK ONITOR ADVISED DO NOT CROSS, PEDESTRIAN DROP DARK-ROAF PEDESTRIAN'S 220 36168482 4/2/2016 9:48:00 PM INJURY WET RAIN WEST OTHER NU UNKNOWN ITEM AND BENDS DOWN TO GRAB IT. DRIVER OF VI DOES NOT OBSERVE PEDESTRIAN IN THE ROADWAY, SUBSEQUENTLY STRIKING HER. PEDESTRIAN ERROR/CONFUSION RANSPORTED BY MONROE AMBULANCE TO STRONG PROPERT 221 36179447 4/4/2016 12:00:00 AM 2 HINKNOWN TINKNOWN HINKNOWN TINKNOWN TINKNOWN OVERTAKING PPROACHING A GREEN LIGHT AT STATE ST. (V2) WAS OING TO MAKE THE LEFT TURN ONTO STATE ST WHEN NON-STREET. (VI) DID NOT REALIZE (VZ) WAS STOPPING AND STRUCK THE BACK OF (VZ). NO REPORT OF INJURIES 222 36168454 4/8/2016 12:40:00 PM DAYLIGHT DRY CLOUDY DRIVER INATTENTION FAST REAR END REPORTABLI NO BOTH VEHICLES TAKEN CAPE OF BY DRIVERS RAVELING WEST BOUND ON EAST MAIN ST.HE CHANGI NON-PASSING OR LANE USAGE ANE DID NOT SEE VEHICLE #2 ALSO TRAVELING WEST 223 36168432 4/9/2016 7:42:00 AM DAYLIGHT DRY CLEAR WEST OVERTAKING EPORTARI IMPROPERLY OLIND ON EAST MAIN ST SIDE SWIPING VEHICLE #2 AUSING DAMAGE TO VEHICLE #2 LEFT FRONT BUMPE ND OLIARTER PANEL AREA On 04/11/16 at 1848 hours Tresponded to 497 State St for a MV eport. There I met with the driver of V2. She stated she was triving her car North on State St at 0845 hours that morning wing rier car word on State Scaloed Floors flat miniming. river of VZ stated she was slowing down for the yellow light at tate Stand Allen St when the driver of V1 rear ended he. Both rivers exchanged information and went on there way for the day Both parties had to be at work. I called and spoke to the driver of NON V1. She stated she was driving North on State St. She stated she 224 36173012 4/12/2016 8:45:00 AM DAYLIGHT DRY CLEAR FOLLOWING TOO CLOSELY NORTH REAR END It is also sales as a living from the sales as one sales as olked behind her real fast and when she turned around she didh' I have time to stop and rear ended V2. Driver of V1 taled she did not have any damage to the front bumper of her ehicle. Driver of V2 stated she had very minor damage to the REPORTABLI ear bumper. Neither vehicle needed to be towed. The nger in V2 stated he had complains of ":whiplash&qu sked him several times if he wanted medical attention and he refused saving he would see his Dr in the morning. Driver OPERATOR OF VEHICLE #2 STATES THAT HE WAS TURNING EAST ON EAST MAIN STREET FROM THE INNER URNING EAST OW THE WINE!

OOP WHEN VEHICLE #1 ALSO TURNING EAST ON EAST
IAIN STREET FROM THE INNER LOOP TURN INTO HIS
ANE AND STRIKING HIS VEHICLE RIGHT FRONT BUMPER AREA. OPERATOR OF VEHICLE #1 DID STATE THAT SHE WAS MAKING A LEFT TURN ONTO EAST MAIN STREET 225 36613346 4/15/2016 11:55:00 AM 2 DAYLIGHT DRY CLEAR EAST (WITH OTHER REPORTABLI IMPROPERLY CAR) ROM THE INNER LOOP, AND TURN INRO VEHICLE #2 TRIKING THE RIGHT FRONT BUMPER AREA. THE

ITNESS DID STATE THAT VEHICLE #1 WAS IN FRONT OF IS VEHICLE AND SHE WAS TURNING LEFT ONTO EAST IAIN ST TURNING INTO VEHICLE #2 RIGHT FRONT BUMPER AREA. - WITNESS 1 FODDEN, AARON 448 DRIVER OF VEHICLE 2 MAKUCH STATED SHE WAS PROCEEDING WB ON CUMBERLAND ST OVER ST PAUL ST GOING STRIGHT WHEN HER VEHICLE WAS SIDESWIPED B' VEHICLE 1 ON HER DRIVERSIDE ALSO PROCEEDING WB ON CUMBERLAND ST GOING OVER ST. PAUL ST.DRIVER OF VEHICLE 1 BROWN STATED THAT HE WAS IN THE WRONG LANE ON CUMBERLAND ST. BROWN STATED HE WKONG LAINE ON COMBERLAND 31. BROWN 31ATED HE WAS IN THE LEFT TURN LAINE BUT NEEDED TO GO STRAIGHT. BROWN ATTEMPTED TO ACCELERATE PASSED VEHICLE 2 WHICH WAS GOING STRAIGHT OVER NON-REPORTABLE T. PAUL ST, AS HE DID HIS VEHICLE STRUCK VEHICLE 2 226 36173643 4/15/2016 1:24:00 PM DAYLIGHT DRY CLEAR WEST OVERTAKING IMPROPERLY HIS CAUSED DAMAGE TO HIS PASSENGER SIDE.R/O NOTES BOTH VEHICLE PULLED OVER ON COMMERICAL ICHES BOTH VERICLE PULLED VER ON COMMERCAL ST AT MILL ST. MVA WAS NOT INVESTIGATED AT SCENE IO INJURIES REPORTED OR COMPLAINED OF BY DRIVERS AND PASSENGERS.WITNESS/ PASSENGER IN VEHICLE 1 (COUGH) CONFIRMED DRIVER OF VEHICLE &apos:S STORY, WITNESS/PASSENDER IN VEHICLE 2 R MAKUCH) CONFIRMED DRIVER OF VEHICLE 2&anos:S SIDE DOOR AREA. - WITNESS 1 COUGH, JEREMY /EHICLE 2 WAS IN THE NORTH BOUND LANE OF STATE ST. STOPPED AT A RED LIGHT AT ALLEN ST., VEHICLE 1 NAS TRAVELING NORTH BOUND ON STATE ST APPROACHING ALLEN ST.. VEHICLE 1 FAILED TO STOP FOR THE RED LIGHT AND STRUCK THE REAR OF VEHICLE 36188519 INJURY FOLLOWING TOO CLOSELY 227 7:35:00 PM DAYLIGHT DRY CLEAR NORTH 4/23/2016 A WITNESS (JON LYNCH 585-455-5882) TOLD THE RIVER 1 THAT HE OBSERVED DRIVER 2 TEXTING ON HER PHONE WHEN SHE STRUCK VEHICLE 2 PASSANGER 1 OMPLAINED OF PAIN IN HER LEFT KNEE, BUT REFUSED

TE 213 (9/79)

MEDICAL. VEHICLE 1 WAS TOWED TO EAST AVE AUTO

TE 213 (9/79) ROUTE NO. OR STREET NAME: P.I.N.: NOT APPLICABLE CASE No.: ADJACENT ROADWAY NETWORK FILE: BY: DATE: TOWN CITY AT INTERSECTION WITH/OR BETWEEN: PSC VILLAGE OF ROCHESTER 5/13/2020 SEE MAP ENVIRONMENTAL: Light Conditions:
Use Codes from MV 104 (shown 1. Daylight atright) for these calegories 2. Dawn 3. Dusk 4. Dark Road Lighted 5. Dark Road Unlighted Weather:
1. Clear
2. Cloudy
3. Rain
4. Snow
5. Sleet/Hail/Freezing Rain
6. Fog/Smog/Smoke
10. Other Roadway Surface Condition: 1. Dry 2. Wet 3. Muddy 4. Snowl/ce 5. Slush 10. Other TIME PERIOD FROM: 8/1/14 7/31/19 No. OF MONTHS: 60 Use Codes from MV 104 Police Report REFERENCE MARKER DIRECTION TYPE¹ DESCRIPTION

CRASH No.	CASE No.	DATE	TIME	No. of VEHIO	SEVERITY	CONDITION	ROADWAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING FACTORS	BIRECTION	TIPE.	DESCRIPTION	MARKER
228	36185403	4/24/2016	3:02:00 AM	2	NON- REPORTABLE	DARK-ROAD LIGHTED	DRY	CLEAR	PASSING OR LANE USAGE IMPROPERLY	NORTH	LEFT TURN (AGAINST OTHER CAR) LEFT TURN	veh 2 was slowing down to make a left turn into a driveway. veh 1 was aftempling to pass on the left and struck veh 2.	
229	36187869	4/25/2016	4:46:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLOUDY	DRIVER INATTENTION	NORTH-WEST	(AGAINST OTHER CAR)		
230	36185374	4/25/2016	5:15:00 PM	3	NON- REPORTABLE	DAYLIGHT	DRY	CLOUDY	DRIVER INATTENTION	WEST	OTHER	Liver or Verbick 2 shalled that the light was green (WB) on Allen St at Sibe St but was supper on Allen St (WB) at Sibe St behind vehicle 3, which was also stopped (WB) on Allen St at State St, when her vehicle was struck from behind by vehicle 1 which was moving. This caused welve 2 b as they whele 3. Driver of vehicle 2 had very, very minor damage to the front end and rear end of her vehicle. The vehicle 3 which was stopped (WB) on Allen St at State St with a green light, but before she was able to go have whiche was struck by vehicle 2 from behind. This caused very eny minor damage to the rear end vehicle 3. Driver of vehicle 3 state she was (WB) on Allen St at State St, behind vehicle 2 when he light had mend green and proceeded to go, as he did so he struck vehicle 2 from behind. This caused damage to the root end of vehicle 1. No injuries seen or complained of, RIO notes minor damage to vehicles 2 and 3, which I had front end damage. RIO notes that a prior MIVA occurred at State State State shall was also well also go when State	
231	36188949	4/26/2016	8:23:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	WET	RAIN	FAILURE TO YIELD RIGHT OF WAY	SOUTH	RIGHT ANGLE	OPERATOR OF VEHICLE #2 STATES SHE WAS TRAVELINE AST BOUND ON ALLEN ST MAKING A RIGHT TURN ONTO STATE ST SHE WAS WANTING TO TURN RIGHT INTO THE LAFT LANE WHEN VEHICLE #1 TRAVELING SOUTH BOUND ON STATE ST STRUCK HER VEHICLE. OPERATOR OF VEHICLE #1 STATES THAT HE WAS TRAVELING SOUTH BOUND ON STATE ST SAM VEHICLE #2 STEP ON HIS BRAKES HIS VEHICLE DID NOT STOP IN TIME STRIKING VEHICLE #1 WHICH WAS STOP IN TRAFFIC. THE WINNESS STATES THAT VEHICLE #2 WAS STOP IN TRAFFIC WHEN VEHICLE #1 STRUCK VEHICLE #2 WAS STOP IN TRAFFIC WHEN VEHICLE #1 STRUCK VEHICLE #2 WAS STOP IN TRAFFIC WHEN VEHICLE #1 STRUCK VEHICLE #2 WAS STOP IN TRAFFIC WHEN VEHICLE #1 STRUCK VEHICLE #2 WAS STOP IN TRAFFIC WHEN VEHICLE #1 STRUCK VEHICLE #2 WAS STOP IN TRAFFIC WHEN VEHICLE #1 STRUCK VEHICLE #2 WAS STOP IN TRAFFIC WHEN VEHICLE #1 STRUCK VEHICLE #2 WAS STOP IN TRAFFIC WHEN VEHICLE #1 STRUCK VEHICLE #2 WAS STOP IN TRAFFIC WHEN VEHICLE #1 STRUCK VEHICLE #2 WAS STOP IN TRAFFIC WHEN VEHICLE #1 STRUCK VEHICLE #2 WAS STOP IN TRAFFIC WHEN VEHICLE #1 STRUCK VEHICLE #2 WAS STOP IN TRAFFIC WHEN VEHICLE #1 STRUCK VEHICLE #2 WAS STOP IN TRAFFIC WHEN VEHICLE #1 STRUCK VEHICLE #1 WITHOUT STRUCK WHEN VEHICLE #1 STRUCK VEHICLE #1 WAT STRUCK WHEN VEHICLE #1 STRUCK VEHICLE #1 WAS SAFROW WHEN WAS STOP WHEN VEHICLE #1 STRUCK VEHICLE #1 WAS SAFROW WAS SAFROW WAS SAFROW WHEN WAS SAFROW WAS SAFR	
232	36189858	4/27/2016	7:35:00 AM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	DRIVER INATTENTION	SOUTH	REAR END	VEHICLE 2 AND VEHICLE 1 WERE BOTH SOUTH ON N. CLINTON AV. WHEN AT THE INTERSECTION OF CUMBERLAND ST AND N. CLINTON AV. VEHICLE 2 WAS STOPPING FOR THE RED LIGHT. VEHICLE 1 REAR ENDED VEHICLE 2 CAUSING SLIGHT DAMAGE TO BOTH VEHICLES.	
233	36188511	4/27/2016	5:14:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	UNSAFE LANE CHANGE	NORTH	OVERTAKING	If we have the present of the presen	
234	36189363	4/28/2016	11:57:00 AM	3	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	SOUTH-EAST	OTHER	IEH TTRAVELING (SE) FROM INNERLOOP! UNIVERSITY AND ATTEMPTING A LEFT TURN ONTO E MAIN ST (EB), DIS STRIKE VEH 2 WHICH WAS ALSO TURNING LEFT FROM SAME, VEH 2 AS A RESULT, WAS THEN PUSHED INTO VEH 3 WHICH HAD ALSO MADE THE TURN LEFT FROM SAME AND WAS (EB) ON E MAIN ST. VEH 1 STRUCK VEH 28apos. S REAR BUMPER W VEH 1 Aspos. S FRONT BUMPER WHICH STRUCK VEH 38apos. S REAR BUMPER W VEH 1 ASPOS S FROM TEMPER LEFT W VEH 28apos. S FRONT BUMPER LUCENSE PLATE CAUSING WISBLE DAMAGET TO VEH 38apos. S RUMPER (LEFT SDE), VEH 1 THEN IMMEDIATELY LEFT SCENE (EB) ONE MAIN ST VEH 1 DESCRIBED AS MID SIZED, GREEN SCAN NO SURFRE NO SEAN SEAN SEAN SEAN SEAN SEAN SEAN SEAN	
235	36194449 36188965	4/29/2016 4/29/2016	7:52:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	WET	CLOUDY	PASSING OR LANE USAGE MPROPERLY TRAFFIC CONTROL DEWCES DISREGARDED	SOUTH	RIGHT ANGLE	VEHICLE 2 WAS WEST ON ALLEN ST. DRIVER 2 STATED HE HAD THE GREEN LIGHT AND WAS CROSSING OVER STATES TO LIVE TO HEAVY MORNING TRAFFIC THE LIGHT CHANGED AND HE STILL IN THE INTERSECTION. HE SAID SOUTHBOUND TRAFFIC ON STATE ST WAITED AS HE MOVED FORWARD TO CLEAR THE INTERSECTION. BRIVE STATED WHICH IS AND THE HAT RESECTION. BRIVE STATED WHICH IS WAS THE HAR RIGHT LANE AND CAME THROUGH THE INTERSECTION AND HIT HIM. BRIVET STATED SHE WAS IN THE FAR RIGHT LANE COINS STRAGHT THROUGH THE INTERSECTION AND SHE HIT VEHICLE 2. VEHICLE 1 THEN HIT THE LIGHT POLE AT THE SOUTHWEST CORNER OF THE INTERSECTION. BRIVET IS TATED SHE WAS NOT SURE WHERE VEHICLE AND THE STATED SHE WAS NOT SURE WHERE VEHICLE AND THE SOUTHWEST CORNER OF THE INTERSECTION. BRIVET IS TATED SHE WAS NOT SURE WHERE VEHICLE AND FAR HAD THE STATED SHE WAS NOT SURE WHERE VEHICLE AND FAR HAD THE STATED SHE WAS NOT SURE WHERE VEHICLE AND FAR HAD THE STATED SHE WAS NOT SURE WHERE VEHICLE AND FAR HAD THE STATED SHE WAS NOT SURE WHERE VEHICLE AND FAR HAD THE STATED SHE WAS NOT SURE WHERE VEHICLE AND FAR HAD THE STATED SHE WAS NOT SURE WHERE VEHICLE AND FAR HAD THE STATED SHE WAS SOUTHED WHICH SHE WAS NOT SURE WHERE VEHICLE AND FAR HAD THE STATED SHE WAS SOUTHED WHITH HAD SHE AND THE STATED SHE WAS SOUTHED WHITH HE STATED SHE WAS SOUTHED WHITH HAS SATE WHEN THAT HE WAS COMINGS TRAGHT ACROSS THAT INTERSECTION HAS A SICK THAT SHOWS MAKING LEFT TURNS ARE PROHIBITED FOR NOR THROUND TRAFFIC. MAKING AN MPROPER TURN ADDED AS A CONTRIBUTION FACTOR AND WHOLLD WAS SHE WAS BE SAMMANS A. A WHICKE CHART HAD THE SOUTH AND SHE WAS BE ASSIMILATED AND SHE WAS BE SAMMANS A. WHICKE WAS SOURCED THE BOOK NICH SHE WHEN AND RESIDENCE WHO THIS SHE HAD HAD THE SHE ON OR THE SOUTH HAD THE SHE ON THE SHE SHE WHEN AND RESIDENCE WHO THIS SHE HAD HAD THE SHE ON THE SHE SHE WHEN AND RESIDENCE WHO THIS SHE HAD HAD THE SHE ON THE SHE SHE WHEN AND THE SHE SHE WHEN AND THE SHE ON THE SHE SHE WHEN AND THE SHE ON THE SHE WHEN AND THE SHE OND THE SHE WHEN AND THE SHE SHE WHEN AND THE SHE SHE WHEN AND THE	
												had green lights to proceed into the intersection. No nyuries tenoroded no citiz raimeras in the area.	l

TE 213 (9/79) ROUTE NO. OR STREET NAME MONRO P.I.N.: NOT APPLICABLE CASE No ADJACENT ROADWAY NETWORK TOWN FILE: CITY AT INTERSECTION WITH/OR BETWEEN: BY: PSC VILLAGE OF ROCHESTER DATE: 5/13/2020 SEE MAP TIME PERIOD FROM TO NVIRONMENTAL Roadway Surface Condition 1. Dry 2. Wet 3. Muddy 1. Clear 2. Cloudy 3. Rain se Codes from MV 104 (shown right) for these categories 1. Daylight 8/1/14 7/31/19 4. Dark Road Lighted 4. Snow/lo 4. Snow 5. Dark Road Unlighted 5. Slush 5. Sleet/Hail/Freezing Rain 10. Other 6. Fog/Smog/Smoke lo. OF MONTHS 60 Jse Codes from MV 104 Police Report of VEHICLES DIRECTION DESCRIPTION REFERENCE ROADWAY SURFACE CONDITION CRASH No CASE No DATE TIME APPARENT CONTRIBUTING FACTORS IORTH BOUND ON STATE ST MAKING A LEFT TURN ONTO ALLEN ST DID NOT SEE THE NO LEFT TURN SIGN IE MADE THE TURN STRIKING VEHICLE #2 WHICH WAS THE MADE THE TORN'S TRIGHT OF THICLE #2 WINCH WAS RAYELING SOUTH BOUND ON STATE ST. THE WITNESS TATES THAT HE WAS BEHIND VEHICLE #1 TRAVELING IORTH BOUND ON STATE ST HONKING HIS HORN PROPERTY LEET THEN AILURE TO YIELD RIGHT OF 237 36194425 5/2/2016 7:32:00 AM AMAGE AN INJURY DAYLIGHT WET RAIN WEST (AGAINST OTHER CAR) ETTING HIM KNOW THAT HE CANNOT MAKE THE LEFT URN. HE MADE THE LEFT TURN ANYWAY STRIKING EHICLE #2. - WITNESS 1 JAMES, JOE PO BOX 30648 V-1 traveling north on Joseph Ave at intersection with Cumberland St. under a steady red signal. V-2 traveling east on Cumberland of, at intersection with Joseph Ave, under a steady red signal. V-2 segins to proceed east thru the intersection under a steady green signal. V-1, observed the signal light to the west change to green, PROPERTY RAFFIC CONTROL DEVICES 238 36193222 5/3/2016 10:28:00 AM DAYLIGHT DRY CLEAR NORTH RIGHT ANGLE nd proceeds north thru his steady red signal, into the path of V-2. PAUL ST APPROACHING CUMBERLAND ST. WHEN UNDER THE RAILROAD BRIDGE WHERE THE TWO LANES ARE PROPERTY SMALLER, VEHICLE 1 TRIED TO GO BY VEHICLE 2 ON THE RIGHT SIDE. THUS SIDESWIPING VEHICLE 2'S DRIVERSIDE THEN HITTING ONE OF THE PILLARS WHICH 239 36197053 5/4/2016 7:11:00 AM 2 AMAGE ANI DAYLIGHT DRY CLEAR UNSAFE LANE CHANGE SOUTH OVERTAKING INJURY HOLD UP THE BRIDGE. THE DRIVER OF VEHICLE 1HIT HER HEAD ON THE WINDSHIELD AFTER IMPACT. SHE WAS RANSONZOTETA POTH HADDIES VZ WASTGOI AHEAD NORTHBOUND ON NORTH UNION STREET WHEN THE DRIVER STOPPED AT A RED LIGHT AT THE NON DARK-ROAF ITERSECTION ON NORTH UNION AND EAST MAIN 240 36226393 5/7/2016 1:11:00 AM 2 WET RAIN UNKNOWN NORTH REAR END NTERSECTION ON HOR IT UNION AND EAST MAIN STREET. VI WAS TRAVELING NORTHBOUND ON UNION STREET WHEN VI HIT THE LEFT SIDE REAR OF V2 AND LEFT THE SCENE. DRIVER OF V2 STATED THAT HE EPORTARI. LIGHTED ELBJED THE VEHICLE WAS A DODGE MOBILIDIES ch 2 was slowing/ stopping in traffic when struck in the rear by ch 1. Both vehicles were traveling West on E. Main St. 241 36202309 5/7/2016 10:40:00 AM 2 DAYLIGHT DRY CLOUDY FOLLOWING TOO CLOSELY WEST REAR END EPORTAB PROPERT 242 36199649 5/7/2016 4:42:00 PM 3 DAYLIGHT DRY CLEAR DRIVER INATTENTION SOUTH OTHER DAMAGE iversity Av at Union St stopped at the red light. V1 did not stop i ne and collided with V2 causing damage to the rear humper of NONne and contect win v2 causing damage to the read unitipe of 2 and the front bumper of V1. Driver 1 stated she did not see V2 opped. Driver 1 also stated that she only had a permit. Driver 1 as issued a UTT for 509(1). Both drivers were on scene and 243 36202305 5/10/2016 8:52:00 AM DAYLIGHT DRY CLEAR DRIVER INATTENTION SOUTH REAR END REPORTABLI DIVIDED THE PROPERTY OF THE PR NTERSECTION WITH CUMBERLAND ST. VEHICLE 1 WHICH PROPERTY VAS ON CUMBERLAND ST HEADING WEST COMING UP TO 244 36214302 5/10/2016 1:58:00 PM DAYLIGHT DRY CLEAR DRIVER INATTENTION WEST RIGHT ANGLE DAMAGE ORTH ST. WHEN STOPPING FOR THE STOP SIGN ASSED THE STOP LINE AND HIT VEHICLE 2 CAUSING PROPERT 245 36221201 5/10/2016 4:40:00 PM 2 DAYLIGHT DRY CLEAR DRIVER INATTENTION WEST OVERTAKING DAMAGE ver 2 stated that she was traveling North on University Av e center lane of a 3-lane highway. Driver 2 further stated that sh PROPERTY 36205369 DAYLIGHT UNKNOWN NORTH REAR END 246 5/13/2016 9:30:00 AM WET RAIN empted to make a left turn to travel West on E. Main St. During DAMAGE iver 2's left turn, she was struck in the rear by Veh 1. Vel fed from the scene I was easthough on F. Main Stat University by in the center 2 was eastbound on E Main St at University Av in the south lat 1 merged into the south lane and V2 collided with V1 causing NON amage to the rear passenger bumper of V1 and the front drive DRIVER INATTENTION 247 2 DAYLIGHT CLEAR EAST REAR END 36208293 5/16/2016 12:25:00 PM DRY REPORTABLE ide bumper of V2. Driver 1 stated that V2 came out of nowhere and rear ended her. Driver 2 stated that V1 merged into his lane and cut him off. He said he was unable to stop on time. No injuri On 05/17/16 Tresponded to the intersection of E. Main st and niversity Ave for a three car MVA. I spoke to the driver of V1. Ivas On East Main st driving West. He was stopped at the red was Oh Last Main storming West. He was sopped at the red light. He stated the light furned green for Right furn only and he thought it was the green light. He drove through the intersection and struck V2. V2 was on University Ave groing South. She states she had the green light and as she drove through the intersection V1 struck her car and she struck V3. Driver of V3 stated she was DRIVER INATTENTION 248 36214285 5/17/2016 5:15:00 PM 3 DAYLIGHT DRY CLEAR WEST OTHER DAMAGE riving East on East Main St. SHe was stopped at the traffic light iverig Last on East Main St. She was suppled a rine train. Light he stated she saw the driver of VI drive hought he light, hit V2 nd V2 then his her car. V1 had heavy front end damage and seded to be lowed. V2 had damage to the front bumper and fro eft quarter panel. V2 also needed to be towed. V3 had very mind mage to the front bumper. No one was injured. TERRICLE 2 WAS 310 AT THE INTERSECTION WITH ST PAUL ST. WAITING TO MAKE A RIGHT TURN. WHEN VEHICLE 1 WHICH WAS BEHIND VEHICLE 2 WENT TO GO AROUND WEHICLE 2 AS IT WOULDNT GET INTO THE TRAFFIC. AS PROPERTY DAMAGE 2:07:00 PM DRIVER INATTENTION EAST 249 36227203 5/19/2016 DAYLIGHT DRY CLEAR EHICLE 1 WENT TO GO AROUND VEHICLE 2. VEHICLE 1 IT THE REAR LEFT CORNER OF VEHICLE 2&anns:S PER CAUSING DAMAGE TO SAME PHICLE 2 WAS STOFFED AT THE RED LIGHT ON PUMBERLAND ST AT ST PAUL ST HEADING EAST. WHEN EHICLE 1 ALSO ON CUMBERLAND ST HEADING EAST DRIVER INATTENTION REAR ENDED VEHICLE 2 CAUSING DAMAGE TO BOTH

RAFFIC CONTROL DEVICE

SOUTH

RIGHT ANGLE

DDODEDT

DAMAGE

251

36227208

5/21/2016

3:35:00 PM

TE 213 (9/79) ROUTE NO. OR STREET NAME MONRO P.I.N.: NOT APPLICABLE CASE No ADJACENT ROADWAY NETWORK TOWN FILE: CITY AT INTERSECTION WITH/OR BETWEEN: BY: PSC VILLAGE OF ROCHESTER DATE: 5/13/2020 SEE MAP TIME PERIOD FROM TO NVIRONMENTAL 1. Dry 2. Wet 3. Muddy 1. Clear 2. Cloudy 3. Rain se Codes from MV 104 (shown right) for these categories 1. Daylight 8/1/14 7/31/19 4. Snow/lo 5. Dark Road Unlighted 5. Slush 5. Sleel/Hail/Freezing Rain 10. Other 6. Fog/Smog/Smoke lo. OF MONTHS 60 Ise Codes from MV 104 Police Report of VEHICLES DIRECTION DESCRIPTION REFERENCE CRASH No CASE No DATE TIME APPARENT CONTRIBUTING FACTORS net with the driver of V1. She stated she was driving West on niversity Ave. She stated a white male on a Bike cross diagon nimers any river. Sine sales a white made on a block dossubgruide om the South side of University Ave to the North side of the stree she stated the male on the blike was not in the cross walk, and rossed right in front of her car. Driver of V1 struck the blike the nan was on. The man got off his blike, locked it up to a chain NON AILURE TO YIELD RIGHT OF 252 36227198 5/24/2016 6:23:00 PM DAYLIGHT DRY CLEAR WEST OTHER nce near by and walked off. Driver of V1 and passenger were ot injured. V1 had damage to the right front bumper. The man on the Bike walked off and left the scene before I got on scene. V EHICLE 2 WAS WEST ON CUMBERLAND STAT NORTH ST. AFTER STOPPING FOR THE STOP SIGN AND LOOKING OTH WAYS FEELING IT WAS CLEAR VEHICLE 2 PULLED PROPERTY SOUTH OUT TO CROSS NORTH ST. THATS WHEN VEHICLE 1 HEADING SOUTH ON NORTH ST HIT THE REAR RIGHT 253 36237790 5/28/2016 12:38:00 PM DAYLIGHT DRY CLOUDY DRIVER INATTENTION RIGHT ANGLE QUARTER PANEL OF VEHICLE 2 CAUSING DAMAGE TO ROTHS VEHICLE IN TRAINCTOL A TEU TIGHT. VT WAS TRAVEIING Southbound and struck V2 on the rear bumper with his front imper causing damage to the same. The operator of V1 stated at he was slowing down when he observed that V2 was stoppe name was sowing down when he ower even that very as supple. The operator of VT said that while he was in the process of stopping, his phone that was located on the center console fell in the back seat area. The operator of VT said that he turned and ooked back and was reaching for his phone and his foot slipped o NON 254 36240934 6/3/2016 4-04-00 PM DAYLIGHT DRY CLEAR FOLLOWING TOO CLOSELY SOUTH REAR END of the brake and thats when he struck V2. The operator of V1 was RIGHT ONTO CUMBERLAND ST. WHEN AS SHE STARTED HER TURN A MAN ON A BIKE WAS CROSSING THE TREET, VEHICLE 2 STOPPED FOR THE BIKE AND PROPERTY EHICLE 1 REAR ENDED VEHICLE 2. VEHICLE 1 THEN 255 36255326 6/9/2016 9:01:00 AM AMAGE ANI DAYLIGHT DRY CLEAR DRIVER INATTENTION SOUTH REAR END IEMELE I KEAR ENDED VEHIELE Z. VEHIELE I THEN SACKED UP MADE A U-TURN AND WENT WEST UP SENTRAL AV. THE DRIVER OF VEHICLE 2 SAID IT WAS A WHITE MALE DRIVER AND IT LOOKED LIKE A CITY TRUCK INJURY RO CHECKED WITH THE CITY DISPATCH AND THERE WA ICIE P Was slopped in Valle, lacking west in the ehicle 2 was in the right turn only lane for Joseph Ave. Driver ated that when the light turned green, he proceeded west to PROPERTY PASSING OR LANE USAGE nerge into the right turn only lane for N. Clinton Ave. Driver 2 256 36249757 6/10/2016 8:44:00 AM DAYLIGHT DRY CLEAR WEST OVERTAKING ried ger into the right unit only lane to in . Chillion Ave. Diver 2 initially stated that she proceeded west but then recanted and stal hat she was slopped when vehicle 1 shuck vehicle 2. no ndependent witnesses. Damaged taillight on pavement indicate DAMAGE IMPROPERLY PRESPONDED TO 69 TE MAIN STREET FOR THE REPORT OF A MOTOR VEHICLE ACCIDENT. UPON ARRIVAL RO SPOKE WITH (V2) WHO STATED THAT HE WAS TOPPED AT THE LIGHT ON E MAIN STREET AT LINION STREET FACING WEST WHEN HE WAS STRUCK FROM BEHIND BY (V1). RO THEN SPOKE WITH (V1) WHO CONFIRMED THAT HE ACCIDENTLY STRUCK THE REAR F (V2&apos:S) VEHICLE WITH THE FRONT OF HIS VEHICLE 257 36265582 6/10/2016 2:12:00 PM INJURY DAYLIGHT DRY CLEAR FOLLOWING TOO CLOSELY WEST REAR END WHEN HIS FOOT SLIPPED OFF THE BRAKE AS HE WHEN HIS FOOT SIFEED OF THE BARKE AS HE PPROACHED THE INTERSECTION. RO OBSERVED VERY MNOR DAMAGE TO (V2&apos:S) REAR BUMPER AND THERE DID NOT APPEAR TO BE ANY DAMAGE TO V1'S) VEHICLE. (V2) COMPLAINED OF RIGHT ARM NECK, AND BACK PAIN ALTHOUGH HE DID NOT HAVE ANY DBVIOUS INJURIES. (V2) WAS TRANSPORTED TO STRONG
MEMORIAL HOSPITAL FOR PRECAUTIONARY TREATMENT WAS STOPPED AT A RED LIGHT WHEN IT WAS STRU DARK-ROAD ROM BEHIND BY V1. V1 THEN FLED THE SCENE AND FOLLOWING TOO CLOSELY OVERTAKING 258 36348520 6/11/2016 9:26:00 PM 2 DRY CLEAR EAST FPORTABL LIGHTED VAS LOCATED A SHORT TIME LATER. DRIVER OF VI DMITTED TO BEING INVOLVED IN THE MVA. I WAS TRAVELING WIB E. MAIN ST BEHIND V2. DURING HER TRAVELS D1 REACHED BACK TO TEND TO HER 2 THEN TARVELS OF THE BACKSEAT AND DDN&apos. T REALZE THAT TRAFFIC IN FRONT OF HER HAD COME TO A STOP THIS CAUSED VI TO REAR-END VZ. VZ THEN REAR-ENDED V3 WHO IN TURN REAR-ENDED V4. D1 WAS ADDITIONALLY ARRESTED FOR AUO 1ST AS WELL AS SSUED THE ABOVE APPROPRIATE TRAFFIC CITATIONS I WAS SUBSEQUENTLY TOWED. D2 WAS TRANSPORTED OR FOR COMPLAINT OF PAIN TO HER RIGHT KNEE. WAS OCCUPPIED BY ON-DUTY RPD INVESTIGATOR DRIVER INATTENTION WEST 259 36285826 6/13/2016 3:40:00 PM AMAGE AND DAYLIGHT DRY CLOUDY MOTHY GOURLAY, INVESTIGATOR GOURLAY WAS NOT II INJURY MERGENCY OPERATION BUT WAS IN AN UMARKED EMERCEIN TO PERAITON BUT WAS IN AN UMARKED
POLICE CAR ENROUTE TO THE EAST DIVISION OFFICE TO
TEND TO OFFICIAL POLICE DUTIES (EMERGENCY
EQUIPMENT WAS NOT ACTIVATED). THIS OFFICIAL VEHICLE IS POLICE-GES4483/FLEET#13-1280 AND IS WNED BY THE CITY OF ROCHESTER, V2-4 WERE ALL TOPPED IN TRAFFIC FACING W/B. TECHNICIAN 260-OTHAM RESPONDED AND TOOK PHOTOS. INCIDENT AS CAPTURED BY NEAR-BY BUSINESS CAMERA(FASTRAC) AND ALSO COLLECTED (SEE TECH arallel to each other in a single lane that has the width to commodate 2 vehicles. V2 was traveling on the passen f V1. The operator of V1 stated that he decided at the last at he wanted to make a right hand turn (southbound) onto N. 2:43:00 PM DAYLIGHT CLEAR TURNING IMPROPER SOUTH-EAST 260 36269053 6/17/2016 DRY (WITH OTHER linton Ave. When V1 began to turn he struck the driver side REPORTABLI CAR) uarter panel and doors of V2 with his passenger side quarter and partie and out of Vermin and passenger of VT said that e used his lurn signal at the last second and did not see V2 in ne to avoid the collision. The operator of V1 was issued a UTT

TE 213 (9/79) ROUTE NO. OR STREET NAME MONRO P.I.N.: NOT APPLICABLE CASE No ADJACENT ROADWAY NETWORK TOWN FILE: CITY AT INTERSECTION WITH/OR BETWEEN: BY: PSC VILLAGE OF ROCHESTER DATE: 5/13/2020 SEE MAP FROM NVIRONMENTAL TIME PERIOD TO Roadway Surface Condition Daylight
 Daylight
 Dawn
 Dusk 1. Dry 2. Wet 3. Muddy 1. Clear 2. Cloudy 3. Rain se Codes from MV 104 (shown right) for these categories 8/1/14 7/31/19 4. Snow/lo 4. Snow 5. Sleet/Hail/Freezing Rain 5. Dark Road Unlighted 5. Slush 10. Other 6. Fog/Smog/Smoke lo. OF MONTHS 60 Ise Codes from MV 104 Police Report of VEHICLES DIRECTION DESCRIPTION REFERENCE SOADWAY SURFACE CONDITION CRASH No CASE No DATE TIME APPARENT CONTRIBUTING FACTORS was driving S/B on N. Clinton Ave. and she said there was PROPERTY DARK-ROA driving N/B with its high beams on and she couldn't e. V1 said she tried to just keep straight but the road curved an 36263878 3:50:00 AM GLARE SOUTH Liumned the curb and struck the fire bydrant P V-1 WB CUMBERLAND STREET. OP V-2 WB PROPERTY DARK-ROA CUMBERLAND STREET, OP V-2 SLOWS FOR TRAFFIC 36261615 9:55:00 PM 2 AMAGE AN INJURY CLEAR FOLLOWING TOO CLOSELY WEST REAR END 262 6/18/2016 Main St. University Av does merge into one lane at that point. ehicle #2 was in the right lane when vehicle #1 attempted to erge in with traffic. Driver #2 stated that driver #1 tried to get NONround her vehicle but did not have adequate room and side wiped the rear driver side corner and mirror as a result. Driver: 263 36273607 6/21/2016 7:57:00 AM DAYLIGHT DRY CLEAR LINSAFE LANE CHANGE SOLITH OVERTAKING EPORTARI I ted that the he could not tell which lane merges at that time, an nat it is not clearly specified on the signs. The accident caused REPORT OF A MOTOR VEHICLE ACCIDENT. UPON ARRIVAL RO SPOKE WITH (V2) WHO STATED THAT SHE WAS IN THE RIGHT LANE TRAVELING WEST ON E MAIN TREET ABOUT TO TURN RIGHT INTO A PARKING LOT WHEN (V1) HIT THE REAR DRIVER SIDE BUMPER OF (V2'S) VEHICLE WITH THE FRONT PASSENGER SIDE OF (V1&apos:S) VEHICLE. RO THEN SPOKE WITH (V1) WHO NON-SAID THAT SHE WAS TRAVELING WEST ON E MAIN 264 36273580 6/21/2016 12:19:00 PM DAYLIGHT DRY CLEAR DRIVER INEXPERIENCE WEST OVERTAKING REPORTABLI TREET IN THE CENTER LANE WHEN SHE ACCIDENTLY TRUCK THE REAR DRIVER SIDE BUMPER OF (V2'S EHICLE WITH THE FRONT PORTION OF (V1'S) VEHICLE. RO ASKED (V1) HOW SHE CAME TO ACCIDENTLY HIT (V2&apos.S) VEHICLE AND (V1) REPLEID, "i DON&apos.T KNOW. IMUST HAVE DRIFTED OUT OI MY LANE A LITTLE AND ACCIDENTLY BUMPED INTO HER CAR.". NEITHER PARTY REPORTED ANY INJURIES A' HE TIME OF THIS REPORT AND NEITHER VEHICLE rivers claimed they were in the right hand lane. Driver of V1 sta at she was making a right hand turn onto Delevan St. from North RIGHT TURN NONt in the right hand lane and V2 approached from her right. Drive 265 36269043 6/22/2016 2:46:00 PM 2 DAYLIGHT DRY CLEAR UNSAFE LANE CHANGE NORTH-EAST (AGAINST ... in the right hard user and v.2 approaches to thin in fight. Dive V2 states that he was driving straight on North St. and that V1 rmed into him from the left hand lane. V1 struck V2 causing front imper damage to V1 and driverside door panel damage to V2. REPORTARII OTHER CAR In 06/26/2016 at about 1728 hours police were called to the area On tourbuzulo a rabout i i ze nours ponce were caned no he area of it Main Stand hidwestly Ave of an MVA. Driver of V2 sales she was on University Ave at E Main St facing north at a red traffic light in the right lane. When her traffic light numed green, with a green let lum arrow, driver of V2 began her let turn on to E Main St, wib, in the let lane. Driver of V2 stated V1 made a lett lum off o RIGHT TURN NONe Inner Loop exit ramp on to E Main St, entered the left lane and TURNING IMPROPER 266 36279227 6/26/2016 5:28:00 PM DAYLIGHT DRY CLEAR SOUTH-WEST (WITH OTHER REPORTABLE uck her vehicle. When I asked driver of V1 what had hanne CAR) e said " I have no freaking clue" When I asked to olor of his traffic light, he said "I do not know" V1 had amage to the left front bumper and left front quarter panel. V2 ha lamage to the right front quarter panel and right front door. No juries were reported or observed. Both driver were provided a cident Exchange Slip. Both vehicles were cared for by thei rsection of st paul st/ cumberland st in the center lane. veh as also traveling wb on cumberland st in the left turning lane. NON-DRIVER INATTENTION 267 36288587 6/30/2016 12:27:00 PM DAYLIGHT DRY CLEAR WEST (AGAINST h1 attempted to change lanes when his driver side front bump REPORTABLI OTHER CAR) ruck veh2&apos:s pa: enger side rear quarter panel causin veh1 sustained damage to his drivers side front qua ROPERTY RE TWO TUNRING LANES THERE. HOWEVER HALF WAY 36281184 12:13:00 PM DRIVER INATTENTION NORTH OVERTAKING 268 7/1/2016 DAYLIGHT WET RAIN DAMAGE ITO THE TURN VEHICLE 1 WENT INTO VEHICLE 2'S ANE HITTING VEHICLE 2&apos:S PASSENGER SIDE ALISING DAMAGE TO BOTH VEHICLES ehicle #2 was stopped in traffic at the red light when vehicle # NON-EPORTABLI vas traveling northbound behind vehicle #2. Vehicle #1 did not 269 36283523 DAYLIGHT FOLLOWING TOO CLOSEL' top in time for traffic and rear ended vehicle #2 as a result causi mage to both vehicles.
HICLE 2 WAS STOPPED AT THE LIGHT OF UMBERLAND ST AT ST PAUL ST HEADING EAST. WHEN NON-REPORTABLI 270 10:58:00 AM DAYLIGHT CLEAR DRIVER INATTENTION EHICLE 1 ALSO ON CUMBERLAND ST COMING UP TP ST PAUL ST. WHEN IT REAR ENDED VEHICLE 2 CAUSING DDUDED. PASSING OR LANE LISAGE 271 7/16/2016 DAMAGE IMPROPERLY was westbound on E Main St passing through the intersection of E Main St and University Av. V1 was in the furthest lane south /2 was in the middle lane also traveling westbound on F Main S vz was in the induce table also haveling westbould on the main St passing through the intersection of E Main St and University. V1 merged into V2' lane, side swiping the driver side of V2, causing damage to the driver side of V2 and the passenger side o V1. Driver 1 stated that she didn' think it was her fault and

DRIVER INATTENTION

WEST

nat V2 would not let her over. Driver 2 stated that he had as session of the lane and V1 did not yield to him prior to changin nes. V2 was an RTS Bus. RTS supervisor responded and book olos of accident. The bus did not have any passengers on it at

272

TE 213 (9/79)

TE 213 (9/79)								_					
	MONROE		P.I.N.:	NOT APPLICA	BLE		R STREET NAM				CASE No.		_
	TOWN CITY						TION WITH/OR				FILE: BY:	PSC 5/13/2020	=
	VILLAGE OF	ROCHESTER	!			SEE MAP					DATE	5/13/2020	-
TIME PERIOD		FROM: 8/1/14	TO: 7/31/19	ENVIRONMEN Use Codes from at right) for these	MV 104 (shown	Light Conditions 1. Daylight 2. Dawn 3. Dusk 4. Dark Road Li 5. Dark Road U	ghted	Roadway Surface 1. Dry 2. Wet 3. Muddy 4. Snow/Ice 5. Slush 10. Other	ce Condition: Weather: 1. Clear 2. Cloudy 3. Rain 4. Snow 5. SleeVHall/Fre 6. Fog/Smog/Sn 10. Other				
No. OF MONTH	IS:		50	S					TO. Oalei		¹ Use Codes from	MV 104 Police Report	
CRASH No.	CASE No.	DATE	TIME	No. of VEHICLES	SEVERITY	LIGHT	ROADWAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING FACTORS	DIRECTION	TYPE ¹	DESCRIPTION	REFERENCE MARKER
273	36313991	7/23/2016	5:36:00 PM	3	INJURY	DAYLIGHT	DRY	CLEAR	UNSAFE LANE CHANGE	WEST	OTHER	White I was in the right lane of the with lanes on Cumberland stapproaching he reor of Vehicle 2. Neiche 2 was at the intersection of Joseph ave waiting to lurn right. Vehicle 3 was in the center lane of the with lanes of Cumberland stapproaching Joseph ave. As Vehicle 1 approached the reard Vehicle 2. Vehicle 1 attempted to change lanes into the center lane. Vehicle 1 Rapposs passenger side of the forth bumper struck the driver side of the rear bumper of Vehicle 2. Vehicle 1 Rapposs of the vehicle 1 Rapposs of Vehicle 3. The rear driver side passenger of Vehicle 6. The rear driver side passenger of Vehicle 1 Sapposs of the vehicle 1 Rapposs of Vehicle 3. The rear driver side passenger of the Vehicle 1 Sapposs of Hospital via Rural metro. Driver 2 was transported to Strong Hospital via Rural metro. Driver 2 was transported to Rochester General Nospital via Rural metro for the compilation of languer back on in Vehicle 1 Strong Hard Rural Pott 10 Rev 10 Re	
274	36314462	7/25/2016	8:57:00 AM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLOUDY	DRIVER INATTENTION	WEST	REAR END	VEHICLE 2 WAS PARKED AT THE CURB IN FRONT 250 CUMBERLAND ST MAKING A DELIVERY. WHEN ITS DRIVER RETURNED TO THE VEHICLE HE FOUND DAMAGE TO THE REAR OF THE VEHICLE. VEHICLE 1 HAD AIREADY LEFT THE SCENE.	
275	36338364	7/28/2016	4:37:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	BRAKES DEFECTIVE	SOUTH	REAR END	In In Item 1 responded to the interest of the and VIZ. Driver of VIZ stated he was driving South on State Is and support of the red light and State In Item 1 state In Item I	t
276	36359491	8/1/2016	6:11:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	DRIVER INATTENTION	SOUTH	LEFT TURN (WITH OTHER CAR)	Driver of vehicle 2 states that she was haveling Westbound on Lyndhust St in the lettlane crossing through the intersection of Sci OS. Driver stated that she was going sarbight when vehicle law, which was to her right, made a let furn in fort of the crussing her strick the drivers side door of vehicle 1. Driver of vehicle 2 stated that they were in the middle of the intersection when this occurred. Driver of vehicle 1 stated the same, except that she stated that she was not in the intersection and was just East of Sci OS. IS have that she was not in the intersection and was just East of Sci OS. IS he stated that as she was adempting to change lanes, from the right lane to the lett lane, in order to make a lett turn onto Sci OS. IS he stated that as she was making the lane change vehicle two beging passing her causing the collision. There were no complaints of visible signs of Intuity upon arrival. Or carramen an osio stress force the orthorous further upon arrival. Or carramen an osio stress force from upon arrival. Or carramen an osio stress force from the properties of the stress of the intuition of the control of from the properties of the properties the properties of the properties the properties of the properties of th	
277	36327085	8/3/2016	4:28:00 PM	2	PROPERTY DAMAGE AND	DAYLIGHT	DRY	CLEAR	FAILURE TO YIELD RIGHT OF WAY	SOUTH	RIGHT ANGLE	ingui y agon anna. Ony camera on sale si mas idening tron neodina	
278	36338373	8/5/2016	11:34:00 PM	2	NON- REPORTABLE	DARK-ROAD LIGHTED	DRY	CLOUDY	DRIVER INATTENTION	WEST	REAR END	VI WAS TRAVELING WIB ON LYNIDHURST AND REAR ENDED V2 WHO WAS PARKED LEGALLY FACING WIB N FRONT OF 74 LYNDHURSTS TI. YAS DI THAT SHE WAS ARGUING WITH P2 WHO WAS INSDE OF THE DRIVER SDE DOOR AND DIDN'T REALIZE THAT THE VEHICLE WAS IN DRIVE. P2 SAD HE TIRED TO STOP THE VEHICLE FROM THE DRIVER SDE BUT FALLED. P2 COMPLAINED OF FAIN THE STOP WAS THE STOP THE VEHICLE FROM THE DRIVER SDE DIT FACE WAS DESCRIBED. THE STATE OF SONDED BUT P2 REFUSED TREATMENT. WI SAD HE HEARD PEOPLE FIGHTING AND OBSERVED VI DRIVING DOOM. THE ROAD WITH P2 HANKING OUT THE DRIVERSDE DOOR. WI SAD THAT VI THEN REARENDED V2. NO VEHICLES TOWED. OCITY CAMERAS IN THE AREA WITNESS I THOMPSON.	
279	36338346	8/6/2016	1:33:00 AM	2	INJURY	DARK-ROAD LIGHTED	WET	RAIN	TRAFFIC CONTROL DEVICES DISREGARDED	NORTH	RIGHT ANGLE	DARRY 7.4 I VINDHURST 5 ROCHESTER NY 14605 VWSN TAWALENS EN ON COMBERAND 5.1 AT JUSEPH AVE AND WAS STRUCK BY 17 WHO WAS TRAVELING WIS ON JOSEPH AT CUMBERLAND 5.1 AT JUSE WAS TRUCK BY 18 WHO WAS TRAVELING WIS HER PASSENGER SIDE DOOR AND THEN V2 STRUCK A LIGHT POLE SUPPORTED BY A CONCRETE BASE. VI THEN LEFT THE SCENE. IDD LOCATE VINAPORS PLATE AT THE SCENE. BOTH OCCUPANTS OF V2 WERE TRANSPORTED TO STRONG FOR BACK, MCCK AND LEG PAIN. IRELOCATED TO 279 RANDOLH ST WHICH IS THE CROAPPORS ADDRESS TO VI. 150PKE TO THE ROO FV V WHO STATED THAT THE VEHICLE IS IN HER NAME BUT HER DAUGHTER DRIVES TI. RELOCATED TO 150 DELAMANIS TA AND LOCATED IT PARKED IN THE DRIVEWAY WITH FRONT END DAMAGE. I SPOKE TO THE DRIVEWAY WITH FRONT END DAMAGE. I SPOKE TO THE DRIVEWAY WITH FRONT END DAMAGE. I SPOKE TO THE DRIVEWAY WITH FRONT END DAMAGE. I SPOKE TO THE DRIVEWAY WITH FRONT END DAMAGE. I SPOKE TO THE DRIVEWAY WITH FRONT END DAMAGE. I SPOKE TO THE DRIVEWAY WITH FRONT END DAMAGE. I SPOKE TO THE DRIVEWAY WITH FRONT END DAMAGE. I SPOKE TO THE DRIVEWAY WITH FRONT END DAMAGE. I SPOKE TO THE DRIVEWAY WITH FRONT END DAMAGE. I SPOKE TO THE DRIVEWAY WITH FRONT END DAMAGE. I SPOKE TO THE DRIVEWAY WITH FRONT END DAMAGE. I SPOKE TO THE DRIVEWAY WITH FRONT END DAMAGE. I SPOKE TO THE DRIVEWAY WITH FRONT END DAMAGE. I SPOKE TO THE DRIVEWAY WITH FRONT END DAMAGE. I SPOKE TO THE DRIVEWAY WITH FRONT END DAMAGE. I SPOKE TO THE DAMAGE WAS TO THE THE TO THE T	
280	36343650	8/10/2016	5:15:00 PM	1	NON- REPORTABLE PROPERTY	DAYLIGHT	DRY	CLEAR	DRIVER INATTENTION UNSAFE LANE CHANGE	SOUTH	LEFT TURN (WITH OTHER CAR)	SAIN SUE WAS LIVEN BY THE REPORT FOR WAS ATTORY BY WAS URING BY WESDOOD (IN COMBETAIN STEEL FOR IN A STEEL AND STEEL WHILE YE WAS LIVEN BY BY BASE AND STEEL WHILE YE WAS TAVEING SOUTHOUR OF SEEL AND STEEL WHILE YE WAS LIVEN BY	t
201	5555557	G 1172010	5. 71.00 FW		DAMAGE	PATEROTTI	DICT	JLLAR	Swit offinion	500111	OVERTARING	I	1

TE 213 (9/79) ROUTE NO. OR STREET NAME MONRO P.I.N.: NOT APPLICABLE CASE No ADJACENT ROADWAY NETWORK TOWN FILE: CITY AT INTERSECTION WITH/OR BETWEEN: BY: PSC VILLAGE OF ROCHESTER DATE: 5/13/2020 SEE MAP ENVIRONMENTAL TIME PERIOD FROM TO Daylight
 Daylight
 Dawn
 Dusk 1. Dry 2. Wet 3. Muddy 1. Clear 2. Cloudy 3. Rain se Codes from MV 104 (shown right) for these categories 8/1/14 7/31/19 4. Snow/lo 4. Snow 5. Dark Road Unlighted 5. Slush 5. Sleel/Hail/Freezing Rain 10. Other 6. Fog/Smog/Smoke lo. OF MONTHS 60 Jse Codes from MV 104 Police Report of VEHICLES DIRECTION DESCRIPTION REFERENCE SOADWAY SURFACE CONDITION CRASH No CASE No DATE TIME APPARENT CONTRIBUTING FACTORS NTERSECTION AT E MAIN ST WHEN HE STRUCK V2 WHO S A BICYCLIST WHO WAS RIDING HIS BIKE E/B ON E MAIN T. ACCORDING TO ALL SWINDSISS VI HAD A GREEN IGHT. V2 SUSTAINED A CONCUSSION, POSSIBLE BROKE OOT AND OTHER MINOR SCRAPES. - WITNESS 1 DARK-ROAF AILURE TO YIELD RIGHT OF 36364214 11:58:00 PM INJURY DRY CLEAR NORTH 282 8/11/2016 OTHER ORRES, RAUL 239 BRYAN ST ROCHESTER NY 14621 352709020 - WITNESS 2 ROLAND, CHRIS 78 OXFORD ST ROCHESTER NY 14609 5853157673 - WITNESS 3 CIALYS Operator #1 reports that he was traveling South on state in lane # uperatur #1 reports trait ne was tavening sount on state in traite #. (from the west curb going east), and stated he saw a green light for south bound direction. Operator #1 reports white exiting the hner loop W/B at State st with a green signal , altempt to make a eft hand turn to go South on State St, when vehicle #1 passed a ed light at said intersection and struck vehicle #2. Witness congrin as and missecular and solve which etc. which etc.

Blurke reports he was behind vehicle etc. and further stales the affici light was green for WiB traffic exiting the Stale St Offramp one Inner loop. Witness also has an e-mail address for contact, lanielburke@teddybearportraits.com - WITNESS 1 BURKE, LEFT TURN RAFFIC CONTROL DEVICES 283 12:16:00 PM DAYLIGHT SOUTH (AGAINST OTHER CAR) DRY CLEAR EPORTABLE ANIEL 7167523361 87783277423024 Tickets Issued: MOHAN KAMI Driver of vehicle number (1) tickets: Ticket Number MONTONG of Vertice Humber: WM01606JEF Wollation: 4024 Ticket Number: WM01606GFK fiolation: 5091 Ticket Number: VM01606GCN Violation: 3191U Ticket Number: VM01606GSB Violation: 1111D1 Ticket Number M01606GVT Violation: 4011A Ticket Number: VM01606H2)
was traveling n/b on State st approaching Allen st behine \ NON-REPORTABL /1 was traveling n/b on State st approaching Allen st behine V2. /2 began to stop for a red light at Allen st. V1 was unable to stop 284 36348568 8/16/2016 5:20:00 PM DAYLIGHT WET RAIN FOLLOWING TOO CLOSELY NORTH REAR END me and stuck the rear of V2. No injuries reported. IRIVER 1 STATED SHE WAS GOING NORTH ON N. LYMOUTH AVE. SHE SAID CROSS TRAFFIC WAS TOPPED, AND SHE WAS UNSURE OF THE COLOR OF THE LIGHT. AS SHE ENTERED THE INTERSECTION EHICLE 2 CAME OUT AND SHE TRIED TO AVOID IT BUT PROPERTY AILURE TO YIELD RIGHT OF FHICLE 1 AND VEHICLE 2 COLLIDED, DRIVER 2 STATED 285 36350195 8/19/2016 12:48:00 PM AMAGE AN DAYLIGHT DRY CLEAR NORTH RIGHT ANGLE TEMBLE 1 AND VENELE 2 COLLIDED, DRIVER 2 STATED TE WAS WESTBOUND STOPPED AT THE LIGHT. THE LIGHT TURNED GREEN AND HE PROCEDED FORWARD AND WAS STRUCK BY VEHICLE 1. WITNESS SCOTT NEWBURGE STATED HE WAS BEHIND VEHICLE 2 AND THE LIGHT IRNED GREEN AS VEHICLE 2 WENT FORWARD IT WAS RUCK BY VEHICLE 1. - WITNESS 1 NEWBURGE, SCOTT UMBERLAND. VEH 1 WAS IN THE LEFT LANE ESIGNATED FOR BOTH STRAIGHT AND LEFT HAND URNS ONTO N CLINTON. VEH 2 WAS IN THE MIDDLE LEFT TURN ANE DESIGNATED FOR STRAIGHT AHEAD ONLY. VEH 1
VAS TRAVELING EAST PAST N. CLINTON. VEH 2
VITEMPTED TO MAKE A LEFT HAND TURN IN THE
STRAIGHT AHEAD LANE ONLY, CUTTING OFF VEH 1. VEH NON-FAILURE TO YIELD RIGHT OF (AGAINST OTHER CAR) 286 36449042 8/28/2016 10:55:00 AM 2 DAYLIGHT DRY CLEAR FΔST FPORTABL DID STRIKE VEH 2 IN THE LEFT BACK DRIVERSIDE, NO 02 Stated that while he was traveling southbound on State St V1 ideswipe V2 right side breaking the right side mirror. V1 contin NON-287 36363227 8/29/2016 10:40:00 AM 2 DAYLIGHT DRY CLEAR UNKNOWN SOUTH OVERTAKING astbound on Allen St and did not stop to asses the damages. D2 REPORTABLI assurunce on America, and one not stop to asses the damages, look pictures with his cell phone of V1 NYSL. No injuries were eported at the time of the accident V2 was cared by owner. reported as the little of the above listed Van cashed into a non the above date and time the above listed Van cashed into a wooden shockade fence owned by FastTrac Gas Station located a 672 E. Main St. The driver backed his van up of the curb and parked if in the FastTrac Parking in The driver is a white male in his 40&aposs. The driver then got into a pickup truck and left the NON cation. At the time of this report the above listed striking vehicle i DRIVER INATTENTION 288 36382508 9/3/2016 2:23:00 PM DAYLIGHT DRY CLEAR NORTH OTHER Deadors. At the time of this report are according to elections with a full parked in the parking lot. The Manager of FastTrac have bee officed of the property damage. Lattempled to speak with the winer of the van on two separate days but was unable to get a esponse at 446 Stone Rd. According to FastTrac management. REPORTABLI ey have video footage of the accident but are unable to retrieve t this time. I advised them to call back when they are able to view I was traveling eb on delevan street. v2 was traveling sb on scio RIGHT TUR AILURE TO YIELD RIGHT OF PROPERTY DAYLIGHT SOUTH 289 36391384 9/7/2016 4:21:00 PM 2 DRY CLEAR (AGAINST reet. v1 attempted to make a right sb turn on scio and with its fro DAMAGE THER CAR mper struck v2 in its front bumper, no injuries. ANE ON CUMBERLAND. V1 LEAVES HIS LANE AND NON TRIKES V2 ON THE PASSENGER SIDE. WITNESS STAYED UNSAFE LANE CHANGE 2 WEST OVERTAKING 290 36375273 9/9/2016 12:40:00 PM DAYLIGHT DRY CLOUDY REPORTABLE ON SCENE, NO INJURIES, NO TOWS. - WITNESS 1 BURCH ERRI A 48 CEDAR ST ROCHESTER NY 146110000 52870776 Was luming onto be evan 31. on ornorn and se ail. The driver first said that there was a car that he had to avoid hat its why he hit the guard rail. but it lold him Delevan is a one w to there wouldn&apost be any cars on the road. Then he said THAT SOMETHING CAME OVER the guard rail and was in the 291 36386910 EAST OTHER 9/11/2016 3:27:00 AM WET RAIN AMAGE ANI oad i pointed out that there was about a 12 foot drop off for the LIGHTED INJURY ard rail, so then be changed it to no it was just in the road be know what it was or where it went to, based on my ining and experience I would say with the rain he just came ound the corner too fast. The male went to strong for a head TICLE I WAS TRAVELING WESTBOOND CUMBERLAND ST. VEHICLE 2 WAS TRAVELING OWNDERLAND ST. VEHICLE ZWAS TRAVELING ORTHBOUND ON JOSEPH AVE. THE DRIVER OF VEHICLE STATED THAT HIS TRAFFIC CONTROL WAS GREEN AND ROCEEDED INTO THE INTERSECTION. VEHICLE 2 RAFFIC CONTROL DEVICE PROPERT 292 6:31:00 PN DAYLIGHT DRY CLEAR WEST RIGHT ANGLE 9/13/2016 DISREGARDED DAMAGE CONTINUED INTO THE INTERSECTION AND WAS STRUCK N THE RIGHT REAR TIRE/ QUARTER PANEL BY THE RONT RIGHT BUMPER OF VEHICLE 1. NO INJURIES WERE BSERVED OR REPORTED. VEHICLE 1 SUSTAINED MINOR

TE 213 (9/79) ROUTE NO. OR STREET NAME MONRO P.I.N.: NOT APPLICABLE CASE No ADJACENT ROADWAY NETWORK TOWN FILE: CITY AT INTERSECTION WITH/OR BETWEEN: BY: PSC VILLAGE OF ROCHESTER DATE: 5/13/2020 SEE MAP ENVIRONMENTAL TIME PERIOD FROM TO Roadway Surface Condition Daylight
 Daylight
 Dawn
 Dusk 1. Dry 2. Wet 3. Muddy 1. Clear 2. Cloudy 3. Rain se Codes from MV 104 (shown right) for these categories 8/1/14 7/31/19 4. Snow/lo 4. Snow 5. Sleet/Hail/Freezing Rain 5. Dark Road Unlighted 5. Slush 10. Other 6. Fog/Smog/Smoke lo. OF MONTHS 60 Jse Codes from MV 104 Police Report of VEHICLES DIRECTION DESCRIPTION REFERENCE OADWAY CRASH No CASE No DATE TIME APPARENT CONTRIBUTING FACTORS or (vz) states sne was driving E/B on East Main St W ray van struck her on the left quarter panel. Driver of (V2) state ay vari stuck he for he len quale parter. Driven (122) sales: at she wasn&post sure what (V1) was doing before the MVA ecause of the glare from the sun. (V1) pulled over but then drov f according to Driver of (V2). Driver of (V2) stated that she NON. 293 36416535 6:58:00 PM DAYLIGHT FOLLOWING TOO CLOSELY EAST REAR END 9/15/2016 DRY CLEAR lowed (V1) for a little bit of time but did not copy down a license late or see who was driving. No tow needed for (V2)no injuries No compare in the area of the location
On 09/18/16 I responded to the intersection of State st at Allen St.
met with and spoke to the drivers of V1 and V2. Driver of V1 state she was on Allen St stopped at the traffic light facing West. She ras in the left turn lane. She stated when the light turned gro as in the left turn lane. She staked when the light turned green he realized she was in the wrong lane and needed to go straight, he began to pull into the right lane to go straight and hit V2. Drive f V2 was on Allen St stopped at the traffic light. He was facing NON. DARK-ROAF FAILURE TO YIELD RIGHT OF 294 36392356 9/19/2016 8:29:00 PM DRY CLEAR WEST OVERTAKING West and was in the right lane, looking to drive straight. When the ght turned green he drove straight and driver of V1 struck his car age to the right front guarter panel. V2 had damage e driver side door and rear passenger side door. No one was 1 STRUCK V2 IN REAR, CAUSING V2 TO MOVE INTO AND 295 36393492 9/20/2016 7:30:00 AM DAYLIGHT DRY CLEAR DRIVER INATTENTION SOUTH OTHER EPORTABL IIT V3. V2 AND V3 WERE STOPPED AT A RED LIGHT.
3 was stopped at the red light at Cumberland St going NE on so was appear at material and administration and spirit and vision to despit Ave. V2 was slopped behind V3. V1 was driving behind V1. V1 and did not stop in time before striking the rear of V2, which cause V2 to strike the rear of V3.No injuries. D1 was issued a ticket for inflicensed operator. V2 and V3 were cared for by drivers and V1. PROPERTY 296 36396825 9/23/2016 4-54-00 PM DAYLIGHT WET RΔIN FOLLOWING TOO CLOSELY NORTH-EAST OTHER as driven away by the RO on Venicies were traveling sounbound on State St beto templing to make a left turn onto Allen St with the green light. river #2 stated that he had to slow down to a stop while turning where the band of PROPERTY 297 36408609 9/28/2016 8:18:00 AM DAYLIGHT DRY CLEAR FOLLOWING TOO CLOSELY SOUTH-EAST REAR END DAMAGE n the middle of the intersection, and that he did not have enough EA'2 WAS PARKED IN FRIDN'T OF 276 LYNDHURST ACING WEST BOUND, VEH 1 WAS TRAVELING FAILURE TO YIELD RIGHT OF NON-VESTBOUND ON LYNDURST, WHICH IS A ONE WAY 298 36405524 9/30/2016 9:42:00 AM 2 DAYLIGHT DRY CLOUDY WEST OVERTAKING REPORTARI STREET WESTBOUND. VEH 1 DID SIDESWIPE VEH 2 CAUSING DAMAGE TO THE DRIVER SIDE MIRROR. NO ULIRIES WERE REPORTED OR ORSERVED CUMBERLAND ST WHEN VI TRIED TO PASS HIM ON THE LEFT SIDE AND REAR ENDED V2. DRIVER OF VI EXITED HE CAR AND TOLD DRIVER OF V2 THAT THERE WAS NO NON-DAMAGE AND THE POLICE DID NOT NEED TO BE CALLED 2 FOLLOWING TOO CLOSELY REAR END 299 36458605 10/5/2016 6:36:00 AM DAYLIGHT DRY CLEAR WEST IRIVER OF V2 TOLD HIM TO WAIT FOR POLICE TO ARRIVE UT V2 TOOK OFF. THERE WAS VISIBLE DAMAGE TO THI LEAR BUMPER OF V2. I WAS UNABLE TO CHECK TO EPORTABL ADDRESS FO THE R/O OF V1 BECAUSE IT IS IN THE (V2) WAS TRAVELING W/B ON CENTRAL AVENUE ABOUT TO PASS THROUGH THE ST PAUL INTERSECTION WITH A RAFFIC CONTROL DEVICES GREEN LIGHT. BIKE1 WAS TRAVELING N/B ON ST PAUL 36419113 INJURY OTHER 9:43:00 AM DAYLIGHT DRY CLOUDY NORTH 300 10/8/2016 DISREGARDED WITH A RED LIGHT. AS (V2) ENTERED THE INTERSECTION BIKE1 WAS UNABLE T STOP AND RAN INTO THE DRIVERS OOOR OV (V2). MINOR SHOULDER INJURY TO BIKE RIDER On 10/12/16 at about 1220hrs, Chris Klemenz, driver for flower of wing called 911 to report the MVA hit and run, upon arrival he uving cance 31 to Epplot the Work in and this, upon a river in enforced me that vehicle 1 was parked at pump 16 while he wanside the store located at 672 E Main St (Fastrack). While inside he store a Lowes box truck (V2) did side swipe his vehicle as it vas exiting the parking lot causing damage to vehicle 1. V2 continued without stopping. A review of the video footage shows DRIVER INEXPERIENCE OVERTAKING 301 36424537 10/12/2016 12:15:00 PM DAYLIGHT DRY CLEAR SOUTH REPORTABLE ne MVA occurring, but does not reveal an driver&aposs, lescription or license plate. V2 exited the lot and continued W/B or E Main St. A check of the credit card system shows the operator aid for fuel with some sort of unnamed "Fleet Fuel" edit card, no usable information was able to be obtained from th eipt. No injuries reported as a result of the MVA ver or venicle 2 stated that she was traveling No rrough the intersection of East Main St and North Union St, who ehicle 1 struck her left rear fender/fire. Vehicle 2 sustained lamage to the rear tire/axle. Vehicle 2 required to be towed due t a flat tire and possible damage to axel. Driver of vehicle 1 stated at he was at the intersection of North Union St and East Main at he was at the medisculor of votin to mind is a fast wait, do observed an uninvolved vehicle in the Westbound lane of Eas ain St in the center median. Driver stated that this caught his tention when the vehicle began moving forward even though the NON OUTSIDE CAR DISTRACTION SOUTH-EAST 36429237 10/12/2016 9:58:00 PM DRY CLEAR 302 (AGAINST REPORTABLI LIGHTED ast/West traffic had a red light. Driver stated that as he was OTHER CAR) aking a left turn onto East Main St. he needed to make a wide lashing a leak until with a 253 Maint 3,000 in the resecute unit mise a wide min in order to get around the vehicle. As he was doing so, vehicl was traveling Northbound and driver of vehicle 1 mis-judged the istance between his vehicle and vehicle 2, and struck vehicle two with his front left bumper. Vehicle 1 sustained damage to the front

eft bumper/fender area. Vehicle two also required to be towed. No complaints or visible signs of injury at the time of report. Driver of webicle 2 did base a suspended license with 1 scoff TE 213 (9/79) ROUTE NO. OR STREET NAME MONRO P.I.N.: NOT APPLICABLE CASE No ADJACENT ROADWAY NETWORK TOWN FILE: CITY AT INTERSECTION WITH/OR BETWEEN: BY: PSC VILLAGE OF ROCHESTER DATE: 5/13/2020 SEE MAP FROM ENVIRONMENTAL TIME PERIOD TO Roadway Surface Condition Daylight
 Daylight
 Dawn
 Dusk 1. Dry 2. Wet 3. Muddy 1. Clear 2. Cloudy 3. Rain se Codes from MV 104 (shown right) for these categories 8/1/14 7/31/19 4. Dark Road Lighted 4. Snow/lo 4. Snow 5. Dark Road Unlighted 5. Slush 5. Sleet/Hail/Freezing Rain 10. Other 6. Fog/Smog/Smoke lo. OF MONTHS 60 Jse Codes from MV 104 Police Report of VEHICLES IGHT DIRECTION DESCRIPTION REFERENCE SOADWAY SURFACE CONDITION CRASH No CASE No DATE TIME APPARENT CONTRIBUTING FACTORS T Bicycle) was traveling northbound on Joseph Ave and made (v) bucket was very an unusual or busen whee and mad a quarters of the way across the intersection at Cumberland St. and turned back southbound when he observed that the traffic signal for westbound traffic on Cumberland Street turn green. While (V1) was turning southbound he struck the passenger side door of (V2) casing a dent in the door and him to fall off of his icvole. The operator of (V1) had been transported to Strong Cypie: The operation (i/V) had use harsparked to 3 storing memorial hospital prior to my arrival. NYS police Trooper Sears 99093(SP16E) was already on scene prior to (V1) operator beir insported. (V1) operator was transported to Strong Memorial ospital by AMR ambulance # 7499. I met with the operator of V1) at Strong memorial hospital. The operator of (V1) said that V2) ran over his ankle. (W1) aid that he observed the accident, PEDESTRIAN'S nd said that (V1) went behind (V2) and was not using the osswalk. (W1) said that while (V1) was crossing there was INJURY WEST 303 36440348 10/14/2016 3:01:00 PM DAYLIGHT nother vehicle that was traveling westbound on Cumberland anoher vehicle hat was traveling westbound on Cumberland sixelet hal (VI) was tying ba void hat was in he lane to hen orth (right) of (V2). (WI) said that (VI) jerked his handlebar to the left and wasnkapost sure if the other vehicle clipped him, but said this he did see hat (VI) operator kapos so told id get stuck between the bible pedal and ground as is was turning around and struck (V2). (W1) said that (V2) was barely moving and did not run over the erator of (V1). The operator of (V2) said that she never saw (V1 peraturu (v V). Her beraturu (22 sau utat sie lieve saw ind slopped when he struck her car.The operator of (V1) did sustain a fractured left ankle verified by Crystal James-Hebbs fi ne radiology dept of Strong Memorial Hospital. - WITNESS 1 NISEY ALLEN 2454 PARKER RD PALMYRA NY 14522 Was traveling NB on University Ave in the left lane toward is fain St. V2 was also traveling NB on University Ave and was to NON-DARK-ROAL e right of V1 in the center lane. As both cars were going forwing in the center lane was a right sideview mirror of V1 struck the left sideview mirror of V1. 304 36438215 10/22/2016 7:09:00 PM DRY CLEAR UNKNOWN NORTH OVERTAKING EPORTABL LIGHTED No injuries. Both vehicles cared for by drivers.
was in the left turning lane of the S/B lanes on State Stat A St waiting to turn left on to Allen St. V1 was in the right lane of the or walling to lath learn to Parell 3.4 was fill alter injurate to line WB lanes on State St approaching Allen St. D2 states that the car in the left lane of the N/B lane stopped. He then turned left not seeing V1 still traveling N/B. V2 failed to yield to V1 causing V1 kr AILURE TO YIELD RIGHT OF NON 305 36446839 10/27/2016 3:45:00 PM DAYLIGHT WFT RAIN NORTH RIGHT ANGLE EPORTARI WAY table 3.7 No inhinter proported on the above date and lime I responded to the above dates and lime I responded to the above address for it and run MVA. There the driver of V2 told me that she was aveiling West on Lyndhurst st from N. Union St. when V1 (which s described as a small red SUV) turned East on Lyndhurst St fror avs Alley and struck the front of her vehicle with the front of his PROPERTY DARK-ROAD AILURE TO YIELD RIGHT OF ays alley and struct whe button the value with the button the shick lit appears that V2 disregarded the traffic signal indicating yndhurst is a one way road from East to West. V2 had significa amage to lit's front bumper and hood. The driver of V1 306 36447510 10/27/2016 5:41:00 PM 2 WFT RAIN FAST HEAD ON DAMAGE LIGHTED ould not describe the driver of V2 and stated that the accident appened so fast she could not get a license plate. Photographs ere taken of V2 and a camera check of the area was negative velet black in Vizialia of calinera Unios of inter area was relegative. Thirter of Vehicle two stated he was passing through the intersection of the inner loop exit and North Clinton Ave, when vehicle one urmed left striking the passenger side of his vehicle. He stated that be stopped, and vehicle one confinued Northbound on Clinton LEFT TURN Ave, briefly stopping, and appeared that he was going to get out. NON 307 36469399 10/29/2016 6:45:00 PM 2 DUSK DRY CLEAR DRIVER INATTENTION NORTH (AGAINST iver of vehicle two stated that he then attempted to make contact FPORTABLI where or vehicle was sale in a new left authination on N Clinic with vehicle one when it speed off traveling Northbound on N Clinic we. Vehicle two sustained small cosmetic damage to the front wassenger door/lender. Delayed report and no complaints/visible igns of injury. Driver of vehicle two stated that the only description OTHER CAR) f the vehicle was a white taxi van. oth vehicles were backing out of parking spots at fastrac. no NON-DARK-ROAL 2 BACKING UNSAFELY 308 36452899 11/1/2016 1:14:00 AM DRY CLEAR SOUTH OTHER lamage to veh 1. veh 1's tow hitch caught the rear bumpe EPORTABLI LIGHTED 2 and nulled it off In 11/01/16 I responded to the intersection of State ST and Alle ist for the report of a MVA. I met with and spoke to the drivers of /1 and V2. Driver of V1 stated she was slopped at the traffic light in State st facing North. She state her light was red, but was RIGHT TURN oking at a traffic light further down the street that just turned gree NON DRIVER INATTENTION obbets and a familiary frough the intersection and stuck the rear wassenger door on V2. Driver of V2 stated he was driving East or Allen St. He stated he had the green light and drove east through he intersection. As he drove through, his car was struck by V1. 309 36454943 11/1/2016 3:41:00 PM DAYLIGHT DRY CLEAR NORTH (WITH OTHER REPORTABLI CAR) 1 had front bumper damage. V2 had damage to the rear ssenger door on the right side of the car. No one was injured inver of vehicle two states she parked her car at 282 Lyndhurst treet at approximately 9:00 P.M. on (11/04/16). Driver of Vehicle to states she returned to her car at approximately 11 P.M. on PROPERTY DARK-ROAL DRIVER INATTENTION 310 36480240 11/4/2016 11:00:00 PM 2 DRY CLEAR UNKNOWN UNKNOWN 11/04/16) to find damage on the passenger side rear door that vas not their before she parked her car. Driver of vehicle two DAMAGE UNLIGHTED and the block of the plant of the Conference where the conference were found the area. (See technician report for photographs of damage). Micers were in the area when they heard a found crash. A MVA as discovered at the intersection of N. Union St and University

ALCOHOL INVOLVEMENT

DRY

LIGHTED

CLEAR

3

DAMAGE

2:19:00 AM

311

36471432

11/5/2016

Ave.. V2 was slowing down to make a left hand turn and was struck by V1 and it pushed V2 into V3. TSgt Glynn Responded to

ssist and conducted a DWI investigation and determined Jaime to

OTHER

NORTH

ROUTE NO. OR STREET NAME MONRO P.I.N.: NOT APPLICABLE CASE No ADJACENT ROADWAY NETWORK TOWN FILE: CITY AT INTERSECTION WITH/OR BETWEEN: BY: PSC VILLAGE OF ROCHESTER DATE: 5/13/2020 SEE MAP NVIRONMENTAL TIME PERIOD FROM TO Daylight
 Daylight
 Dawn
 Dusk 1. Dry 2. Wet 3. Muddy 1. Clear 2. Cloudy 3. Rain se Codes from MV 104 (shown right) for these categories 8/1/14 7/31/19 4. Snow/lo 5. Dark Road Unlighted 5. Slush 5. Sleel/Hail/Freezing Rain 10. Other 6. Fog/Smog/Smoke lo. OF MONTHS 60 Ise Codes from MV 104 Police Report of VEHICLES DIRECTION DESCRIPTION REFERENCE CRASH No CASE No DATE TIME APPARENT CONTRIBUTING FACTORS WAS TRAVELLING S/F ON UNIVERSITY AVENUE AND VAS TRAVELLING N/E ON N. UNION, WHEN VI FAILED TO TOP AT THE RED TRAFFIC LIGHT AND THIS IS WHEN V2 WAS UNABLE TO STOP IN TIME AND THEN DID STRIKE THE REAR PASSENGER SIDE QUARTERPANEL OF V1 WIT THE FRONT BUMPBER OF V2. V1 THEN WENT UP ONTO HE CURBING CAUSING DAMAGE TO THE FRONT RIVER'S SIDE TIRE AND RIM OF VI. NO INJURIES EPORTED. DRIVER OF VI STATES THAT SHE RAFFIC CONTROL DEVICES 312 36465011 9:26:00 AM DAYLIGHT DRY CLEAR SOUTH-EAST RIGHT ANGLE JISTAKENLY WENT THROUGH THE RED LIGHT WHICH THEN CAUSED THE ACCIDENT. FAMILY MEMBERS OF VI REQUESTED THAT SAID DRIVER OF V1 GO TO THE HOSPITAL TO GET CHECKED OUT. AMR RESPONDED AND TRANSPORTED SAID DRIVER OF VI TO RGH. RAFFIC CITATION ISSUED TO DRIVER OF V2 FOR

/1 was traveling n/b in the left lane of State st behind V2. As V2 r was traveling in bill the letranie of state screening v2. As v2 lowed for traffic, V1 attempted to change lanes into the right lan und struck the p/s corner on the rear bumper of V2. No injuries PASSING OR LANE USAGE 313 36473712 11/10/2016 2-27-00 PM DAYLIGHT DRY CLEAR NORTH OTHER AUL ST AT CUMBERLAND ST. VEHICLE 1 WAS IN THE CENTER LANE AND VEHICLE 2 WAS IN THE LEFT LAND NCE YOU CROSS CUMBERLAND ST THE TWO LANES ONCE TO GROSS COMBERCATION STATE TWO SAMES ARE SMALLER IN WIDTH. VEHICLE 1 WAS SLIGHTLY IN FRONT AND TO THE RIGHT OF VEHICLE 2. AS BOTH VEHICLES MOVED FOREWARD VEHICLE 1 REAR LEFT BUMPER MADE CONTACT WITH VEHICLE 2'S FRON! PROPERTY 314 36485430 11/17/2016 12:58:00 PM DAYLIGHT DRY CLEAR DRIVER INATTENTION NORTH OVERTAKING RIGHT BUMPER. THUS CAUSING DAMAGE TO BOTH ON ST PAUL ST AT CUMBERLAND ST. WHEN VEHICLE ALSO ON ST PAUL ST HEADING SOUTH HIT THE REAR RIGHT CORNER OF VEHICLE 2&apos:S REAR BUMPER. HUS CAUSING DAMAGE TO IT&anos S BUMPER. THE PROPERTY 315 36490741 11/18/2016 8-12-00 AM DAYLIGHT DRY CLEAR DRIVER INATTENTION SOUTH REAR END OAD HAS TWO UNMARKED LANES AND VEHICLE 1 WAS DAMAGE ROAD HAS I WO UNMARKED LANES AND VEHICLE I WAS TRYING TO GET PASS VEHICLE 2 WHEN IT MADE CONTACT WITH IT. THE DRIVER OF VEHICLE 1 FIRST TOLD THE DRIVER OF VEHICLE 2 THAT HE BARELY TAPPED HER CAR, THEN CHANGED HIS STORY ONCE RO WAS ON urn right onto Cumberland St. V2 lost control and spun out on e/snow on the road and spun into a snow embankment. V1 wa NON OTHER (VEHICLE) eveling southbound on North St. behind V2. As V2 started to spi 316 36486683 11/21/2016 3:32:00 PM DAYLIGHT SNOW/ICE SNOW SOUTH RIGHT ANGLE REPORTABL PAVEMENT SLIPPERY out, V1 applied brakes and slid into V2. No one was injured. V1 and minor front end damage. V2 had rear passenger side pand amage and a rear tire axle break. V2 had Excel tow his vehicle SOUTH BOUND ON STATE ST SHE STOP AT THE LIGHT AT STATE ST/ALLEN ST WHEN VEHICLE #1 REAR ENDED HER NON EHICLE CAUSING DAMAGE TO THE REAR BUMPER 317 36489924 11/22/2016 9:01:00 AM DAYLIGHT WFT CLEAR FOLLOWING TOO CLOSELY SOUTH REAR END EPORTABL AREA OPERATOR OF VEHICLE #1 STATES THAT SHE WAS RAVELING SOUTH ROUND ON STATE ST SHE STEP ON ER BRAKES AND HER VEHICLE REAR ENDED VEHICLE oth v's were traveling west on Cumberland St. V1 beg PASSING OR LANE USAGE NON change lanes to the left lane and then to turn left onto Clinton Av 2 OVERTAKING 318 36493994 11/22/2016 12:15:00 PM DAYLIGHT SNOW/ICE CLOUDY WEST his action by V1 caused a collision to occur with V2. V1 change EPORTABL IMPROPERLY nes improperly and/or turned improperly EHICLE TAND VEHICLE 2 WERE BOTH TRAVELING EASTBOUND ON EAST MAIN STREET. VEHICLE 2 WAS IN THE FAR LEFT LANE. VEHICLE 1 WAS IN THE RIGHT LANE

DRIVER INATTENTION

DRIVER INATTENTION

DRIVER INATTENTION

EAST

SOUTH

(AGAINST

OTHER CAR)

RIGHT ANGLE

319

320

321

36552880

11/23/2016

11/24/2016

1:32:00 PM

5:10:00 PM

DAYLIGHT

LIGHTED

LIGHTED

REPORTABLE

EPORTABL

INJURY

DRY

CLEAR

VEHICLE 1 DID MAKE A LEFT HAND TURN IN FRONT OF VEHICLE 2 CAUSING VEHICLE 2 TO STRIKE THE DRIVER SIDE REAR OF VEHICLE 1. VEHICLE 2 SUSTAINED DAMAGE TO THE PASSENGER SIDE FRONT END. VEHICLE 1 WAS NOT AT THE SCENE UPON MY ARRIVAL BUT THE DRIVER DID CALL 911 TO REPORT THAT SHE

AD BEEN IN AN ACCIDENT. DRIVER #2 DESCRIBED THI

DRIVER OF VEHICLE 1 AND THIS DESCRIPTION DD MATCHAT OF THE PERSON THAT I SPOKE WITH AT 1264 EAST HAN STREET. TYONINA DUNN DID ADMIT TO DRIVING REHICLE 1. A UTTWAS ISSUED FOR OPERATING THE MOTOR VEHICLE WITHOUT A LICENSE NOR A LICENSED DRIVER IN THE VEHICLE. BOTH VEHICLES WERE DRIVABLE. NO INJURIES NOR COMPLAINT OF PAIN. WITHOUS STREET, PERSON THE VEHICLES WERE DRIVERS 1. DRIVERS 1. BIT DRIVERS

onflicting as to who had the green light at the 4 way intersection

hich in turn struck V3, who finally struck V4. - WITNESS 1, ROCHU DANIEL 185 EXCHANGE BLVD

OCHESTER NY

eh 1 rear left bumper and veh 2 front right bumper sustained amane, weh 1 lowed via AAA private low 1-4 were all traveling no on Union St lowards E Main St V2-4

TE	213	(9/79)	

E 213 (9/79)						DOLLTE NO. O	R STREET NAM	ır.			ı		
	MONROE		P.I.N.:	NOT APPLICA	BLE		ADWAY NETWO				CASE No.:		=
	TOWN CITY					AT INTERSEC					FILE: BY:	PSC 5/13/2020	-
	VILLAGE OF	ROCHESTER			-	SEE MAP					DATE:	5/13/2020	-
TIME PERIOD		FROM: 8/1/14	TO: 7/31/19	ENVIRONMEN Use Codes from at right) for these	MV 104 (shown e categories	Light Conditions 1. Daylight 2. Dawn 3. Dusk 4. Dark Road Li 5. Dark Road U	ghted nlighted	Roadway Surface 1. Dry 2. Wet 3. Muddy 4. Snow/Ice 5. Slush 10. Other	ce Condition: Weather: 1. Clear 2. Cloudy 3. Rain 4. Snow 5. Sleet/Hail/Fre 6. Fog/Smog/Sr 10. Other				
lo. OF MONTH	IS:	(50	ES								MV 104 Police Report	
CRASH No.	CASE No.	DATE	TIME	No. of VEHICLES	SEVERITY	CONDITIONS	ROAD WAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING FACTORS	DIRECTION	TYPE ¹	DESCRIPTION	REFERENCE MARKER
322	36508089	11/27/2016	12:34:00 PM	1	NJURY	DAYLIGHT	WET	CLEAR	DRIVER INATTENTION	NORTH	OTHER	Ut was in the center Nts lare of University Ave. supper at the ratific light for East Main St. Once he light turned green, he headed N/B toward the hiner Loop on-ramp. As he began moving, he stakes the pedestain was headed W/B on East Main St and stepped in front for hear at the pedestrian initially staked the ratific light for W/B traffic on East Main St was amber when she loop an crossing he steet. As she was headed W/B, V1 stuck her as it was headed N/B on University Ave toward the hiner Loop on- ramp. After her initial stakement, however, she said the light was green. She hen bid medical personnel who arrived on scene the light was green V1 had pre-existing paint scrapes on the front light turninger and no new damage. D I did not have any injuries. The pedestrian complained of chest pain and back pain, but could not articulate where she was struck. AMR rig #730-responded to the scene and transproted the pedestrian to Strong Memorial Hospilal. There were no independent whesses to his MVA.	
323	36495829	11/28/2016	2:46:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	DRIVER INATTENTION	EAST	OVERTAKING	On 11/28/2016 at about at about 1446 hours police were dispatched to E Main St and University Ave for a reported MVA. Driver of V1 stated she was in the left lane of E Main St, e/b. Driver of V2 stated he was in the right lane (curb lane), also e/b E Main St. Driver of V1 stated the left lane was coned off for	
324	36503187	11/30/2016	3:58:00 PM	2	NON- REPORTABLE	DARK-ROAD LIGHTED	DRY	CLEAR	UNSAFE LANE CHANGE	WEST	OVERTAKING	VI IS A SCHOOL BUS WHO HAD STUDENTS ABOARD AT TIME OF ACCIDENT DI PROVIDED A ROSTER OF STUDENTS. AN ADDITIONAL BUS WAS REQUESTED AND ALREADY TRANSPORTED THE STUDENTS FROM THE SCHEWERY TO POLICE ARRIVAL. ACCORDING TO DI THERE WERE NO INJURIES. V2 WAS LEGALLY PARKED AND UNIOCCUPED AT TIME OF ACCIDENT. DI REPORTS THAT SHE WAS TRAVELING WIS ON CUMBERTAND ST IN THE FAR RIGHT LAME ADJACENT TO THE RIGHT LAWE SA PARKING LAME FOR VEHICLES TO LEGALLY PARKED A PARKING LAME FOR VEHICLES TO LEGALLY PARK DI SAID THAT SHE STARTED CHANGENG LAMES TO THE RIGHT WHERE THE PARKING LAME ENDS AND TURNS NOTO A RIGHT HAND TURN LAME AT JOSEPH ANE. AT THAT MEY OF PREMATURELY CHANGED LAMES AND STRUCK V2. V1 SUSTAINED DAMAGE TO DIS FROM THE STRUCK V2. V1 SUSTAINED DAMAGE TO DIS FROM THE STUDENTS ADD THAT ORIGINALLY SHE WAS LINAWABE THAT THE ACCIDENT OCCURED AND WAS TOLD BY THE STUDENTS ABOARD. UPON NY ARRIVAL DI WAS ABLE TO SHOW HE WHICH PART OF VI MADE CONTACT WITH V2. BOTH THE DAMAGE ON V1 AND V2 WAS CONSISTANT WITH DI DESCRIPTION OF THE ACCIDENT. V2 OWNER WAS ON SCENE UPON MY ARRIVAL AND WAS NOT WITH THE VEHICLE AT TIME OF ACCIDENT. DI WAS ISSUED UTT FOR UNSAFE LAME CHANGE AND NOT WITH THE VEHICLE AT TIME OF ACCIDENT. DO WAS LISAMED BANG SURE LAND SELECT OF THE ACCIDENT OF WITH THE WAS CLEAR BEFORE MOWING OVER. BOTH THE CAMBE CHANGE AND NOT MAKING SURE LAND SELECASED FROM THE ROSTER PROWIDED ARE AS FOLLOWS. RAZ COLORY THE ROSTER PROWIDED ARE AS FOLLOWS. RAZ COLORY THE REGENE EDIGES 11 YOA, JOL LANIEK, CYALA KEZAYS K GRADE, SHANICUAD DIGSS 14 YOA, ARMANI BROWN 13 TO AGRIBLELY SON LANGE RESONE DIGGS 11 YOA, ARMANI BROWN 13 TO AGRIBLE SYOA LANGER CON YOA, CALORY CRUZ 14 YOA, CARBERLLA ROWN LAND WAS FOUL DIVA.	
325	36503242	12/1/2016	9:38:00 PM	2	PROPERTY DAMAGE	DARK-ROAD LIGHTED	DRY	CLOUDY	FALURE TO YIELD RIGHT OF WAY	NORTH	RIGHT ANGLE	IV MAS TRAVELING NIS ON N CLINTON AVE APPROACHING THE CUMBERLANDS 1E JB INTERSECTION 12 WAS TRAVELING SIS ON N CLINTON AVE APPROACHING THE CUMBERLAND SIE JB INTERSECTION. BOTH VEHICLES HAD A GREEN SKANAL AS THEY APPROACHED THE INTERSECTION. V2 ATTEMPTED TO MAKE A LEFT TURN ONTO CUMBERLAND SIT OHEAD LIFE FROM N CLINTON AVE FALING TO YELD THE RIGHT OF WAY OF V1 TRAVELING NIS ON N CLINTON AVE AT THAT TIME V1 STRUCK THE PISO OF V2 WITH THE FRONT OF V1. VI SUSTAMED DAMAGE TO FROM BUMPER AND V2 SUSTAMED DAMAGE TO STRIFT BY, SU ZWAS SUSTAMED DAMAGE TO STRIFT BY, SU ZWAS SUSTAMED DAMAGE TO STRIFT BY, SU ZWAS	

TE 213 (9/79) ROUTE NO. OR STREET NAME MONRO P.I.N.: NOT APPLICABLE CASE No ADJACENT ROADWAY NETWORK TOWN FILE: CITY AT INTERSECTION WITH/OR BETWEEN: BY: PSC VILLAGE OF ROCHESTER DATE: 5/13/2020 SEE MAP ENVIRONMENTAL TIME PERIOD FROM TO Daylight
 Daylight
 Dawn
 Dusk 1. Dry 2. Wet 3. Muddy 1. Clear 2. Cloudy 3. Rain se Codes from MV 104 (shown right) for these categories 8/1/14 7/31/19 4. Snow/lo 5. Sleet/Hail/Freezing Rain 5. Dark Road Unlighted 5. Slush 10. Other 6. Fog/Smog/Smoke lo. OF MONTHS 60 Jse Codes from MV 104 Police Report of VEHICLES DIRECTION DESCRIPTION REFERENCE ROADWAY SURFACE SONDITION CRASH No CASE No DATE TIME APPARENT CONTRIBUTING FACTORS 12/2/16 I responded to 1 cumberland st for a MVA. I met with and spoke to the drivers of V1 and V2. Driver of V1 stated she wa driving East on Cumberland St in the right lane. She stated the ca I front of her was parked in the right lane because it ran out of ga The driver of V1 realized she needed to move into the left lane, sh NON. DARK-ROAL PASSING OR LANE USAGE 36503250 12/2/2014 4:58:00 PM CLEAR EAST OVERTAKING raw V2 and thought he was going to get her in the lane. She ther ift V2. Driver of V2 was driving East in the left lane. He stated he 326 aw V1 and thought she was going to wait for him to pass her before she moved into her lane, she didn't and struck her ar. V1 had damage to the drivers side rear door and rea anel. V2 had minor damage to the front left head light. No one DELEVAN ST VEHICLE 2 WHICH WAS SOUTH ON NORTH ST AND WAS MAKING A LEFT TURN FROM NORTH ST. TO FLEVAN ST. THUS TURNING INTO THE PATH OF VEHICLE PROPERTY DELEVAN ST. THUS TURNING INTO THE PAITH OF VEHICLE 1. VEHICLE 1 HIT THE PASSENGER SIDE OF VEHICLE 2 CAUSING DAMAGE AND INJURING THE PASSENGER IN VEHICLE 2 - WITNESS 1 TYNDALL, EDWARD 835 HUDSON AV ROCHESTER NY 14621 5853364129 - WITNESS 2 SOTO, 327 36514676 12/9/2016 12:52:00 PM DAYLIGHT DRY CLOUDY DRIVER INATTENTION NORTH RIGHT ANGLE INJURY ANIFL 220 GARLAND AV ROCHESTER NY 14611 T was traveling eastbound approaching Joseph Ave. V2 was NON. DARK-ROAL All LIRE TO YIELD RIGHT OF 328 36514644 12/10/2016 6:52:00 PM DRY CLOUDY FAST RIGHT ANGLE REPORTABL takening wit, veriz, was also leavening wit on influenties by the struck vehical Ropes passenger side doorf rear door crausing a lon scratch with his front driver side bumper, veh1 did not sustain any damage. The passenger of veh1 stated that they were attempting ha back up eb on lyndhurst st when the accident occurred because they made a wrong turn, the driver of veh2 stated that were lookin NON-329 36531000 12/12/2016 1:23:00 PM 2 DAYLIGHT WFT SNOW DRIVER INATTENTION WEST OVERTAKING REPORTABLE t a gps device when the accident happened. It was traveling westbound on allen st crossing state st when V2 ras waiting in traffic on state st. D1 stated someone cut him off an REACTION TO OTHER NON-330 36524442 12/14/2016 1:20:00 PM 2 DAYLIGHT DRY CLEAR WEST RIGHT ANGLE e reacted to an uninvolved vehicle causing his trailer to hit V2 on REPORTABLI UNINVOLVED VEHICL rear left bumper. no injuries reported on the scene. Both whicles were care by owners /eh#1 was proceeding N/B in the right curb lane of N. Union St. retir i was proceeding vinds in the right cub laine of N. Union St. dowing and approaching intersection of E. Main St. when Vehi^eT offlided with Vehi^eZ, which was stopped in the roadway facing NI[†] in the right curb lane of N. Union St. at E. Main St. At the time of he collision, Vehi^eZ was immobilized (broke down) with the hood up and the operator checking under the hood for the cause of the 2 REAR END mobilization. There were no hazard lights operating at the tim the slow speed collision. Upon impact, Veh#2 moved slightly 331 36558893 12/14/2016 3:27:00 PM INJURY DAYLIGHT SNOW/ICE SNOW PAVEMENT SLIPPERY NORTH invard into operator with the front bumper striking his knee. No amage to Veh#1. Damage to Veh#2 was pre-existing from a ast MVA. Blowing snow was covering roadway surface and stricting visibility, W1 (SHABAZZ) was front seat passenger in - WITNESS 1 SHABAZZ, AMANDA 19 BARNUM ST PROPERT 332 36524419 12/15/2016 10:50:00 AM 2 DAYLIGHT SNOW/ICE SNOW PAVEMENT SLIPPERY WEST REAR END DAMAGE n Allen street. Both vehicles entered the intersection which is introlled by a traffic signal. Vehicle 1 struck, with its front end DARK-ROAD NON ehicle 2 broadside in the right side. Both drivers claimed to ha 333 36552022 12/16/2016 5:56:00 PM 2 WET CLEAR BACKING UNSAFELY NORTH RIGHT ANGLE REPORTABLI LIGHTED green light and no witnesses were on scene to interview. Driver f Vehicle 2 said a witness, Ed Brown 261-0279, saw what andez was westoould on E maints approaching the fersection of University ave with a steady green light in lane 3. ehicle 1 was in center lane of westbound E main stright next to shicle 2. Driver of vehicle 1 states there was something going on PASSING OR LANE USAGE 334 36526125 12/17/2016 12:09:00 PM DAYLIGHT SNOW/ICE SNOW WEST OVERTAKING the curb lane of Westbound E main st so he started to change REPORTABLE IMPROPERLY es not seeing vehicle 2. Vehicle 1 then struck vehicle 2. Mino lamage to both vehicles. Driver of vehicle 1 admits fault by not naintaining lane and not seeing vehicle 2. Vehicles cared for by All 12/19 fo, at approximately 12/15 inst, I was uspanizated to E. Alain SV Union St for the report of a hit and run MVA. When I urrived on scene, I talked to the driver of V2. Driver of V2 stated hat he was waiting at the red light at E. Main St and N. Union St, FOLLOWING TOO CLOSELY REAR END 335 12/19/2016 12:13:00 PM DAYLIGHT CLEAR WEST 36556009 DRY cing WB. V1 rear ended V2 as he sat at the red light. When th REPORTABL iver of V2 pulled over on N. Union St. V1 continued straight. WB on E Main St. He was unable to get the make/model of the vehicle, or the LP #. There was no damage to the V2. Neither the 336 36549447 12/28/2016 10:57:00 AM DAYLIGHT DRY CLOUDY NORTH RIGHT ANGLE DAMAGE DISREGARDED Paul St, and was slowing to in traffic to make a right turn onto the intrance for the inner loop. Driver stated that as he stopped to allow oncoming traffic to pass, he was struck by vehicle one, on the efter ar bumper. Driver of vehicle one stated that he was also FOLLOWING TOO CLOSELY 337 36552892 1/3/2017 4:42:00 PM WET REPORTABLI LIGHTED aveling Southbound and was unable to stop in time to avoid ehicle two, as he was moving around the vehicle. Driver of chicle one had a learners permit only and did not have a lice

AILURE TO YIELD RIGHT OF

SOUTH

RIGHT ANGLE

CLEAR

36553747

338

1/5/2017

7:57:00 AM

2

DAYLIGHT

DAMAGE AND

TE 213 (9/79)						ROUTE NO. OF	CTDEET MAN	45.					
COUNTY:	MONROE		P.I.N.:	NOT APPLICA	BLE	ADJACENT RO					CASE No.:		-
	TOWN CITY					AT INTERSECT	ION WITH/OR	BETWEEN:			FILE: BY:	PSC 5/13/2020	-
	VILLAGE OF	ROCHESTER	!		=	SEE MAP					DATE:	5/13/2020	-
TIME PERIOD		FROM: 8/1/14	TO: 7/31/19	ENVIRONMEN Use Codes from at right) for thes	n MV 104 (shown e categories	Light Conditions: 1. Daylight 2. Dawn 3. Dusk 4. Dark Road Lig 5. Dark Road Ur		Roadway Surfact 1. Dry 2. Wet 3. Muddy 4. Snow/Ice 5. Slush 10. Other	ce Condition: Weather: 1. Clear 2. Cloudy 3. Rain 4. Snow 5. Sleet/Hall/Fre 6. Fog/Smog/Sn 10. Other				
No. OF MONTH	HS:	(50	ILES		9				DIRECTION		MV 104 Police Report DESCRIPTION	REFERENCE
CRASH No.	CASE No.	DATE	TIME	No. of VEHICLES	SEVERITY	CONDITIONS	ROADWAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING FACTORS	DIRECTION	TYPE ¹		MARKER
339	36555456	1/6/2017	7:07:00 PM	2	NON- REPORTABLE	DARK-ROAD LIGHTED	DRY	CLEAR	PASSING OR LANE USAGE IMPROPERLY	EAST	OVERTAKING	ON DIRECT TRESPONDENT ON the above location for a NIVA. Time with and spoke to the other of VI. She sheld she was in the second left turn leave on Cummberland Stall the intersection at St. Paul st, facing east. She stated it is a one way road with 4 lanes. The left 2 lanes are turning lanes, the right lane closest to the left turn lane is for gring station from Cummberland st and the far right lane is for turning right onto St Paul. Diver of VI stated V2 was not here left side of their in the left turn lane. She stated she had her directional on and started to make the Left turn and struck VZ. She stated V2 was not turning left, but was gring straight. The driver of V2 left the location. There was close to a hour wait little. I called he driver of V2. She stated She was in the middle lane and the V1 was to the right of the She stated she was in the middle lane and the V1 was be the right of the She stated she was in the middle lane and the V1 was to the right of the She stated she was in the middle lane and the V1 was to the right of the She stated she was in the middle lane and the V1 was to the right of the She stated she was in the middle lane and the V1 was to the right of the She stated she was in the middle lane and the V1 was to the right through the light and V1 turned Left, and shuck the race of the V1 was considered to the state of the was the respect to the was of the was the respect to the was of the value of the was the value of the was the right side door. No one was the respect of the state of the was of the was of the was of the value of the was of the	
340	36562530	1/6/2017	8:26:00 PM	1	PROPERTY DAMAGE	DARK-ROAD LIGHTED	DRY	CLEAR	ALCOHOL INVOLVEMENT	NORTH	OTHER	VEHICLE 2 WAS STOPPED AT THE RED ON CUMBERLAND	
341	36580407	1/8/2017	9:47:00 AM	2	PROPERTY DAMAGE AND INJURY	DAYLIGHT	SNOW/ICE	SNOW	DRIVER INEXPERIENCE	WEST	REAR END	VEHICLE 2 WAS STOPPED AT THE NEED ON COMBERCAND VIEWED VEHICLE 1 WHICH WAS ALSO ON CUMBERCAND ST HEADING WEST. IN WHICH WAS ALSO ON COUNBERCAND ST HEADING WEST. WHICH WAS ALSO ON COUNBERCAND ST HEADING WEST. THE PROSENCER OF VEHICLE 2 COMPLAND FOR COMPLAND OF COMPLEX PACK PAR BUT WOULD SEEK MEDICAL LATER FAMES AND ST. WOULD SEEK MEDICAL LATER OF LOWER BOACH 2 WHICH 2 WHICH 2 WEST AND WEST WEST WAS AND ST. WHICH ST. WEST AND WEST WEST WEST WEST WAS AND ST. WE WAS	
342	36567489	1/11/2017	2:42:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	DRIVER INATTENTION	EAST	OVERTAKING	MAIN. VEH 1 CROSSED THE LINE AND STRUCK VEH 2 (SDESWIPED) CAUSING DAMAGE TO BOTH VEHICLES. VEH 2 PULLED TO THE SIDE OF THE ROAD AND CALLED 911 WHILE VEH 1 LET THE SCENE WEST ON EAST MAIN. NO WITHOUS NO CAMPAGES NO IN HI	
343	36562545	1/11/2017	5:35:00 PM	2	NON- REPORTABLE	DARK-ROAD LIGHTED	DRY	CLEAR	DRIVER INATTENTION	NORTH	OVERTAKING	The intersection at SI-Paul SI and Cumberland STeet northbound is a free law new with Two laws (law buffest west can also be used to lum westbound) for northbound traffic and one lane to lum right (easbound) onto Certal Ave. The Two northbound lanes werge into one lane just north of the inities resciou. VI and V2 were traveling northbound on SI-Paul SI, VI was in the left lane and V2 were traveling northbound on SI-Paul SI, VI was in the left lane and V2 were traveling northbound onto SI-Paul SI. When the lane merged VI stuck V2 on the rear left quarter panel and left near door with its front right door causing dramage to the same. The operator of VI said that V2 sped past him and tried to cut him of and the operator of V2 said that he was alread of VI the enter lime. There were on infusion seported.	
344	36573397	1/18/2017	10:10:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	WET	RAIN	TRAF CNTRL DEV IMPROPER/NON-WRKING	SOUTH	OVERTAKING	V2 was stopped in traffic in the left lane of the N/B lanes of State St.	
345	36591861	1/20/2017	3:47:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLOUDY	TURNING IMPROPER	EAST	LEFT TURN (AGAINST OTHER CAR)	V2 was attempting to make a left turn on to Allen St from the S/B lanes of State St. As V1 made the turn it struck the D/S corner of the rear bumper of V2. No injuries reported. D1 was unaware that	
346	36591960	1/21/2017	8:53:00 PM	2	NON- REPORTABLE	DARK-ROAD LIGHTED	DRY	CLEAR	REACTION TO OTHER UNINVOLVED VEHICL	EAST	RIGHT ANGLE	he had made copted with V7 and continuest ERR or Allers Stu- liver 1 state of the State of Cuntiferation Studgers all the State of the signal at St. Paul St. She said the vehicle next to her started to move so she also stated proceeding in the intersection when she struck V2. Driver 1 did not recall if the light facing her was red or green. Driver 2 states he was north on St. Paul St and was proceeding statiglin under a green light with V1 struck him. Driver 2 moved his car off the road and made provisions to have it	
347	36577819	1/23/2017	8:05:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	PASSING OR LANE USAGE MPROPERLY	NORTH	RIGHT ANGLE	Vehicle 2 was northbound on Clinton ave stopped at the intersection of cumberdunt Vehicle 1 was freety behind vehicle 2. Vehicle 2 had their driver side turn signal on to turn into the parking lot of 207 N clinton ave which is just soun of the intersection. Driver of vehicle 1 states hat the light turned green at cumberland and noticed that driver 2 had her turn signal on but was not going so he assumed that she was broke down. Driver of vehicle 2 then crossed over the solid yellow line and entered southbound clinton was be pass vehicle 2 on the left. Driver of vehicle 2 then started her turn as staffic was clear and vehicle 1 then ran into vehicle 2 tront wheel well. Minor damage is both vehicles. Driver of vehicle 1 admitted datal and was issued a cilidator. No linguires.	
348	36591997	1/31/2017	3:02:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLOUDY	UNSAFE LANE CHANGE	EAST	UNKNOWN	VI AND VZ WERE INAVELING ON THE FASTISMAN	
349	36598005	2/4/2017	11:03:00 PM	2	NON- REPORTABLE	DARK-ROAD LIGHTED	SNOWICE	CLOUDY	PASSING OR LANE USAGE MPROPERLY	EAST	OVERTAKING	PORTION OF CUMBERLAND STREET IN THE AREA OF 186 CUMBERLAND. AT THE INTERSECTION OF CUMBERLAND AND JOSEPH AVE, THIS PORTION OF CUMBERLAND HAS THREE LAMES, AND THERE ARE TRAFFE, SIGNS POSTED AT THIS NITERSECTION THAT INDICATE THAT TRAFFE, ON THE LEFT LAME MAY TURN LEFT, THAT TRAFFE, ON THE CENTER LAME MAY TURN LEFT, OR CONTINUE STRAGHT, AND THAT TRAFFE ON THE RIGHT LAME MUST CONTINUE STRAGHT, ACCORDING TO THE DENTER OF V2, HIS VEHICLE WAS IN THE CENTER LAME AND AS HE WAS TURNING LEFT ONTO JOSPEH AVE V1, WHICH HE CLAMED WAS IN THE RIGHT LAME, ALSO MADE A LEFT TURN INSTEAD OF CONTINUING STRAGHT AND THE FRONT LEFT OF V1 STRUCK THE FRONT RIGHT OF V2, WHEN IN SPOKE TO THE DOTHER OF V1, SHE INITIALLY CLAMED THAT SHE WAS IN THE RIGHT LAME AND THOUGHT THAT THE SISKNS AT THE INTERSECTION INDICATED THAT THE TRAFFE IN THE KRIFT LAME MAY DIVINCE LASE. SHE THERE CHARLED STRATE AND FOR THE CASE, SHE THERE CHARLED FALLED HER CHARLED CONTINUE CONTINUED.	

TE 213 (9/79) ROUTE NO. OR STREET NAME MONRO P.I.N.: NOT APPLICABLE CASE No ADJACENT ROADWAY NETWORK TOWN FILE: CITY AT INTERSECTION WITH/OR BETWEEN: BY: PSC VILLAGE OF ROCHESTER DATE: 5/13/2020 SEE MAP ENVIRONMENTAL TIME PERIOD FROM TO se Codes from MV 104 (shown 1. Daylight right) for these categories 2. Dawn 3. Dusk 1. Dry 2. Wet 3. Muddy 1. Clear 2. Cloudy 3. Rain 8/1/14 7/31/19 4. Snow/lo 4. Snow 5. Sleet/Hail/Freezing Rain 5. Dark Road Unlighted 5. Slush 10. Other 6. Fog/Smog/Smoke lo. OF MONTHS 60 Jse Codes from MV 104 Police Report of VEHICLES IGHT DIRECTION DESCRIPTION REFERENCE SOADWAY SURFACE CONDITION CRASH No CASE No DATE TIME APPARENT CONTRIBUTING FACTORS VI AND OP V2 WERE BOTH TRAVELING EAST ON TH NNER LOOP OFF RAMP AT ST. PAUL ST. BOTH VEHICLES
WERE STOPPED SIDE BY SIDE AT THE INTERSECTION AND AS THE LIGHT TURNED GREEN BOTH ENTERED THI INTERSECTION. AT WHICH TIME V1'S FRONT PASSENGER SIDE STRUCK V2&apos: S REAR 'ASSENGER SIDE STRUCK VZ&BDROS'S KEAK DRIVER&BDDS:S SIDE. OP V2 STATED THAT HE WAS IN THE NDDLE RIGHT LANE GONG STRAIGHT AND THAT OP V1 WAS NEXT TO HIM IN THE MIDDLE LEFT LANE GONG STRAIGHT. HE CLAIMS THAT IN THE INTERSECTION OP V1 350 36600571 2/9/2017 3:08:00 PM DAYLIGHT DRY CLEAR UNSAFE LANE CHANGE EAST OVERTAKING MOVED TOWARDS HIM AND STRUCK HIM, OP V1 STATED THAT SHE WAS IN THE MIDDLE RIGHT LANE AND THAT OF THAT SHE WAS IN THE MIDDLE KENT LANE AND THAT OF V2 WAS IN THE FAR RICHT LANE TURNING RIGHT. SHE CLAIMS THAT AS THE LIGHT TURNED GREEN HE CUT HEI OFF AND STRUCK HER VEHICLE. BOTH VEHICLES DRIVEN ROM SCENE, NO IN JURIES REPORTED. 2 WAS HEADING WIB ON UNIVERSITY AVE A IL UNION ST. VI WAS BEHIND V2. VI WAS FOLLOWING TOC CLOSE AND HIT V2. DRIVER OF V1 SAID BRAKES TO V1 RRE NOT PROPERLY WORKING, SO V1 COULD NOT STOP NON 351 36613332 2/14/2017 5:21:00 PM DUSK DRY CLEAR BRAKES DEFECTIVE WEST REAR END EPORTABLE TIME TAND V2 WERE EASTBOUND ON THE INNERLOOP EXITING TO F MAIN ST IN THE CROCHESTER. AS V2 WAS PROPERTY SLOWING DOWN TO EXIT THE INNERLOOP, VI COULD NOT SLOW DOWN IN TIME, TRIED TO GO AROUND V2 ON THE 352 36608896 2/15/2017 9:00:00 AM DAYLIGHT WFT CLOUDY FOLLOWING TOO CLOSELY FAST OVERTAKING DAMAGE RICHT RUIT COULD NOT AND STRUCK V2. CLOSED.
V1 was in the left turning lane making a left turn from Cumberlar
Street to turn Northbound onto N.Clinton Avenue. V2 was in the
lane directly north (right) of V1, which is a straight only lane that continues westbound on Cumberland Street. The operator of V2 aid that he was unfamiliar with the road and thought that the lar NON and that he was unfamiliaed with the could and whough in that the rain and the was in could be utilized for turning left onto N.Clinton. V2 then turned left when the traffic signal turned green. While V1 was urning left onto N.Clinton ave V2 turned left crossing into 353 36614015 2/17/2017 4:39:00 PM DAYLIGHT DRY CLEAR TURNING IMPROPER SOUTH-WEST RIGHT ANGLE EPORTARI. V1's path, causing V1 to strike V2 on the rear left quarte anel with its front right corner of his bumper causing damage to ne same. The operator of V2 elected to have his vehicle towed /ehicle 2 was southbound on university ave approaching N union st. Vehicle 1 was eastbound on N union stapproaching University acing a steady red light. Vehicle 1 driver states she then received lacing a skedy red light Vehicle I driver shies she hen received i green light and continued easbound. Other wehible 2 shies she looked down for a moment as she approached the intersection and when she looked up the light was red as she was driving through the lintersection. Vehicle 1 them made contact with vehicle 2 causing vehicle 2 to spin 90 degrees. Vehicle 1 had front end damage and whelice 2 had driver side rear quarter panel damage. Driver of vehicle 2 admits fault. Vehicle 2 came back via NYSPN with no insurance on file. Olicer Algaria saked driver of vehicle 2 for insurance card and she shaled that she did not have insurance on the proper side of the PROPERTY RAFFIC CONTROL DEVICES 354 36613831 2/18/2017 12:05:00 PM 2 AMAGE AND DAYLIGHT DRY CLEAR FAST RIGHT ANGLE INTURY er vehicle as progressive dropped her. Driver of vehicle 2 had a oked ID only. Driver of vehicle 2 issued appropriate citations Driver of vehicle 1 complained of a headache and stated she was joing to go to hospital via private vehicle when her parents sponded. Vehicle 2 lowed to auto pound. Vehicle 1 airbag di 1 IS WB ON CUMBERLAND ST IN THE FAR RIGHT LAN PASSING OR LANE USAGE NON DARK-ROAD 2 IS WB ON CUMBERLAND ST IN THE CENTER LANE. V1 OVERTAKING 355 36614928 2/20/2017 8:58:00 PM 2 DRY CLOUDY WEST FPORTABL LIGHTED IMPROPERLY EAVES HIS LANE AND STRIKES V2 IN THE CENTER LAN O IN JURIES, NO TOWS J 1 and veh 2 were driving w/b on cumbe eh 2 sideswiped veh 1 along the drivers side door of veh 1. veh NON alled into parkinglot on the west side of the intersection, veh 2 wa DRIVER INATTENTION 2 WEST OVERTAKING 356 36626524 2/24/2017 4:24:00 PM DAYLIGHT DRY CLEAR REPORTABLI ast driving n/b on n clinton ave, driver of veh 1 could not describe ch 2 more than a dark colored suv. veh 1 sustained damage to rivers side of vehicle IT STATED THAT THEY WERE TRAVELING N/B ON ST PAU IT TURNING N/E ONTO CENTRAL AVE WHEN THEY WERE

NON

REPORTABLI

357

36637998

2/27/2017

4:57:00 AM

DARK-ROAD

LIGHTED

CLEAR

DRY

UNKNOWN

STRUCK BY V2 WHO WAS TRAVELING WIB ON
ZUMBERLAND ST. VI STATED THAT THE LIGHT WAS
YELLOW WHEN THEY WENT THROUGH THE
NTERSECTION. V2 STATED SHE WAS
TRAVELING WIB ON CUMBERLAND ST WHEN SHE WAS
STRUCK BY V11 WHO WAS TRAVELING WB ON ST PAUL ST

I/Z STATED THAT THE LICHT WAS GREEN WHEN SHE WAS GOING THROUGH THE INTERSECTON. BOTH Vappos. S STATED THAT THERE WAS A BUS STOPPED IN TRAFFIC FACING WIS ON CUMBERLAND ST PREVENTING EACH DITHER PROM SEERING ONE ANOTHER TILL IT WAS TO LATE. NO WITNESSES. NO CAMBERS IN THE AREA. VI WAS TREATED ON SFEN BY AM BIG \$734 FOR IF ET

RIGHT ANGLE

NORTH-EAST

TE 213 (9/79) ROUTE NO. OR STREET NAME MONRO P.I.N.: NOT APPLICABLE CASE No ADJACENT ROADWAY NETWORK TOWN FILE: CITY AT INTERSECTION WITH/OR BETWEEN: BY: PSC VILLAGE OF ROCHESTER DATE: 5/13/2020 SEE MAP ENVIRONMENTAL TIME PERIOD FROM TO Roadway Surface Condition Daylight
 Daylight
 Dawn
 Dusk 1. Dry 2. Wet 3. Muddy 1. Clear 2. Cloudy 3. Rain se Codes from MV 104 (shown right) for these categories 8/1/14 7/31/19 4. Snow/lo 4. Snow 5. Dark Road Unlighted 5. Slush 5. Sleel/Hail/Freezing Rain 10. Other 6. Fog/Smog/Smoke lo. OF MONTHS 60 Jse Codes from MV 104 Police Report of VEHICLES IGHT DIRECTION DESCRIPTION REFERENCE OADWAY CRASH No CASE No DATE TIME APPARENT CONTRIBUTING FACTORS APPROACHING THE ST PAUL ST INTERSECTION. V1 WAS N THE FAR LEFT LANE AND V2 IN THE ADJACENT LANE TO THE RIGHT. THE FAR LEFT LANE OCCUPED BY VI HAS MARKINGS THAT REQUIRE VEHICLES IN THAT LANE TURN TURN LEFT ONTO ST PAUL ST. THE ADJACENT RIGHT ANE OCCUPIED BY V2 HAS MARKINGS THAT ALLOW EHICLES IN THAT LANE TO TURN LEFT ON ST PAUL ST OR REMAIN STRAIGHT ON CUMBERLAND ST. V1 MADE A LEFT TURN ONTO ST PAUL ST FROM CUMBERLAND ST AND FALED TO MAINTAIN THE DESIGNATED LANE. V2 ALSO TURNED LEFT ONTO ST PAUL ST FROM LEFT TURN NON PASSING OR LANE USAGE 3:37:00 PM DAYLIGHT CLOUDY NORTH-EAST (AGAINST OTHER CAR) IMPROPERLY UMBERLAND ST MAINTAINING THE DESIGNATED LANE AND WAS STRUCK BY V1. D1 STATED THAT HE WAS AND WAS STRUCK BY VI. DISTATED THAT HE WAS UNAWARE THAT THE ADJACENT LANE WAS ALSO A TURNING LANE SO HE TOOK THE TURN TOO WIDE AND DID NOT STAY IN HIS LANE. VI SUSTAINED DAMAGE TO P/S FRONT BUMPER AND FENDER. V2 SUSTAINED DAMAGE TO D/S REAR TRUCK BED AND BUMPER. NO N JURIES WERE OBSERVED OR REPORTED BOTH 6:17:00 PM WET UNSAFE LANE CHANGE NORTH-WEST OVERTAKING 359 36639330 3/1/2017 RAIN LOSEST TO THE EASTSIDE CURB OF UNIVERSITY AVE HAT APPROACHES E MAIN ST PASS N UNION ST. V1 WA IEXT TO V2. IN THE MIDDLE LANE, DRIVER OF V2 STATED PASSING OR LANE LISAGE NON THAT V1 VEERED INTO HIS LANE AND HIT THE LEFT SIDE OF HIS VEHICLE. DRIVER OF V1 STATED THAT V1 HIT HER 360 36639331 3/4/2017 3:00:00 PM DAYLIGHT WET SNOW WEST OVERTAKING IMPROPERLY EHICLE. AT THIS TIME, THERE ARE NO WITNESSES IN THE AREA OR CAMERAS TO CORROBORATE EITHER TIMBERI AND ST. WHEN VEHICLE 1 ALSO ON NON 361 36652951 3/6/2017 1:55:00 PM DAYLIGHT DRY CLOUDY DRIVER INEXPERIENCE WEST OVERTAKING CUMBERLAND ST. WHEN VEHICLE TALSO ON CUMBERLAND ST HEADING WEST PULLED IN TO PARK IN FRONT OF VEHICLE 2. HITTING VEHICLE 2'S FRONT EPORTABL ET OHARTER PANEL CALISING DAMAGE WAS STOPPED AT A TRAFFIC SIGNAL IN FRONT OF V VZ WAS STOPPED AT A TRAFFIC SIGNAL IN FRONT OF VI ON THE INTERSECTION OF STATE ST AND ALLEN ST, TRAVELING SOUTH BOUND. VI INTIATED TRAVEL WHILE V REMAINED STOPPED AT THE TRAFFIC SIGNAL. THIS JLTIMATLEY CAUSED V1 TO STRIKE V2 IN THE REAR OF THE VEHICLE CAUSING MINIMAL DAMAGE TO BOTH NON DARK-ROAL 362 36648076 3/12/2017 8:22:00 PM DRY CLEAR DRIVER INATTENTION SOUTH REAR END HICLES THE DRIVER OF VI STATED THAT SHE WAS REPORTABLE LIGHTED REHICLES. THE DRIWER OF 91 STATED THAT SHE WAS AYMIG ATTENTION TO HER DAUGHTER WHO KEPT RYING TO GET OUT OF HER SEAT. IN DOING SO HER COOT SLIPPED OFF OF THE BRAKE PEDDLE AND HER EHICLE MOVED IN RESULT STRIKING V2. NO INJURIES VERE REPORTED. NO VEHICLES WERE TOWED FROM SCENE. THE DRIVER OF V1 WAS ISSUED A UTT FOR the above date and time I responded to the above address fi on the above date aim life responded to the above additional and MVA. There the driver of V2 told me he was travelling West on E. Main St and was going to turn South on N. Union St but the light turned from green to red so he stopped his vehicle. That is when V1 struck his rear bumper with his vehicle. V2 stated that he changed some information with V1 but V1 had to leave and he did not have all the information he needed to complete an accide NON-363 36654516 3/20/2017 5:01:00 PM 2 DAYLIGHT DRY CLEAR FOLLOWING TOO CLOSELY WEST REAR END or to the area and the minimater in embedding and the second of the provided me with V1&aposs phone number and ense plate. I called V1 and he told me that he had to leave to get s nephew off the bus. He told me that he was traveling behind V. REPORTABLI hen he thought V2 was going to go through the traffic light. V1 ien fold me " I released the brake and struck V2". V1 interribut mie adquot neieuseut interribute and state vZadquit. V had minor damage to itikaposs rear bumper and v1 had minor damage to itikaposs s front bumper. I lold both parties to contact. V1 was traveling westbound on Cumberland St. in he far right. vi was raveing weshound on combenand st. in the rainghi hand lane. V2 was also traveling westbound on Cumberland St. ir the middle lane. Both drivers are claiming that the other tried to tur NON 364 36659342 3/25/2017 5:12:00 PM 2 DAYLIGHT DRY CLEAR UNKNOWN WEST OVERTAKING nto their lane and struck the other. It is not known which vehicle caused the accident. No one was injured. V1 had damage to fron other side wheel panel. V2 had damage to passenger side door. Vacy was not on it. cambra was C, V1 was 1100 cambra 3 car had was yas yaws not on it. cambra was C, V1 was 1100 cambra 3 car had was yas yaws not on it. cambra was C, V1 was 1100 cambra 3 car had was yas yaws not on cambra 4 car had was yas yaws not one of the cambra 4 car had was yas yaws not one of the cambra 4 car had was yas yaws not one of the car had was yas yaws not one of the car had yaws yas yaws not one of the car had yaws REPORTABLI rning w/b onto cumberland st. (v1) then turned right to go aro e car, into the lane of (v2). (v1) struck (v2). according to driver 2 nd the witnesses, driver 1 was not going to stop until she noticed ney got her license plate information. i located all parties PASSING OR LANE USAGE NON-365 36687627 3/30/2017 5:40:00 PM DAYLIGHT WET CLOUDY NORTH OVERTAKING oximately 3/4 of a mile from the orginal scene, in a parking lo REPORTABLI IMPROPERLY WITNESS 1 WERR, ALVIN 23 CURLEW ST ROCHESTER NO WITHESS I WEBS, ALWAY 25 URLEW 31 ROUTES IER N 8883170017 - WITHESS 2 BROOKS, ZYEASIA L 3255 WHITE 5WAN DR ROCHESTER NY 5858025521 - WITNESS 3 MCCULLOUGH, BRIANA O 3840 WHITE SWAN DR /eh.2 was parked on the South curb of Lyndhurst St., facing We REACTION TO OTHER NON Veh. 1 was attempting to back into the driveway at 194 Lyndhurst St. and struck Veh. 2 in the rear bumper. There was very limited 366 36685250 4/9/2017 11:15:00 AM DAYLIGHT DRY CLEAR EAST SIDESWIPE EPORTABLE UNINVOLVED VEHICLE ace due to cars being parked on both sides of the street TWAS SKON STATE STATIATIEN STWHEN HE SAWY

DRIVER INATTENTION

2

DAYLIGHT

REPORTABLE

DRY

CLEAR

12:47:00 PM

367

36686316

4/9/2017

BEGAN TO SLOW AND LOOKED BEHIND TO SEE IF THERI

NAS TRAFFIC SO HE COULD DRIVE AROUND V2. V1 THEN STRUCK V2 WHICH WAS ALREADY SLOWING/STOPPING. JO IN LUBIES REPORTED OR ORSERVED.

REAR END

SOUTH

TE 213 (9/79) ROUTE NO. OR STREET NAME: MONROE TOWN CITY P.I.N.: NOT APPLICABLE CASE No.: ADJACENT ROADWAY NETWORK FILE: BY: DATE: AT INTERSECTION WITH/OR BETWEEN: PSC VILLAGE OF ROCHESTER 5/13/2020 SEE MAP

TIME PERIOD		FROM:	TO:	ENVIRONMEN	TAL:	SEE MAP Light Conditions		Roadway Surfa	ce Condition: Weather:				
	8/1/4 7/31/19 atright) for			MV 104 (shown		ghted	1. Dry 2. Wet 3. Muddy 4. Snow/Ice 5. Slush 10. Other	1. Clear 2. Cloudy 3. Rain 4. Snow 5. SleeVHaiVFre 6. Fog/Smog/Sn 10. Other					
No. OF MONTH	IS:	(60	ES						DIDECTION		MV 104 Police Report	DEFEDENCE
CRASH No.	CASE No.	DATE	TIME	No. of VEHICLES	SEVERITY	CONDITIONS	ROADWAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING FACTORS	DIRECTION	TYPE ¹	DESCRIPTION	REFERENCE MARKER
368	36691382	4/11/2017	8:20:00 PM	1	INJURY	DARK-ROAD LIGHTED	DRY	CLOUDY	WEW OBSTRUCTED/LMITED, TRAFFIC CONTROL DEVICES DISREGARDED	SOUTH	OTHER	VI was southbound out of the parking list at 250 Cumberland SI. to im westbound on Cumberland SI. This portion of Cumberland SI. This portion of Cumberland SI. This portion of Cumberland SI. is a one way street westbound. Diriver 1 stated the discydist as the public out of the parking to Orbier 1 stated the bicyclist struck the foot right quarter panel of VI, causing damage to VI and the bitle. The bicyclist stated VI struck him. The damage to the right state of VI was consistent with Diriver 12 aposs; account that he bicycle struck he side of his vehicle. It is to be noted that was dark at the time of the accident and he bitle did not have a headlight. The bicyclist complained of back pain but refused medical readment. This report was ammended on 7/3/17 to	
369	36684289	4/12/2017	10.25.00 PM	3	NON- REPORTABLE	DARK-ROAD LIGHTED	DRY	CLEAR	DRIVER INATTENTION	SOUTH	OTHER	DENDER OF VI STATES THAT HE IS UNFAMILIAR WITH THE AREA DRIVER OF VI STATES HE WAS TRAVELING NOBOUND ON N UNION ST JUST NORTH OF UNIVERSITY AND WHEN HE REALIZED HIS DESTINATION WAS ACTUALLY THE OPPOSITE DRECTION. DENDER OF VI STATES THAT HE TURNED AROUND IN A LOT NEAR THE CORNER OF E MAIN STIN UNION ST, THEN HEADED SBOUND ON N UNION ST UNAWARE THAT HE WAS TRAVELING THE WEONG WAY ON A ONEWAY STREET. V. WAS TRAVELING FILE WEONG WAY ON A ONEWAY STREET. V. WAS TRAVELING EBOUND ON UNIONESSITY AVE TOWARDS N UNION ST AND HAD THE GREEN LIGHT. AS VI CAME THROUGH THE METERSECTION TRAVELING THE WRONG WAY V2 STRUCK V1 CAUSING V1 TO SPIN AROUND NOW V1 FACING WEST. V2 CONTINUED THROUGH THE MORNES WAS V1 TO SPIN AROUND NOW V1 FACING WEST. V2 CONTINUED THROUGH THE RESECTION THAT THE RED TRAFFIC SIGNAL FACING WIS UNION STAND HOUSE OF WHICH THE RESECTION OF NOT V3 WHICH WAS STOPPED AT THE RED TRAFFIC SIGNAL FACING WIS UNION STYLOW. HE NOW SHE WIS WIS SIGNED AT THE REPORTED ALL 3 VEHICLES HAVE DAMAGE. DRIVERS REPORTED A LL 3 VEHICLES HAV	,
370	36686304	4/13/2017	8:20:00 AM	2	INJURY	DAYLIGHT	DRY	CLEAR	UNSAFE LANE CHANGE	WEST	OVERTAKING	(DZ) WAS TRAVELING WIS ON COMBERGAND ST 1031 STARTING IN TRAFFIC IN THE CENTER LANE. (VI) WAS TRAVLEING WIS ON CUMBERLAND ST IN THE RIGHT LANE. (D1) ATTEMPTED TO CHANGE LANES INTO THE CENTER LANE, BUT WAS NOT PAST (VZ) AND STRUCK THE RIGHT	
371	36685266	4/13/2017	6:13:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	NORTH	REAR END	V2 was traveling northbound on Scio St. just north of Lyndhurst St. and going straight ahead. V1 was behind V2 also going northbound. V1 rear-ended and struck V2. No one was injured. V1 had very minor scratches to front center bumper. V2 had minor scratches to rear humper.	
372	36693984	4/13/2017	6:53:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	PASSING OR LANE USAGE MPROPERLY	NORTH	OVERTAKING	V2 was in the center lane on University Ave at the approaching East Main Street northbound. V1 was in the right lane on University Ave heading northbound as well took the turn to wide making and atilled to wide crossing over into the left labe shiking his V2 in the process. V1 then left the scene of the accident as V2 followed	,
373	36695166	4/22/2017	5:26:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	DRIVER INATTENTION	NORTH-EAST	OVERTAKING		
374	36700953	4/26/2017	5:38:00 PM	1	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	FALURE TO YIELD RIGHT OF WAY	NORTH-WEST	OTHER	IV was a rawing vis to it v. Union's land allembro to make a left hum to head With upsidhud SIL Diriver of VI sheld that fallic going SB had stopped to let him furn. While doing his, the bicyclist did drive SB in the roadway and rain in the pessesper fort door of VI causing damage to both his bike and VI. There was a construction truck that was parked on N. Union SI facing SB Bicyclist did see traffic stopped and was traveling slating they were what the vice were taking to south of the s	
375	36708795	4/26/2017	6:27:00 PM	2	PROPERTY DAMAGE	DUSK	DRY	CLEAR	PASSING OR LANE USAGE MPROPERLY, PASSING TOO CLOSELY	SOUTH-EAST	RIGHT TURN (WITH OTHER CAR)	I all U. were sharly cassionated to the wast as in the tries scott. With University Jiver. I was in one line and V2 was to be right of V1 in the fair right lane. V1 and V2 both made a right turn onto V1 where Spi. Diver 1 stated as he made his right lurn. Driver 2 must have gone out of her line and struck V18 aposs; near passenger panel just above the wheel with V28 aposs s tond driver panel above he wheel with V28 aposs s tond driver panel above he wheel. There was a minor dent bv V1 and stratcher up he road (Eastbourd on University) before pulling over on the South side of the street. Driver 2 stated had as she made her right run, Driver 1 alterniped to cross over into the fair right lane for the pass in front of her vehicle when he struck V2 with the rear passenger panel. Driver 2 stated he tall the contact of the vehicle as it had now "icut her offiquet and then pulled over once it palled over once it sold of her steed before whether is and now "icut her offiquet and then pulled over once a loaded over once it sold of her steed between the incident where the accident occurred and noticed that as both lanes turn right, here are still two distinct lanes. There is hen a stop light at the N. Union St intersection where University Ave. The single lane of traffic or University Ave. The single lane of traffic is	

ROUTE NO. OR STREET NAME MONRO P.I.N.: NOT APPLICABLE CASE No ADJACENT ROADWAY NETWORK TOWN FILE: CITY AT INTERSECTION WITH/OR BETWEEN: BY: PSC VILLAGE OF ROCHESTER DATE: 5/13/2020 SEE MAP NVIRONMENTAL TIME PERIOD FROM TO 1. Dry 2. Wet 3. Muddy 1. Clear 2. Cloudy 3. Rain se Codes from MV 104 (shown right) for these categories 1. Daylight 8/1/14 7/31/19 4. Snow/lo 5. Dark Road Unlighted 5. Slush 5. Sleel/Hail/Freezing Rain 10. Other 6. Fog/Smog/Smoke lo. OF MONTHS 60 Jse Codes from MV 104 Police Report of VEHICLES DIRECTION DESCRIPTION REFERENCE SOADWAY SURFACE CONDITION CRASH No CASE No DATE TIME APPARENT CONTRIBUTING FACTORS a hit and run accident. Upon arrival I spoke to the driver of Veh 2 ho stated she was north bound on State St when an east bour when the same of the was industrial to the same of the difference of the same DDODEDTY RAFFIC CONTROL DEVICE: 36704318 4/28/2017 12:04:00 PM AMAGE AN INJURY DAYLIGHT CLEAR EAST RIGHT ANGLE ate number but was unsuccessful. The driver of Veh 2 pulled ver at 74 Lake Ave because she had a lot of neck pain. AMR Ric 389 Lic Plate 12756 transported Veh 2 driver to Highland Hospi eh 1 was traveling east, exiting the inner loop at the st paul st ex ren i was ravening east, exhibit your lime houp at the st paut sext feh 2 was slopped in Iraffic, on the inner loop st paul exit ramp, al hat intersection - Cumberland / st paul st. The light at the ntersection turned green, however, veh 2 was slopped due to NON-377 36711561 5/1/2017 10:20:00 AM DAYLIGHT DRIVER INATTENTION EAST REAR END EPORTABL affic. Veh 1 struck veh 2 in the rear. 2 WAS STOPPED IN TRAFFIC AT THE RED LIGHT, VI. NON-REPORTABL 378 36711572 5/4/2017 8:30:00 AM DAYLIGHT DRY CLEAR FOLLOWING TOO CLOSELY SOUTH REAR END DIDN'T SEE V2 WAS STOPPED AND STRUCK THE DIDNAapos:T SEE V2 WAS STOPPED AND STRUCK THE FEAR RND OF V1. VERYMINOR DAMAGE. NO NUILIERS. Veh1 was traveling wib on Cumberland st. Veh2 was stopped in traffic, on cumberland scing wib, at the red light located at the intersection of cumberland stand people vae. Veh1 field to slow down and the front bumper of veh1 struck the rear drivers side uarter panel of veh2 causing damage. The driver of veh2 stated aaree panier or verzi zoassing uarniage. The uriver overzi zaiazu at he was shopped at the red light and saw veht approaching hin om behind. He stated that the light lurned green and he started to tive forward, continuing wb on cumberland. He stated that veh1 NON DARK-ROAF 379 36721469 5/7/2017 1:06:00 AM WET RΔIN DRIVER INATTENTION WEST REAR END lid not slow down and rear ended him. The driver of veh2 said hat he stopped and got out of his vehicle and thought the driver o eh1 was going to do the same. He said the driver of veh1 stated os;t get into trouble" and drove away from the cene of the accident, the driver of vehicle2 stated that he was ne in the far west (left turning) lane and V2 was in the middle lan nat is for continuing straight (northbound) on St. Paul Street. The perator of V1 realized that he wanted to continue northbound on t. Paul Street and merged right into the lane that V2 was alread NON St. Paul steer ain integen tight into the lane that 22 was alread occupying and advancing past V1. When V1 merged into the lan that V2 was traveling in, it struck the front left driver and passenge side doors of V2 with its front right corner and quarter panel 380 36736011 5/11/2017 3-41-00 PM DAYLIGHT DRY CLOUDY UNSAFE LANE CHANGE NORTH OVERTAKING REPORTABLE ausing damage to the same. The operator of V1 said that he did not see V2 because V2 was already in his blind spot. There were NORTH BOUND ON UNIVERSITY AVENUE JUST SOUTH OF MAIN ST IN THE EAST LANE WHEN V1 WHICH WAS IN THE LANE WEST OF V2 ATTEMPTED TO MERGE INTO HER THE DAVIEWEST OF WATER THE TO MINERAL WITHOUT AND THE LAND. THIS CAUSED V2 TO STRIKE THE EXTENDED SIDE VIEW MIRROR ON THE DRIVERS SIDE OF THE BUS. THE MIRROR DID OBTAIN DAMAGE. THIS BUS HAD 17 PASSENGERS. NO INJURIES WERE REPORTED. UPON PASSING OR LANE USAGE NON-SPEAKING WITH THE DRIVER OF VI HE STATED THAT HE 381 36725770 5/12/2017 3:20:00 PM DAYLIGHT DRY CLOUDY NORTH OVERTAKING SPEARING WILH THE DRIVER OF VEHE STATED THAT IN WAS TRAVELING NORTH BOUND ON UNIVERSITY AVE UST SOUTH OF E MAIN ST WHEN V2 WHICH WAS TRAVELING IN THE LANE EAST OF HIS ATTEMPTED TO REPORTARII IMPROPERI Y MERGE INTO HIS LANE. THIS CAUSE V2 TO STRIKE HIS EHICLE, LEAVING A SCRATCH FROM THE MIDDLE OF HIS VEHICLE TO THE REAR, HE DID NOT REPORT ANY JURIES. NO VEHICLE WAS TOWED FORM THE SCENE. A US SEATING CHART CONTAINING THE NAMES AND EATING POSITIONS OF PASSENGERS, WAS SUBMITTED.

/EHICLE 1 WAS GOING WESTBOUND ON CUMBERLANI STREET TOWARDS THE SAINT PAUL STREET STREET TOWARDS THE SAINT PAUL STREET NTERSECTION. VEHICLE 2 WAS GOING NORTHBOUND ON SAINT PAUL STREET TOWARDS THE SAME NTERSECTION. VEHILCE 2 DRIVER STATES THAT SHE PROPERTY DARK-ROAL AD A GREEN LIGHT AND WAS STRUCK BY VEHICLE 1 382 36725724 5/14/2017 2:05:00 AM AMAGE AND DRY CLOUDY ALCOHOL INVOLVEMENT WEST RIGHT ANGLE LIGHTED THE DRIVER OF VEHICLE 1 THOUGHT HE HAD THE GREET INJURY THE UNIVER OF VEHICLE 1 INDUCATI HE HAD THE GREET
WIND THAT VEHICLE 2 WAS SPEEDING THE VEHICLE 1
RIVER WAS ARRESTED FOR DWI. Tickets Issued: KADILAC
MAPANA Driver of vehicle number (1) fickets: Ticket Number: M016Z2BLN Violation: 11923 Ticket Number: VM016Z2F9K fiolation: 5111A Ticket Number: VM016Z2FB5 Violation: 5091 /2 was in the S/B lane of N Plymouth Ave stopped at a red light a NZ was in the 3rd saled on Prijinious invest suppess of a real light a Allen St. V1 was traveling S/B on N Plymouth Ave approaching V2. V1 failed to stop and shock the rear of V2. No injuries reported Both vehicles pulled over to the right shoulder. Both drivers got out of the their vehicles. D2 states that in his conversation with D1 that NON e admitted he did not have a license. D1 then left on foot N/B on REAR END 36730352 DAYLIGHT FOLLOWING TOO CLOSELY SOUTH 383 5/15/2017 2:23:00 PM DRY CLEAR he admitted ne du not not wave a license. D I time ni etn on loot viden N Plymouth Ave towards the hiner loop. D I then and got into a dark sedan that pulled over to the side of the road. Vehicle seen raveling NIS on N Plymouth Ave. D1 was described as MIS 20&aposs 5&apos:8&apos.&apos 170lbs Gray clothes beard braided hair. REPORTABLI 1 towed to auto pound. DAYLIGHT UNKNOWN RIGHT ANGLE 384 36725758 5/16/2017 1:40:00 PM 2 AMAGE AND DRY CLOUDY WEST INJURY In 5/20/17 at 0753 hours. I responded to University Avenue at E and Scient of the Control of the Con stopped as he approached the intersection because the light turne FOLLOWING TOO CLOSELY DAYLIGHT REAR END 385 36748165 5/20/2017 7:53:00 AM DRY CLEAR SOUTH DAMAGE ed. Driver #1 states that he saw the light turn from green to vellow co. Divide #1 sales want le saw live light until 10 (light light lind light li

oorted by any of the drivers or occupants. Neither vehicle was ved. Citation issued to Driver #1 for following too closely.

						ROUTE NO. OI	R STREET NAM	ME:					
	MONROE		P.I.N.	NOT APPLICA	BLE		ADWAY NETW				CASE No.		_
	TOWN CITY					AT INTERSECT					FILE:	PSC	-
	VILLAGE OF	ROCHESTER					IION WITH/OR	DETWEEN:			DATE	5/13/2020	-
					_	SEE MAP							-
ME PERIOD		FROM:	TO:		n MV 104 (shown			Roadway Surfa 1. Dry	1. Clear				
		8/1/14	7/31/19	at right) for thes	e categories	2. Dawn 3. Dusk		2. Wet 3. Muddy	2. Cloudy 3. Rain				
						4. Dark Road Li		4. Snow/Ice 5. Slush	4. Snow 5. Sleet/Hail/Fre	ezina Rain			
						S. Duik Road O	ingi iio d	10. Other	6. Fog/Smog/Sr 10. Other				
o. OF MONTH	HS:	(50	so.					TO. Office		¹ Use Codes from	MV 104 Police Report	
				of VEHICLES	>	SNC	≿ 8	<u>~</u>		DIRECTION	TYPE1	DESCRIPTION	REFEREN
CRASH No.	CASE No.	DATE	TIME		SEVERITY	CONDITIONS	ROADWAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING				MARKE
				NO.	SE	99 8	288	WE	FACTORS			vz was navening sounbound on scho st. vi was navening	
												eastbound exifing the Inner Loop on Delamaine St. As V1 approached the stop sign at the intersection of Delamaine St and	
					PROPERTY				FAILURE TO YIELD RIGHT OF			Scio St, V1 failed to yield the right of way for oncoming traffic. There is no stop sign for traffic on Scio St at this intersection. UTT	
386	36740609	5/23/2017	6:40:00 PM	2	DAMAGE AND INJURY	DAYLIGHT	DRY	CLEAR	WAY	EAST	RIGHT ANGLE	issued for the driver of V1. Driver of V1 brought to Strong Hospital by AMR ambulance. V1 towed. No UTT issued to the driver of V2.	
												Driver of V2 and 4 passengers brought to RGH hospital by AMR	
												ambulance. V2 lowed WITNESS 1 ROSS, DENIELLO 169	
												STREET APPROACHING THE INTERSECTION OF JOSEPH	
												AVENUE. THE INTERSECTION OF CUMBERLAND/JOSEPH FOR E/B TRAFFIC CONSISTS OF THREE TRAFFIC LANES.	
												THE FAR LEFT LANE IS A TURNING ONLY LANE, THE CENTER LANE IS OPTIONAL TO TURN LEFT OR GO	
												STRAIGHT, AND THE RIGHT LANE IS STRAIGHT ONLY. BOTH PARTIES HAD CONFLICTING STORIES ABOUT HOW	
												THE ACCIDENT OCCURRED. DRIVER OF V2 STATES THAT SHE WAS TRAVELING E/B ON CUMBERLAND AND WAS IN	1
											LEFT TURN	THE CENTER LANE WHILE V1 WAS OCCUPYING THE FAR	
387	36739905	5/25/2017	8:55:00 AM	2	NON- REPORTABLE	DAYLIGHT	WET	RAIN	DRIVER INATTENTION	EAST	(AGAINST OTHER CAR)	LEFT LANE (TURNING ONLY LANE). V2 THEN DID MAKE A LEFT TURN ONTO JOSEPH AVENUE TO HEAD N/B ON	
											OTHER CAR)	JOSEPH AND THIS IS WHEN V1 DID PROCEED STRAIGHT ON CUMBERLAND DISREGARDING THE ",TURN	
												ONLY" SIGN AND THUS STRUCK V2. DRIVER OF V1	
												STATES THAT SHE WAS IN THE CENTER LANE ON CUMBERLAND HEADING E/B TO GET ONTO THE EAST	
												INNER LOOP AND THAT V2 WAS IN THE FAR RIGHT LANE. V1 THEN PROCEEDED THROUGH THE INTERSECTION OF	
												CUMBERLAND/JOSEPH AND THIS IS WHEN V2 DID MAKE A LEFT TURN AND DID STRIKE V1, DISREGARDING THE	١
												TRAFFIC SIGNS TO GO STRAIGHT. DIAGRAM REFLECTS V2': S VERSION. MINOR DAMAGE TO BOTH VEHICLES	
					NON-							VEHICLE 1 WHEN MAKING A LEFT TURN FROM CUMBERLAND ST TO N CLINTON AV. TURN TO WIDE THUS	
388	36748143	5/29/2017	12:58:00 PM	1	REPORTABLE	DAYLIGHT	DRY	CLEAR	DRIVER INATTENTION	NORTH	OTHER	HITTING THE CURB WITH IT'S RIDE TIRES. DAMAGING IT'S TIRES AND FRONT RUMPER	
												Both vehicles were traveling north on S Plymouth Av. Driver #2 stated that he was in the right-hand turning lane attempting to make	
												a right turn onto Allen St when vehicle #1 also made a right turn	
												next to him on the left-hand side as if she was trying to go around him and side swiped the front driver side of his vehicle as a result.	
389	36745789	5/30/2017	11:45:00 AM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	PASSING OR LANE USAGE IMPROPERLY	NORTH-EAST	OVERTAKING	Driver #1 stated that vehicle #2 was sitting at the green light for awhile, so she looked in her mirrors and saw him behind her. She	e
												then said that she safely went around vehicle #2 before making the right turn onto Allen St, and that he came up on the right side of	
												her to turn. There is only one right turning lane on N Plymouth Av	
												to utilize for Allen St. 2 vehicles cannot turn adjacent to one another. There was minor damage to both vehicles and no injuries	s
												Vehicle 1 (V1) was driving west on Cumberland St attempting to make a righthand northbound turn onto St. Paul St on the green	
												light when vehicle 2 (V2) did not stop for the red light located at the intersection of St. Paul/Cumberland. Vehicle 2 was driving south	
					Non	DADY DOAD			TRAFFIO CONTROL DELECTO			on St. Paul attempting to make a righthand eastbound turn onto Central Ave at the time of the accident. (V2) then left the scene of	
390	36749499	6/2/2017	11:32:00 PM	2	NON- REPORTABLE	DARK-ROAD LIGHTED	DRY	CLEAR	TRAFFIC CONTROL DEVICES DISREGARDED	WEST	RIGHT ANGLE	the accident. A refused witness grabbed a possible plate of GKF5588 for (V2). Photos taken of (V1). No injuries reported or	
												observed. On 6/7/17 the investigation led to (V2) being located at	
												the owner's address. Type, color of car and damage is all consistent with description driver of (V1) gave day of accident.	
												Photos taken of (V2). Attempts made to speak with registered owner of (V2) were negative. Unable to issue citations to (V2) for Driver 1 states she was east on E. Main. making a right onto	
												University Av when driver 2 tried to beat the light and struck her.	
391	36773417	6/6/2017	3:24:00 PM	2	INJURY	DAYLIGHT	WET	CLOUDY	FAILURE TO YIELD RIGHT OF	EAST	RIGHT ANGLE	Driver 2 states he was traveling south from the Inner Loop exit ramp to continue onto University av. Driver 2 states driver 1 never	
371	55/1541/	GUIZU17	5.24.00 FW		-45041	SALEGITI	WE!	SEOGDI	WAY	Eno1	ANOTH ANGLE	stopped and struck the side of his van. Both drivers claim they had the green light. Based on the damage of the vehicles and	i i
												positioning of the crash it appears vehicle 2 was almost through the	е
											-	V1 was traveling east on Delevan St approaching Scio St. As the V1 began to make the right turn onto Scio she struck the bicyclist.	
												The bicyclist was traveling north on Scio St on the sidewalk and as he was approaching the intersection he thought V1 was going to	5
												slop. Once he realized the car was not going to slop he attempted to go around the car leaving the sidewalk and heading into the	1
												road. V1 was blocking the crosswalk so the bicyclist was forced to	1
392	36769593	6/7/2017	5:11:00 PM	1	INJURY	DAYLIGHT	DRY	CLEAR	FAILURE TO YIELD RIGHT OF	SOUTH-EAST	OTHER	come off the sidewalk and enter the road and that is when V1 struck the bicyclist with the front portion of the vehicle. The bicyclist	
J72	30/07373	G//201/	3.71.00 PW	'	TNUCE	PRILIGHT	DRT	GLEAK	WAY	JOU IN EASI	JIHEK	went up on the hood and fell off on the driver side. The bicyclist was taken to Strong Hospital as a precaution. The bicyclist did	
												have a complaint of pain on the right side of his body and some neck pain. Heft the hospital around the time that the bicyclist was	
												sent for x-rays. There is video footage of the accident and it will be	
												collected and turned into property as soon as possible. It appears as though the driver of V1 did not come to a complete stop before	
												making the right turn WITNESS 1 MILLER, CHANCE R 922 RIDDITT OD HIL TON NY 14446 5853454688 Pedestrian (Simon Wilson) was at the Southeast corner of the	
												intersection of E. Main St. and N. Union St When the traffic light	
				1	Ī	DARK-ROAD	l	1	FAILURE TO YIELD RIGHT OF			turned green, he attempted to cross Northbound across E. Main	1
393	36758540	6/9/2017	9:33:00 PM	1	INJURY	LIGHTED	DRY	CLEAR	WAY	NORTH-EAST	OTHER	St. While in the intersection, Veh 1 was Northbound on N. Union	

TE 213 (9/79) ROUTE NO. OR STREET NAME MONRO P.I.N.: NOT APPLICABLE CASE No ADJACENT ROADWAY NETWORK TOWN FILE: CITY AT INTERSECTION WITH/OR BETWEEN: BY: PSC VILLAGE OF ROCHESTER DATE: 5/13/2020 SEE MAP FROM ENVIRONMENTAL TIME PERIOD TO Roadway Surface Condition Daylight
 Daylight
 Dawn
 Dusk 1. Dry 2. Wet 3. Muddy 1. Clear 2. Cloudy 3. Rain se Codes from MV 104 (shown right) for these categories 8/1/14 7/31/19 4. Snow/lo 4. Snow 5. Sleet/Hail/Freezing Rain 5. Dark Road Unlighted 5. Slush 10. Other 6. Fog/Smog/Smoke lo. OF MONTHS 60 Jse Codes from MV 104 Police Report of VEHICLES DIRECTION DESCRIPTION REFERENCE OADWAY CRASH No CASE No DATE TIME APPARENT CONTRIBUTING FACTORS ERATUR OF VEHICLE #2 STATES THAT SHE WA RAVELING EAST BOUND ON UNIVERSITY AVE. SHE STOP TRAFFIC WHEN VEHICLE #1 REAR ENDED HER VEHICL PROPERTY AILURE TO YIELD RIGHT OF AUSING DAMAGE TO THE REAR BUMPER OF HER EHICLE. OPERATOR OF VEHICLE #1 GOT OUT OF HIS 36767441 5:10:00 PM DAYLIGHT EAST 394 6/12/2017 DRY CLEAR REAR END EHICLE CHECK THE DAMAGE EXCHANGE INFORMATION NITH OPERATOR OF VEHICLE #2 AND STATED HER HAD ST AT ST PAUL ST WITH A RED LIGHT HEADING EAST. BOTH VEHICLES WERE TURNING LEFT ONTO ST PAUL ST WHICH HAS TWO TURNING LANES. BOTH VEHICLES MAD PROPERTY WHICH HAS IND URNING LANES, BOTH VEHICLES MAD THEIR TURN WITH VEHICLE 2 IN THE INSIDE LANE AND VEHICLE 1 IN THE OUTSIDE LANE. ONCE THE VEHICLES STRAIGHTENED OUT FROM THE TURN VEHICLE 1 WENT 395 36779163 6/16/2017 9:45:00 AM DAYLIGHT DRY CLOUDY DRIVER INATTENTION NORTH OVERTAKING NTO VEHICLE2&apos:S LANE MAKING CONTACT WITH RELIGIES CALEBRIC DAMAGE TO BOTH VEHICLES

Both Vehicle #1 and Vehicle #2 were making legal left turns from
the linner Loop onto E Main Street headed east bound. Vehicle #1 was in the inside turning lane, Vehicle #2 was in the outside turni ne. During the turn, the front right passenger-side of Vehicle #1 ne. During the bull, the bull right plassenger sale of vertices or vertices or ade contact with the rear driver-side corner of Vehicle #2. This sulled in damage to those two areas. Neither driver claims to ave left their designated turning lane, both claim they were in the NON 396 36769597 6/16/2017 2:01:00 PM DAYLIGHT DRY CLEAR TURNING IMPROPER SOUTH-EAST REAR END EPORTARI. nes. No injuries observed or reported. Neither vehicle was ved, no citations issued. Both drivers were given copies of the formation exchange form. Vehicle #1 had out of state insurance lational General Auto, Home and Health Insurance (Policy /1 was pulling into the parking when the vehicle struck a pole wi he punch code box on it. V1 then backed up and struck the gate The patrictode box of "Virtual boxes up and showing gate and went down behind the vehicle. The rear gate was snapped of and the pole with the punch box code was snapped at the base. Buckingham Properties owns the entry operating system. The stimated value of the damage is about \$500.00. There were no NON-397 36771611 6/19/2017 1:04:00 PM DAYLIGHT DRY CLOUDY DRIVER INATTENTION NORTH OTHER REPORTABLE operted injuries. On the above date and time I responded to the above address for of the above data and which responded to the above address on in MVA where the driver fled. There the owner of VZ lold me she vas in her residence when she heard a loud crash. She went subside and saw that the front bumper of V1 had struck the rear umper of her vehicle. The owner of V2 stated that there was no ne in the vehicle when she went out. V2 was still running and a PROPERTY PASSING OR LANE USAGE 398 36779234 6/20/2017 6:53:00 PM DAYLIGHT DRY CLEAR WEST REAR END enistration check showed that is was stolen on 06/18/17 in DAMAGE IMPROPERLY egistation theix showed that is was soluent on to APT/IIII ondequoit. It appears that V1 did not use the Xeveling lane roperly and struck the rear bumper of V2 which was parked in ont of the location. V1 had damage to it's front bumper and V2 had damage to her rear bumper. V1 was towed by 453 to the ity Pound per the request of IPD. Photographs were taken of the cident. Due to a lack of solvability this investe driver of VT stated that he was traveling St. As he traveled closer to the intersection of State St and Allen S he had a vellow light so he continued his travel south bound. This ltimately resulted in V1 colliding with V2. The driver of V1 did number of visual and visual members of visual members of visual pipear to be in shock and complained of chest pains. However, have treated and released at the scene by responding AMR. No urther information was given. Upon speaking with the driver of V2 LEFT TURN e stated that he was traveling north bound on State St. When he 399 36779188 6/21/2017 5:21:00 PM 2 INJURY DAYLIGHT DRY CLEAR DRIVER INATTENTION SOUTH (AGAINST proached the intersection of State St and Allen St he realized produces the intersection of states at an Artiers at its realized at the couldna-apost, make a left hand turn. He did admit to me at the was already slightly turned left. However, he did try to gain the proper course of travel. This resulted in V2 and V1 littling with each other. The driver of V2 did not report any OTHER CAR) niuries. Edid issue a LITT to the driver of V2 per NYS VTL 5091 oth vehicles did obtain extensive damage with air bag eployment, also, both vehicles were towed from the scene THE LEFT LANE OF TWO LANES. VEH 1 WAS WB ON UMBERLAND ST. VEH 1 STOPPED AT THE NON-DRIVER INATTENTION NTERSECTION OF NORTH/CUMBERLAND, THEN 400 36779229 6/22/2017 9:00:00 AM 2 DAYLIGHT DRY CLEAR WEST RIGHT ANGLE REPORTABLI TTEMPTED TO TRAVEL STRAIGHT, THROUGH TRAFFIC. ROSSING NORTH ST. WHILE ATTEMPTING TO DO SO H 2 PASSED IN FRONT OF VEH 1 AND VEH 1 STRUCK (CL) 2 71 facing Northbound slopped on N. Clinton Ave @ Innerloop. Ust exiting the Innerloop at N. Clinton Ave. V2 made a left hand NON-REPORTABLE urn to go Northbound and attempted to enter the lane East of V1 2 DRIVER INEXPERIENCE OVERTAKING 401 36808062 6/22/2017 9:30:00 AM DAYLIGHT DRY CLEAR NORTH V2 is a large box truck. V2 scraped the passenger rear bumpe ea of V1. V2 did not take any observable damage. No injuries ninor damage to rear passenger humper area eh 1 traveling straight ahead in middle left eastbound lane lar did strike Veh 2 which was also in the left eastbound lane and ha stopped quickly reacting to an uninvolved motor vehicle which wa uupped uutsty readurig v ari uriinvolved modor Venice winch was veveling in the rt eastbound lane and had crossed in front of Veh 1 titempting left furn onto innerloop. Veh 1 struck Veh 2&aposs left ear bumper w/ Veh 1&aposs right front bumper.No injuries eported.DRIVER 2 staling that she stopped quick to avoid DRIVER INATTENTION NON-REPORTABLE 2 DAYLIGHT CLOUDY EAST REAR END 402 36779236 6/22/2017 12:50:00 PM DRY UNINVOLVED VEHICLE ollision with another vehicle.DRIVER 1 stating that veh 2 reacting

Journal of the William and the Work of the Construction of the William and the Work of the Construction of the Construction of the Work of

TF	21	3	/ 0	/70\	

TE 213 (9/79)								_			1		
	MONROE		P.I.N.:	NOT APPLICAL	BLE	ROUTE NO. OI	R STREET NAM				CASE No.		
	TOWN					AT INTERSECT					FILE: BY:		_
	CITY VILLAGE OF	ROCHESTER				SEE MAP	IION WITH/OR	BETWEEN:			DATE		_
TIME PERIOD		FROM: TO: ENVIRONMENTAL: Use Codes from MV 10 at right) for these category: S: 60					ghted nlighted	Roadway Surfact 1. Dry 2. Wet 3. Muddy 4. Snow/Ice 5. Slush 10. Other	ce Condition: Weather: 1. Clear 2. Cloudy 3. Rain 4. Snow 5. SleeVHail/Fre 6. Fog/Smog/Si 10. Other				
No. OF MONTH	IS:		60	ES							¹ Use Codes from	MV 104 Police Report	
CRASH No.	CASE No.	DATE	TIME	No. of VEHICLES	SEVERITY	LIGHT	ROADWAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING FACTORS	DIRECTION	TYPE ¹	DESCRIPTION	REFERENCE MARKER
403	36779253	6/23/2017	9:47:00 PM	2	PROPERTY DAMAGE AND INJURY	DARK-ROAD LIGHTED	DRY	CLEAR	ALCOHOL INVOLVEMENT	WEST	LEFT TURN (WITH OTHER CAR)	DANNER OF VEHICLE TWAS TRAVELING IN THE NORTHEOMID ON STATE ST IN THE LEFT TURN ONLY LANE. DRIVER OF VEHICLE 1 TURNED LEFT TO ENTER WESTBOUND ON ALLEN ST. VEHICLE 2 WAS TRAVELING SOUTHBOUND IN THE CENTER LANDE ON STATE ST. VEHICE 1 FAILED TO YELD THE RICHT OF WAY AND TURNED IN FRONT OF VEHICLE 2 AND CAUSED A TWO CAR COLLISION. DRIVER OF VEHICLE 1 WAS OBSERVED UNDER THE NIFLUENCE OF ALCOHOL, AND A TRAFFIC CAR WAS SUMMONED TO THE SCENE FOR THE DRIVERAGE SS. SSSESSMENT. BOTH VEHICLE ARRACS DEPLOYED FROM THE CAR CHASH. BOTH VEHICLE SENGER FOR THE VEHICLES OF THE SCHEDE WITH EXTENSIVE FRONTEND DAMAGE TO BOTH VEHICLES. DRIVER OF VEHICLE 1 WAS PLACED UNDER ARREST BY TRAFFIC UNIT POLICE OFFICER SAM WEECHI1483. WITNESS 1 UNIT POLICE OFFICER SAM WEECHI1483. WITNESS 1 WAS PLACED UNDER ARREST BY TRAFFIC UNIT POLICE OFFICER SAM WEECHI1483. WITNESS 1 WAS PLACED UNDER ARREST BY TRAFFIC UNIT POLICE OFFICER SAM WEECHI1483. WITNESS 1 WAS PLACED UNDER ARREST BY TRAFFIC UNIT POLICE OFFICER SAM WEECHI1483. WITNESS 1	
404	36788618	6/26/2017	6:35:00 PM	2	INJURY	DAYLIGHT	DRY	CLEAR	WAY	NORTH	HEAD ON	VZ WAS TAVELING WIS ON E. MAIN St. AND VI WAS TAVELING WIS	
405	36823440	7/2/2017	9:56:00 PM	2	INJURY	DARK-ROAD LIGHTED	DRY	CLEAR	TRAFFIC CONTROL DEVICES DISREGARDED	NORTH	RIGHT ANGLE	from University Ave. confinuing on to the inner loop. The operator of VZ bidd me that he had a green light and as the entered the intersection his fower other liV. The operator of VI bidd me that he had a yellow light and entered the intersection and hit V2. The operator of VI said VZ was speeding. Both vehicles suffered durange. The torul passenger of VI was transported to Strong by AMR rig #7399 with a minor injury to her fool. Both vehicles were	
406	36808111	7/14/2017	10:52:00 PM	2	NON- REPORTABLE	DARK-ROAD LIGHTED	WET	CLOUDY	PASSING OR LANE USAGE IMPROPERLY	WEST	OVERTAKING	VI WAS TRAVELING WEST ON LYNDHURST ST, WHEN VI CAME FROM HER PASSENGER SIDE TRYING TO PASS WHEN BOTH HERCLES COLLIDED. VZ WAS TRAVELING WEST ON LYNDHURST ST BEHIND VI, DRIVEROF OF VESTATED THE BLIKKER ON VI WAS SIGNALING TO TURN LEFT. DRIVER OF VESTHOUGHT VI WAS TURNING INTO A DRIVEWAY AND ATTEMPTED TO PASS VI FROM THE RIGHT, WHEN COLLISION OCCURRED.	
407	36821954	7/20/2017	2:34:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	PASSING TOO CLOSELY	WEST	OVERTAKING	Direct of vehicle 1 stated that she was in lane 43, traveling West on Cumberland S.1. She stated as her and welche 42, who was in lane 472, passed through the intersection, vehicle 42 side swiped har vehicle, causing damage to her let side view mirror. She stated that she maintained proper positioning in her lane and did not were into lane 42. Driver of vehicle 42 stated that he was in lane 27 zwelleng Westround on Cumberland SI. He stated that as he and vehicle #1, who was in lane #3, passed through the intersection, vehicle #1 drifted thin bits lane and side swiped his vehicle, causing damage he the right rear fender, rear passenger door, and right front passenger door. He stated that he maintained proper positioning within his lane and did not veer into lane 11 is a left turn/straight lane; Lane #1 is a left turn/straight lane; Lane #1 is a left turn/straight lane; Lane #1 is a left turn/straight lane; Lane #2 is a straight only lane;	
408	36816506	7/21/2017	7:42:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	VIEW OBSTRUCTED/LIMITED	NORTH-WEST		Line #3 is a staint roll' lane: Jane #4 is a right furn only lane. We was turning right (Northound) on to \$P and \$1 from a weshound direction on Chertal Ave town a northound direction on \$1 Paul \$1.0 with \$1 Paul \$1.0 with \$2 Paul \$1.0 with \$2 Paul \$2 Paul \$2 Paul \$3 Pa	3
409	36839329	7/28/2017	2:58:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	TURNING IMPROPER	NORTH-EAST	OTHER	cumberland SI to turn northbound onto Joseph Ave. While making the turn VI&aposs rear driver side (Left) the shuck a sharp point of a curb causing the same five to blow, causing debris from the road to shrike and damage the front end of V2 who was directly behind V1 making a left turn as well . The operator of V1 said that he did not see the curb until the lest second and couldnikapost; avoid	đ
410	36929926	7/30/2017	8:55:00 AM	1	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	DRIVER INEXPERIENCE	SOUTH-WEST	OTHER	Vivias Tarting soun on token nor and began to continue soun on Joseph past Cumberland. But al Cumberland, Joseph turns into a one way northbound. D1 realized bot late is the could not continue south and altempted to turn west and ran up onto the curb, causing extensive damage to the car. D1 is learning to drive and the north passenger was a licensor definer.	
411	36831355	8/1/2017	7:09:00 AM	1	INJURY	DAYLIGHT	DRY	CLOUDY	FAILURE TO YIELD RIGHT OF WAY	NORTH	OTHER	self **Back newwo custon a New approblishing cummers are sell- Bicyclist rode in fort of Veh 1 traveling WB on Cumberland St. According to Veh 1 she had a green light. Bicyclist did sustain a troken right arm and was transported to Strong Hospial. Bicyclist bid officers hat the hought hat Veh I was ging by yield it was Veh 1 sustained denting to front right fender and door. Bicyclists take was returned to her residence by Otc. Frisbie. Otc. Shawn Jordan was he investigating officer at the scene. This information was passed on to me to write he report on his behalf since his consend a seld-this contine.	

TE	213 (9/79)	

TE 213 (9/79)						DOLLTE NO. OF	D CTDEFT NAM	AC.					
	MONROE		P.I.N.:	NOT APPLICAL	BLE	ROUTE NO. OF ADJACENT RO					CASE No.:		
	TOWN CITY					AT INTERSECT					FILE:	PSC	
	VILLAGE OF	ROCHESTER	!		=	SEE MAP	HOW WITH/OK	DETWEEN.			DATE:	5/13/2020	
TIME PERIOD		FROM: 8/1/14	ITAL: n MV 104 (shown e categories	Light Conditions:	ghted	Roadway Surfa 1. Dry 2. Wet 3. Muddy 4. Snow/Ice 5. Slush 10. Other	ce Condition: Weather: 1. Clear 2. Cloudy 3. Rain 4. Snow 5. SleeVHail/Fre 6. Fog/Smog/Si 10. Other						
No. OF MONTH	IS:	6	50	ES								MV 104 Police Report	
CRASH No.	CASE No.	DATE	TIME	No. of VEHICLES	SEVERITY	CONDITIONS	ROAD WAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING FACTORS	DIRECTION	TYPE ¹	DESCRIPTION	REFERENCE MARKER
412	36902209	8/1/2017	10:47:00 AM	2	INJURY	DAYLIGHT	DRY	CLEAR	FALURE TO YIELD RIGHT OF WAY	NORTH-EAST	LEFT TURN (WITH OTHER CAR)	The RPD liest number for vehicle 2's 161307, plate number 20's whiche 2 is a plote whiche owned by the Clyol Fotchester and operated by an employee of the City of Rochester. Vehicle 1 was fraveling west on St. Paul St. luming right notice Central Ave. Whiche 2 was streaming south on Cumberland St. Vehicle 1 ran a red light at the intersection of St. Paul St and Cumberland St. Vehicle 2 had stream light and was streamly sakelyth frough the intersection. Vehicle 1 struck whiche 2 had a green light and was streamly sakelyth frough the intersection. Vehicle 1 struck whiche 2 his from the front ender with whiche 18 pages stream light 18 will be seen 1 gifts the Willesses 1 aamp; 2 confirmed vehicle 1 went through a red light. Driver of vehicle 1 was issued a clution for passings a red signal (11110). The driver of vehicle 1 was soued a clution for passings a red signal (11110). The other of vehicle 1 reported no in lighters. Passenger of vehicle 2 (Harden) was transported to Highland Hospilal vila police vehicle for neck, wrist and back plan. "WIRSSS 1 LOPEZ; 2 LUMA 167 HOLLENBECK ST ROCHESTER NY 14614 7875649400.	
413	36848098	8/1/2017	11:50:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	DRIVER INATTENTION	WEST	OVERTAKING	WINNESS 2 PRHETE DAMS 100 SOUTH AMERICALISTER THE CENTER LANE WHEN VEHICLE 1 AFER MAKING A RICH TURN OFF ON CLINTON AV MENT INTO VEHICLE Zaspos SLANE SIDESWIPING SAME. VEHICLE 1 THEN LEFT THE SCENE. HOWEVER THE DRIVER OF VEHICLE 2 THAT SET ALSO AUTHORS SWING ALSO STATED WHAT HAPPENED . WINNESS I COLEMAN, ELLISON W 19 ACORN VALLEY TR COCENIAN LANE REFERENCE.	
414	36835726	8/4/2017	4:30:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	WET	CLOUDY	TRAFFIC CONTROL DEVICES DISREGARDED	NORTH	RIGHT ANGLE	COLON MANAGE SEASON TO THE WAY A STATE OF THE WAY AS SATING IN IN STATE WAY AS SATING IN IN STATE WAY AS SATING IN IN STATE WAY AS SATING IN STATE WAY AS SATING IN STATE WAY AS A SATING WAY A SATING	
415	36847556	8/9/2017	1:57:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	TRAFFIC CONTROL DEVICES DISREGARDED	SOUTH	RIGHT ANGLE		
416	36845478	8/11/2017	9:53:00 AM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLOUDY	PASSING OR LANE USAGE IMPROPERLY	SOUTH-EAST	RIGHT TURN (WITH OTHER CAR)	Opr 1 was driving V1 on Allen St making a right turn onto N Plymouth Ave in the outside lane. Opr 2 was driving V2 in the same direction making a right turn from Allen St onto N Plymouth Ave in the inside lane. V1 struck V2 in the above described area	
417	36867767	8/17/2017	6:45:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	FAILURE TO YIELD RIGHT OF WAY	NORTH	RIGHT ANGLE	cusion above described damane. No injuries, veh 1 was N/B on st paul. Veh 2 was W/B on Cumberland st, stopped at the traffic light at the SI Paul intersection. When the light lurned green for W/B traffic, Veh 2 proceeded W/B. Veh 1 continued N/B into the Cumberland intersection, on SI Paul st, and	
418	36860001	8/18/2017	5:42:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	BACKING UNSAFELY	EAST	REAR END	shursk upb. 2. 'If Was backing on Lyndhurst St heading Easbound. V1 did shike the front of V2 while backing. V2 was stopped in traffic behind V1 facing Westbound. This did cause damage to the front bumper of V2 and damage to the rear bumper of V1. No city cameras in the	
419	36873381	8/31/2017	11:51:00 AM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	FALURE TO YIELD RIGHT OF WAY	NORTH	OVERTAKING	area Minitides reported or even. Both Vs tavelin NS on University Ave where it approaches with E. Main SL VI was in he right lane and VZ was in he left. Driver of Main SL VI was in he right lane and VZ was in he left. Driver of Main SL when she felt a crash on he rieft side. She stakes shat when be looked to see whoto hother, she saw what she finitis is a large tuck, possibly a dump truck but she was uncertain as he vehicle continued straight not be liner loop. The striking vehicle, VI then rocceeded out of sight and did not shop or return to the scene. When asked she was unsure of the color of the truck but says possibly white. RIO checked with he administration channel and on other accidents propered. No camera at this intersection. From prior accidents in his area, the tire store and gas station cameras.	
420	36896962	9/6/2017	7:09:00 PM	2	INJURY	DUSK	WET	RAIN	TRAFFIC CONTROL DEVICES DISREGARDED	NORTH	RIGHT ANGLE	ovarhar bruch bir jameras sobie 41 the potagone jamel in 11 the road. No traveling 12 th on Allen St approaching Sales St. Nib Traffic on Sales St. Nib Traffic on Sales St. Ada dashing yeal for light Nib Traffic on Allen St. Nib Ada a fashing red light V.Z failed to stop at the fashing red light and eathered the intersection of Sales St. causing VI to strike V2 on the PPS. V2 then span out and struck light pole 125 on the north east comer of Sales Stand Allen St. D2 complained of pain in his lettleg but refused medical. Bioth cars lowed to 455. East Alve auto . MITNESS I VOLUMAR, NEERON 391 FROST AVE	
421	36901177	9/8/2017	4:48:00 AM	2	PROPERTY DAMAGE	UNKNOWN	UNKNOWN	UNKNOWN	UNKNOWN	UNKNOWN	RIGHT ANGLE		
422	36885717	9/8/2017	2:45:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	EAST	REAR END	V2 WAS TRAVELING E/B ON E MAIN ST. V1 WAS BEHIND V2. V2 SLOWED FOR TRAFFIC IN FRONT. V1 WAS FOLLOWING TOO CLOSELY AND HIT THE PEAR FIND OF V2	
423	36896971	9/14/2017	10:36:00 AM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	DRIVER INATTENTION	SOUTH-EAST	REAR END	TIOO CLOSELY AND HIT THE REAR END OF VZ. VWAS STOPPED WIT WATH FE ARONS SE OVI UNIVERSITY JUST BEFORE EAST MAN STREET INTERSECTION. VI DRECTLY BEHIND V2 ALSO TRAVELING SE ON UNIVERSITY AVE. VI FRONT BUMPER STRUCK V2 REAR BUMPER CAUSING MINOR DAMAGE TO V2. VI EXCHANGED NOROMATION AND LEFT BEFORE POLICE ARRIVAL NO NILIDEES SEGOSTED AT SCENE. WE WE WILL SEVEN SERVICE OF THE MARKED PARKING SPOT	
424	36918431	9/19/2017	1:34:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	DRIVER INATTENTION	EAST	REAR END	WITH IT'S DRIVER SITTING IN THE DRIVERS SEAT. VEHICLE 1 WAS BACKING OUT OF A PARKING SPOT. WHEN	
425	36953082	9/20/2017	11:05:00 PM	2	NON- REPORTABLE	DARK-ROAD LIGHTED	DRY	CLEAR	BACKING UNSAFELY	SOUTH	OTHER	IT BACKED INTO VEHICLE 2 CALLSING DAMAGE . THE THAT BOARD UNIT BATTER THE	

TE 213 (9/79)						ROUTE NO. O	R STREET NAM	ME:					
	MONROE		P.I.N.	NOT APPLICA	BLE		ADWAY NETW				CASE No.:		_
	TOWN CITY					AT INTERSECT					FILE:	PSC	-
	VILLAGE OF	ROCHESTER			=	SEE MAP					DATE:	5/13/2020	_
TIME PERIOD		FROM:	TO:	ENVIRONMEN	VTAL:	Light Conditions		Roadway Surfa	ce Condition: Weather:				
		8/1/14	7/31/19	Use Codes from at right) for thes	n MV 104 (shown e categories			1. Dry 2. Wet	1. Clear 2. Cloudy				
				J u. u	J	Dusk Dark Road Li	ahted	Muddy Snow/lce	3. Rain 4. Snow				
						5. Dark Road U		5. Slush 10. Other	5. Sleet/Hail/Fre 6. Fog/Smog/Sr				
					1	T	ı	TO. OBICI	10. Other	IIIOKC			1
No. OF MONTH	IS:	6	0	CLES		S	_			DIRECTION		MV 104 Police Report DESCRIPTION	REFEREN
CRASH No.	CASE No.	DATE	TIME	of VEHICLES	SEVERITY	CONDITIONS	ROADWAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING				MARKE
				No. o	SEVI	HOH	ROA SUR CON	WEA	FACTORS			VT was raveling westbound on E Main St and was going straight	
												ahead through the intersection at N Union St. V2 was traveling northbound on N Union St. and was going straight ahead through	
426	36899870	9/21/2017	4:33:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	TRAFFIC CONTROL DEVICES DISREGARDED	WEST	RIGHT ANGLE	normbound on N Union St. and was going straight ahead inrough the intersection at E Main St. V1 had the green light, and per city cameras, V2 ran the red light by approximately 4 seconds, causing	
					REPURTABLE				DISKEGARDED			the accident (bookmarked at 1629hrs). No one was injured. V1	g
												had front bumper damage. V2 had passenger side door panel damage. VT was traveling northbound on N Union St towards E Main St. V2	2
												was traveling westbound on E Main St towards N Union St. V2 had a solid green and was proceeding through the intersection at	
												N Union St and E Main St when V1 had a solid red light. V1	
												disregarded the red light on the traffic signal and proceeded through the intersection. V2 attempted to avoid V1 by turning her	
												car in a south direction when it struck V1 in the rear passenger quarter panel with it's passenger side front bumper.	
												V1's momentum carried the vehicle northbound and spun around until it struck the west exterior wall of 690 E Main St. V1	
												had damage to it's rear passenger wheel area and rear passenger door and was towed by 454. V2 had minor damage to	
					PROPERTY	DARK-ROAD						the front passenger bumper area and was able to be driven away from the scene. V1 was suspected to driving while intoxicated and	
427	36963497	9/24/2017	11:27:00 PM	2	DAMAGE	LIGHTED	DRY	CLEAR	ALCOHOL INVOLVEMENT	NORTH	RIGHT ANGLE	was subsequently placed under arrest for DWI by Officer Bonacci.	
												Pictures were taken of the scene by Officer Shone and a tech report was completed. Officer Shone also completed the tow repor	
												for V1, and a hold was placed on the vehicle for AUO 1st. W1 was deposed by Officer Cario, and in sum and substance stated, W1	5
												witnessed V1 pass through the red light at the intersection and strike V2. There were no city or private cameras in the area that	
												captured the event. 690 E main St was notified of the damage to their building WITNESS 1 PHILLIPS, ELEANOR 19 ARCH ST	
												ROCHESTER NY 14609 5852016737 Tickets Issued: SHANA A	
												REED Driver of vehide number (1) tickets: Ticket Number: 271W7FBXXF Violation: 1111D1 Ticket Number: 271W7FBXWX	
400	2/020774	ninrinna.	40.00.00.414		BUILDY.	LIBUZALONA	LINUALOUAL	LINUCALOUR	UNIZAZONA	LIBUKNOMBI	DEAD END	Violation: 5091 Ticket Number: 271W7FBXW3 Violation: 5113A Ticket Number: 271W7FRXV9 Violation: 11922&& Ticket Number:	r.
428 429	36930771 36911127	9/25/2017	12:00:00 AM 12:30:00 PM	2	PROPERTY	DAYLIGHT	UNKNOWN	UNKNOWN	UNKNOWN DRIVER INATTENTION	UNKNOWN	REAR END OVERTAKING	veh 1 was traveling West on Lyndhurst st. veh 2 was legally parked	ed
429	30911127	9/25/2017	12:30:00 PW	2	DAMAGE	DAYLIGHT	DRT	CLEAR	DRIVER INATTENTION	WEST	OVERTAKING	near 234 Lyndhurst st, along the Northern curb on the roadway. veh 1 lost control and sideswiped veh 2.	_
												V2 stated that he was traveling northbound on St Paul St. V1 stated that he was traveling westbound on Central Ave. The operator of	
												V2 stated that he had a yellow light northbound on St paul St as he proceed to go through the intersection when V2 then stuck his	Э
430	36916713	10/2/2017	4:39:00 PM	2	NON-	DAYLIGHT	DRY	CLEAR	TRAFFIC CONTROL DEVICES DISREGARDED	WEST	RIGHT ANGLE	vehicle. The operator of V1 stated that he had a green light westbound as he proceeded through the intersection when V1	
					REPORTABLE				DISKEGARDED			stuck his vehicle. (W)-Waterhouse stated that he was at the location when the incident occurred and witnessed V1 run the red light	n
												striking V2. V1 was lowed due to damage. No injuries. No city or private camera in the area WITNESS 1 WATERHOUSE, MIKE	
												811 WEST AVE ROCHESTER NY 14611 5857777777 92 Was naveming into on St. Paul St. at Cumberland St. vz. nau vie	
												green light. Driver of V1 was traveling wb on Cumberland St at St. Paul St and had the red light. According to driver of V1, he	
A31	26020040	10/3/2017	2-11-00 DM	2	PROPERTY DAMAGE AND	DAYLIGHT	DRY	CLEAR	RDAVES DEEECTAGE	WEST	RIGHT ANGLE	engaged his brakes and the vehicle did not stop, causing the	
431	36929948	10/3/2017	2:11:00 PM	2	INJURY	DATEIGHT	DKT	CLEAR	BRAKES DEFECTIVE	WEST	KIGHT ANGLE	towed because of defected brakes, he said that he just failed to	
												engage the brakes. V1 was towed. Passenger of V2 had some bleeding coming from his hands. He was examined by AMR and	
432	36941803	10/4/2017	10:48:00 AM	2	NON-	DAYLIGHT	DRY	CLEAR	DRIVER INATTENTION	NORTH	RIGHT ANGLE	VZ IS A COUNTY VEHICLE AND WAS LEGALLY PARKED. VI WAS OPERATED BY NEW DRIVER. OPERATOR 1 BAVCKED	
					REPORTABLE PROPERTY	DARK-ROAD			PASSING OR LANE USAGE			NTO V2 CAUSING VERY MINOR DAMAGE.	1
433	36919360	10/4/2017	7:14:00 PM	2	DAMAGE PROPERTY	UNLIGHTED	DRY	CLEAR	IMPROPERLY	SOUTH-EAST	OVERTAKING		1
434	36929896	10/7/2017	5:58:00 PM	3	DAMAGE AND INJURY	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	NORTH	OTHER		
												VEHICLE T WAS GOING WESTBOOND ON COMBERCAND STREET APPROACHING THE SAINT PAUL STREET	
												INTERSECTION. VEHICLE 2 WAS GOING NORTHBOUND ON SAINT PAUL STREET COMING UP TO THE SAME	1
435	36929900	10/7/2017	10:25:00 PM	2	PROPERTY DAMAGE	DARK-ROAD LIGHTED	DRY	CLOUDY	FAILURE TO YIELD RIGHT OF WAY	WEST	RIGHT ANGLE	INTERSECTION. VEHICLE 1 DRIVER STATES HE GOT A GREEN LIGHT AND WENT STRAIGHT STRIKING VEHICLE 2	
												IN THE INTERSECTION. THE DRIVER OF VEHICLE 2 STATES THAT SHE HAD A GREEN LIGHT AND SHE WENT	
										L	<u></u>	THROUGH THE INTERSECTION AND WAS HIT. THERE	L
												ven T was traveling n/b on st paul st, behind ven 2. ven 2 was traveling n/b on st paul st. ven 2 was in the left lane of two n/b	
436	36946235	10/15/2017	11:15:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	DRIVER INATTENTION	NORTH	RIGHT ANGLE	lanes. veh 2 attempted to make a u-turn by driving slightly to the right, into the right lane, then turning left to make a u-turn. this gave	e
										<u></u>		veh 1 insufficient notice to avoid colliding with veh 2 and veh 1 struck weh 2	L
												On 10/17/17 officers were dispatched to scio/lyndhurst for a 2 vehicle accident. Upon arrival, r/o spoke with Sarah Banker.	
												Banker was driving vehicle bearing NYS plate GXT1392. Banker	
					NON-							says she turned onto Lyndhurst from Scio. As Banker turned onto Lyndhurst, Banker says there was sun glare, causing her not to	
													a I
437	36959789	10/17/2017	10:38:00 AM	2	REPORTABLE	DAYLIGHT	DRY	CLEAR	GLARE	WEST	REAR END	see the vehicle in front of her. Banker did rear end vehicle bearing NYS plate HGB3896. R/o spoke with driver of second vehicle	9
437	36959789	10/17/2017	10:38:00 AM	2		DAYLIGHT	DRY	CLEAR	GLARE	WEST	REAR END		

TE 213 (9/79) ROUTE NO. OR STREET NAME MONRO P.I.N.: NOT APPLICABLE CASE No ADJACENT ROADWAY NETWORK TOWN FILE: CITY AT INTERSECTION WITH/OR BETWEEN: BY: PSC VILLAGE OF ROCHESTER DATE: 5/13/2020 SEE MAP ENVIRONMENTAL TIME PERIOD FROM TO Roadway Surface Condition 1. Dry 2. Wet 3. Muddy 1. Clear 2. Cloudy 3. Rain se Codes from MV 104 (shown right) for these categories 1. Daylight 8/1/14 7/31/19 4. Snow/lo 4. Snow 5. Dark Road Unlighted 5. Slush 5. Sleel/Hail/Freezing Rain 10. Other 6. Fog/Smog/Smoke lo. OF MONTHS 60 Jse Codes from MV 104 Police Report of VEHICLES DIRECTION DESCRIPTION REFERENCE SOADWAY SURFACE CONDITION CRASH No CASE No DATE TIME APPARENT CONTRIBUTING FACTORS of Scio St and the Inner Loop for a reported MVA. Both vehicle: were eVD Delevan St, approaching Soio St in heavy stop and go raffic. Driver of V1 stated she had hit the rear of V2, but did not know if V2 had been moving or had stopped. Driver of V2 was r sure if she was moving or stopped when she was hit. No injurie NON 438 10/19/2017 4:13:00 PM DAYLIGHT CLEAR DRIVER INATTENTION EAST 36939386 DRY REAR END rere reported or observed. V1 had minor damage to the front cense plate holder. V2 had minor damage to the rear left mper. Both drivers were given an Accident Exchange Form. Pehicle 1 was southbound on stale street approaching the ntersection of Allen st. Driver of vehicle 1 states she was lost as nulfiple roads were being shut down due to an event. Vehicle 2 numpie roads were being snut down due to an event. Ventice 2 vas westbound on Allen approaching he intersection of state st. Vehicle 2 states he had green light and confinue through the intersection and vehicle 2 ran the red light and ran into the assesneger side of his car causing minor damage. Vehicle 1 drives tates she was lost and thought she had a green arrow. I fold her RAFFIC CONTROL DEVICES 439 34040455 10/21/2017 0-40-00 AM DAYLIGHT DRY CLEAR SOUTH RIGHT ANGLE EPORTABL e light she was at had no green arrow and that light just south of er had a green arrow. Driver of vehicle 1 states she must of be oking at that one. No injuries. Driver of vehicle 2 only had permi with no licensed driver in vehicle. No tickets issued, vehicles care meet (V2) Driver-Matias regarding a Hit & Driver-Matias regard river informed me that he was traveling west bound on Cumberland SI approaching SI Paul SI when (VI) came on the right side of his vehicle and struck it. According to (v2) Driver (v1) side swiped his vehicle with there driver side to v2 passenger side of the vehicle.(v2) Driver further stated that (v1) then continued to urn onto St Paul St (Northbound). (V2) Driver followed (v1) and obtained there license plate number. (v2) Driver stated (v1) did no ull over to exchange information regarding the MVA. (v2) Drive nen stopped following (v1) and pulled over to call 911. On 10-28-7.1 did a follow up investigation regarding the MVA and called the egistered owner of (v1). (585-683-1656) I informed Flagg I was NON PASSING OR LANE USAGE 440 36959809 10/26/2017 9:57:00 AM 2 DAYLIGHT DRY CLEAR WEST OVERTAKING EPORTABL IMPROPERLY estigating a H&:R MVA with her license plate and vehicle lescription giving.V1) Driver Flagg informed she was driving (v1) nescription (young, vir) priver reagy minimines are was univing (vir) in 10-26-17 in the area of Cumberland SVS Paul SL (vir) Also informed me she was having car issues which she explained to b ter front left tire was wobbly which was causing her vehicle to pull to the left.(v1) Stated she didn't think she hit (v2) but could o ecause her car was shaking.(v2) Driver did not have any visible the driver of V1 stated that he was facing east bound stopped at The unvertor's stated until the Washading das bound supplies at responsible from the intersection of Delevan St and Scio St. He then slowly accelerated an attempted to turn right (South bound) onto Scio St. The driver of V1 did inform R/O that he was looking lowards oncoming traffic as he was going to merge onto Scio St. As he continued his travel the front of V1 collided with the rear of NONis the commindent his water the notify of Y contact with the read of 1/2. The driver of V1 further stated that he thought V2 would have thready been a distance away considering that he completely topped at the stop sign. The driver of V1 did not report any injury. 441 36959839 10/31/2017 3-40-00 PM 2 DAYLIGHT DRY CLEAR DRIVER INATTENTION SOUTH REAR END EPORTARI I V1 did not appear to have damage. The driver of V2 stated that sh as stopped at a stop sign at the said location when she was rended by V1 out of no where. The driver of V2 did not report, any niury. V2 obtained very minimal damage. No vehicle was towed 71 was fraveling northbound on N Clinton Ave. V2 was traveling orthbound on N Clinton Ave. The operator of V2 stated that as he ras turing onto N Clinton the operator of V1 came into his lane an NON PASSING OR LANE USAGE vas uning union V annon in experiant of V1 stated that as she turning or NC Linton Ave V2 came into her lane and struck her vehicle. Mint lamage. No injuries. No city or private camera&apos:s in the 442 36963505 10/31/2017 4:09:00 PM DAYLIGHT DRY CLEAR NORTH OVERTAKING REPORTABLI IMPROPERLY THICLE TSTRUCK VEHICLE 2 AS SHOWN IN TH IAGRAM. NO INJURIES WERE REPORTED BY ANY PART NON DARK-ROAL IVOLVED IN THE ACCIDENT. VEHICLE 1 HAD PRIOR DRIVER INATTENTION 443 37024451 11/6/2017 5:15:00 AM WET RAIN WEST REAR END REPORTABL LIGHTED AMAGE ON THE REAR LEFT BUMPER THAT IS NRELATED TO THIS ACCIDENT, VEHICLE 2 WAS TOWED PROPERT REACTION TO OTHER OVERTAKING 444 36973212 11/7/2017 7:45:00 AM 2 DAYLIGHT DRY CLEAR NORTH DAMAGE UNINVOLVED VEHICL was traveling eastbound on Cumberland St. V2 was trav astbound on Cumberland St. The operator of V1 stated that a chicle in front of him braked causing him to stop quickly and ve NON UNSAFE LANE CHANGE OVERTAKING 445 36982444 11/7/2017 4:07:00 PM DAYLIGHT DRY CLEAR EAST nto the left lane causing him to strike V2. The operator of V2 state nat V1 veer into his lane to avoid the car in front of him striking the REPORTABLI ide of his vehicle. Minor damage. No injuries. No city or pri amora & anos:s in the area 2 was fraveling S/B on N. Union St., and had just made the righ rm from N. Union St. onto E Main St., and was traveling W/B or Main St. V1, was traveling N/B on N. Union St., and made the NON 36974117 CLEAR WEST 446 11/8/2017 2:47:00 PM DAYLIGHT DRY (AGAINST OTHER CAR) oft hand turn onto E Main St., facing W/B to fall in behind V2, V1 REPORTABLI ade the turn too soon, and clipped the left rear quarterpannel o with the front right corner or V1. No damage to V1. Cosmetic The driver of V2 stated that he was traveling east on University A ust south of E Main St. He could not recalled what happened but only that the front drivers side of his vehicle collided with the rear unity had the form of the stated that both vehicles pulled over an decided to drive to 88 Alexander St. White at 88 Alexander St the reg owner of V2 provided his insurance information to the driver of 447 1:32:00 PM DAYLIGHT DRY CLEAR UNKNOWN UNKNOW UNKNOWN V1 but did not collect her information. Nor did he obtain a plate REPORTABL urthermore, the driver of V2 stated that the driver of V1 told him uniformitale, the divise of vs. saled that the curve of villabilith and she was going to call this insurance. V2 did obtain damage. The driver of V2 does have a photo of the damage on the other ehicle. However, he failed to capture a registration tag. V1 can be

scribed as a red vehicles possibly a pick up truck or Suburban be of vehicle. The driver of V1 left before police arrival.

E 213 (9/79)						ROUTE NO. OF	R STREFT NAM	ME:					
COUNTY:	MONROE		P.I.N.	: NOT APPLICA	BLE	ADJACENT RO					CASE No.:		_
	TOWN CITY		-			AT INTERSECT					FILE: BY:	PSC	_
	VILLAGE OF	ROCHESTER					IION WITH/OR	BETWEEN:			DATE		-
	•				-	SEE MAP							-
IME PERIOD		FROM:	TO:	ENVIRONME Use Codes fro	NTAL: n MV 104 (shown	Light Conditions: 1. Daylight		Roadway Surfa 1. Dry	ce Condition: Weather: 1. Clear				
		8/1/14	7/31/19	at right) for thes	e categories	2. Dawn 3. Dusk		2. Wet 3. Muddy	2. Cloudy 3. Rain				
						4. Dark Road Lig		4. Snow/Ice 5. Slush	4. Snow	onina Daia			
						5. Dark Road Ur	ilignieu	10. Other	 Sleet/Hail/Fre Fog/Smog/Sr 				
lo. OF MONTH	IS:		60						10. Other		Illse Codes from	MV 104 Police Report	
10:01 11101111	15.	,		of VEHICLES		S				DIRECTION	TYPE ¹	DESCRIPTION	REFERE
CRASH No.	CASE No.	DATE	TIME	J V E	SEVERITY	CONDITIONS	ROADWAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING				MARK
				No.0	SEVI	COND	ROA SUR CON	WEA	FACTORS				
												VI was traveling southbound on St Paul St. V2 was traveling westbound on Cumberland St attempting to make a left hand turn	
448	36982449	11/9/2017	7:57:00 PM	2	NON- REPORTABLE	DARK-ROAD LIGHTED	WET	RAIN	TRAFFIC CONTROL DEVICES DISREGARDED	SOUTH	RIGHT ANGLE	on St Paul St. The operator of V2 stated that he ran the red light and stuck V1. The operator of V2 stated that when he was	
					KEI OKTABLE	LIGHTED			DISTREGUISES			attempting to make that turn at the intersection V1 stuck his vehicle. Minor damage. No injuries. No city or private camera's in	
												the area venicle i stated white traveling east on E. Main St ne	
												attempted to stop for the red light at Union St. Driver of vehicle 1 further stated that when he used his brakes his car did not stop.	
449	37009699	11/18/2017	3:45:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLOUDY	FAILURE TO YIELD RIGHT OF WAY	EAST	RIGHT ANGLE	Driver of vehicle 2 states while traveling north on the Union St	
												through the intersection of E Main St she collided with vehicle 1. Driver of vehicle 2 further states that she had the green light. Driver	1
									1			of validle 1 issued LITT for unlicensed operation. ON THE ABOVE DATE AND TIME I RESPONDED TO JOSEPH	1
												AVE AND UPPER FALLS BLVD FOR THE REPORT OF A MVA HIT AND RUN. UPON ARRIVAL, I SPOKE WITH D2 WHO SAID	1
											LEFT TURN	THAT SHE WAS TRAVELING EAST ON EAST MAIN ST AND ATTEMPTING TO TURN LEFT ONTO THE INNER LOOP. D2	
450	37052382	11/23/2017	4:49:00 PM	2	NON- REPORTABLE	DUSK	DRY	CLOUDY	FAILURE TO YIELD RIGHT OF WAY	WEST	(WITH OTHER	SAID THAT WHILE MAKING THAT TURN, V1 MADE A RIGHT	
											CAR)	TURN AGAINST THEIR RED LIGHT AND STRUCK HER VEHICLE. D2 SAID THAT V1 TOOK OFF IN A UNKNOWN	1
												DIRECTION. D2 SAID THAT SHE COULD NOT GIVE A DISCRIPTION OF D1. D2 SAID THAT V1 WAS A WHITE	1
												HONDA BUT COULD NOT GIVE ANY OTHER DETAILS ON On the above date and time U2 stated that while waiting for the	
					NON							traffic light to change V1 struck the rear bumper. D1 stated that she	
451	37030972	11/29/2017	7:03:00 AM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	SOUTH	REAR END	thought she had enough space to stop but was unable to due so. Both vehicles were cared by owners. V1 was a school Bus with	
												three passengers inside and reported no injuries. V2 rear	
												passenger renorded of head pain. VEH T TRAVELING NORTHBOUND STRAIGHT AHEAD ON STATE ST DID STRIKE VEH 2 WHICH WAS EASTBOUND	
												TRAVELING STRAIGHT AHEAD ON ALLEN ST AND CROSSING THROUGH THE INTERSECTION AT STATE	
												ST.VEH 1 STRUCK VEH 2'S RT FRONT FENDER /	
												WHEEL AREA WITH VEH 1'S FRONT BUMPER / HOOD AREA. THE MOMENTUM OF VEH 2 ALSO CAUSING	
												DAMAGE TO ENTIRE RIGHT SIDE OF VEH 2 BY VEH 1 AND	
												FORCING VEH 2 TO STRIKE THE CURBING ON THE NORTHEAST SIDE OF THE INTERSECTION WITH VEH	
												2'S LEFT REAR WHEEL CAUSING DAMAGE TO SAME.NO INJURIES REPORTED.DRIVER 1 UNCERTAIN	
				_	PROPERTY				DDIED BLATTENTION			ABOUT TRAFFIC SIGNAL THAT WAS BEING OBSERVED AS	
452	37100524	11/30/2017	3:16:00 PM	2	DAMAGE	DAYLIGHT	DRY	CLOUDY	DRIVER INATTENTION	NORTH	RIGHT ANGLE	THERE ARE TWO WHICH FACE THE NORTHBOUND LANES IN CLOSE PROXIMITY TO EACH OTHER AND FUNCTION	
												INDEPENDENTLY.DRIVER 2 STATING THAT TRAFFIC SIGNAL WAS SOLID GREEN FOR EASTBOUND TRAFFIC ON	
												ALLEN ST.WITNESSES AT SCENE BOTH STATED THAT	
												THE SIGNAL FOR THE NORTHBOUND TRAFFIC ON STATE ST WAS SOLID RED AS BOTH WITNESSES WERE FACING	
												THIS SIGNAL AT THE TIME OF COLLISION.MONROE COUNTY PROBATION SUPERVISOR ON SCENE.RO WITH	
												TECH PHOTOS @ SCENE.CITY CAMERA @ STATE & amp;	
												ANDREWS UNABLE TO PROVIDE ANY FOOTAGE FOR THIS INTERSECTION AT TIME OF COLLISION.VEH 1 TOWED TO	
												452 BY SAME.VEH 2 TOWED BY GATES AUTOMOTIVE.MISC; FLEET # VEH 2 · 4954NO FURTHER _ WITNESS 1	
453	37021719	12/4/2017	10:57:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLOUDY	DRIVER INATTENTION	NORTH	OVERTAKING		
					****							veh 1 was traveling Westbound on Cumberland st. Veh 1 passed through the N.Clinton ave intersection, in the left lane of three lanes	
												of traffic. After veh 1 passed through the intersection, veh 2 drove in	
454	37039692	12/8/2017	7:15:00 AM	2	PROPERTY	DAYLIGHT	DRY	CLEAR	DRIVER INATTENTION	WEST	RIGHT ANGLE	front of veh 1, in an apparent attempt to change lanes. driver of veh 2 does not specifically recall what happened, but believes she was	
				1	DAMAGE							in the middle lane, and thought that the left lane had to turn left	
												(could not continue straight) at the N.Clinton ave intersection, which is not true. driver of veh 2 license is currently suspended.	
					ļ				1			passenger of veh 2 was not in required child safety seat. VI and V2 were both traveling E/B on E.Main St. VI attempted to	
												Merge into the right lane striking V2. The light impact caused damage to the driver side door and B pillar of V2. V1 sustained	Ì
455	37024448	12/8/2017	6:31:00 PM	2	NON- REPORTABLE	DARK-ROAD LIGHTED	DRY	CLEAR	UNSAFE LANE CHANGE	EAST	OVERTAKING	damage to the front right fender. There were no report of injuries	Ì
												from either party. Both vehicles had minor damage and were in drivable condition. Both drivers were given a driver exchange. I	1
					PROPERTY	DARK-ROAD			FAILURE TO YIELD RIGHT OF			advised holb drivers to call and inform their insurance companies	
456	37028806	12/9/2017	12:40:00 AM	2	DAMAGE AND INJURY	LIGHTED	DRY	CLEAR	WAY	NORTH	OVERTAKING		
457	37033175	12/9/2017	10:56:00 AM	2	NON-	DAYLIGHT	DRY	CLEAR	UNSAFE LANE CHANGE	NORTH	OVERTAKING	D1 stated that she was confused to which lane to drive on and while attempting to change going into the lanes D1 did not see V2.	
131	5,005175	I DANIA	10.50.00 AW		REPORTABLE	SAILIONI	DICT	JLLAR	SHOW E PARE CHANGE	NORTH	OVERTARING	V1 struck V2 in the right rear quarter panel, no injuries reported at the scene. Both vehicles were cared by owners.	L
												DRIVER #1 WHILE ATTEMPTING TO STOP AT THE RED	
458	37030950	12/13/2017	8:45:00 AM	2	NON- REPORTABLE	DAYLIGHT	SNOW/ICE	SNOW	PAVEMENT SLIPPERY	EAST	RIGHT ANGLE	LIGHT DID SLIDE ON THE SNOW AND ICE COVERED ROADWAY AND STRIKE VEHICLE #2 THAT WAS TRAVELING	
								<u> </u>	ļ			S/B ON STATE ST AND WHO HAD THE GREEN LIGHT.	
]							<u> </u>		operator of V2 stated that he was in the middle lane attempting to	
												make a left hand turn onto St Paul St. The operator of V1 stated that he was in the left turing only lane attempting to drive straight.	
459	37046113	12/18/2017	6:43:00 PM	2	NON- REPORTABLE	DARK-ROAD LIGHTED	SLUSH	CLEAR	PASSING OR LANE USAGE IMPROPERLY	EAST	RIGHT ANGLE	V2 stated that V1 was in the turn only lane when he attempted to	
	i l		Ī	1	1	1	i	I	1	Ì	1	drive straight and struck the side of his vehicle. V1 stated that he	I
												was in the turn only lane and attempted to drive straight on	

TE 213 (9/79) ROUTE NO. OR STREET NAME MONRO P.I.N.: NOT APPLICABLE CASE No ADJACENT ROADWAY NETWORK TOWN FILE: CITY AT INTERSECTION WITH/OR BETWEEN: BY: PSC VILLAGE OF ROCHESTER DATE: 5/13/2020 SEE MAP FROM ENVIRONMENTAL TIME PERIOD TO Roadway Surface Condition 1. Dry 2. Wet 3. Muddy 1. Clear 2. Cloudy 3. Rain se Codes from MV 104 (shown right) for these categories 1. Daylight 8/1/14 7/31/19 4. Snow/lo 4. Snow 5. Dark Road Unlighted 5. Slush 5. Sleel/Hail/Freezing Rain 10. Other 6. Fog/Smog/Smoke lo. OF MONTHS 60 Jse Codes from MV 104 Police Report of VEHICLES DIRECTION DESCRIPTION REFERENCE SOADWAY SURFACE CONDITION CRASH No CASE No DATE TIME APPARENT CONTRIBUTING FACTORS niversity Ave. V2 entered the intersection at University and N nion St. and had started to make the left turn on N Union St in orlioting, and had saled by linke the length of more of the orlioting. Orlioting the opposite direction, and struck the driver side front corner of V1. V2 pulled over, and V1 look off W/B. The driver of V2 said that it PROPERTY 37051979 12/19/2017 5:10:00 PM DAYLIGHT CLOUDY DRIVER INATTENTION WEST SIDESWIPE 460 DRY appened so fast that he was unable to tell if the other driver was nale or female, but thought that they were white. He was also nable to give any better description of the vehicle than that it wa 1 stated that while turning right on a green arrow P1 did not see of solate in a wine turning right of a greet arrow in our into set of funding the properties of the properties of the properties of the RGH with foot pain, no visible injuries or any other injuries at the scene, D1 stated that P1 did have the Don't Walk sign. V1 DARK-ROAF 461 37050694 12/20/2017 6:54:00 AM INJURY SNOW/ICE RΔIN FAILURE TO KEEP RIGHT NORTH OTHER was cared by owner Vehicle 1 was heading northbound on University Ave crossin Main St. and entering the inner loop. Vehicle 2 was heading estbound on E. Main St. and was making a right turn north onli ne inner loop. Both vehicles then struck each other. Both driver e littler loop, both refines their stack each offer. Both allives aim fhat they had the green light. I did check the lights at the tersection in both directions for several light cycles and both spear to be functioning correctly. Driver 1 claimed that Driver 2 NON 462 37055354 12/20/2017 1:26:00 PM DAYLIGHT WET CLOUDY LINKNOWN NORTH OVERTAKING PORTABL id she had a green arrow, but would only tell me that she had a een light. It should be noted that the light on E. Main St heading und at the inner loop cycles from green to red to a right tu reen arrow to red again, before turning green. No injuries were perator of V2 stated that he was in the middle lane on mberland St and was attempting to make a left hand turn on Si NON-DARK-ROAF LANE MARKING aul St. He said that V1 was in the left turing only lane and 463 37046102 12/21/2017 8:20:00 PM 2 DRY CLEAR EAST OVERTAKING uaur St. ne said uited i'r was in the ent uiting drift ya life aid allempled to drive straight on Cumberland St and struck his vehicle. The operator of V1 stated that he did attempt to drive straight on Cumberland St. Minor damage. No city or private EPORTARI. IMPROPER/INADEQUATE nemoral, it has one.

Triver of vehicle 1 states while traveling south on St Paul St he proached the intersection of Cumberland St, observed the light m green, proceeded through the intersection, then observed the ght turn right back to red, at which time he collided with vehicle 1 iver of vehicle 1 states that the light malfunction. Driver of vehic TRAF CNTRL DEV DARK-ROAD 2 stated while traveling west on Cumberland St through the 464 37087925 12/22/2017 6:35:00 PM INJURY SNOW/ICE CLOUDY SOUTH RIGHT ANGLE tersection of St Paul St, she was struck by vehicle 1. Driver of ehicle 2 states that she had the green light. Witness states that LIGHTED IMPROPER/NON-WRKING as behind vehicle 2 when he observed the traffic light at St Paul St and Cumberland St switch from red to green and then back to ed in a matter of seconds. Driver of vehicle 2 was cited for no WITNESS 1 MARROQUIN, OMAR 218 BIRR ST RAVELING S/B ON SCIO ST BEHIND (V2) APPROACHING HE INTERSECTION. DUE TO UNTREATED ROADWAYS NON PAVEMENT SLIPPERY 465 37080947 12/23/2017 12:57:00 PM DAYLIGHT SNOW/ICE SNOW SOUTH REAR END AND ICE/SNOW. (V1) WAS UNALBE TO STOP AND SLID REPORTABLI NTO THE REAR OF (V2) CAUSING MINOR DAMAGE AND NO SLID NOT THE REAR OF (V2) CAUSING MINOR DAMAGE AND NO INJURY. NOTE, THERE WAS AN EXCESSIVE AMOUNT OF MOTOR VEHICLE ACCIDENTS AT THIS TIME DUE TO On 12/24/2017 at approximately 23:24 hours, RPD fleet vehicle On 12/24/2017 at approximately 23:24 hours, RPD fleet vehicle was involved in a mort vehicle accident. OE. Jeremy Lindauer II was operaling Police vehicle 151399 (P-87) in a non-emergency wehicle capacity West bound on Allein St approaching State St. White approaching the intersection of the inter-loop of ramp and State St., 151399 rear ended vehicle HME:2043, vehicle 2. Driver DARK-ROAD DRIVER INATTENTION REAR END 466 37069044 12/24/2017 11:24:00 PM SNOW/ICE CLEAR SOUTH of vehicle 2 stated that he was at a solid red light (for an extended REPORTABLE LIGHTED in venicue 2 seaeu una rie was ar a sour eungin (ui an elemende period of lime) when he was rear-ended by Vehicle 151399. Neither the driver or any of the passengers in Vehicle 2, or Ofc. Lindhauer reported any type of injury. T/Sgt. Rathfelder responde to the scene. Photos of the vehicle damage were taken. Vehicle 2 ffered a crack to the rear bumper to the left of the license plate. 51399 had no visible damage to the front bumper.NFI. v1) is a tractor snow plow. (v1) was northbound on Scio St. ppproaching the light on Lyndhurst St. (v2) was in front of (V1) 467 37059255 12/31/2017 10:54:00 AM 2 DAYLIGHT SNOW/ICE CLOUDY PAVEMENT SLIPPERY NORTH REAR END topped at the traffic light facing northbound. (V1) slid on the ice REPORTABL ing the front end of the plow to strike the rear bumper of (V2) or damage VI STATES HE WAS TRAVELING WIBOUND ON MAIN ST. AS DRIVER OF V1 ENTERED THE NTERSECTION WITH UNIVERSITY AVE/INNERLOOP ON AMP, HE BEGAN TO SLIDE ON THE SNOW/ICE/SLUSH DRIVER OF VI STATES THAT HE COULD NOT STOP AND SLID INTO V2. DRIVER OF V2 STATES THAT SHE WAS PROPERTY 468 37064002 1/1/2018 2:55:00 AM SNOW/ICE SNOW PAVEMENT SLIPPERY NORTH-WEST RIGHT ANGLE ACING N/BOUND ON THE INNERLOOP OFF RAMP AT THI DAMAGE LIGHTED RAFFIC LIGHT. DRIVER OF V2 STATES THAT HER LIGHT JRNED GREEN AND SHE BEGAN TO MOVE INTO THE URIVED GREEN AND SHE BEGAN TO MOVE INTO THE TYTERSECTION WHEN SHE WAS STRUCK BY VI. NO NJURIES REPORTED. V2 HAS EXTENSIVE DAMAGE TO THE DRIVER'S SIDE. V1 HAS DAMAGE TO THE ONT END. PHOTOS TAKEN (SEE OFC BODEKOR T WHICH IS A RTS BUS, CAME TO A STOP AT THE R

DRIVER INATTENTION

DAMAGE

469

TIME AND DID STRIKE THE REAR BUMPER OF V2 CAUSIN DAMAGE TO THE FRONT BUMPER OF V1. NO VISIBLE TE 213 (979)

COUNTY: MONROE P.I.N.: NOT APPLICABLE ROUTE NO. OR STREET NAME: CASE No.:

COUNTY:	MONROE TOWN		P.I.N.:	NOT APPLICATE	BLE	ADJACENT RO	DADWAY NETW	ORK			CASE No.: FILE:		
	CITY					AT INTERSEC	TION WITH/OR	BETWEEN:			BY:	PSC	
	VILLAGE OF	ROCHESTER	!		-	SEE MAP					DATE:	5/13/2020	
TIME PERIOD		FROM: 8/1/14	TO: 7/31/19	ENVIRONMEN Use Codes from at right) for these	n MV 104 (shown e categories	Light Conditions 1. Daylight 2. Dawn 3. Dusk 4. Dark Road Li 5. Dark Road U	ghted	Roadway Surface 1. Dry 2. Wet 3. Muddy 4. Snow/Ice 5. Slush 10. Other	ce Condition: Weather: 1. Clear 2. Cloudy 3. Rain 4. Snow 5. Slee\forall Hail/Fre 6. Fog/Smog/Sn 10. Other				
No. OF MONTH	HS:	(60	ES							¹ Use Codes from	MV 104 Police Report	
CRASH No.	CASE No.	DATE	TIME	No. of VEHICLES	SEVERITY	CONDITIONS	ROADWAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING FACTORS	DIRECTION	TYPE ¹	DESCRIPTION	REFERENCE MARKER
470	37068207	1/2/2018	10:20:00 AM	2	PROPERTY DAMAGE AND INJURY	DAYLIGHT	SNOW/ICE	SNOW	FOLLOWING TOO CLOSELY	NORTH	REAR END	IY WAS TRAVELING NORTH BOUND ON NORTH ST APPROACHING CUMBERLAND ST. VWAS STOPPED IN TRAFFIC ON NORTH ST IN THE NORTHBOUND LANE AWAITING AN OPPORTUNITY TO TURN WEST ON CUMBERLAND ST. VI. ATTEMPTED TO STOP BEHIND V2. HOWEVER DUE TO IKE AND SNOW ON THE PAYEMENT VI. SLID NITO THE REAR OF V2 AT LOW SPEED. BY THIS ACTION THERE WAS NO VOSBILE DAMAGE TO EITHER VEHICLE. THE LACK OF DAMAGE WAS DOCUMENTED ON BODY CAMERA 1910. DRIVER OF V2 WAS PRECINATI AND ROUSETED MEDICAL AS A PRECAUTIONARY MEASURE HOWEVER WHEN THE AMBULIANCE ARRIVED DRIVER OF V2 REFUSED TO GOT OTHE HOSPITAL AND STATED SHE WOULD DRIVE HE WOULD THE RESULT OF THE WERE NO WITNESSES AND NO CITY OR PRIVATE CAMERAS IN HE AREA OF THE WCCEPET THE REAR OF THE MECCEPT THE MEASURE HE ACCEPT THE MEASURE THE MECCEPT THE MEASURE THE AREA OF THE MECCEPT THE MERLE PER PROMATIVE AT THE SIMPLE MECCEPT THE MERLE PER PARAMETERS.	
471	37105930	1/4/2018	9:47:00 AM	2	NON- REPORTABLE	DAYLIGHT	SNOWICE	SNOW	PASSING OR LANE USAGE IMPROPERLY	WEST	OVERTAKING	CUMBERAND ST. WHEN JUST PASS ROME ST VEHICLE T FORCED VEHICLE 2 OFF THE ROAD AND NOT OTHE CURB. THIS HAPPENED AS THE DRIVER OF VEHICLE 1 WAS YELLING SOMETHING AT VEHICLE 28,000S DRIVER THE DRIVER OF VEHICLE 2 STATED THIS MAY BE DUE TO HIM DRIVING AROUND VEHICLE 1 TEARLER. WHEN ITS TOPPED FOR NO APPARENT REASON. VEHICLE 1 THEN LEFT THE	
472	37075978	1/8/2018	2:27:00 PM	2	NON- REPORTABLE	DAYLIGHT	WET	CLOUDY	FOLLOWING TOO CLOSELY	NORTH	REAR END	SY WAS STOPPED IN TRAFFIC AT A RED LIGHT FACING NORTHBOUND ON STATE ST. VI WAS BEHIND VZ AND FALED TO COME TO A COMPLETE STOP. VI REAR ENDED VZ AND THEN VI LEFT THE SCENE GOING NORTHBOUND ON STATE ST. NO IN LIDES. VI and VZ were both who or Cumberland Stapproaching ST Paul	
473	37089636	1/12/2018	8:23:00 PM	2	PROPERTY DAMAGE	DARK-ROAD LIGHTED	SNOW/ICE	SNOW	FOLLOWING TOO CLOSELY	WEST	REAR END	VI and V2 were both who in Cumberland St approaching St Paul St. The light at SI Paul St was a sleady red. V2 began to slow for the light. V1 approached and was unable to stop, due to snow and ice on the road. V1 struck V2 causing damage to both vehicles. No inhibits security approached and vehicles.	
474	37087945	1/14/2018	7:48:00 PM	2	NJURY	DARK-ROAD LIGHTED	WET	CLOUDY	TRAFFIC CONTROL DEVICES DISREGARDED	WEST	RIGHT ANGLE	Ministry with a green light log of in a southerly direction ones of ministry, when yethersess stated that as they observed IV2 crossing were EMain St, they observed IV a trossing were Link and the Stapproaching he intersection of E Main St and University, Ave. Withersess of the Stapproaching he intersection of E Main St and University, Ave. at a high rate of speed, where he had a red light, Withersess Ave. at a high rate of speed, where he he had a red light, Withersess Ave. at a high rate of speed, where he had a red, he will be red on the very front end of VI, and in the rear driversegors side door of V2. The impact to dispace on the very front end of VI, and in the rear driversegors side door of V2. The impact caused V2 he spin 180 degrees, and come to rest in the middle of the intersection facing north. The impact caused V1 he burn in a southwesterly direction had jumped over the curbing on the southern side of E Main St. Hen making context when the paper of II, where the vehicle came to rest All a coupants of the vehicles were transported to Strong Memorial Hospital for exclusion. Of two and building to Police or EMS personnel very much, but did convey that he had some pain in his right hip. Strong challenges are completed in the continum that OT had a shattered right hip, and he also suffered a spinal fracture in his neck. D1 had been taken to the Strong hierarche caused with the spinar of the vehicles were the other strength of the spinar to severe the long to the spinarse sponded to the scene due to the possible need for a DWI car. Trooper Cumringham also responded to the scene due to the possible need for a DWI car. Trooper Cumringham also responded to the scene due to the possible need for a DWI car. Trooper Cumringham also responded to the scene due to the possible need for a DWI car. Trooper Cumringham also responded to the scene due to the possible need for a DWI car. Trooper Cumringham also responded to the scene due to the possible need for a DWI car.	
475	37108594	1/18/2018	5:41:00 PM	2	PROPERTY DAMAGE AND	DARK-ROAD LIGHTED	SNOW/ICE	SNOW	PASSING OR LANE USAGE IMPROPERLY	WEST	OVERTAKING		
476	37105988	1/19/2018	12:55:00 PM	2	NJURY NON- REPORTABLE	DAYLIGHT	WET	CLEAR	DRIVER INATTENTION	SOUTH	REAR END	omme acover user and wine mesponaco of me reports a minimum with specific both and the mass on the off small from the limit cloop and he had stopped at the red light at the intersection with E Mains st. While he was stopped vehicle 2 struck him from behind cassing very minor damage to the bumper of vehicle 1. Driver one was able to get the license plate of the striking vehicle. Other 2 fed the score with outlying driver one and vehicle the contracted of the consequent part provided by their one and it matched the description of the car that he gave to RO. No	
477	37108598	1/19/2018	3:40:00 PM	2	NON- REPORTABLE	DAYLIGHT	WET	CLEAR	FOLLOWING TOO CLOSELY	WEST	REAR END	Twiss raveling was on cumerating suppose in raine, when vi- rear ended VI causing damage to the rear bumper of V2. VI let the scene of the accident but V2 was unable to get a description of the driver. No injuries On 12018 MCSO Deputy Bernettli went to the home of V1 and three was no fort and damage to the vehicle that would have been consistent with the above accident. WINNESS 1 CHORNOBAY, WCTOR ROCHESTER NY suppages 2017.	
478	37121247	1/23/2018	7:38:00 AM	2	NON- REPORTABLE	DAYLIGHT	WET	CLOUDY	DRIVER INATTENTION	WEST	REAR END	WEMCLES WAS STOPPED IN TRAFFIC AT THE RED LIGHT ON CUMBERLAND ST AT ST PAUL ST, VEHICLE 1 WAS COMING UP BEHIND VEHICLE 2 AND FAILED TO STOP. THUS REAR ENDING VEHICLE 2 CAUSING DAMAGE TO VEHICLE 18 apos S HOOD. THERE WAS NO DAMAGE TO USHICLE 18 APPROVED THE WAS NO DAMAGE TO USHICLE 1	

TE 213 (9/79) ROUTE NO. OR STREET NAME MONROE P.I.N.: NOT APPLICABLE CASE No ADJACENT ROADWAY NETWORK TOWN FILE: CITY AT INTERSECTION WITH/OR BETWEEN: BY: PSC VILLAGE OF ROCHESTER DATE: 5/13/2020 SEE MAP FROM ENVIRONMENTAL TIME PERIOD TO Roadway Surface Condition Daylight
 Daylight
 Dawn
 Dusk 1. Dry 2. Wet 3. Muddy 1. Clear 2. Cloudy 3. Rain se Codes from MV 104 (shown tright) for these categories 8/1/14 7/31/19 4. Snow/lo 5. Dark Road Unlighted 5. Slush 5. Sleel/Hail/Freezing Rain 10. Other 6. Fog/Smog/Smoke lo. OF MONTHS 60 Jse Codes from MV 104 Police Report of VEHICLES GHT DIRECTION DESCRIPTION REFERENCE ROADWAY SURFACE CONDITION CRASH No CASE No DATE TIME APPARENT CONTRIBUTING FACTORS 351-4214 river 1 states he was coming to a stop as he approached the inter I sales he was coming to a soy as he approached he hersection of Scio SVE Main St. As Veh 1 was just about to a complete stop, veh 1's front bumper made contact with the eg of Ped 1, who was crossing in the cross walk with the signal. Driver 1 did not realize Ped 1 was where she was, due to driver NON 479 37121228 1/23/2018 10:03:00 AM DAYLIGHT DRY CLEAR DRIVER INATTENTION OTHER hecking traffic as veh 1 was going to make a right turn after it impleted the stop. Pedestrian 1 had no injuries, and continued t school after talking to r/o. Pedestrian 1's parent was notified On 1/25/18 at appx 1502hrs, V1's rear passenger corner side swiped V2's front drivers side corner. V1 said that he was traveling in the right lane of Cumberland St going East bound le was entering the intersection of N Clinton Ave with a green ligh ind proceeded to make a right hand lurn glong South.

Thatkapos;s when V2 squeezed by the shoulder and he collided

with V2. He said he did not know where V@ came from...... V2. FAILURE TO YIELD RIGHT OF SOUTH-EAST OVERTAKING 480 37109510 1/25/2018 3:02:00 PM DAYLIGHT DRY CLOUDY EPORTABLE says that she was in the right lane and that V1 was in the lane to ne left of her. She said that the light was turning yellow and she as going to continue straight on Cumberland St. As she entered e intersection, she said V1 cut in front of her to make a right hand rn onto N. Clinton Ave and that is when he hit her vehicle. Then 2 was raveling westoonto on university ave and was stopped raffic at the red light at N Union St. D2 stated that V1 came up fro chind him traveling in the same direction and did not stop in tim acting a mile avening in the same during a fail of the which confinued arough the intersection after he had pulled his car off to the side ind the light turned green. D2 was not completely sure of the cense plate on V1, he only knew it was a small car. There was NON. DARK-ROAF 481 37113939 1/26/2018 6:57:00 PM DRY CLOUDY DRIVER INATTENTION WEST REAR END DEDODTARII very minor damage to the rear bumper of V2. V2 was still operab edestrian was crossing at State St and Allen St on the East sid Pedestrian was crossing al State St and Allen St on the East side of State St raveling 58. V1 proceeded frrough the intersection striking the pedestrian. Both parties exchanged information and agreed to contact policie for a report at a later time. I spoke with the pedestrian on 21/21/8 at approximately 1100 and he stated to me that he wanted a police report due to having to take himself to the ospital for neck pain. He stated that he went the following morni to spiral or flexic pair. The salest later well are clowing in flat of 0.1731/18) and was treated and released from RGH the same norning. I spoke with the driver of V1 who stated that he had a green light and was proceeding through the intersection and did tot see the pedestrian. He reported no injuries. P1 stated that PEDESTRIAN'S 482 37157521 1/30/2018 9:15:00 AM INJURY DAYLIGHT DRY CLEAR EAST OTHER FRROR/CONFUSION river 1 had a red light and that he was facing a green light. P1 aid that Driver 1 may have gone through a red light. Due to the letay in the report I was unable to investigate their claims further. to cameras are in the immediate area that would have caught the ccident on video. V1 was CFBO. There were no possible TREET APPROACHING THE SAINT PAUL STREET ITERSECTION, VEHICLE 2 WAS NORTHBOUND ON SAINT FAILURE TO YIELD RIGHT OF PROPERTY 483 37117761 1/30/2018 10:28:00 AM DAYLIGHT WFT SNOW WEST RIGHT ANGLE AUL STREET ABOUT TO GO THROUGH A GREEN LIGHT DAMAGE WAY THE SAME INTERSECTION. VEHICLE 1 SLOWED FOR S RED LIGHT BUT WAS SLIDING ON THE SLUSH. VEHICL THEM STRUCK VEHICLE 2 On 01-31-2018 at 10:42 hours, Ofc. Minnick and Fresponded to On 01-31-2016 at 10-42 flouts, Oic million that in Esponded to the intersection of Scio St and Lyndhurst St for the report of an MVA. Upon arrival we spoke with (V1) Cross and (V2) McCrea. Both drivers have the same account of the accident. (V1) was traveling northbound on Scio Stapproaching the above mentions ntersection. (V2) was waiting at the intersection facing westboung indisection. (V2) was waining an inersection facility westboom gelfing ready by pass through the intersection. The traffic control ght changed over and westbound traffic had the green light while orth/southbound traffic on Scio now had the steady red light. (V2) egan to proceed into the intersection and was struck by (V1). (V1) PROPERTY oss says she is not from the area and was confused as she Cross says sets in notification in earea and was confused as see looked around for street signs and slates she did not see the taffic control light for the intersection at all. (W) was traveling southbound on Scio and had come to a complete stop for the red light. She states that (V) Cross did pass through a steady red light and strike, (V2), (W) did also provide a witness deposition which was taken by DRIVER INATTENTION RIGHT ANGLE 484 37121253 1/31/2018 10:42:00 AM AMAGE AND DAYLIGHT WET SNOW NORTH INJURY Ofc. Minnick and is on file at the office. Heavy front end Damage n.c. minimick and is of ine at the office. Theavy from each ballinger as a caused to both vehicles. (VI) Cross complained of pain to he ands and chest and was taken to Strong Hospital by AMR. (V2) IcCrea complained of pain to his shoulder and was taken to ochester General Hospital by AMR. Both vehicles were towed I ohn and Son Collision to their garage at 4 Niagara St. (V1) was ed two traffic tickets documented above in this report. 1 and veh 2 were both traveling south east on Cumberlan it clinton ave. Cumberland st is a 3 lane oneway street sourth NON DARK-ROAD UNSAFE LANE CHANGE SOUTH-EAST OVERTAKING 485 37121245 1/31/2018 6:08:00 PM WET CLOUDY ast, veh 1 attempted to make a left hand turn from the middle REPORTABLE LIGHTED nd of cumberland and struck veh 2 which occupied the left land piniuries no cameras no wilnesses EHICLE 2 WAS STOPPED AT THE RED LIGHT ON UMBERLAND ST HEADING WEST AT JOSEPH AV. WHEN EHICLE 1 ALSO ON CUMBERLAND ST HEADING WEST. PAVEMENT SLIPPERY 37125970 2 WEST REAR END 486 2/2/2018 10:31:00 AM DAYLIGHT SNOW/ICE SNOW REPORTABLE REAR ENDED VEHICLE 2 AFTER SLIDING ON THE SNOW ND ICE, VEHICLE 2 HAD SLIGHT DAMAGE, IT'S FAD RUMPED THERE WAS DAMAGE TO VEHICLE 1. on above date, white and location to was takening as on Joseph kwe and was shopped at the red arrow at he intersection of Jose kwe and Cumberland ST. V2 had a red arrow to turn WB on Cumberland Ave and was slopped as traffic was coming WB on

FOLLOWING TOO CLOSELY

SOUTH

REAR END

umberland and had the right a way. V1 was directly behind V2

and didnt realize V2 had stopped and as a result V1 rear ended V2 which damaged the rear bumper on V2 with the front bumper of his vehicle. V1 had no damage from the incident and no one

37131547

2/5/2018

487

3:18:00 PM

2

DAMAGE

DAYLIGHT

WET

CLEAR

TE 213 (9/79) ROUTE NO. OR STREET NAME: MONRO P.I.N.: NOT APPLICABLE CASE No ADJACENT ROADWAY NETWORK TOWN FILE: CITY AT INTERSECTION WITH/OR BETWEEN: BY: PSC ROCHESTER VILLAGE OF DATE: 5/13/2020 SEE MAP FROM ENVIRONMENTAL TIME PERIOD TO Daylight
 Daylight
 Dawn
 Dusk 1. Dry 2. Wet 3. Muddy 1. Clear 2. Cloudy 3. Rain se Codes from MV 104 (shown right) for these categories 8/1/14 7/31/19 4. Snow/lo 5. Sleet/Hail/Freezing Rain 5. Dark Road Unlighted 5. Slush 10. Other 6. Fog/Smog/Smoke lo. OF MONTHS 60 Jse Codes from MV 104 Police Report of VEHICLES DIRECTION DESCRIPTION REFERENCE SOADWAY SURFACE CONDITION CRASH No CASE No DATE TIME APPARENT CONTRIBUTING FACTORS 2 was traveling n/b on Joseph Ave. V1 was traveling w/b or umberland St making a right hand turn on to Joseph Ave. V1 led to yield to V2 and struck her. V2 had complaint of hip and PROPERTY FAILURE TO YIELD RIGHT OF WAY DADK-DOAF 37131549 8:37:00 PM AMAGE AN INJURY CLOUDY LIGHTED omach pain and was taken to Rochester General by AMR 7649). No tows needed on scene St Paul St. Driver V1 states that V2 cut the corner short striking V' river V2 states that driver V1 took his turn too wide and Driver V2 States that univer V1 look is alt nito whoe and didn'aRapost, time into the closest lane that he should have. Driver V2 states that V1 came into his lane striking him. After looking at both vehicles damage and the debris from the vehicles in the PROPERTY DARK-ROAD 489 37134278 2/7/2018 12:55:00 AM DRY CLEAR TURNING IMPROPER NORTH-EAST OVERTAKING oadway it was determined the crash occurred as V2 had escribed it. No injuries were reported and damage was minor t orb V1 and V2 in 02-08-2018 at 10:20 hours, Tresponded to the area of St Paul on toz-lo-zo i a i tozo flouis ; i report spontee to the area of is Paul St and Central Ave for the report of a hit and run MVA. Upon arrival I located (V2) Malloy. (V2) was operating northbound on SI Paul St crossing over Central Avenue approaching the railroad underpass. (V2) was in the left lane and had the right of way. (V2) tables that (V1) aggressively drove up along her passenger side he right hand lane which merges into the lane that (V1) was occupying. (V1) struck (V2) side swiping (V2)&apos:s rear assenger side with its front driver side. (V2) slowed a bit to let PROPERTY AGGRESSIVE DRIVING/ROAD 490 37157532 2/8/2018 10:20:00 AM DAYLIGHT DRY CLOUDY NORTH OVERTAKING (V1) in front of her at that point and captured (V1)'s license ate information. (V1) did not stop and sped off northbound on SI Paul St. (V2) pulled over and called 911. No Injuries. (V2) was ared for by its owner. R/O's did attempt several times to acate (V1) at the registered owners address with negative resul was unable to find a good address in the system for (V1) Lindse Both vehicles were traveling southbound on State St prior to topping at the red light for Allen St. Driver #1 stated that she was opping at the recurring the means of the was okking at the other light ahead of that traffic light and did not notice turn red at Allen St. As a result, vehicle #1 struck the rear assenger side corner of vehicle #2 causing minor damage to NON-491 37141384 2/12/2018 9:51:00 AM DAYLIGHT DRY CLEAR FOLLOWING TOO CLOSELY SOUTH REAR END EPORTARI Phicle #2 No injuries were reported at the scene.
O SPOKE TO THE DRIVER OF VEHICLE 2 WHO STATED. THAT HE WAS STOPPED UNDER THE BRIDGE AT THE REI IGHT ON STATE ST AT ALLEN ST NR. WHEN HIS VEHICLE NAS STRUCK FROM BEHIND BY VEHICLE 1 WHICH WAS TRAVELING NB ON STATE ST.THIS CAUSED MINOR DAMAGE TO VEHICLE 2 REAR BUMPER.DRIVER OF EHICLE 1 STATED THAT SHE WAS NB ON STATE AND NON-492 37165608 2/12/2018 1:14:00 PM 2 DAYLIGHT DRY CLOUDY UNKNOWN NORTH HER MIND WAS PRE OCCUPIED AND SHE DID NOT NOTICE REPORTABLI ER MIND WAS FRE OCCUPED AND SHE DID NOT NOTICE
HICLE 2 STOPPED AT THE LIGHT NB ON STATE ST AT
LLEN ST, WHEN HER VEHICLE STRUCK VEHICLE 2.
RIVER OF VEHICLE 1, ALSO STATED THAT THE PAVEMENT UNDER THE BRIDGE WAS ICEY, R/O DID CHECK THE AREA AND DID NOT NOTICE ANY SLICK OR CEY PAVEMENT, MINOR DAMAGE TO VEHICLE 1&apos:S of stated she was ravening soundound on it officions to approaching the intersection at N Union St and University Ave. D1 stated that she did not realize in filme that she was facing a red light D1 stated she applied her brakes but was unable to come to a stop to avoid entering the intersection. D1 stated that upon entering the tersection she struck V2. V2 was traveling westbound on PROPERTY intersection site struck V2. V2 was raveing westbound on University) Ave, with a green light D2 stated that he did in fact have a green light when he entered the intersection. V2 sustained minor damage to the passenger 8 aposs; side rear door area, and V1 sustained major damage to the forther off the vehicle. V2 was still operable following the incident and was driven from the scene by 493 37147245 2/12/2018 2:21:00 PM DAYLIGHT DRY CLOUDY DRIVER INATTENTION SOUTH RIGHT ANGLE DAMAGE owner. V1 was not operable and was towed by Excel Towing their garage. There were no injuries observed or complained was stopped at the red light of st paul and cumberland st facin or was supped at the text injurior is paid and combeniate strain, with. v2 was travelling rulb on st paul st. d1 stated that she altempted a right hand turn onto st paul st. white altempting the right ru/b turn, per d1, v2 was attempting a etb right hand turn onto central ave. v1 then struck v2. d2 stated that he was traveling rulb

AILURE TO YIELD RIGHT OF

WEST

RIGHT ANGLE

494

37156260

2/22/2018

4:43:00 PM

DUSK

REPORTABLI

WET

CLOUDY

on st paul. d2 stated that he had the right of way and attempted a

e/b turn onto central ave. as he attempted the turn v1 which was

acing with on cumberland statempted a nit burn onto stead statempted a nit burn onto stead st. his point of stuck v2. There were no visible injuries nor complain of pain. There was minor damage to the left front headight near of of, and minor damage to the right front burnper of v2. If was burned to have a suspended license and have a warrant out of IRO or AUO 2nd. no vehicles were tower and one cristion issued.

TE	213	(9/79)

TE 213 (9/79)											ı		
COUNTY:	MONROE		P.I.N.:	NOT APPLICAB	LE	ROUTE NO. OF	R STREET NAM ADWAY NETWO				CASE No.		
	TOWN CITY					AT INTERSECT					FILE: BY:		-
	VILLAGE OF	ROCHESTER				SEE MAP	HON WITH/OR	DE I WEEN:			DATE		-
TIME PERIOD		FROM: TO: ENVIRONMENTAL: Use Codes from MV 104 (: 8/11/14 7/31/19 at right) for these categories				Light Conditions:	ghted	Roadway Surfac 1. Dry 2. Wet 3. Muddy 4. Snow/Ice 5. Slush 10. Other	ce Condition: Weather: 1. Clear 2. Cloudy 3. Rain 4. Snow 5. SleeVHall/Fre 6. Fog/Smog/Sr 10. Other				
No. OF MONTH	IS:	(0	ES					10. 08101		¹ Use Codes from	MV 104 Police Report	
CRASH No.	CASE No.	DATE	TIME	No. of VEHICLES	SEVERITY	CONDITIONS	ROAD WAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING FACTORS	DIRECTION	TYPE ¹	DESCRIPTION OFFICE USE USE AND Approximate time tresponded to the two venice.	REFERENCE MARKER
495	37187697	2/26/2018	10:35:00 AM	2	NJURY	DAYLIGHT	DRY	CLEAR	UNSAFE LANE CHANGE	WEST	OVERTAKING	motor vehicle collision at Cumberland SiMestooti SI. On my arrival lidentified there vehicle 1 and there vehicles 2 by valid NYSDL. The front seat passenger of vehicle 2 vertably identified harself and her daughler who was in a child booser in her rear left and of vehicle 2. Driver vehicle 1 sites he was westoomd on Cumberland SI after saring from the intersection of N Cumberland SI after saring from the intersection of N Cimberland SI after saring from the intersection of N continent Cumberland SI then as the saring the sales were sales vehicle 2 was westbound in the lane bits high and changed lanes in front him stifting the fortright of his truck. He states he newer saw driver vehicle 2 span but half may be because of the size of his vehicle and proximity of vehicle 2, he was just unable to see it her bed of the truck tipped over forward Driver vehicle 2 and to the sales her barsel hard by and avoid collision, he pointed out he braked hard enough that a heavy loaded pallet in the bed of the truck tipped over forward Driver vehicle 2 and to a passenger vehicle 2 accoused fiver vehicle 1 for and collision, her vehicle 1 for and and sort passenger vehicle 2 states that driver vehicle 1 for and sales passenger vehicle 2 states that driver vehicle 1 for and sales passenger vehicle 2 states that driver vehicle 1 for all the collision has easily the child, she appeared to k. her said her hummy hum however, pointed to her back. Front seat passenger vehicle 5 states that driver vehicle 1 stated a vibers and the vehicle 3 was all her hummy hum however, pointed to her back. Front seat passenger vehicle 2 cand the through your however, pointed to her back. Front seat passenger vehicle 2 cand the through your however, pointed to her back. Front seat passenger vehicle 2 cand the vehicle 2 cand seat when the work of the child. She papeared to k. her said her hummy hum however, pointed to her back. Front seat passenger vehicle 2 cand of the child she passenger vehicle 3 cand the vehicle 2 cand the withes so the vehicle 2 can	
496	37172763	2/27/2018	6:22:00 AM	2	PROPERTY DAMAGE AND INJURY	DAWN	DRY	CLEAR	TRAFFIC CONTROL DEVICES DISREGARDED	NORTH	RIGHT ANGLE	IT WAS TRAVELING WIS ON CUMBERLAND STRUCK VEW HID WAS TRAVELING WIS ON CUMBERLAND ST. BOTH WASPOSS STATED THAT THEY HAD THE GREEN LIGHT. VI WENT ON TO SAY THAT SHE WASNIF EXACTLY SURE THAT SHE HAD A GREEN LIGHT BUT SHE THOUGHT SHE DID. VE WAS TRANSPORTED TO RIGH BY RIG 732 FOR PAIN TO THE NECK AND BACK. BOTH VEHICES WERE TOWED BY EXCEL TOWING. NO CAMERAS IN THE AREA AND NO WASSTRACEMENT OF BOTH STRUCK.	
497	37164512	2/28/2018	4:44:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	FALURE TO YIELD RIGHT OF WAY	NORTH	OVERTAKING	VZ WIST PREVELIENG IND OUT STATE 3 IN THE LANGE CLOSEST TO THE EASTSDE OF STATE 5T. VI WAS TRAVELING NIB ON STATE 5T AND WAS LEFT OF VZ. AS TRAFFIC CONTINUED, THERE WERE COMES AND CONSTRUCTION SIGNS IN VIRAIDOS. SLANE THAT FORCE OF TO TO THE OFFICE OF TO VZAGOSES. LANGE WHILE MERGANG, HOWEVER, VI DID NOT YELD THE RIGHT OF WAY FOR VZ. NAIL WITLING LEFT ONE GALD.	
498	37172805	3/5/2018	8:22:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	PASSING TOO CLOSELY	WEST	OVERTAKING	RIO Contreras responded to Commercial SI © Sales Si for a mort vehicle accident Upon artival interviewed the parties, and found that this accident box jace at Cumberland sI © SI Paul SI. RIO Contreras did dribe to accident colors to confirm the slockage of snow and ice on the left turn lane on Cumberland sI, which was correct and blocking part of the lane. Operator #1 propris that while sistomary in the left lane waiting to burn left by south on SI. Paul, when Vehicle #2 drove passed vehicle #1 himility eth #1 from lane storage in the proper lane at all times and reports hat while with ethics #1 must have swere over to avoid with blockage of snow & (ice. "Trailer being pudied by vehicle 2°, birt on the Trails. NYS dels BBT/382. 2017 Cuality fabote."	
499	37208467	3/5/2018	11:53:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLOUDY	DRIVER INATTENTION	SOUTH	RIGHT ANGLE	Taller, Compre Premise Spin 16 Food IP. Rochesian My 1452: WHILLE ZWASS STOPPED IN TRANSITION CHOMBERCHAND STHEADING WEST IN FRONT OF 216 CUMBERCHAND ST. WHILLE I WAS BACKING OUT OF THE PARKING LOT OF 216 CUMBERCHAND ST. WHEN IT BACKED INTO THE REAR RIGHT OUARTER PANEL AND BUMPER OF VEHICLE 2. THUS CAUSING BOMAIGE TO BOTH VEHICLES. THE DRIVER OF VEHICLE 1 STATED HE FALLED TO LOOK LEFT BEFORD BACKING.	
500	37174702	3/7/2018	3:38:00 PM	2	NON- REPORTABLE	DAYLIGHT	WET	RAIN	UNSAFE LANE CHANGE	SOUTH	OVERTAKING	BEFORE ACCINIC VI and V. Was Service South and Nim and VIZ side swiped earn was alternifting to switch lands and him and VIZ side swiped each other. The operation of VIZ sided that she was driving shallowd VI skutch ker side mirror. No injuries. Minor damage. No oby or private camera Bapos sin the area. Operator of VI contacted RO at a later date to update the report. He sated that during the MVA he was in the turing lane and hatilagoss when both which the dame scheduler with the MVA.	
501	37178551	3/9/2018	8:49:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	WET	SNOW	FAILURE TO YIELD RIGHT OF WAY	NORTH-EAST	OVERTAKING		
502	37191369	3/13/2018	7:03:00 AM	2	NON- REPORTABLE	DAWN	DRY	CLEAR	VIEW OBSTRUCTED/LIMITED	SOUTH	OVERTAKING	FROM 2 LANES NOT DID ET O CONSTRUCTION. VI WAS MERGING FROM THE LEFT LANE TO THE REGHT LANE WHEN THE LEFT FROM TEMPER STRUCK VZ. VZ WAS ALSO SB ON STATE ST AT ALLEN ST. VI STATED THAT HE DID NOT SEE VZ BECAUSE HE WAS SIN BLIMD SPOT AND VI STATED SHOW SHOULD HAVE SHOWN SHOWN THAT WAS MERGING. VZ STATED THAT HE WAS AHEAD OF VI AND SECRED HIS HOWN WHEN HE SAW VI APPROACH. NO NUMBER SHOWN SHOWN SHOWN SHOWN SHOW THE SAW VI APPROACH. NO NUMBER SHOWN SHOWN SHOWN SHOW SHOW SHOW SHOW SHOW SHOW SHOW SHOW	

TE 213 (9/79) ROUTE NO. OR STREET NAME MONRO P.I.N.: NOT APPLICABLE CASE No ADJACENT ROADWAY NETWORK TOWN FILE: CITY AT INTERSECTION WITH/OR BETWEEN: BY: PSC VILLAGE OF ROCHESTER DATE: 5/13/2020 SEE MAP TIME PERIOD FROM TO NVIRONMENTAL Daylight
 Daylight
 Dawn
 Dusk 1. Dry 2. Wet 3. Muddy 1. Clear 2. Cloudy 3. Rain se Codes from MV 104 (shown right) for these categories 8/1/14 7/31/19 4. Snow/lo 5. Dark Road Unlighted 5. Slush 5. Sleel/Hail/Freezing Rain 10. Other 6. Fog/Smog/Smoke lo. OF MONTHS 60 Ise Codes from MV 104 Police Report of VEHICLES DIRECTION DESCRIPTION REFERENCE CRASH No CASE No DATE TIME APPARENT CONTRIBUTING FACTORS hicle 2 was stuck in traffic facing northbound in the right mos urn lane on University Ave at the intersection of E. Main SI ehicle 1 was stuck in traffic northbound in the right most left turn ne on University Ave at the intersection of F. Main St. hehing ine on university ave at he intersection of it. Main b.t. benind whiche 2. When the light turned green driver 2 stated that he was alting for a vehicle in front of him to go. Driver 2 stated he was en struck from behind. Driver 1 stated that the light turned green 503 37201260 10:20:00 AM INJURY DAYLIGHT FOLLOWING TOO CLOSELY CLEAR NORTH and traffic wasn&apos:t moving so he tried to see around vehicle: see what was going on. As driver 1 was doing this he let off the ake and struck the rear of vehicle 2. Minor damage to both ehicles. Driver 2 complained of lower back pain and was DDODEDT 504 37208470 3/24/2018 7:03:00 PM DAYLIGHT DRY CLEAR UNKNOWN WEST RIGHT ANGLE DAMAGE n 3/26/18 0742 hours, r/o was dispatched to scio/lyndhurst for a vehicle mva. Upon arrival, r/o spoke with Johnson, who was th iver of the school bus. Johnson said she was starting in traffic o cio street, going south bound, when she was rear ended from the ehicle behind her. No complaint of injury, no students on the bus did speak with Odey, who was the driver of the chevrolet cruise. PROPERTY 37213131 7:42:00 AM FOLLOWING TOO CLOSELY CLEAR dey said he was traveling south on scio and rear ended the bus complaints of injury. Odey vehicle had front end damage. PROPERT 506 37217812 3/26/2018 1:34:00 PM 2 DAYLIGHT DRY CLEAR DRIVER INATTENTION EAST RIGHT ANGLE PROPERTY All LIRE TO VIELD RIGHT OF 507 37213133 3/27/2018 12:08:00 PM DAYLIGHT CLOUDY FΔST ROPERT 508 37238483 3/29/2018 11:40:00 AM 2 WET RAIN UNKNOWN SOUTH UNKNOWN est bound on Cumberland St. V2 was approaching the ersection of St Paul St and Cumberland street with a green ligh easeculor of St Paul St and Cultification State with a gleen in I was approaching the same intersection with a red light. VT w rew the red light and struck V2 which was also going through tersection with the green light. V2 was struck on the rear right. NON DARK-ROAF 509 37217874 3/30/2018 11:44:00 PM 2 WFT RAIN DRIVER INEXPERIENCE SOUTH SIDESWIPE EPORTABL ssenger side and spun out. Both drivers as well as the three v1 and v2 were in left turn lanes to go n/b on st paul from ner loop, when they tuned on to st, paul the vehicles collided wit nier noby, when mey buted on to st, pain the vehicles coulded with 1 stiking v2, driver of v1 said that v2 was inhialty going straight efore turning left, and that he stayed in his lane, driver of v2 said tat she was signalling to go left and turned into her lane and that NON PASSING OR LANE USAGE 510 37249723 4/4/2018 12:46:00 PM DAYLIGHT DRY CLEAR NORTH OVERTAKING FPORTABL IMPROPERI Y turned into her lane icing eastbound. V2 was attempting to make a right hand turn nto N Clinton South from Cumberland St. V1 attempted to make PASSING OR LANE USAGE e same right turn on the inside of V2 striking the back left NON-DARK-ROAD uaterpanel of V2. V1 then left the scene in an unknown direction, ne driver and passengers of V2 were un injured. Hocaled the iver of V1 at his home address. After speaking to the driver of V1 511 37254999 4/5/2018 1:33:00 AM SNOW/ICE SNOW IMPROPERLY, DRIVER SOUTH-EAST OVERTAKING EPORTARI I LIGHTED INATTENTION ne stated that he was struck by V2. I observed no damage on rth St. and going straigh n the far right hand lane. V1 was travel northbound on North St. and was going straight ahead in the left hand lane. Driver of V2 NON-UNSAFE LANE CHANGE dates that V1 then attempted to change lanes and struck V2 as it titlempted to get into the right hand lane. No one was injured. V1 eft prior to police arrival. V1 is a gray/silver Hyundai Sante Fe 512 37223933 4/7/2018 3:22:00 PM DAYLIGHT DRY CLEAR NORTH OVERTAKING REPORTABLI Non-by a M/H possibly in his 30% apos-s 1 AND V2 WERE TRAVELING W/B ON CUMBERLAND S CROSSING ST PAUL ST ENTERING THE ON RAMP TO THE INER LOOP VI STATED THAT SHE WAS STOPPED AT INVERLICUOP. VESTATED THAT SHE WAS STOPPED AT THE RED LIGHT AT ST PAUL AND AS SHE CROSSED ST PAUL ST ENTERING THE ON RAMP TO THE NIVER LOOP SHE WAS STRUCK BY VZ. VI SAID SHE DID NOT SEE WHERE VZ CAME FROM. VZ STATED THAT HE WAS PROPERTY DARK-ROAL 513 37237826 4/9/2018 10:31:00 PM DRY CLOUDY UNKNOWN WEST OVERTAKING DAMAGE LIGHTED APPROACHING ST PAUL ST AND AS THE LIGHT TURNED PPROJUCTION OF THE CONTINUED STRICLENT TORNED

REEN HE CONTINUED STRIGHT ONTO THE ON RAMP TO

HE INNER LOOP. V2 SAID V1 WAS IN THE TURNING LANE

O MAKE A S/B TURN ONTO ST PAUL BUT WENT TRAIGHT INSTEAD. V1 DENIED BEING IN THE LEFT HANI JRNING LANE. NO INJURIES REPORTED OR OMPLAINED OF NO WITNESSES NO CITY OF PLYMOUTH AVE. THE RTS BUS HAD A GREEN LIGHT EHICLE 1 WAS WEST ON ALLEN ST. IT RAN THE RED LIGHT AND STRUCK VEHICLE 2. WITNESS 1 WAS GOING JORTH ON S . PLYMOUTH AVE AND WITNESSED THE ACCIDENT, STATING THEY HAD THE GREEN LIGHT. ÆHICLE 1 WAS SPUN AROUND AFTER THE INITIAL COLLISION AND THE REAR DRIVER SIDE HIT THE RTS BUS AGAIN IN THE MIDDLE PASSENGER SIDE. THE DRIVER OF ÆHICLE 1 THEN GOT OUT AND WALKED WEST ON ALLEN ST THEN NORTH ON STATE ST. THERE WAS 10-12 PASSENGERS ON THE BUS. 5 WERE INJURED, WITH 4 OING TO HOSPITALS. THE KEYS WERE LEFT IN VEHICLE 514 WEST RIGHT ANGLE 37271279 4/14/2018 7:09:00 AM AMAGE AND DAWN WET RAIN DISREGARDED VEHICLE 1 WAS TOWED TO THE POUND, I WENT TO THE INJURY REGISTERED OWNER&anns:S HOUSE AND SPOKE WITH A KEGISTERED OWNERABUDS:S HOUSE AND SPOKE WITH FEMALE WHO WAS HOUSE SITTING. SHE SAID KAREN COSMANO, THE REG OWNER, WAS IN NC FOR A WEEK. CAREN WAS DUE IN LATER THAT NIGHT. SHE SAID KAREN'S SON USUALLY DROVE THAT CAR. SHE CALLED KAREN ON THE PHONE. I SPOKE BRIEFLY WITH HER. SHE CONFIRMED HER SON USUALLY DRIVES THE HER: SHE COMPINMED HER SOM USBALLT PANKES HIE CAR, SHE DID NOT HAVE ANY OTHER INFORMATION FOR ME. I WENT TO SPEAK WITH HER ON 04/16/18. KAREN SAII HER LAWYER TOLD HER NOT TO TALK WITH US. RIO

PICKED UP VIDEO OF THE ACCIDENT AND TURNED IT IN

ROUTE NO. OR STREET NAME MONRO P.I.N.: NOT APPLICABLE CASE No ADJACENT ROADWAY NETWORK TOWN FILE: CITY AT INTERSECTION WITH/OR BETWEEN: BY: PSC VILLAGE OF ROCHESTER DATE: 5/13/2020 SEE MAP TIME PERIOD FROM TO ENVIRONMENTAL Roadway Surface Condition Daylight
 Daylight
 Dawn
 Dusk 1. Dry 2. Wet 3. Muddy 1. Clear 2. Cloudy 3. Rain se Codes from MV 104 (shown right) for these categories 8/1/14 7/31/19 4. Snow/lo 4. Snow 5. Sleet/Hail/Freezing Rain 5. Dark Road Unlighted 5. Slush 10. Other 6. Fog/Smog/Smoke lo. OF MONTHS 60 Jse Codes from MV 104 Police Report of VEHICLES DIRECTION DESCRIPTION REFERENCE CRASH No CASE No DATE TIME APPARENT CONTRIBUTING FACTORS V1 AND V2 WERE TRAVELLING W/B ON EAST MAIN STREE AS V2 WAS IN THE RIGHT TURNING LANE FOR THE INNER S V2 WAS IN THE RICHT TURNING LAIVE FOR THE MINER.
OOP AND VI WAS IN THE CENTER LAIVE FOR WIB TRAVEL
IN EAST MAIN. VI THEN DID ATTEMPT TO MERGE INTO
HE RIGHT TURNING LANE FOR THE INNER LOOP AND NON. 37237854 DAYLIGHT WET RAIN DRIVER INATTENTION WEST OVERTAKING 515 4/14/2018 8:45:00 AM HIS IS WHEN V1 DID STRIKE V2 CAUSING V2 TO STRIKE HE NORTH SIDE CURBING. NO INJURIES REPORTED. or to SS, mesponded to the call of an invA at the intersection of lorth St. and Cumberland St. Upon arrival, I saw two vehicles ulled over, one facing west on CumberlandSt, the other facing south on North St. There were also two individuals standing by th sount of notines. There were also two introducts standing by the care on Cumberland St. a black male and a white female. I approached female white and she identified herself as the driver o vehicle 1, Jessica Hefferan. Hefferan states that while driving south on North St. Hefferan was attempting to make a right hand turn into Cumberland St. She states that she was in the far left lane nind cultification 3 are states that size was in the attention and did not realize she was not in the turning lane. When she tarted the turn, she did not see Vehicle 2 to her right and proceeded to hit Vehicle 2 on the driver side. I then spoke with nale black, Stethann Crosby, and he identied himself as the NON 516 37313332 4/16/2018 8:13:00 AM DAYLIGHT WET RΔIN UNSAFE LANE CHANGE SOUTH OVERTAKING REPORTABLE ssenger of Vehicle 2. His girlfriend, Rachel Morgan, who was eated in Vehicle 2, was the driver of Vehicle 2, Crosby and searou in Venicue 2, was alle univer of venicule 2. Crossy and Morgan both confirmed Helferan&apos,s statements. Vehicle 2&apos,s front side passenger wheel had a flat from striking the curb after being pushed by Vehicle 1.There were no injuries. Morgan only had a Learners Permit. Her Crosby, had a uspended license #240760246, but was in the passenger seat ehicle 1 was registered and insured out of state. Her insurance STATE ST AND APPROACHING ALLEN ST, DID STRIKE VEH WHICH WAS TRAVELING FASTBOUND STRAIGHT AHEAD Z WHICH WAS I RAVELING EASTBOUND STRAIGHT AFTER DON ALLEN ST CROSSING THE INTERSECTION OF ALLEN ST AT STATE ST.VEH 1 STRUCK VEH 2'S RT FRONT DOOR W/VEH 1'S FRONT BUMPER/ HOOD AREA @ CENTER. VEH 2 THEN STRUCK UTILTY POLE AT NE CORNER OF INTERSECTION WITH VEH 2&anos:S LEFT PROPERTY RONT BUMPER/ FRONT END DRIVER 1 STATING THAT SHE OBSERVED THE TRAFFIC SIGNAL NORTH OF OCATION AS GREEN AND MISTAKENLY TOOK THAT 517 37239665 4/16/2018 1:46:00 PM AMAGE AND DAYLIGHT WET RΔIN DRIVER INATTENTION NORTH RIGHT ANGLE SIGNAL TO BE HER SIGNAL MISSING THE ACTUAL TRAFFI SIGNAL DESIGNATED FOR HER INTERSECTION WHICH WAS RED.DRIVER 2 STATING THAT HIS SIGNAL WAS GREEN DRIVER 2 WITH COMPLAINT OF KNEE PAIN IN OTH LEGS AND BACK PAIN. TRANSPORTED BY AMR MBULANCE RIG #7889.NO FURTHER INJURIES REPORTED.RFD ON SCENE.RPD OFC. SMITH - 251B W REPORTED AND OWNERS MAD DAMAGE TO JUST BY Both drivers stated they were starting in traffic on a green light traveling southbound off of the Inner Loop Exit Ramp onto E Mail St. Both drivers stated as they were starting from a stopped position they observed an ambulance approaching them on E main St with its emergency equipment activated. D2 stated that h pplied his brakes to let the ambulance pass, and D1 stated that the did not realize that the car ahead of her (V2) had hit their rakes until it was too late. D1 stated that she did try to avoid the PROPERTY 518 37239685 4/17/2018 4:47:00 PM DAYLIGHT WET CLOUDY DRIVER INATTENTION SOUTH REAR END pact by turning to the right but she was not able to avoid the npact and struck the rear passenger's side of V2 with the ont driver's side of her vehicle. There were no injuries erved or complained of by either party. Airbags did not deplo oth vehicles were driven from the scene by their owners.
stated that he was walking westbound on the southern crossw of F Main St. P stated that he did have the "walk": sign or E main St. P Stated with the but never the educulormaceQuits. Sign as he started to cross University Ave. P stated that when he got to the median on University Ave, he did not realize that the traffic signal had changed, and that he now had a " do not alk" sign facing his direction. P stated that he continued ossing westbound across University Ave. where V2 would soo NON DARK-ROAD PEDESTRIAN'S ussaing wesucului aclusis orinieratig view, iniciae 24 woului soon et driving. P stated that when he noticed the traffic was coming he ied to run across to make it in time, but did not make it and ran to the front driver& 519 37243430 4/18/2018 8:30:00 PM DRY CLOUDY OTHER REPORTABLI LIGHTED ERROR/CONFUSION iver's side mirror. P did not complain of any injuries and to injuries were observed on P. P refused all medical attention. lid observe P up and walking around at the scene, as well as elf and D2. V2 was driven from the scene by the or insect user and approximate time contents responded to the airload bridge crossing on SI Paul SI just south of 360 SI Paul SI or the pedestrian struck MVA. On my arrival I spoke with W1-IAYKE YUSUF, she states the pedestrian struck, V2-TOMA YUSIF, is her family, she states she was with her husband whe nev stonned in the southbound lane of St Paul St just before the rey supple in the solutious traine in St Paul Stjust beare the ridge and waved to her lo come to their car to get into it, to pick ter up. V2 entered the roadway and was shuck by northbound V1 Driver V1-MARIO ORTIZ, states that he was northbound on St Paul St and observed V2 walk into the roadway, he states he was PROPERTY PEDESTRIAN'S nable to stop and struck V2 with the front left bumper of his car.W. 520 37251407 4/19/2018 2:38:00 PM AMAGE AND DAYLIGHT WET CLOUDY NORTH OTHER ERROR/CONFUSION MOHAMMED KAMEL and W3-MICHELLE DELATTE verified th INJURY Ornamied Ramet and wis-micrette bearte veilied in resion of the incident/21 transported to SMH by AMR rig#7719 is implain of pain to left leg, lower leg and hip area. She was inscious when transported. I relocated to SMH and spoke with V2, she states she was going to get a ride from her family and looked to cross St Paul St but did not see V1 approaching. Photo taken of V1 and V2.BWC foolage on file. • WITNESS 1 YUSUF, HAYKE 225 GLENWOOD AVE ROCHESTER NY 14613 5854144744 - WITNESS 2 KAMEL, MOHAMMED 109 DAVID AVE ROCHESTER NY 14620 5859678065 - WITNESS 3

TE 213 (9/79)

TE 213 (9/79) ROUTE NO. OR STREET NAME MONRO P.I.N.: NOT APPLICABLE CASE No ADJACENT ROADWAY NETWORK TOWN FILE: CITY AT INTERSECTION WITH/OR BETWEEN: BY: PSC VILLAGE OF ROCHESTER DATE: 5/13/2020 SEE MAP TIME PERIOD FROM TO NVIRONMENTAL 1. Dry 2. Wet 3. Muddy 1. Clear 2. Cloudy 3. Rain se Codes from MV 104 (shown right) for these categories 1. Daylight 8/1/14 7/31/19 4. Snow/lo 5. Dark Road Unlighted 5. Slush 5. Sleel/Hail/Freezing Rain 10. Other 6. Fog/Smog/Smoke lo. OF MONTHS 60 Jse Codes from MV 104 Police Report of VEHICLES DIRECTION DESCRIPTION REFERENCE CASE No CRASH No DATE TIME APPARENT CONTRIBUTING FACTORS TRACTOR TRAILER TRUCK) AND V2 (TAX CAR #30 VI (TRACTOR TRAILER TROUS) AND VE (TACCAS 3305)
WERE TRAVELING WIB IN THE RIGHT LANE ON ALLEN
STREET APPROACHING THE INTERSECTION OF N
PLYMOUTH AVENUE AND HAD THE GREEN LIGHT. VI
THEN BEGAN TO MAKE A LEFT TURN ONTO N PLYMOUTH AVENUE TO HEAD S/B AND THIS IS WHEN V2 DID GO AROUND YIN IN THE TURN ONLY LANE, WHICH WAS PARTIALLY BLOCKED OFF WITH CONES DUE TO CONSTRUCTION, AND THEN DID ATTEMPT TO PASS VI ON THE LEFT AND PROCEED WIB ON ALLEN STREET TO GET ONTO THE ROUTE 490 WB ON RAMP. V1 WAS NOT ABLE STOP IN TIME AND DID STRIKE V2 ON THE ON PROPERTY LEFT TURN O STOP IN TIME AND DID STRIKE V2 ON THE VA ASSENGER SIDE OF SAID VEHICLE 2 CAUSING DAMAGE O V2. REAR SEAT PASSENGER (P) COMPLAINED OF AIN ON THE ENTIRE RIGHT SIDE OF HER BODY. FIRE FAILURE TO YIELD RIGHT OF 37255575 521 10:19:00 AM AMAGE ANI INJURY SOUTH-WEST AND EMS RESPONDED AND (P) WAS TRANSPORTED TO ROCHESTER GENERAL HOSPITAL VIA AMR AMBULIANCE DCHES JER GENERAL ROSPITAL VA AMR AMBOLANCE RWER OF V2 STATED THAT HE THOUGHT THAT VI HAD TOPPED AND THAT&APPOSS WHY HE WENT AROUND VI. RWER OF VI STATES THAT HE NEVE STOPPED AND BSERVED V2 COMING UP ALONG SIDE HIS TRUCK ATTEMPTING TO PASS HIM AS V1 WAS MAKING THE LEFT LIRN AND VI WAS LINABLE TO STOP IN TIME. R/O SPOKE ITH (P) AT THE HOSPITAL AND (P) STATED THAT SHE BSERVED VI MAKING THE LEFT TURN AND DID NOT OW WHY THE DRIVER OF V2 WAS TRYING E/B EXIT RAMP TO E MAIN ST WITH THE TRAFFIC IN FRON F HER WAITING TO GO STRAIGHT. VI IS IN THE LEFT FINER WAILING TO GO STRAIGHT. VES IN THE LEFT JUME AND SIGE-SWIPES V. V2 THEN CONTINUED AND JURNED LEFT ONTO E MAIN ST. I LOCATED THE PERATOR OF VI WHO STATED THAT SHE WAS AT THE PROPERTY PASSING OR LANE USAGE 522 37267404 5/3/2018 4:45:00 PM DAYLIGHT DRY CLEAR FAST OVERTAKING OCATION AND THOUGHT SHE HIT A CURB. NO INJURIES OUTCOMES

I was traveling S/B on St. Paul Street. V2 was traveling W/B o

umberland Street. OP V1 stated that he saw the next traffic light own was green and he mistook that for the light he was about to go through. By the time he realized his mistake he was entering PROPERTY intersection at Cumberland and St. Paul. When OP V1 reali: DARK-ROAF RAFFIC CONTROL DEVICES te intersection at Cutterland and or Fault, when of V Heature is he slammed on his brakes and turned right, but it was too lall IP V2 stated that she had a green light and went through the itersection at St. Paul SVC umberland St when she was suddenly 523 37355539 5/4/2018 12:39:00 AM AMAGE ANI WFT RAIN SOUTH RIGHT ANGLE INJURY struck by V1.V1 had damage to the driver's side area, ncluding the front door, and V2 had damage to the hood, bumpe nd right fender. P1 of V2 complained of minor lower arm pai enicle 1 and vehicle 2 boin were slop at the red light on Cumberland St facing west at the intersection of St Paul St and th 490 on ramp. V1 was in the left most lane which is a left turn only ne. V2 was in the middle lane which is a straight on to the 490 amp only lane. V2 is a marked police car owned by the City of Rochester. D1 is a police officer and was on routine patrol, not in mergency operation mode, inside of marked police vehicle fleet #151391 (255). When the light turned green V1 did attempt to driv traight onto the on ramp from the turn only lane side swiping the NON DARK-ROAD PASSING OR LANE USAGE the state of the s 524 37274186 5/7/2018 11:38:00 PM DRY CLEAR WEST OVERTAKING REPORTABLE LIGHTED IMPROPERI Y scratches to the body of the vehicle from the mirror. V1 was scalables a the body in the investigation was found to be intoxicated.

VI was lowed to the pound as a result of the DWI arrest. There
were no cameras in the area or any witnesses as this occurred of
the expressway on ramp in the middle of the night. Tickets were YWA'S READING WIB ON ACCENIST OF WAS HEADING S ON STATE ST. THE DRIVER OF V1 SAID SHE WAS TRYING PROPERTY AILURE TO YIELD RIGHT OF D BEAT THE LIGHT BUT DID NOT MAKE IT THROUGH IN 525 37275951 5/9/2018 2:05:00 PM DAYLIGHT DRY CLEAR SOUTH OTHER DAMAGE WAY ME. V2. WHO HAD A GREEN LIGHT. DROVE THROUGH HAT INTERSECTION V1 WENT THROUGH AND HIT V1. V1 All ED TO VIELD FOR TRAFFIC LIGHT

11 stated that she was in the far left turn lane facing northbound of iniversity Ave. D1 stated that as she was in this tane she realized the needed to actually go straight across onto the Inner Loop nitrance. D1 stated that she thought that the lane to her right was une to go straight across E Main St. and because of this, she PASSING OR LANE USAGE NON tated she tried to merge to the left behind V2. This resulted in the OVERTAKING 37311435 NORTH 526 5/24/2018 3:23:00 PM DAYLIGHT DRY CLEAR REPORTABLE IMPROPERLY ollision because the middle lane is a left turn lane as well as a official to be a seried of the intersection. Did not not not the total through the intersection. Did not know that V ras going to be turn left with her instead of going straight. As D1 field to merge right, she struck V2 in the mid section of the bus on ne driver's side. There were no injuries observed or complained of. Both vehicles were driven from the scene followin 72 WAS TRAVELING WESTBOUND ON ALLEN STREET AND IZ WAS TRAVELING WESTBOUND ON ALLER STREET MITH THE MAKING A LEFT TURN ONTO STATE STREET WITH THE SREEN LIGHT WHEN IT WAS STRUCK BY VI WHICH WAS TRAVELING SOUTHBOUND ON STATE STREET. AILURE TO YIELD RIGHT OF PROPERTY 527 9:50:00 AM DAYLIGHT CLEAR SOUTH RIGHT ANGLE 37331746 5/25/2018 DRY DAMAGE WAY OPERATOR OF V1 STATED " I RAN THE RED LIGHT ND IT&apos:S MY FAULT&gupt. OPERATOR OF V2 OMPLAINED OF PAIN TO THE BACK BUT REFUSED Soft vehicles were traveling south on Clinton Ave. Vehicle 1 w tempted to change lanes and did not see vehicle 2 while enterin 37327981 CLEAR DRIVER INATTENTION SOUTH OVERTAKING 528 6/5/2018 2:02:00 PM DAYLIGHT DRY

DAMAGE

ne east lane. this caused vehicle 1 to hit the front passenger side

ehicle 2. This caused damage to the front passenger side of chicle 2 and damage to the rear driver side of vehicle 1. No

TE 213 (9/79) ROUTE NO. OR STREET NAME MONRO P.I.N.: NOT APPLICABLE CASE No ADJACENT ROADWAY NETWORK TOWN FILE: CITY AT INTERSECTION WITH/OR BETWEEN: BY: PSC VILLAGE OF ROCHESTER DATE: 5/13/2020 SEE MAP ENVIRONMENTAL TIME PERIOD FROM TO Roadway Surface Condition Daylight
 Daylight
 Dawn
 Dusk 1. Dry 2. Wet 3. Muddy 1. Clear 2. Cloudy 3. Rain se Codes from MV 104 (shown right) for these categories 8/1/14 7/31/19 4. Snow/lo 4. Snow 5. Sleet/Hail/Freezing Rain 5. Dark Road Unlighted 5. Slush 10. Other 6. Fog/Smog/Smoke lo. OF MONTHS 60 Jse Codes from MV 104 Police Report of VEHICLES DIRECTION DESCRIPTION REFERENCE OADWAY CRASH No CASE No DATE TIME APPARENT CONTRIBUTING FACTORS ed that while traveling towards the inter loop B2 was stbound on E Main St disregarding the DON&apos:T WALK assubunium in E. Mani Studisegaluming in et Dowagops, i MALE. Igin VI struck B2 throwing B2 off the bicycle, D1 stated that she lid not see B2 in the crosswalk. B2 stated that he thought he had me to cross but V1 was going to fast. B2 suffered minor injuries t AILURE TO YIELD RIGHT OF 37367933 8:14:00 AM INJURY DAYLIGHT NORTH 529 6/14/2018 DRY CLEAR OTHER is right shoulder and head. B2 was transported to RGH. V1 was ared by driver 1. No other injuries were reported on scene. B2 AVE APPROACHING CUMBERLAND ST. DRIVER 1 STATED SHE THOUGHT THE LIGHT WAS STILL GREEN BUT THEN REALIZED IT WAS RED WHEN SHE WENT THROUGH. REALIZED IT WAS RED WHEN SHE WENT I THROUGH.

DRIVER I FALLED TO SEE DRIVER 2 (GORDON) COMING
WEST BOUND ON CUMBERLAND ST. DRIVER 1 STRUCK
VEHICLE 2 IN THE FRONT DRIVER SIDE PORTION OF THE PROPERTY RAFFIC CONTROL DEVICE: 530 37340089 6/16/2018 2:09:00 PM DAYLIGHT DRY CLEAR NORTH RIGHT ANGLE VEHICLE, VEHICLE 1 SUSTAINED HEAVY DAMAGE TO THE RONT PASSENGER SIDE DOOR AREA. THERE WERE NO NUMBER AND NO MATHERSE PROPERTY AND A CONTROLL FROM THE REST OF TH IDN-8208, was also stopped at the same traffic light in the right Dre-gove, was also supper at a legal as a learner aller, and in the light ne, walling to make a left onto N. Clinton Ave. Once the light med green both vehicles began to turn left. At some point duri e turn Veh #1 and Veh #2 made contact. Veh #1 sustained ve LEFT TURN PROPERTY 531 37354648 6/26/2018 1-49-00 PM DAYLIGHT DRY CLEAR LINKNOWN NORTH inor scrapes to the right side of the trailer while Veh #2 suffered oken driver's side mirror. There were conflicting stories is Op #1 stated he did not know where Veh #2 came from er he maintained his lane throughout the turn. While Op #2 tated she maintained her lane as well. No injuries reported and eh 2 was tacing south on Union St and, stopped at a red light at niversity waiting to make a right turn. When the light turned gree eh 2 started his turn. Veh 1 disregarded the red light and en 2 saineu ins auf ... Ven't uissegueur eit et eu gint an u ontinued west bound on university into the intersection at union driking veh 2 causing damage to both vehs. i was sitting at the ntersection on union facing north at university and witnessed PROPERTY FAILURE TO YIELD RIGHT OF 532 37354659 6/27/2018 4:18:00 PM 2 DAYLIGHT WFT RAIN WEST RIGHT ANGLE DAMAGE ove. I could not see veh 2 green light but i could see vehs PROPERTY RAFFIC CONTROL DEVICES 533 37392854 7/4/2018 10:55:00 AM 2 DAMAGE ANI DAYLIGHT DRY CLEAR WEST RIGHT ANGLE DISREGARDED INJURY iversity traveling EB just ahead of V1 stopped at the light (facing red light) at E Main and University. V1 did not stop in time at the aht and collided with the back of V2 causing damage to the front of PROPERTY in and the rear of V2. Driver 2 stated he was stopped at the light nd V1 collided with him. Driver 1 stated that V2 attempted to witch lanes in front of her causing her to collide with the rear of V. 534 37382421 7/11/2018 7:45:00 AM 2 DAYLIGHT DRY CLEAR DRIVER INATTENTION EAST REAR END DAMAGE Both drivers were uninjured. V1 was towed by 454 to their garage hicle 3 was facing southbound on state street in a left turn only remute s was staing soundbould on took seem in a few in unit of my ane altempting to turn eastbound onto the innerloop. Vehicle 1 was lirectly behind vehicle 3. Vehicle 2 was southbound in lane 1 of State street traffic approaching the intersection of Allen st. An ininvolved truck the began making a wide right turn to head from len st to northbound state street and began taking up most of the PROPERTY 535 37386907 7/18/2018 8:14:00 AM DAYLIGHT DRY CLEAR DRIVER INATTENTION SOUTH OTHER oad. Vehicle 3 tried to create more room for the truck to turn and DAMAGE uodo. Venicle 3 rieu o Lazen inter ovin in the tub. o un'i an u venicle 1 driver states he was trying to do the same and he finen changed lanes to enter lane 1 of southbound State st but did not see vehicle 2 in that lane. Vehicle 1 then made slight contact with vehicle 2 on the driver side front fender which caused vehicle 1 to nunce into vehicle 3. No injuries. Vehicles were cared for by PROPERT UNKNOWN REAR END 536 37412909 7/18/2018 4:00:00 PM 2 DAYLIGHT DRY CLEAR WEST DAMAGE 1) WAS IN THE LEFT (STRAIGHT ARROW) LANE ON UMBERLAND ST TRAVELING W/B. (V2) WAS IN THE RIGH STRAIGHT ARROW) LANE ALSO TRAVELING WIS ON CUMBERLAND. AS BOTH VEHICLES PASSED THROUGH THE INTERSECTION AT N CLINTON THEY DID MAKE PASSING OR LANE USAGE CONTACT, THE RIGHT FRONT WHEEL LUGS FROM (V1) DII NON 537 37400211 7/19/2018 1:13:00 PM 2 DAYLIGHT DRY CLEAR WEST OVERTAKING REPORTABLI IMPROPERLY CAUSE DAMAGE TO THE DRIVERS DOOR OF (V2), BOTH RIVERS CLAIM TO HAVE MAINTAINED THEIR PROPER ANE. (WI) PROVIDED HIS INFORMATION TO (DI) BUT EFT PRIOR TO MY ARRIVAL. (D2) NOTED THAT THE MTNESS APPROACHED (D1) ABOUT 30 MINUTES AFTER HE ACCIDENT, A CALL TO (W1) WAS NOT ANSWERED. HROUGH THE INTERSECTION AT ALLEN ST AND HAD A PROPERTY AILURE TO YIELD RIGHT OF REEN TRAFFIC LIGHT. V1 WAS HEADING W/B ON ALLEN 2 WEST 538 37411741 7:24:00 PM DAYLIGHT DRY CLEAR RIGHT ANGLE 7/22/2018 AMAGE AND T. DRIVER OF V1 SAID HE WENT THROUGH RED LIGHT INJURY INKING HE COULD MAKE IT THROUGH BUT V2 WAS PROACHING AT THE SAME JUME HE BANDINTOS ST. THE OPERATOR OF V2 STATED THAT HE WAS GOING TRAIGHT WHEN V1 SIDE SWIPED HIS VEHICLE. V2
TATED THAT V1 FLED THE SCENE BUT HE WAS ABLE TO

2

DAMAGE

4:00:00 PM

DAYLIGHT

WET

RAIN

IMPROPERLY

539

37413640

7/23/2018

ET HIS LICENSE PLATE NUMBER. PICTURES WERE

CAMERA'S IN THE AREA. I PUT A JOB IN FOR COUNTY DEPUTY'S TO CHECK THE RO OF VINDRESS TO LOCATED THE VEHICLE INVOLVED IN THE

TAKEN ON SCENE OF THE DAMAGE. NO CITY OR PRIVATE

SOUTH

OVERTAKING

TE	213	(9/79)		

TE 213 (9/79)													
COUNTY:	MONROE		PIN	NOT APPLICAL	BI F	ROUTE NO. OF					CASE No.:		
	TOWN					ADJACENT RO					FILE	PSC FM/2000	
	CITY	DOGUECTED				AT INTERSECT	TION WITH/OR	BETWEEN:			BY	PSC 5/13/2020	-
	VILLAGE OF	ROCHESTER			•	SEE MAP					DATE	5/13/2020	
TIME PERIOD		FROM: 8/1/14	TO: 7/31/19	ENVIRONMEN Use Codes from at right) for these	MV 104 (shown e categories	Light Conditions: 1. Daylight 2. Dawn 3. Dusk 4. Dark Road Lig 5. Dark Road Ur		Roadway Surfact 1. Dry 2. Wet 3. Muddy 4. Snow/Ice 5. Slush	ce Condition: Weather: 1. Clear 2. Cloudy 3. Rain 4. Snow 5. SleeVHalWFre	ezing Rain			
						1		10. Other	6. Fog/Smog/Sr 10. Other		1		
No. OF MONTH	IS:	(50	TES		10				DIDECTION		MV 104 Police Report	REFERENCE
CRASH No.	CASE No.	DATE	TIME	No. of VEHICLES	SEVERITY	LIGHT	ROADWAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING FACTORS	DIRECTION	TYPE ¹	DESCRIPTION Cit tile above dates littles location, rifesportided for a report of all	MARKER
540	37408111	7/27/2018	9:08:00 PM	2	PROPERTY DAMAGE	DARK-ROAD LIGHTED	DRY	CLEAR	FOLLOWING TOO CLOSELY	EAST	REAR END	MVA. The driver of VZ said hat she was traveling eb on E Main St. VI was traveling behind het, traveling in he same direction. As VZ proceeded brough the green light, VI altempted to make a elst run onto Union St, but was bo close to VZ. VI rear ended VZ, on the rear driver side of the vehicle. VI continued rib on Union St. The driver and passenger of VZ was not injured. There is rear driver side bumper demage on VZ. Driver exchange given to	
541	37411711	7/29/2018	1:45:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	FAILURE TO YIELD RIGHT OF WAY	NORTH	RIGHT ANGLE	THAVELING WIS ON A PLYMOUTH AVE VZ WAS TRAVELING WIS ON ALLEN ST. BOTH V&APDES WERE APPROACHING THE INTERSECTION OF ALLEN ST AND N PLYMOUTH AVE. MOREVER, BOTH DRIVERS OF VARPOS. SADI THEY HAD A GREEN LIGHT. BOTH V&APDOS. CONTINUED TO TRAVEL AND RAN INTO EACH OTHER. THERE WERE NO CAMERAS OR WITNESSES TO VERIFY EITHER STOW.	
542	37421262	8/4/2018	12:01:00 AM	2	NON- REPORTABLE	DARK-ROAD LIGHTED	DRY	CLEAR	FOLLOWING TOO CLOSELY	WEST	REAR END	V-2 stopped at red light is struck in rear bumper area by V-1, both vehicles traveling west on Cumberland street.	
543	37466414	8/8/2018	8:44:00 PM	2	PROPERTY DAMAGE	DARK-ROAD LIGHTED	DRY	CLEAR	BACKING UNSAFELY	WEST	RIGHT ANGLE	V/1 WAS BACKING OUT OF A PARKING SPOT AND V/2 WAS DRIMING STRAIGHT. V/1 THEN BACKED INTO THE SIDE OF	
544	37425032	8/10/2018	8:03:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	PASSING OR LANE USAGE IMPROPERLY	NORTH-EAST	OVERTAKING	Viz. No NURIES OR COMPLANTS OF PAN. On 81078 at Janobromahely 08181s in responded to the area of SI. Paul S1 and Central Ave for the report of a MVA. When I arrived on sone I spoke to Bown who was the driver of vehicle 1. He says that he was coiling the oftening of the inner bop and making a left hand Lum onto S1 Paul S1. He says that he was in the lane Linest with cits a left turn only lane. Bowner says that there was an RTS bus in the lane next to him also turning left onto S1 Paul S1. During the Lum, the whicles subbed up against each other bending the front push bar of vehicle in Toward. Hens spoke to Powell who was the officer of vehicle 2 which is an RTS bus. She said that the was making a left hand turn onto S1 Paul from the inner loop and that during the turn the bus and vehicle 1 tubbed up against each other. She was burning from a lane halfs used for both left turns and going straight onto Cumberland S1. There was no damage to he bus Stelling the was interested and there were non passesoners.	
545	37441935	8/10/2018	6:07:00 PM	3	PROPERTY DAMAGE	DAYLIGHT	DRY	CLOUDY	DRIVER INATTENTION	NORTH	OTHER		
546	37432402	8/10/2018	7:35:00 PM	2	PROPERTY DAMAGE AND INJURY	DAYLIGHT	DRY	CLEAR	PASSING OR LANE USAGE MPROPERLY	NORTH-EAST	RIGHT TURN (AGAINST OTHER CAR)	A was a reward you or used to a count as the count of the way of used with A. Orlived T needed to make a right turn form the right lane and quickly changed lanes, not observing VZ. VZ was traveling N/B in the right hand lane and was struck by VI. There was damage to the bear intigit of VI including a fast front right for and damage to the bumper and headlights. There were heavy dents on VZ on the bumper and headlights. There were heavy dents on VZ on the other left where VI struck VZ and there were scraathes along the driverdagoss is side of the vehicle. The driver of VZ complained of some shoulder pain but declined medical attention. No other injuries. Driver VZ was besued tickes for unlicerseed operation. Both	
547	37429104	8/11/2018	10:56:00 PM	2	PROPERTY DAMAGE AND INJURY	DARK-ROAD LIGHTED	DRY	CLEAR	ALCOHOL INVOLVEMENT	WEST	REAR END	VI was faveling WIB on Cumberland St approaching St Paul St and V2 was stopped at the red line facing WIB on Cumberland St 2-3 car lengths back from St Paul St. V1 did not stop shiking the back of V2. Moderate damage to both vehicle. Only a complaint of pain from occupants in V2 no injuries reported in V1. Both	
548	37429038 37436190	8/12/2018	3:45:00 PM 7:00:00 PM	2	PROPERTY DAMAGE AND NJURY PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	TRAFFIC CONTROL DEWCES DISREGARDED TRAFFIC CONTROL DEWCES DISREGARDED	WEST NORTH	RIGHT ANGLE	SWENGER SHOULD THE SCRIPE. WHAS HEADING WE ON E MAIN ST. V.2 WAS HEADING NB ON LINNERSITY AVE. V.2 WAS N THE INTERSECTION AND ON LINNERSITY AVE. V.2 WAS N THE INTERSECTION AND THEN Y LENTERSECTION ACHING VID TO STRIKE V.2 V.2 THEN CAME TO REST PARTIALLY OFF THE ROAD FACING SB. N. THE NB LANE. AND HIT A STREET SIGN. THE DRIVER OF V.2 STATED THAT SHE HAD THE GREEN LIGHT AND THE PASSENGER OF V.2 STATED THAT VISEMED TO BE COMING REALLY PAST. THE DRIVER OF VI STATED SHE HAD THE GREEN LIGHT AND THAT V.2 WAS TRAVELING AT ABUADADOT THAT V.2 WAS TRAVELING AT ABUADADOT TO MEN A SHENDER OF V.2 STATED THAT V.2 WAS COMOT HANDLOT HAD THE V.2 FLY OFF THE ROAD INTO THE STREET SIGN. W.2 STATED THAT V.2 WAS COMOT HANDLOT HAD THEN V.2 FLY OFF THE ROAD INTO THE STREET SIGN. W.2 STATED THAT V.2 WAS GONOT HANDLOT HAD THEN V.2 FLY OFF THE ROAD INTO THE STREET SIGN. W.2 STATED THAT V.2 WAS GONOT THROUGH THE GREEN LIGHT AND V.2 RAN THE RED LIGHT. THERE ARE NO CAMERAS AT THE INTERSECTION. THE PASSENGER OF VITAM COMPLANS ON PAIN BUT NO VESILE INJURIES. THE DRIVER OF V.2 HAD GENERAL COMPLANTS OF PAIN AND NO VISIBLE NUMBES. THE DRIVER OF V.2 HAD GENERAL COMPLANTS OF PAIN AND NO VISIBLE NUMBES. THE DRIVEN OF V.2 HAD GENERAL COMPLANTS OF PAIN AND NO VISIBLE NUMBES. THE DRIVEN OF V.2 HAD GENERAL COMPLANTS OF PAIN AND NO VISIBLE NUMBES. THE PROVIDED ON SCENE WITNESS TIELTON, SERENA & BI GREEN LLOVER OR HENRETTAN VI 14467 S854157045 -	
					DAININGE				DISTEGRADED	1		APPROACHING THE INTERSECTION OF E MAIN ST. WHILE	
550	37479217	8/12/2018	7:20:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	DRIVER INATTENTION	NORTH	REAR END	APPROACHING THE INTERSECTION THE TRAFFIC SIGNAL CHANGED FROM GREEN TO YELLOW AT THAT TIME VZ BEGAN TO SLOWDOWN AND ATTEMPT TO COME TO A STOP. VI CONTINUED ON AND FALED TO SLOW IN TIME TO STOP AND REAR ENDED VZ THIS COLLISION CAUSED DAMAGE TO THE REAR OF VZ AND THE FRONT END OF VI. NO NUMBERS WERE OBSERVED OR REPORTED BY VI. NO NUMBERS WERE OBSERVED OR REPORTED BY	

TE 213 (9/79) ROUTE NO. OR STREET NAME MONRO P.I.N.: NOT APPLICABLE CASE No ADJACENT ROADWAY NETWORK TOWN FILE: CITY AT INTERSECTION WITH/OR BETWEEN: BY: PSC VILLAGE OF ROCHESTER DATE: 5/13/2020 SEE MAP TIME PERIOD FROM TO ENVIRONMENTAL Roadway Surface Condition Daylight
 Daylight
 Dawn
 Dusk 1. Dry 2. Wet 3. Muddy 1. Clear 2. Cloudy 3. Rain se Codes from MV 104 (shown right) for these categories 8/1/14 7/31/19 4. Snow/lo 4. Snow 5. Dark Road Unlighted 5. Slush 5. Sleel/Hail/Freezing Rain 10. Other 6. Fog/Smog/Smoke lo. OF MONTHS 60 Ise Codes from MV 104 Police Report of VEHICLES DIRECTION DESCRIPTION REFERENCE OADWAY CRASH No CASE No DATE TIME APPARENT CONTRIBUTING FACTORS umberland St waiting for the light to turn green. Driver of vehicl 1 further states that when the light turned green she started to turn nd vehicle 2 struck her. Driver of vehicle 1 also told me that she and ventue 2 study and . Drived to ventue 1 also un the trist size recorded video of the scene right after the accident occurred. Driver of vehicle 1 showed me the video. The video shows vehic 2 in its lane of travel and shows vehicle 1 east of vehicle 2 and acing east. It did not show her in the turning lane nor did it show ner car facing north to turn. Driver of vehicle 1 gave told me thre different stories of how the accident happened each time I asked her what happened. Driver of vehicle 1 also stated that her back nurt but refused medical treatment by the ambulance. Driver of PROPERTY PASSING OR LANE USAGE AMAGE AN INJURY 37446771 CLOUDY EAST OVERTAKING ehicle was also on my body worn camera walking around as if othing burt her, and then all of a sudden falling to the ground. ning that her back burt. She was offered medical atte screaming that ner back nurt. She was othered medical attention again, and again refused. Driver of vehicle 1 stated that she woul drive herself to Strong Memorial Hospital. Driver of vehicle 2 stat that she was stopped on Cumberland St at the red light at St Paul St. Driver of vehicle 2 further stated that she was in the middle ane of travel. When the light turned green driver of vehicle 1 started to turn left, at which time vehicle 1 drove straight, and struc top light on Cumberland St and N. Clinton Av PROPERTY 552 37461324 8/15/2018 9:29:00 PM DAYLIGHT DRY CLEAR DRIVER INATTENTION EAST REAR END trear ended him. V-1 left scene, unable in locate unberland Stor an MVA. Officer Kevin Jakes was driving his narked patrol vehicle P47 (fleet number 161323) westbound on Cumberland St. As Ofc Jakes approached the intersection of St Paul St he was passing through a green light to continue estbound onto the inner loop ramp. Vehicle 2 was traveling outhbound on St Paul. Vehicle 2 traveled through the solid red PROPERTY RAFFIC CONTROL DEVICES ight at the corner of St Paul and Cumberland. Vehicle 2 entered the intersection in front of Vehicle 1, causing Vehicle 1 to strike it or 553 37437711 8/16/2018 5:36:00 AM DAYLIGHT DRY CLEAR WEST RIGHT ANGLE ne driver's side door. Ofc Jakes and Driver 2 were not iured. Sat Pitts responded to the scene. Technician Mueller too notos and completed a technician&anos s report. The marked P47 car was towed by 452 to 945 Mt Read Blvd. Ofc Gulla completed a tow report. Ofc Nettnin issued Driver 2 2 T&anos:s. 1 licket was for passing through a solid re was stopped in traffic on E Main St. just west of N Ur PROPERTY ersection, V1 was traveling eastbound on E Main St. behind V2 554 37446818 8/17/2018 7:31:00 PM 2 DAYLIGHT DRY CLEAR FOLLOWING TOO CLOSELY FAST REAR END DAMAGE 1 rear ended and struck V2. No one was inju WNED/OPERATED BY THE ROCHESTER POLICE DEPARTMENT WHILE RESPONDING TO AN EMERGENCY DEPARTMENT WILLE RESPONDING TO AN EMERCENCY ZWAS BEING OPERATED BY SGT ALLIET. THE FLEET NUMBER FOR V2 IS 162575. VI WAS A BICYCLE BEING OPERATED BY WASHINGTON WHO WAS FLEENG AFTER SHOOTING AT A GROUP OF PEOPLE. WHEN V2 LOCATED PEDESTRIAN'S NON 555 37476898 8/22/2018 6:19:00 PM DAYLIGHT DRY CLEAR NORTH-EAST OTHER /1 V1 WAS TRAVELING FRON THE SIDEWALK ALONG REPORTABLI FRROR/CONFUSION UMBERLAND AVOIDING POLICE VZ WAS TRAVELING WB N CUMBERLAND. V2 PULLED UP ON THE SIDEWALK OF UMBERLAND TO TRY TO GET VI TO STOP. V1 ATTEMPTED TO MAKE A LEFT HAND TURN IN THE GAP BETWEEN V2 AND A FENCE. DURING THE TURN THE ACK TIRE OF V1 HIT THE FRONT RUMPER OF V2 AUSING THE OPERATOR OF V1 TO FALL OFF THE In above date and time, I responded to the area of main st and of above date and mile, irresponded to the after on milan scalin indiversity ave for a miva. Upon arrival, I spoke to Paul Chapman who was the driver of the bus. Chapman said he was on the off amp at the interloop, where the lanes start to turn into the 3 lanes of travel. His bus was stopped in traffic. Chapman says the of tavel. It is bus was stopped in taillie. Chapman says the vehicle behind find matempled to gel in the fair left lane, going around his bus. When the car attempted to get over, there was re enough room, and the vehicle struck the back of the bus. I spoke with the driver of the involved vehicle, Jessica Thome. Thora agrees with what Chapman said, she hought there was enough PROPERTY 556 37456517 8/23/2018 8:18:00 AM DAYLIGHT DRY CLEAR PASSING TOO CLOSELY SOUTH REAR END DAMAGE om and get into the lane. While trying to get into the lane, did strike the bus with her right passenger side of the vehicle. No 72 WAS TRAVELING NB ON NORTH ST. V1 WAS TRAVELING SB ON NORTH ST. V1 WENT TO MAKE A LEFT HAND TURN ONTO DELEVAN ST CAUSING VI TO STRIKE V2. THE DRIVER OF V2 FELL OFF THE MOTORCYCLE. VI WAS LAS' SEEN LEAVING THE SCENE EB ON DELEVAN ST. V2 CAME O REST ON ITS RIGHT SIDE FACING SW. WITNESSES STATED THE DRIVER HAD BLOOD COMING FROM HIS IOSE. THE DRIVER OF V2 WAS TRANSPORTED TO STRONG MEMORIAL HOSPITAL VIA AMR RIG #7369. AT THI TIME OF THIS REPORT THE DRIVER IS IN CRITICAL ONDITION. SEE DEPOS FOR WITNESS ACCOUNTS LEFT TURN PROPERTY FAILURE TO YIELD RIGHT OF AMERAS WERE CHECKED IN THE AREA WITH NEGATIVE 557 37467012 8/24/2018 8:16:00 PM AMAGE AND DRY CLEAR EAST (AGAINST LIGHTED RESULTS, V1 WAS NOT LOCATED IN THE AREA INJURY OTHER CAR) RESULTS, VI WAS NOT LOCATED IN THE AREA. WITNESS I KING, MAHOGANY 33 BROOKLYN ST
ROCHESTER NY 14613 5852822385 - WITNESS 2 NELSON,
TYASIA 319 CURLEWST ROCHESTER NY 14613 585642713
WITNESS 3 DORSEY, ADRIANA 6 SUPERIOR ST

ROCHESTER NY 14611 5853613203 - WITNESS A REEZES, SHYASIA 33 BROOKLIVI ST ROCHESTER NY 14613 865010007 - WITNESS S HENDERSON, JAYONE 71 DEPEW ST ROCHESTER NY 14611 - WITNESS A GROMSON, AHJANAVE 33 BROOKLIVI ST ROCHESTER NY 14613 -WITNESS 7 JORDAN, ANGUNDIETTE 628 AFFINITY LANE ROCHESTER NY 14616 586532142 - WITNESS B

TE 213 (9/79)						DOUTE NO. 22	O CTDEET NO.	ır.						
	MONROE		P.I.N.:	NOT APPLICA	BLE	ROUTE NO. OF ADJACENT RO	R STREET NAM				CASE No.			
	TOWN CITY					AT INTERSECT					FILE: BY: PSC DATE: 5/13/2020			
	VILLAGE OF	ROCHESTER	!		=	SEE MAP					DATE	5/13/2020	-	
TIME PERIOD		FROM: 8/1/14	TO: 7/31/19	ENVIRONMEN Use Codes from at right) for these	n MV 104 (shown e categories	Light Conditions: 1. Daylight 2. Dawn 3. Dusk 4. Dark Road Light 5. Dark Road Ur	ghted	Roadway Surfact 1. Dry 2. Wet 3. Muddy 4. Snow/Ice 5. Slush 10. Other	ce Condition: Weather: 1. Clear 2. Cloudy 3. Rain 4. Snow 5. SleeVHall/Fre 6. Fog/Smog/Sn 10. Other					
No. OF MONTH	IS:		60	ES					TO. Other		¹ Use Codes from	MV 104 Police Report		
CRASH No.	CASE No.	DATE	TIME	No. of VEHICLES	SEVERITY	CONDITIONS	ROADWAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING FACTORS	DIRECTION	TYPE ¹	DESCRIPTION	REFERENCE MARKER	
558	37693309	8/24/2018	11:37:00 PM	2	PROPERTY DAMAGE AND	DARK-ROAD LIGHTED	DRY	CLEAR	FAILURE TO YIELD RIGHT OF WAY	NORTH	RIGHT ANGLE			
559	37464903	8/28/2018	5:47:00 PM	2	PROPERTY DAMAGE AND INJURY	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	NORTH	REAR END	On the above date and time Officers responded to the area of Joseph Ave and Cumberland St. for the report of a motor vehicle accident. Upon arrival I spoke with driver 2. Driver 2 stated he was stopped at the intersection facing northbound on Joseph are when vehicle I rear ended him. Driver 2 stated he had surgery on his back a year ago and is in pain and vould like to be transported to the hospital to be checked out. Male was transported via AMR to RGH. Vehicle 2 was handed off to a friend of driver 2s. Driver of vehicle 1 stated he was rushing and vehicle 2 stopped quickly causing him to stifle the other vehicle. Passenger of vehicle 1 was checked out due to being pregnant but was determined to be labor and was not transported to a medical facility. The traffic lights		
560	37475312	8/31/2018	8:39:00 PM	2	PROPERTY DAMAGE	DARK-ROAD LIGHTED	DRY	CLOUDY	TRAFFIC CONTROL DEVICES DISREGARDED	WEST	OVERTAKING	at he intersection were out and not operational at he time of the Univer of vertice in was trader to give assument recleases because the total leave before Police arrived on scene. Driver of vehicle 1 did exchange in the with offer of vehicle 2 Divier of vehicle 2 stelled he was in the middle lane of ravel on Cumberland St, traveling west, through the intersection of ST Paul St when he was struck by which 1. Driver of vehicle 2 further stated that which I was in the jett furn only lane and went straight included of turning left. causing		
561	37460154	9/2/2018	8:20:00 PM	2	PROPERTY DAMAGE AND INJURY	DARK-ROAD LIGHTED	DRY	CLEAR	OTHER (VEHICLE)	WEST	RIGHT ANGLE	he accident Diver of It was taveling wesbound on E Main Street. Driver #2 was taveling northbound through the E Main St Intersection to get out to the Inner Loop. Driver #1 ran the cell gith at the intersocial and said that her flip to he options stack underneath the gas podd as other couldn's appost move the foot to treat. This resulted in damage to the front end of Vehicle #1 and to the passenger side of Vehicle #2. Both vehicles were towed by 452. A clation was sessed to Driver #1. A passenger in Vehicle #2, who said she has chronic pain issues, was transported to Strong for the complain of minor pain. Photos were taken by Colfice I seen.		
562	37490323	9/4/2018	3:39:00 PM	2	PROPERTY DAMAGE AND INJURY	DAYLIGHT	DRY	CLEAR	FALURE TO YIELD RIGHT OF WAY	SOUTH	LEFT TURN (AGAINST OTHER CAR)	v. was in the extension the rave laters or norm rution is approaching University Ave. It was reveiling SH6 not N Union SI approaching University Ave. Do States that he had a solid green light and attempted to burnled not but Invessity Ave. causing VI buske V.D. 20 was taken to strong by AMR for a large laccration on his right arm. D1 was taken be RGH for the complaint of arm and head pain from the air bag. Both vehicles bowed by 425 to the		
563	37477449	9/10/2018	3:27:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	WET	RAIN	FALURE TO YIELD RIGHT OF WAY	WEST	OTHER	The drive or UZ stated that she was traveling north bound on University, Ave passing through E. Main St.D. get on the inner loop. While doing so simultaneously IV was traveling west bound. This resulted in the font of V1 colliding with the rear passengers side of V2. The driver of V2 did not report any largy. V2 did obtain damage. OKE. Eichas was stopped in south bound raftle on he men foop when he observed what he essenthed as a normal flow of taffic heading north bound because hey had the right of way. He hen disserved V1 traveling west bound on E. Main St.V1 hen skidded into V2. The said collision occurred. The driver of V1 stated than he was traveling west bound on E. Main St and was paying attention. He did attempt to brase his visible but could not do so in a firely manner. the said collision occurred. The driver of to complete driver Bair had read from scene. V1 was shared.		
564	37491147	9/20/2018	12:14:00 PM	1	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	ALCOHOL INVOLVEMENT	SOUTH	OTHER	In MPAITIR around 122 links, Inesponded to the intersection of Worth Clinton Avenue and Cumberland SL for the report of a male overdosing who crashed into a pole. Upon arrival, AMR and Frie were already on scene. The above fished vehicle, 14/52873, was cashed in the fully pole, near the quarted, and North Clinton Avenue at Cumberland SL The vehicle was facing south. The device, Anthropy, Johnson, was still located in the driver-apposs; seat, Asl approached the car, Inoticed a small clear plastic bagy with lettower residue of a substance appearing to be heroin on the foor of the car to the left of the driver-apposs seat. AMR shaled that when they arrived, Johnson was awake and did not receive macran. Towerer, It was appearent that he had overdosed theroin in Nisman. Johnson also admitted that he had injected heroin in Nisman. Johnson also admitted that he had injected heroin in Nisman. Johnson also admitted that he had injected heroin in Nisman. Johnson also admitted that he had injected heroin in Nisman. Johnson also admitted that he had injected heroin in Nisman. Johnson and admitted that he had injected heroin in Nisman. Johnson and admitted that he had injected heroin in Nisman. Johnson and admitted that he had injected heroin in Nisman. Johnson and admitted that he had injected heroin in Nisman. Johnson and admitted that he had injected heroin in Nisman. Johnson was supplied to the carried on scene and had Johnson perform a prescreen. At 1249 hrs, Officers Milispaugh and Dibisceglie botk cusloyd of Johnson Nisman in Nisman and the Nisman and was stoped in the readway for a few minutes. When a car honked at him, he started driving south and hen It he utility pole. The car was locked and the driver was sharing, so an unknown male used he mamme to break pole in the arman and mention unknown male was the mamme to break open the back passenger side vindow. An unknown female unfocked the arman and mention unknown male was th		

ROUTE NO. OR STREET NAME MONRO P.I.N.: NOT APPLICABLE CASE No ADJACENT ROADWAY NETWORK TOWN FILE: CITY AT INTERSECTION WITH/OR BETWEEN: BY: PSC VILLAGE OF ROCHESTER DATE: 5/13/2020 SEE MAP NVIRONMENTAL TIME PERIOD FROM TO 1. Dry 2. Wet 3. Muddy 1. Clear 2. Cloudy 3. Rain se Codes from MV 104 (shown right) for these categories 1. Daylight 8/1/14 7/31/19 4. Snow/lo 4. Snow 5. Dark Road Unlighted 5. Slush 5. Sleel/Hail/Freezing Rain 10. Other 6. Fog/Smog/Smoke lo. OF MONTHS 60 Jse Codes from MV 104 Police Report of VEHICLES GHT DIRECTION DESCRIPTION REFERENCE SOADWAY SURFACE CONDITION CASE No CRASH No DATE TIME APPARENT CONTRIBUTING FACTORS 9/20/18 at approximately 1225 nrs (Ave and Cumberland St for a 2 car MVA. When I arrived onscel we and cumulations at the 2 can wive, when rainived unsen found vehicle 1 and vehicle 2 Ch N Clinton Ave facing Southbound at Cumberland St. I spoke to the driver of vehicle 2 who says that she was stopped at a red light heading Southboun at this intersection when she was rear ended by vehicle 1. The driver of vehicle 1 had already been transported to RGH by an nknown ambulance, but the R/O of vehicle 1 was with the vehic te said he was not, you like NO or value. If was will see value to said he was not there when the accident happened, but that I on Jaime R Rivera, 7/20/87 had been the driver. The airbags h gone off in vehicle 1 and the R/O called a tow truck to take it to a PROPERTY 12:25:00 PM 565 37501921 9/20/2018 DAYLIGHT DRY CLEAR DRIVER INATTENTION SOUTH REAR END INJURY arage. I then went to RGH to speak with the driver of vehicle 1. le says that he had just made a left turn from Central Ave onto N te says mat he had usen hade a tention from Central avec min Clinton Ave. He says that he was looking off to his right at an Inrelated accident that had happened about 50 feet away and w tot walching what was in front of him. When he turned his head ack he was about to rear end vehicle 2 and did not have time to top. He went to RGH to get looked at with a complaint of head. eft turn only lane at the intersection of main st. Vehicle 2 was in surb lane of University ave facing southbound next to Vehicle 1 in activities of virtual years acting sometimes of vertices in straight or left turn lane and vehicle 2 started to head eastbound or Main st. Driver of vehicle 1 staled he wanted to enter the lane vehicle 2 was in but did not realize vehicle 2 was there as he PROPERTY AILURE TO YIELD RIGHT OF 37501961 9/24/2018 7:39:00 AM DAYLIGHT DRY CLEAR SOUTH-EAST OVERTAKING wanted to head south on university. As vehicle 1 started to change nes, he did make contact with vehicle 2 driver side rear fender vith vehicle 1&anos s passenger side front humper, no injuries MAIN ST FOR THE DELAYED REPORT OF A HIT AND RUN NVOLVING A CITY STREET SWEEPER, ONCE THERE I INVOLVING A CHITSTREET SWEEPER. OWCE THERE IS SPOKE WITH DZ, MARISA STORKE. DZ STATES THAT SHE WAS AT THE INTERSECTION OF UNIVERSITY AVE AND E MAIN ST IN THE LEFT LANE FACING NB. SHE STATES THAT VI, A CITY STREET SWEEPER APPROACHED FROM BEHIND HER AND TO HER RIGHT IN THE RIGHT LANE. AS DEFINITION THE MIST OF THE MOST OF THE MOST OF MEMORY. AS IT PASSED DO STATES SHE FELT HER VEHICLE MOVE. AT IT IT IT IS THE SHE WAS UNSURE WHETHER OR NOT THE WEHICLE HAD HIT HER, AND SHE OBTAINED THE LICENSE PLATE FOR VI. SHE LATER NOTICED THE DAMAGE AND PROPERTY 567 37719390 9/27/2018 11:30:00 AM DAYLIGHT DRY CLEAR FOLLOWING TOO CLOSELY NORTH OVERTAKING DAMAGE CONTACTED US FOR THIS REPORT. I CHECKED THE AREA FOR CAMERAS, I DID NOT OBSERVE ANY CAMERAS THAT MAY HAVE CAPTURED THE INCIDENT, LATTEMPTED TO CONTACT SPECIAL SERVICES TO SEE IF AN ACCIDEN OR ANY DAMAGE TO THEIR FLEET VEHICLE HAD BEEN REPORTED. I WAS UNABLE TO REACH ANY INDIVIDUAL HATE WOULD BE ARLE TO TELL ME SAID IN FORMATION eh 2 was sitting in the shoulder parked occupied by the driver. eh 1 struck the rear left quarter panel of veh 2 and then continue take off from the scene. No plate information was received from PROPERTY DARK-ROAF PASSING OR LANE USAGE ance on non-nice scene. No pine insumation was received in e witherses or the occupant of veh 2. No injuries reported on ene, medical refused. No cameras in the area that would havate information or caught the accident on camera. - WITNES 568 37522920 9/30/2018 12:08:00 AM DRY CLEAR FAST OVERTAKING DAMAGE LIGHTED IMPROPERLY GRANT, RACHEL 126 DEERHURST LANE APT 16 WEBSTE Y WAS TRAVELING S/B ON N CLINTON AVE. THE DRIVE OF V1 STATED THERE WAS A CAR BEHIND V1 THAT WAS OLLOWING TOO CLOSELY AND TO AVOID THAT VEHICLE PASSING OR LANE USAGE PROPERTY 569 37516633 10/3/2018 7:10:00 PM DAYLIGHT DRY CLEAR SOUTH OTHER AT DEICIDED TO DRIVE OFF THE ROAD WAY AND DAMAGE IMPROPERLY CCIDENTALLY RAN INTO A FIRE HYDRANT. PHOTOS OF IRE HYDRANT WERE TAKEN AND WATER AUTHORITY NOTIFIED. VT Was With exiting the erb tane or the inner Loop onto E. Main St. The Bicyclist was wib on E. Main St. The Bicyclist stated he was ossing in front of the slopped traffic exiting the Inner Loop when NON-DARK-ROAL AILURE TO YIELD RIGHT OF e was struck by V1. The Bicyclist stated that the car did not stop 570 37549894 10/3/2018 7:19:00 PM WET SNOW SOUTH OTHER EPORTABL LIGHTED WAY ter striking him. The collision caused the Bicyclist to fall to the ound. He had a small scrap to his right knee however refused edical treatment. V1 was described as a green Pontiac however. rise upable to be located. The driver of V2 stated that she was traveling south bound on S Paul St. Once at the intersection with Cumberland St traffic had rain st. Once at the messaulor with Cultimeterial as a multi-stopped for the red light. V2 was getting ready to conduct a right hand turn onto Cumberland ST but had to halt for west bound traffic on Cumberland St. In doing so she felt the front of V1 collic with rear of her vehicle. The driver of V2 further stated that she NON ulled over and a female passenger of V1 exited the vehicle to REAR END 571 37517276 2:47:00 PM DAYLIGHT FOLLOWING TOO CLOSELY SOUTH 10/4/2018 DRY CLEAR REPORTABLI sses the collision and asked if the driver of V1 needed the isses live cuitisful and asked live further by I received the sourcare. The passenger then got back in the vehicle and V1 wa believed to have headed west bound onto RT 490 West. V2 did obtain very minimal cosmetic damage to the rear of the vehicle. he passenger of V2 complained of pain but medical attention wa eclined. The driver of V2 described V1 as possibly being a urgundy 4 door sedan Nissan Sentra. A license plate was not I WAS TRAVELING SB ACROSS E MAIN ST IN THE CRO VALK, V2 WAS FACING EB, STOPPED AT THE RED LIGHT ON F MAIN ST. VI STATED THAT HE STARTED CROSSING HE STREET WHEN THE TRAFFIC LIGHT WAS RED BUT IT THE STREET WHEN THE TRAFFIC LIGHT WAS RED BUT I CHANGED GREEN WHEN HE WAS ABOUT HALFWAY ACROSS BUT HE KEPT GOING. VZ WAS STARTING TO TRAVEL FORWARD WHEN THE LIGHT CHANGED AND VI AILURE TO YIELD RIGHT OF NON 572 37516642 10/5/2018 2:58:00 PM DAYLIGHT DRY CLEAR SOUTH OTHER REPORTABLI RAN INTO V2. V2 WAS IN THE RIGHT MOST LANE AND HAD OBSTRUCTED/LIMITED A BUS TO HIS LEFT SO HE COULD NOT SEE VI APPROACHING. VI ALSO STATED THAT HE COULD NOT SEE VZ WHEN HE STARTED TO PULL FORWARD BECAUSE OF THE BUS AND THAT CAUSED HIM TO RUN INTO V2. NO INJURIES. DRIVER EXCHANGE INFORMATION FORMS

TE 213 (9/79)

OVIDED ON SCENE, DAMAGE TO V2 CONSISTED OF

TE 213 (9/79) ROUTE NO. OR STREET NAME MONRO P.I.N.: NOT APPLICABLE CASE No ADJACENT ROADWAY NETWORK TOWN FILE: CITY AT INTERSECTION WITH/OR BETWEEN: BY: PSC VILLAGE OF ROCHESTER DATE: 5/13/2020 SEE MAP ENVIRONMENTAL TIME PERIOD FROM TO Roadway Surface Condition Daylight
 Daylight
 Dawn
 Dusk 1. Dry 2. Wet 3. Muddy 1. Clear 2. Cloudy 3. Rain se Codes from MV 104 (shown right) for these categories 8/1/14 7/31/19 4. Snow/lo 4. Snow 5. Dark Road Unlighted 5. Slush 5. Sleel/Hail/Freezing Rain 10. Other 6. Fog/Smog/Smoke lo. OF MONTHS 60 Ise Codes from MV 104 Police Report of VEHICLES IGHT DIRECTION DESCRIPTION REFERENCE SOADWAY SURFACE CONDITION CRASH No CASE No DATE TIME APPARENT CONTRIBUTING FACTORS The driver of V1 changed her story a couple of times as to what happened first said she was driving and didn&apos.t see the curb and hit it and eventually claimed that she had just turned on to linton from cumberland, and a car hit her from behind and nition from confidencial and a cal filt file from both the fire hydrant. Even ough the physical evidence did not support that claim at all. The ilness who was driving and ambulance lowards her said V1 was st driving southbound on north clinton and hit the curb and said PROPERTY DAMAGE DARK-ROAD 573 37541439 10/13/2018 1:56:00 AM WET RΔIN DRIVER INATTENTION SOUTH OTHER ere was no one around her at the time. When speaking to the ness he said at the time he was only 20 yards away when the ving S/B on clinton ave. and wasn't making a turn like imed. - WITNESS 1 SMITH. BRYAN 811 WEST AVE 574 10/14/2018 12:00:00 AM INJURY UNKNOWN UNKNOWN UNKNOWN UNKNOWN UNKNOWN RIGHT ANGLE 37566857 een traffic light at intersection with Allen St in V1. Opr2 was Jopped at intersection waiting to make an illegal left turn facing torth on State St at Allen St in V2. Opr2 then turned left in front of a latempting to travel onto Allen St. V1 struck V2 on passenger de of V2 pushing V2 out of way spinning it so it struck wall on PROPERTY LEFT TURN outh side of Allen St eventually stopping further West down Alle St. V1 struck the same wall on South side of Allen St causing 2 SOUTH 575 37545023 10/16/2018 7:21:00 AM AMAGE AND DAYLIGHT DRY CLEAR TURNING IMPROPER (AGAINST where front end damage. Passenger and Opr1 were transport of Strong Hospital. Opr1 complains of pain and passenger was ansport for precautionary reasons. Two witnesses stated V2 IN ILIRY OTHER CAR) rned left illegally in front of V1 causing accident. Opr2 was issu icket for illegal left turn. Both vehicles were towed. - WITNESS 1 MCGOWAN, DAVID 250 STATE ST ROCHESTER NY 14614 354067886 - WITNESS 2 TORRES, WI FREDO 134 FUI TON VF ROCHESTER NY 14612 5854195144 T was raveling E/B on Cumberland St. in the midd nes. V2 was traveling E/B on Cumberland St. in the Northern ost lane of the three lanes. V2 had the option of either turning lef nto N. Clinton Ave. or continue straight on Cumberland St. PROPERTY EAST 576 37539706 10/21/2018 4:35:00 PM 2 DAYLIGHT DRY CLOUDY (AGAINST DAMAGE DRIVER INEXPERIENCE /1's lane is straight only. V1 attempted to turn left N/B onto I. Clinton Ave. at the green light but V2 struck the side of V1 OTHER CAR) using damage. D2 has a permits only license ABOVE LOCATION FOR A REPORT OF A MOTOR VEHICLE ACCIDENT. UPON ARRIVAL I DID TALK TO BOTH DRIVERS NVOLVED IN THE ACCIDENT. (D1) PAUL BROWN DOB 1/18/63 STATES THAT HE GOING E/B ON CUMBERI AND 18063 STATES THAT HE GOING EID ON COINDERCARD ND THAT HE WAS IN THE INSIDE LANE AT THE ITERSECTION OF CUMBERLAND ST/N. CLINTON AVE. 11) WAS ABOUT TO MAKE A LEFT HAND TURN ONTO N. DRIVER INATTENTION OVERTAKING 37547169 11:44:00 AM DAYLIGHT CLEAR EAST 577 10/25/2018 DRY CLINTON AVE. (V2) WAS IN THE OUTSIDE LANE AS (D1) NAS MAKING HIS TURN. (D2) WAS ALSO MAKING A LEFT REPORTABLI AND TURN FROM THE OUTSIDE LANE. AS BOTH HAND TORN FROM THE OUTSIDE CAINE. AS BOTH VEHICLES WERE MAKING A LEFT HAND TURN, (VI) WITH ITS FRONT PASSENGER SIDE FENDER AREA DID STRIKE (V2) IN THE REAR DRIVER SIDE FENDER AREA. THERE IS NO SIGNS OR ROAD MARKINGS AT THE LOCATION NDICATING WHICH LANE IS A TURNING LANE. NEITHER ENTER WAS IN HURED NOD COMPLAINED OF ANY PARTY STOPPED N/B ON N UNION ST AT UNIVERSITY AVE PROPERT DARK-ROAL BRAKES DEFECTIVE 578 37555288 10/26/2018 6:23:00 PM 2 DRY CLOUDY NORTH REAR END WHEN V1 STRUCK V2 FROM BEHIND. V1 STATES HE HIT DAMAGE LIGHTED IS BRAKES TO STOP AND THEY FAILED. /1 was traveling N/B on N. Clinton Ave. in the West side lane. Va vas traveling N/B on N. Clinton Ave. in East side lane. V1 AILURE TO YIELD RIGHT O DAYLIGHT NORTH OVERTAKING 579 37555301 10/28/2018 4:22:00 PM WET RAIN tempted to turn into V2's lane due to an uninvolved vehicle DAMAGE king a left turn at the green light. V1 entered V2&apos:s lane ausing an accident. Both drivers story corroborated eachothers causing air according out divers saily conflocated each orbits.

ON TH ABOVE DATE AND TIME TIDID RESPOND TO THE
ABOVE LOCATION FOR A REPORT OF A MOTOR VEHICLE
REPORT. UPON ARRIVAL, I DID TALK TO BOTH DRIVERS.
(D1) AIDEE ZORRILLLA DOB 7/18/97 STATES THAT SHE WAS TAKING A NEW ROUTE TO WORK AND LOOKED DOWN AT HER GPS. (D1) DID NOT REALIZE THAT TRAFFK
HAD STOPPED AND SHE ENDED UP STRIKING (V2). (V1)
WITH ITS FRONT BUMPER DID STRIKE (V2) IN THE REAR NON-REPORTABLI DRIVER INATTENTION 580 37587008 10/30/2018 8:04:00 AM DAYLIGHT DRY CLEAR SOUTH UMPER. (D1) DID ONLY HAVE A PERMIT WITH NO OTHER PASSENGER IN THE VEHICLE. (D2) SHAYLA BELL DOB 8/89 STATES THAT SHE WAS STOPPED IN TRAFFIC DUE TO A RED LIGHT AT THE INTERSECTION OF ST PAUL ST AND CUMBERLAND ST. (D2) WAS GOING SOUTHBOUND ON ST PAUL ST WHEN SHE FELT BEING STRUCK IN THE REAR FROM (V1). THERE WAS MINOR DAMAGE TO BOTH EHICLES AND THE VEHICLES WERE CARED FOR BY THE

UNSAFE LANE CHANGE

DAYLIGHT

DAMAGE

581

37571416

WEST

OVERTAKING

tive for the report of a two car MVA. Both drivers stated that the friver of (VI) was in the center lane when he started moving over other right lane and thit (V2). The only damage to (V1) was to his assenger side rear view mirror. Damage sustained to (V2) uppears to be to the driver's side rear view mirror, scratch

on the right front panel, and denting to the front driver&apos.s side rim. No visible injuries or complaints of any made by any party. Both parties received their accident exchange informations.

TF	213	(9/79)	

TE 213 (9/79)											1			
COUNTY:	MONROE		P.I.N.:	NOT APPLICAE	BLE	ROUTE NO. OF					CASE No.:			
	TOWN		•			ADJACENT RO					FILE:			
	CITY	DOCUECTED				AT INTERSECT	TION WITH/OR	BETWEEN:			BY:	PSC 5/13/2020	-	
	VILLAGE OF	ROCHESTER	:		-	SEE MAP					DATE	5/13/2020	=	
TIME PERIOD		FROM: 8/1/14	TO: 7/31/19	ENVIRONMEN Use Codes from at right) for these	MV 104 (shown	Light Conditions: 1. Daylight 2. Dawn 3. Dusk 4. Dark Road Lig 5. Dark Road Ur	ghted	Roadway Surfact 1. Dry 2. Wet 3. Muddy 4. Snow/Ice 5. Slush 10. Other	Wet 2. Cloudy .Muddy 3. Rain .Snowl/ce 4. Snow .Slush 5. Sleel/HaWFreezing Rain					
No. OF MONTH	IS:	(50	S					10. 00101		¹ Use Codes from	MV 104 Police Report		
CRASH No.	CASE No.	DATE	TIME	No. of VEHICLES	SEVERITY	CONDITIONS	ROADWAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING FACTORS	DIRECTION	TYPE ¹	DESCRIPTION	REFERENCE MARKER	
582	37577479	11/6/2018	11:57:00 AM	4	PROPERTY DAMAGE	DAYLIGHT	WET	CLEAR	UNKNOWN	WEST	OTHER	BOTH VI AND V2 WERE WEST ON EAST MAN STREET WITH THE GREEN LIGHT AT NUMD STREET NTERSECTION. V3 DRIVER STATED THAT THE VEHICLE N FRONT OF HIM WENT THROUGH THE ABOVE WTERSECTION SO DRIVERS ASSUMED HE YHAD THE GREEN LIGHT BUT SAW THAT IT WAS RED WHILE IN THE NTERSECTION. VI AND V2 FRONT ENDS STRUCK PASSENGER SIDE OF V3 KNOCKING V3 INTO V4 FRONT DRIVER SIDE WHEEL AREA V2 LEFT LOCATION BEFORE POLICE ARRIVAL NO INJURIES REPORTED AT LOCATION. V3 TOWED BY RPD. V1 TOWED BY PRIVATE TOW.		
583	37578963	11/6/2018	3:29:00 PM	2	PROPERTY DAMAGE AND	DAYLIGHT	WET	CLEAR	FAILURE TO YIELD RIGHT OF WAY	WEST	RIGHT ANGLE			
584	37581171	11/7/2018	3:27:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLOUDY	WAY TURNING IMPROPER	NORTH-EAST	LEFT TURN (AGAINST OTHER CAR)	VEH TWAS EAB IN THE FAIR LEFT CURB LANE OF CUMBERAND ST MAKE ALSO FIG. DOLL ON HIS ST PAUL ST. VIEH 2 WAS ALSO DE DOLL OWNER FLAND ST IN THE CENTER LANE MAKING A LEFT TURN TO NIB ST PAUL ST. IT APPEARS VEH I MADE A WIDE TURN, CROSSING INTO THE CENTER LANE, CAUSING THE FRONT PASSENGER OF HIS VEHICLE TO STRIKE THE DRIVER REAR QUARTED PANLE OF VEH. 2 LIWS SIMPLIBETLY ONISCENE AND OSSERVED A SMALL PART OF VEH 1 OCCUPYNG THE CENTER LANE OF ST PAUL. DRIVER I CLAIMS THAT VEHICLE 2 CROSSED HIS LANE HOWEVER THE PLACEMENT OF THEIR VEHICLES DOES NOT SUPPORT THIS UPON MY ARRIVAL DRIVER TO ONLY POSSESSES A CLASS OP FEMIL WITH THE OLIC MY SESSES AND CLASS OP FEMIL WHITH SESSES STAYED AT SCHEME IN SID OF MAKESSES STAY THE WITH DRIVEN SESSES AT WIS DOT CAMEDA AT THE WITH DRIVEN SEYS STAYED TO WE THIS TOWN.		
585	37594111	11/8/2018	11:31:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	BACKING UNSAFELY	EAST	REAR END	Cumberland SI and Wescott SI for the report of a 2 whiche MVA. When I arrived on scene I spoke to Boyles who was the driver of whiche 1. Vehicle 1 is a semi and was towing a haller, MF plate # 2274923. Boyles said half he was being westbound on Cumberland SI He says after looking behind him, he sharled to back up Eastbound onto Westbott SI to make a delivery. After he parked, he was approached by Ajboje who was the driver of whiche 2. She thid him half he had backed into her car. He says hat he didrikapost realize he had hit anything, Ajboje bild ments the was stoppood behind vehicle 1 on Cumberland SI when he started to back up. She says hat there were cars behind her and the could/whapost move out of he ways. Ne says hat she tied blowing her horn several times but vehicle 1 continued to back up. until 1 hither front bumper. There was damage to he front bumper and gilled or leheld 2. There was not amage to whiche 1 or the		
586	37579019	11/9/2018	11:51:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	WET	RAIN	DRIVER NATTENTION	NORTH-WEST	LEFT TURN (AGAINST OTHER CAR)	THE THROUGH WE SAFTE STATE OF THE SAFT OF		
587	37576789	11/9/2018	9:14:00 PM	2	PROPERTY DAMAGE	DARK-ROAD LIGHTED	WET	CLEAR	DRIVER NATTENTION	NORTH	OTHER	On he above date and lime I responded to he above intersection or a MVA. There I met with the driver of VI. He stated he was driving North on state st with a green light. As he as going through the intersection he other or V2 was strong West or Allen St and V stuck V2. The driver or V2 was sound the corner with his car. I spoke be him. He did not recall what clor the 1 falls (sight was for him. He stated he was driving West on Allen St and V1 stuck store. A unidentified withess stated V1 had he green light and V2 man he red light. V1 had heavy from dramage with air bags deployed. V2 had heavy dramage to the others side door and some processors of the dramage with a red specified for or at the said selections.		
588	37706520	11/9/2018	11:40:00 PM	1	PROPERTY DAMAGE	DARK-ROAD LIGHTED	WET	SLEET/HAIL/F REEZING RAIN	DRIVER INATTENTION	NORTH	OTHER	or assessmer door. At base also designed. Both care were vival set being believe mixed with by the clucipant is driver. Driver stated he was traveling west on Cumberland St and started to turn south not SI Paul SI. Driver stated he wasnikapost, paying attention and realized he was supposed to turn north. Driver stated he began to correct his turn north, however in the process over corrected. VI did coilide with he cube and with post he railroad overpass with the passenger side front tumper. No damage appeared on the post or curb. Driver stated he was wearing his seal that and did not have any flighties and defined medical attention. VI airbags were not deployed and was not		
589	37594138	11/12/2018	2:17:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	FAILURE TO YIELD RIGHT OF WAY	NORTH	RIGHT ANGLE	Some of visited in states were arresting tool from coopen was set was passing from only the intersection of Cumberland St When she was struck by vehicle 2, which was traveling west on Cumberland states that she had be green light and we which a 2 states while traveling west on Joseph Ave. When she was passing frough the intersection of Joseph Ave, when she was struck by vehicle 1, which was traveling north on Joseph Ave. Driver of vehicle 2 states that she had the green light and that vehicle I rat her red light Not video cameras located in he area. No witness. It is unknown who had		

75	040	(0.170)

TE 213 (9/79)													
COUNTY:	MONROE		P.I.N.:	: NOT APPLICAI	BLE	ROUTE NO. OF					CASE No.:		
	TOWN		-			ADJACENT RO					FILE:		-
	VILLAGE OF	ROCHESTER	!		_	AT INTERSECT SEE MAP	TION WITH/OR	BETWEEN:			BY: DATE:		-
TIME PERIOD		FROM:	TO:	ENVIRONMEN	ΙΤΔΙ ·	Light Conditions:		Roadway Surface	ce Condition: Weather:				
		8/1/14	7/31/19		n MV 104 (shown e categories		ghted	1. Dry 2. Wet 3. Muddy 4. Snow/Ice 5. Slush 10. Other	1. Clear 2. Cloudy 3. Rain 4. Snow 5. Sleet/Hail/Fre 6. Fog/Smog/Sn 10. Other				
No. OF MONTH	HS:	6	60	ES							¹ Use Codes from	MV 104 Police Report	
CRASH No.	CASE No.	DATE	TIME	No. of VEHICLES	SEVERITY	CONDITIONS	ROADWAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING FACTORS	DIRECTION	TYPE ¹	DESCRIPTION DESCRIPTION DESCRIPTION DESCRIPTION	REFERENCE MARKER
590	37607051	11/14/2018	11:58:00 AM	2	PROPERTY DAMAGE AND INJURY	DAYLIGHT	WET	CLOUDY	FALURE TO YIELD RIGHT OF WAY	SOUTH	LEFT TURN (AGAINST OTHER CAR)	ST WITH A GREEN LIGHT AND SAW VEHICLE 2 ATTEMPTING TO TURN LEFT (MW) ON TO UNIVERSITY AVE FROM NORTH UNION ST. DRIVER OF VEHICLE I STATED THAT HE ATTEMPTED TO STOP, BUT COULD NOT STOP IN THE. AT WHICH TIME HIS VEHICLE STRUCK VEHICLE 2, WHICH WAS IN THE PROCESS OF TURNING LEFT. THIS CAUSED DAMAGE OF THE FRONT DRIVERS SIDE OF VEHICLE 1. DRIVER OF VEHICLE 2 STATED THAT SHE HAD A GREEN LIGHT, AND WAS ATTEMPTING TO TURN LEFT (MW) ONTO UNIVERSITY AVE FROM NORTH UNION ST. WHEN HER VEHICLE WAS STRUCK BY VEHICLE 1. WHO WAS SBO AN ORTH UNIONS ST. DRIVER OF VEHICLE 2 STATED SHE DID NOT KNOW WHAT HAPPENED WHEN SHE ATTEMPTED TO TURN LEFT. DRIVER OF VEHICLE COMPLAINED OF PAIN AND BENG LIGHT HEADED. AND WAS TRANSPORTED TO HIGHLAND HOSPITAL BY AMR RIG TOPS. VEHICLE 2 SUSTANDE FROM THO DRIVERS SO.	
591	37591766	11/18/2018	5:44:00 PM	2	PROPERTY DAMAGE	DARK-ROAD LIGHTED	WET	RAIN	TRAFFIC CONTROL DEVICES DISREGARDED	WEST	RIGHT ANGLE		
592	37602829	11/22/2018	11:20:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	WET	SNOW	FALURE TO YIELD RIGHT OF WAY	SOUTH	RIGHT ANGLE	VEH 1 WAS SIB ON N CLINTON AVE APPROACHING CUMBERLAND INNER LOOP NITERSECTION. VEH 2 WAS NB ON N CLINTON APPROACHING SAME INTERSECTION WANTING TO MAKE LEFT TURN TO GO WIB DONTO NINER LOOP (CUMBERLAND. VEH ZHABOL LEFT TURN IN FRONT OF VEH 1 AND VEH 1 STRUCK THE PASS REAR WHEEL WITH PASS FRONT CORNER OF VEH 1 CAUSING SIGNIFICANT DAMAGE TO VEH 1 AND VEH 2. BOTH CARS REQUIRE TOWNED GIVE TO VEH 1 AND VEH 2. BOTH CARS REQUIRE TOWNED GIVE TO DAMAGE. NO NUIVES OSESKYED OR REPORTED. DRIVER VEH 2 HAD SUSP IN'S ID ONLY WITH EXP TX ID AND ADULT PASS HAD SUSP IN'S ID ONLY WITH EXP TX ID AND ADULT PASS HAD SUSP	
593	37609830	11/22/2018	10-40-00 PM	2	PROPERTY DAMAGE AND NJURY	DARK-ROAD LIGHTED	DRY	CLEAR	FOLLOWING TOO CLOSELY	WEST	RIGHT ANGLE	INSTILL LITTESLIED FOR UNIDERSED TO DORMER WH. ST.A. VOJ STATES SHE WAS TRAVELING NO NST PAUL ST.A. THE INTERSECTION OF ST PAUL ST AND CUMBERRAND ST. (V2) WAS STRUCK BY (V7), (W6) STATED HE WAS ATT HE RED LIGHT IN THE FAR LEFT LAME TO TURN SB ON ST PAUL ST AT THE RED LIGHT IN THE FAR LEFT LAME TO TURN SB ON ST PAUL ST AT THE SAME INTERSECTION. (W) STATED HE STRUCK (V2), (V2) AND (W) BOTH STATE THAT (V7) MADE A RICHIT TURN ONT ST PAUL ST AT TER THE COLLISION. (V7) STATED THAT A DARK GRAY INSTANS MISU'S THE VEHICLE THAT HER (W) CAVE THE SAME DESCRIPTION OF (V1) AND A W1 ALE CANSON SILVEN THE VEHICLE THAT HER (W) CAVE THE SAME DESCRIPTION OF (V1) AND A W1 ALE CANSON SILVEN THE VEHICLE THAT HER W1) CAVE THE SAME DESCRIPTION OF (V1) AND A W1 ALE CANSON SILVEN THE VALUE AND SILVEN SILV	
594	37680367	11/24/2018	3:26:00 AM	1	PROPERTY DAMAGE	DARK-ROAD LIGHTED	DRY	CLEAR	REACTION TO OTHER UNINVOLVED VEHICLE	WEST	OTHER	MVA with a vehicle crashed into a text. Driver Beverly Smith identified hesself with her NYS drivers license, and claimed hast best stud; he text on reading to a vehicle hat was driving the wrong way down the one way. Beverly could not offer up any description of this vehicle, and there was no evidence to prove or disprove his claim. Beverly declined any medical attention. While the other way was provided up in a private vehicle and left the scene prior to obtaining the MVA report	
595	37611382	11/24/2018	6:58:00 PM	2	PROPERTY DAMAGE	DARK-ROAD LIGHTED	WET	RAIN	TRAFFIC CONTROL DEVICES DISREGARDED	SOUTH	RIGHT ANGLE		
596	37618594	11/25/2018	5:10:00 AM	2	NON- REPORTABLE	DARK-ROAD LIGHTED	DRY	CLEAR	UNSAFE LANE CHANGE	EAST	OVERTAKING	Driver #2 shade that he was haveling rapid nor Cumberland Steel eastbound frough the St. Paul Steel intersection. Vehicle 12, who had been sitting in the left turn only lane at the intersection, also proceeded shaight frough the intersection, despite not being in an appropriate lane to do so. This caused the passenger side whiche #1 to brush up against her eart where side of Vehicle causing minor scratches and small dents. Both drivers stopped, but did not eachange information before Vehicle #1 left the scene. Driver #2 both a picture of Vehicle #1 #4 #4apors is forms glab before Driver #2 both a picture of Vehicle #1 #4apors is forms glab before	
597	37605630	11/25/2018	8:28:00 PM	2	PROPERTY DAMAGE AND INJURY	DARK-ROAD LIGHTED	DRY	CLOUDY	ALCOHOL INVOLVEMENT	EAST	REAR END	VZ EIB ÜNE MÄNI ST AND STOPPEU AT THE RED LIGHT FOR DUNKERSITY AVE WHEN VI STRUCK VZ FROM BEHND. DI WAS NTOWCATED AND IS SUED A TICKET FOR FOLLOWING TO CLOSE. DI FLED THE MVA ON FOOT AFTER GUNNO THE OFFICER HIS DERVERS LICENSE AND WAS TAKEN INTO CUSTODY AT 69 F WANN ST. DI TURNED OVER TO NYSP AND ARRESTED FOR DWI AND SSUED ADDITIONAL TICKETS. DZ AND PASSENGER LICENSE CHAINAL MAD COR CONTRAINT OF AND	

TE 213 (9/79) ROUTE NO. OR STREET NAME MONRO P.I.N.: NOT APPLICABLE CASE No ADJACENT ROADWAY NETWORK TOWN FILE: CITY AT INTERSECTION WITH/OR BETWEEN: BY: PSC VILLAGE OF ROCHESTER DATE: 5/13/2020 SEE MAP TIME PERIOD FROM TO NVIRONMENTAL Roadway Surface Condition Daylight
 Daylight
 Dawn
 Dusk 1. Dry 2. Wet 3. Muddy 1. Clear 2. Cloudy 3. Rain se Codes from MV 104 (shown right) for these categories 8/1/14 7/31/19 4. Snow/lo 5. Dark Road Unlighted 5. Slush 5. Sleet/Hail/Freezing Rain 10. Other 6. Fog/Smog/Smoke lo. OF MONTHS 60 Ise Codes from MV 104 Police Report of VEHICLES DIRECTION DESCRIPTION REFERENCE CRASH No CASE No DATE TIME APPARENT CONTRIBUTING FACTORS fficers were called to 97 Warsaw ST on 11/28/2018 for a d eport of a motor vehicle accident. There, officers spoke with the driver of V2 Rondelle Moore who stated that she was operating h ehicle Easthound on Cumberland St. Moore stated that while she erince Eastbulind or Cumberland vs., twoder Saland is all will self-ars slopped at the solid red light on Cumberland st @ N. Clinton ve, a Ford Ranger (V1) had rear ended her. (V1) was being perated Eastbound directly behind (V2), (V2) stated that (V1) ther mediately fled the scene without exchanging any information vith V2. Moore was however able to take a picture of the striking will vz. mode was invived aute blace a picture of the simility ehicle's license plate which was registered to an address to 20 Quamina Drive Officers went to the registered address to follow pon the investigation and locate V1. Officers then observed V1 at he location. The driver of V1 was identified as Ricardo Cruz. Cruz DRIVER INATTENTION EAST REPORTABLE admitted to officers that he was involved in an accident with V2 on Cumberland St. However. V1 did state that he immediately exite umberland St. However, VT out state that he immediately e is vehicle after the accident to check on the status of V2. coording to V1, the driver and all passengers of V2 were ninjured and refused any medical treatment. V2 then spoke V1 and came to an agreement that V1 would pay V2 \$50 cash to pair the damages caused by the accident. V1 agreed to this cision. V2 then followed V1 to 42 Quamina Dr. so that V1 ma \$50 from his house and pay V1. V1 then left the so d 911 from 97 Warsaw St claiming she was in a hi PROPERTY DAMAGE AILURE TO YIELD RIGHT OF 37613941 11/29/2018 11:38:00 AM DAYLIGHT RIGHT ANGLE NON. was stopping in traffic as other vehicles were preparing to turn when driver of v1 said her foot slipped causing her strike v2. n 37702915 11/30/2018 7:49:00 AM DRIVER INATTENTION DAWN CLOUD NORTH REAR END njuries were reported. VEH 1 AND VEH 2 WESTBOUND CUMBERLAND ST. VEH 1 PROPERTY DAMAGE 601 37616822 11/30/2018 3:17:00 PM DAYLIGHT WET CLOUDY UNSAFE LANE CHANGE WEST OVERTAKING HANGED LANES UNSAFE AND STRUCK VEH 2 CAUSING MAGE TO BOTH VEHICLI ALURE TO VIELD RIGHT O DDODEDT DADK DOA 602 37619392 12/2/2018 10:10:00 PM 2 WET RAIN WEST RIGHT ANGLE DAMAGE LIGHTED WAY NTERSECTION OF CUMBERLAND ST AND ST PAUL, V1 IS N THE MIDDLE LANE (STRAIGHT ONLY LANE) EACING VITE MIDDLE EARL (STRAIGHT ONE) FACING VESTBOUND. THE TURN SIGNAL PROCEEDED TO TURN REEN AND V2 ENTERED THE INNER LOOP ON RAMP. PROPERTY PASSING OR LANE LISAGE 603 37628094 12/7/2018 9:37:00 AM DAYLIGHT WET CLEAR WEST OVERTAKING IMPROPERLY HE DRIVER OF V1 ACCELERATED AND ATTEMPTED TO MERGE BACK INTO V2' S LANE, SUBSEQUENTLY PROPERTY LEFT TURN DARK-ROAL AILURE TO YIELD RIGHT OF 604 37634705 12/8/2018 7:37:00 PM 2 AMAGE ANI DRY CLOUDY NORTH (AGAINST OTHER CAR INJURY In 12/09/2018 I responded to the intersection of N. Union Stree on Taylocot in responded but in line account in Kinning seek and East Main Street for the report of a motor vehicle accident. Upon arrival I noticed two vehicles that were involved and I quickly learned that nobody was injured in this incident. I began to speak with the driver of vehicle 1 who stated that he rear ended the vehicle that was slowing down in from of him. Vehicle 1 stated tha ernice in an was subunig down in 1 oin on initi. Verince i Saleau iai. erhicle 2 was stopping to allow someone to pull into the fastrac karking lot. When Vehicle 2 slowed down to let the other ininvolved vehicle in, vehicle 1 rear ended vehicle 2. Vehicle 1 did PROPERTY 605 37638432 12/9/2018 11:40:00 AM DAYLIGHT DRY CLEAR FOLLOWING TOO CLOSELY SOUTH REAR END ot suffer any damage in the crash and vehicle 2 had minor lamage to its back left bumper. The operator of vehicle 2 stated aming to be seek whether the content of the content 606 37636498 12/11/2018 1:59:00 PM 2 DAYLIGHT WET SNOW DRIVER INATTENTION NORTH RIGHT ANGLE DAMAGE OPPED N/B ON UNIVERSITY AVE AT THE LIGHT F NON-DARK-ROAF 607 37649728 12/15/2018 4:56:00 PM DRY CLEAR FOLLOWING TOO CLOSELY NORTH REAR END IAIN ST WHEN VI STRUCK V2 FROM REHIND VI HAD NO EPORTARI. LIGHTED PROPERTY ARK-ROA 608 37704803 12/20/2018 5:30:00 PM UNKNOW UNKNOW UNKNOWN UNKNOWN OTHER DAMAGE JNLIGHTE N/B ON UNIVERSITY STOPPED FOR THE RED LIGHT A MAIN ST WHEN SHE WAS STRUCK FROM BEHIND BY VI PROPERTY DARK-ROAF 609 37653642 12/21/2018 7:36:00 PM WFT RAIN FOLLOWING TOO CLOSELY NORTH REAR END STATES SHE SLID ON THE WET ROADWAY AND DAMAGE LIGHTED ssed a red traffic signal at the intersection of East Main Street RAFFIC CONTROL DEVICES PROPERTY ecause he was looking at his GPS and struck Vehicle 2. Driver 2 aled that he was west bound in the middle lane of East Main 610 37660490 12/27/2018 1:57:00 PM DAYLIGHT DRY CLEAR NORTH RIGHT ANGLE DAMAGE DISREGARDED /2 was traveling E/B on Allen St approaching State St. As V2 tered the intersection, D1 ran the red light striking V2 on the Pa RAFFIC CONTROL DEVICES PROPERTY DARK-ROAL 611 37671874 1/2/2019 6:06:00 PM DRY CLOUDY NORTH RIGHT ANGLE was slopped behind V1 and observed D1 run the red light. D2 DAMAGE LIGHTED DISREGARDED as found to be driving with a revoked NYS ID. No injuries ported. D2 issued UTS for unlicensed operator. - WITNESS 1 NTHE ABOVE DATE AND TIME, V2 WAS TRAVELING EB ON UNIVERSITY AVE AND STOPPED AT THE RED LIGHT AT THE INTERSECTION OF N LINION ST IN THE LEFT LANE. V THE INTERSECTION OF IN UNION STATE THE LEFT CAME. YEARS ALSO TRAVELING EB ON UNIVERSITY AVE IN THE FAR RICHT LANE. YEARS AD BARK COLORED SEMI-WITH TRAILER AND CONTINUED THROUGH THE IN UNION ST INTERSECTION. YEARSON'S REAR LEFT PART OF THE PROPERTY PASSING OR LANE USAGE 12:44:00 PM EAST OVERTAKING 612 37681822 1/4/2019 DAYLIGHT DRY CLEAR RAILER MADE CONTACT WITH V2&apos:S PASSENGER DAMAGE IMPROPERLY SIDE CAUSING DAMAGE TO SAME. VI DID NOT STOP AND ONTINUED EB ON UNIVERSITY AVE. V2 FOLLOWED AND AVE 911 OPERATORS NYS REG "PT2742Y" WHICH DOES NOT COME BACK WITH ANY REGISTRATION NFORMATION. V2 STOPPED AT 30 ANDERSON AVE AND

ALLED POLICE, NO INJURIES REPORTED. V1 DID NOT

TE 213 (9/79) ROUTE NO. OR STREET NAME MONRO P.I.N.: NOT APPLICABLE CASE No ADJACENT ROADWAY NETWORK TOWN FILE: CITY AT INTERSECTION WITH/OR BETWEEN: BY: PSC VILLAGE OF ROCHESTER DATE: 5/13/2020 SEE MAP NVIRONMENTAL TIME PERIOD FROM TO Roadway Surface Condition 1. Dry 2. Wet 3. Muddy 1. Clear 2. Cloudy 3. Rain se Codes from MV 104 (shown right) for these categories 1. Daylight 8/1/14 7/31/19 4. Snow/lo 4. Snow 5. Dark Road Unlighted 5. Slush 5. Sleel/Hail/Freezing Rain 10. Other 6. Fog/Smog/Smoke lo. OF MONTHS 60 Ise Codes from MV 104 Police Report of VEHICLES DIRECTION DESCRIPTION REFERENCE ROADWAY SURFACE SONDITION CRASH No CASE No DATE TIME APPARENT CONTRIBUTING FACTORS WAS STOPPED IN TRAFFIC FACING WIR ON F MAIN ST PROPERT DAMAGE 37691949 1/11/2019 1:00:00 PM DAYLIGHT DRY CLEAR FOLLOWING TOO CLOSELY REAR END 613 2 WEST TIME AND STRUCK V2. ehicle 2 was in the left lane on Allen St. he een light. Vehicle 1 was in the left lane on Allen St. heading peen ignit ventuer I was in the ent after of it needs is need in season of seasobound with a green light behind vehicle 2. An uninvolved fire lepartment suv activated their emergency equipment as vehicle 1 and 2 entered the intersection. Driver 2 braked to stop. Driver taked that she thought Driver 2 was going to clear out of the intersection rather then stopping in the middle of it and ended up. PROPERTY 614 37705375 1/18/2019 11:30:00 AM AMAGE AN INJURY DAYLIGHT UNKNOWN UNKNOWN FOLLOWING TOO CLOSELY EAST REAR END triking the rear of vehicle 2. Both Drivers exchanged information ene and the police were not called. Today 1/22/19 driver 2 alled 911 to report the accident after being advised to do so. iver 2 states that she is now having back, neck, and jaw triver 1 had no complaints of injuries. No city cameras captured I traveling 5 bound on University Ave passing inrough the tersection of E Main st struck V2 who was traveling E bound on Main st traveling through the same intersection. Both drivers stated hey had the green light. Officers observed the traffic signals for four rotations and the lights were working properly. No cameras captured the incident and there were no witnesses. Operator of V2 PROPERTY DARK-ROAF 11:16:00 PM 615 37722507 SNOW PAVEMENT SLIPPERY SOUTH RIGHT ANGLE as operating the vehicle with a suspended drivers license. Both V1 and V2 were towed from the scene of the accident. No one wa SNORTH ON N UNION ST RED AND SHE WAS STOPPING AT THE LIGHT, VEHICLE 1 THE HIT HER FROM BEHIND. DRIVER I STATED HE WAS RYING TO STOP BUT THE ROADS WERE SLIPPERY AND HIT VEHICLE 2. THE ROAD CONDITIONS WERE VERY POOI PROPERTY 616 37705371 1/22/2019 8:54:00 AM DAYLIGHT SNOW/ICE CLEAR PAVEMENT SLIPPERY NORTH REAR END ITH SIGNM AND ITE ON THEM NO IN HIDES

IN 1281/19 at approximately 1230 has I was dispatched to the are
I Cumberland St and St Paul St for the report on a MVA. When I
rrived onscene I located vehicle 1 off of the road and into light pol #24 on Cumberland St approximately 300 ft East of St Paul. I ooke to Turner who was the driver. He said that he was going PROPERTY REACTION TO OTHER 617 37720310 1/24/2019 12:30:00 PM DAYLIGHT SNOW/ICE CLOUDY WEST OTHER astbound on Cumberland St when an uninvolved gray van ca DAMAGE LININVOLVED VEHICL as abount on Cumberhald Styrier an Uninvolved gay van cam o a stop in the road in front of him. He hit his brakes to avoid triking the van and his car slid on the ice and went off the road in he light pole. There was no damage to the pole. The van which as not hit drove away. Turner did not get a license plate numbe hicle 1 was lowed by 454 and Turner was picked up by his a operator of V1 said that he was traveling porth bound on The operator of V1 said that he proceeded to the intersection Allen SVState St to turn left (Westbound) on to Allen St. The operator of V1 said he did not see that he had a steady red traffic ignal and struck the front left quarter panel of V2 with his front righ PROPERTY imper, causing damages to the same. The operator of V2 said at he was traveling Westbound on Allen St and did have a stead 618 37712302 1/25/2019 3:30:00 PM DAYLIGHT DRY CLEAR DRIVER INATTENTION NORTH-WEST RIGHT ANGLE DAMAGE t he was traveling westbound on Allen St and did have a ste een traffic signal at the time of the accident. (W) said that she served the accident and did see V1 run the red light and striki V2. There were no injuries or complaints of pain reported at the ene of the accident. - WITNESS 1 POWELL. BRITTANY 848 HASE RD HILTON NY 14468 5856227380 Clinton facing East bound. The light turned green and V1 proceeded straight through the intersection. V2 attempted to turn FAILURE TO YIELD RIGHT OF PROPERTY eft illegally in front of V1 causing V1 to strike V2 in a right angle 619 37749924 1/28/2019 9:24:00 AM 2 DAYLIGHT SNOW/ICE SNOW EAST RIGHT ANGLE in liegary in floritor of values by the State Very and the State Very and the State of West Very and the State of Very and The State DAMAGE um half kom all lance on Author information V1 was traveling west bound on Cumbertand St. V2 was traveling north bound on Joseph Ave. V1 and V2 were both approaching the ntersection of Joseph Ave and cumbertand St. V2 had a green PAVEMENT SLIPPERY, PROPERTY DARK-ROAL light and V1 had a red light, as V2 drove through the intersection 620 37724456 1/30/2019 6:42:00 PM 2 SNOW/ICE SNOW WEST RIGHT ANGLE DAMAGE LIGHTED OTHER (VEHICLE) /1 was attempting to stop at the red light. V1 was unable to stop lue to the snow/icy pavement and slid through th intersection driking V2 at a right angle. Both drivers complained of pain on ON THE ABOVE DATE AND TIME I DID RESPOND TO THE ABOVE LOCATION FOR A REPORT OF A MOTOR VEHICLE ACCIDENT. UPON ARRIVAL I DID TALK TO BOTH DRIVERS (D2) ADALBERTO RIVERA DOB 2/1/63 DID STATE THAT HE WAS GOING S/B ON N. CLINTON AVE AND WAS APPROACHING THE INTERSECTION WITH CUMBERLAND (D2) THEN SAID THAT HE WAS MAKING A LEFT HAND URN ONTO CUMBERLAND ST GOING E/B WHEN (V1) INN OWN COMBERCARD 31 GOING LIB WITH (VI) TRUCK HIS VEHICLE ON THE PASSENGER SIDE FRONT OOR. (D1) COLLEEN BURWELL DOB 8/21/64 STATES HAT SHE WAS DRIVING N/B ON N. CLINTON AVE JUST FAILURE TO YIELD RIGHT OF 37732324 NORTH 621 2/1/2019 10:44:00 AM DAYLIGHT CLEAR WET (AGAINST SOUTH OF THE CUMBERLAND INTERSECTION. WHEN DAMAGE OTHER CAR) HE GOT TO THAT INTERSECTION, (D2) MADE A LEFT SHE GOT TO THAT MICHESTEL HOW, (U2) MADE A LET-HAND TURN RIGHT IN FRONT OF HER. (D1) DD NOT HAVE ENOUGH TIME TO AVOID THE ACCIDENT AND DD STRKE (V2). (V1) WITH ITS FRONT PASSENGER SIDE BUMPER DID STRIKE (V2) IN THE PASSENGER SIDE FRONT DOOR. (W1) RICHARD GIUFFRIDA SAID THAT HE SAW EVERYTHING AND THE (D2) DID MAKE THAT TURN RIGHT VERTITING AND THE (U2) DID MAKE THAT TORN KISH I FRONT OF (D1). THIS DID NOT GWING (D1) ENOUGH IME TO REACT. BOTH DRIVERS SAID THAT THEY WERE IOT INJURED AND DID NOT NEED AMR TO RESPOND. OTH VEHICLES WERE CARED FOR BY THE OWNERS UMBERLAND ST. (V2) AND (V3) WERE FACING N/B ON ST AUL ST STOPPED BEFORE THE INTERSECTION OF FOLLOWING TOO CLOSEL' OTHER

37732335

622

2/1/2019

10:50:00 AM

DAYLIGHT

DAMAGE

DRY

CLEAR

NORTH

UMBERLAND ST. (V1) WAS UNABLE TO STOP IN TIME ND REAR ENDED (V2), THIS CAUSED (V2) TO MOVE

TE 213 (9/79) ROUTE NO. OR STREET NAME MONRO P.I.N.: NOT APPLICABLE CASE No ADJACENT ROADWAY NETWORK TOWN FILE: CITY AT INTERSECTION WITH/OR BETWEEN: BY: PSC VILLAGE OF ROCHESTER DATE: 5/13/2020 SEE MAP ENVIRONMENTAL TIME PERIOD FROM TO Daylight
 Daylight
 Dawn
 Dusk 1. Dry 2. Wet 3. Muddy 1. Clear 2. Cloudy 3. Rain se Codes from MV 104 (shown right) for these categories 8/1/14 7/31/19 4. Snow/lo 4. Snow 5. Sleet/Hail/Freezing Rain 5. Dark Road Unlighted 5. Slush 10. Other 6. Fog/Smog/Smoke lo. OF MONTHS 60 Ise Codes from MV 104 Police Report of VEHICLES IGHT DIRECTION DESCRIPTION REFERENCE SOADWAY SURFACE CONDITION CRASH No CASE No DATE TIME APPARENT CONTRIBUTING FACTORS H T TRAVELING SOUTHBOUND STRAIGHT AHEAD O STATE ST DID VEER LEFT AT INTERSECTION WITH ALLEN ST AND STRIKE THE CROSSWALK LIGHT POLE AT THE SOUTH EAST CORNER OF INTERSECTION.DRIVER 1 STATING THAT HE HAD MISSED HIS TURN AND HAD MISTAKENLY ENTERED THE INTERSECTION ON A RED SIGNAL AND WAS TRYING TO AVOID COLLISION WITH ASTROUND VEHICLES WHEN HE STRUCK POLE DRIVER WITH COMPLAINT OF CHEST PAIN & DRIP; TRANSPORTED Y AMR RIG #7779PASSENGER 1 WITH COMPLAINT OF PROPERTY 623 37730800 2/1/2019 11:39:00 AM DAYLIGHT DRY CLEAR DRIVER INATTENTION SOUTH OTHER INJURY ABDOMINAL PAIN AND BACK PAIN TRANSPORTED BY AM RIG #7429RED ON SCENE OFC. DANN ON SCENE WITH RICH FLAPRED ON SCENE. DRICH, DAINN ON SCENE WITH TRAFFIC DIRECTION & Amp; TOW.WITHESS STATED THAT EASTBOUND TRAFFIC HAD GREEN LIGHT WHEN VEH 1 ENTERED INTERSECTION.COUNTY OF MONROE ON SCENE TO CK LIGHTPOLE. POLE STILL STANDING AND ABOVE LOCATION FOR A REPORT OF A MOTOR VEHICLE ACCIDENT. LIPON ARRIVAL LDID TALK TO BOTH DRIVERS (D2) JOHN MCDERMOTT DOB 3/31/60 STATES THAT HE
WAS STOPPED IN THE INSIDE LANE AT CUMBERLAND ST AND N. CLINTON AVE. (V1) WAS STOPPED RIGHT NEXT TO HIM IN THE OUTER LANE. WHEN THE LIGHT TURNED GREEN. (D2) CONTINUED TO GO STRAIGHT AND (V1) WITH LEFT TURN SKEEN, (LZ) CONTINUED TO GO STRAIGHT AND (VI) WITH TS FRONT BUMPER DID STRIKE (V2) ON THE PASSENGER SIDE SLIDING DOOR. (D1) ROBERT MCCOY DOB 10/08/96 DID STATE A SIMLAR STORY. (D1) DID STATE THAT HE "HOUGHT THAT (V2) WAS IN A TURN ONLY LANE. (D1) NON 624 37732353 2/2/2019 2:18:00 PM 2 DAYLIGHT WET CLEAR DRIVER INATTENTION EAST (AGAINST OTHER CAR) SAID THAT HE WAS TRYING TO MAKE A LEFT HAND TURN SAID THAT HE WAS TRYING I OWARE A LEFT HAND TOKIN ONTO N. CUITON AVE. WHEN HE REALIZED THAT (VZ) WAS NOT TURNING, IT WAS TOO LATE AND STRUCK (VZ). BOTH DRIVERS DID NOT COMPLAIN OF PAIN AND DID NO: REQUEST MEDICAL SERVICES. BOTH VEHICLES WERE ARED FOR RY THE OWNERS TWAS TRAVELING WIS UNLYNDHURST ST AND STR V2 WHO WAS PARKED UNOCCUPIED FACING W/B IN RONT OF 92 I YNDHURST ST. THE REG. OWNER OF V2 FRONT OF YZETNIDHORST ST. THE REG. OWNER OF YZ HEARD THE CRASH AND LOOKED OUT OF THE WINDOW TO SEE A DARK FULL SIZE VAN ATTEMPTING TO LEAVE THE SCENE. LEFT AT THE SCENE WAS THE LICENSE PLATE TO VI. ISPOKE TO THE REG OWNER OF VI WHO CONFIRMED THAT SHE IS THE OWNER OF THE VEHICLE AND THAT ITS SUPPOSED TO BE PARKED. SHE DID SAY I FFT/HAII PROPERTY DARK-ROAD PASSING OR LANE USAGE NO THAT ITS SUPPOSED TO BE PARKED. SHE DID SAY HAT SHE DOES NOT KNOW WHO IS CURRENTLY PRIVING. . EVENTUALLY THE RO OF VI STATED THAT HER SONS RIEND ".JAY POWELL" DROVE THE VEHICLE 625 37742157 2/3/2019 3:15:00 AM SNOWICE REEZING WEST REAR END DAMAGE LIGHTED IMPROPERLY WITHOUT PERMISSION. THE RO OF V1 SAID THAT THE EHICLE WAS PARKED ON VETTER ST. I LOCATED THE PEHICLE IN FRONT OF 8 VETTER ST. I LOBSERVED

DAMAGE TO THE FRONT END OF THE VI WITH IS

CONSISTENT TO THE SCENE ON LYNDHURST ST. I TOOK HOTOS OF V1 AND RETURNED THE FOUND LICENSE The operator of V2 claimed that she was in the right lane facing ne operation of v2 claimine rates in we shi in the injurial releasing astround at the intersection of Joseph Ave/inner loop Eastbound thich is marked for traffic to make a left turn or continue straight to onlinue onto the inner loop eastbound. The operator of V2 said hat V1 was in the lane to the left of her that is marked to turn left nly. The operator of V2 claimed that when she went to turn left PROPERTY ny. The operation for Zealment and when she went to burner orthbound) onto Joseph Ave, V1 continued straight instead of ming left and struck her rear left door with its front right quarter anel, causing damages to the same.The operator of V1 said tha 626 37734104 2/3/2019 1:56:00 PM 2 DAYLIGHT DRY CLOUDY UNSAFE LANE CHANGE FAST RIGHT ANGLE DAMAGE e realized that he was in the wrong lane and did not see V2 whe e attempted to change into the correct lane to continue onto the eastbound. The operator of V1 also claimed that the rator of V2 did not signal her intent, despite say NAS HEADING N/B ON N CLINTON AVE. AS V1 AND B1 PROPERTY DARK-ROAL PASSING OR LANE USAGE NEARED EACH OTHER, V1 HIT B1, V1 DID NOT STOP AND 627 37729185 2/4/2019 8:22:00 PM AMAGE AND WFT CLOUDY NORTH OTHER LIGHTED IMPROPERLY DROVE OFF, LEAVING REAR VIEW MIRROR, B1 HAD MINOR INJURY GUARDIAN OF B1 WAS NOTIFIED VIA PHONE CIDENT
re date and time I responded to E. Main Stat Uni

FAILURE TO YIELD RIGHT OF

EAST

OVERTAKING

PROPERTY

DAMAGE

2

628

37791495

2/6/2019

7:27:00 PM

DARK-ROAD

LIGHTED

WET

RAIN

Ave for the report of a MVA. There I met with the drivers of v1 and v2. Driver of V1 stated she was on University Ave at the traffic light she said she made sure no cars where coming and made the right (east) Jurn onto E. Main St. as she made the turn her car struck V2. Driver of V2 stated she was on the inner loop at the

struck V.2. Univer of V.2 stailed she was on the inner loop at the straffic facing South at the Itaffic flight. Driver of IV2 stated she had the green arrow and made the left (east) furn onto E. main st. As she made the turn V1 hit her car. Driver of V2 stated the driver of V1 did not stop for the red light and drove through the light to mak the right hand turn. V1 had damage to the left front quarter panel.

V2 had damage to the right rear quarter panel and right rea

ROUTE NO. OR STREET NAME MONRO P.I.N.: NOT APPLICABLE CASE No ADJACENT ROADWAY NETWORK TOWN FILE: CITY AT INTERSECTION WITH/OR BETWEEN: BY: PSC VILLAGE OF ROCHESTER DATE: 5/13/2020 SEE MAP NVIRONMENTAL TIME PERIOD FROM TO 1. Dry 2. Wet 3. Muddy 1. Clear 2. Cloudy 3. Rain se Codes from MV 104 (shown right) for these categories 1. Daylight 8/1/14 7/31/19 4. Snow/lo 4. Snow 5. Dark Road Unlighted 5. Slush 5. Sleel/Hail/Freezing Rain 10. Other 6. Fog/Smog/Smoke lo. OF MONTHS 60 Jse Codes from MV 104 Police Report of VEHICLES DIRECTION DESCRIPTION REFERENCE SOADWAY SURFACE CONDITION CASE No CRASH No DATE TIME APPARENT CONTRIBUTING FACTORS N THE ABOVE DATE AND TIME TRESPOND TO THE ABOVE LOCATION FOR A REPORT OF A MOTOR VEHICLE ACCIDENT. UPON ARRIVAL I DID TALK TO BOTH DRIVER: (D1) STATES THAT SHE WAS IN THE OUTSIDE LANE ON CUMBERLAND ST STOPPED AT THE INTERSECTION WITH . CLINTON. THE LIGHT WAS RED. (V2) WAS IN THE SIDE LANE STOPPED TOO. WHEN THE LIGHT TURNED REEN (D.1) ATTEMPTED TO MAKE A LEFT HAND TURN. D1) DID NOT REALIZE THAT NEITHER LANE WAS RESIGNATED AS A TURNING LANE ONLY. (VZ) WENT LEFT TURN PROPERTY 2/10/2019 629 37744145 1:52:00 PM DAYLIGHT DRY CLEAR DRIVER INATTENTION EAST TH OTHE CAR) TRAIGHT WHEN THE LIGHT TURNED GREEN AND THAT WHEN (V1) WITH ITS FRONT DRIVER SIDE BUMPER DID TRIKE (V2) IN THE FRONT PASSENGER WHEEL AREA. D2) STATES A SIMILAR STORY OF THE ACCIDENT.
NEITHER DRIVERS OR PASSENGER COMPLAINED OF AN PAIN AND DID NOT REQUEST AMR TO RESPOND TO THE ne traffic light. Veh #1 which was headed eastbound on East re familiary in the first with the state desident of the cast of Jain, altempted to slow and stop but still on the sush and ice. Vet 11 made contact with the rear bumper of Veth #2 causing minor lamage to the bumper and right rear quarter panel. Driver #2 complained of a headache but had no visible injuries. Both drivers 630 37748160 2/12/2019 12:32:00 PM INJURY DAYLIGHT SLUSH SNOW PAVEMENT SLIPPERY EAST REAR END oth drivers of V1 and V2 had contradicting stories for the incider he driver of V1 stated that she was attempting to make a left har urn south bound onto St Paul St from Cumberland St. She stated hat she had a green light when she began to turn. She stated that naistier laad a green light when she began to brint, she shaked hat V2 drove through the intersection and shock her vehicle on the front drivers side. The driver of V2 stated that he was driving north bound on St Pau St. He said when he was approaching the ntersection of St Paul St and Cumberland St he had a yellow ligh NON 631 37745213 2/13/2019 3:14:00 PM DAYLIGHT WFT SNOW DRIVER INATTENTION SOUTH RIGHT ANGLE le stated he drove through the vellow light at which point V1 was rning and struck him on the passenger side. V2 had damage o anning and stuck min on the passengles block vs. That damlage he passenger side door. Neither driver was injured and both of IT was traveling southbound on St Paul St lowards Cumberlat St. VZ was traveling westbound on Cumberland St lowards St Paul St. V1 was facing a solid red light and V2 was facing a gree light. V1 did not stop at the red light and struck V2 on the passeng side front quarter panel area. No injuries to any parties involved.

W2 was directly behind V2 prior to the accident. All parties stated
the same occurrence of events. Driver of V2 stated she did not si PROPERTY DARK-ROAL 632 37767978 2/16/2019 6:26:00 PM DRY CLEAR DRIVER INATTENTION SOUTH RIGHT ANGLE DAMAGE LIGHTED e red light signal as she was driving underneath the bridge on S aul St. V2 was towed by 451 to the garage, V1 was driven from ie scene. No injuries to any parties involved. - WITNESS 1 JINNICK, DYLAN 630 N CLINTON AV ROCHESTER NY 1461 DARK-ROAD PROPERTY 633 37757204 2/23/2019 8:14:00 PM 2 DRY CLOUDY UNKNOWN EAST RIGHT ANGLE DAMAGE LIGHTED river of V1 staled while traveling west on Cumberland St, V2, ho was also traveling west on Cumberland St, quickly slowed own, causing him to strike V2. Driver of V1 staled that he could ot slow down fast enough because of the snow covered roads. or solv down ass enough because or the show covered roads, where of V2 stated that white larevalley meet on Cumberland St sh as passing through the intersection of N Clinton Ave when the elicity of V2 had to share the state of V2 had to share he brakes to avoid hilling the uninvolved vehicle. When Driver of 2 stammed on the brakes V1 shuck V2. The uninvolved vehicle PROPERTY 634 37770223 2/27/2019 3:53:00 PM DAYLIGHT SNOW/ICE SNOW FOLLOWING TOO CLOSELY WEST REAR END DAMAGE eft the scene. No information on uninvolved vehicle. No ilhesses. No reported injuries. The RPD fleet number for V2 i r was sis on in Prymouth and attempting to make a lett turn on llen st when he struck V2 who was NB on N Plymouth and PROPERTY LEFT TURN naking a right onto Allen st. The driver of V1 left a business card AILURE TO YIELD RIGHT OF 635 37785981 3/5/2019 7:36:00 AM AMAGE AND DAYLIGHT DRY CLOUDY SOUTH (AGAINST vith V2 and left prior to police arrival. I called the business and WAY INJURY OTHER CAR tained the driver info. The driver of V2 did provide a license at number for V1. There appeared to be minimal damage ne drives of V1 did go to PGH for complaint of pain ... linton Ave when she accidentally bumped the rear bumper of V2 thich was facing Westbound. There was no damage to V1, but ninor damage to the passenger side rear bumper of V2. V2 was NON 636 37789691 3/5/2019 2:44:00 PM 2 DAYLIGHT DRY CLEAR BACKING UNSAFELY WEST REAR END arked illegally (not in a parking spot) with no driver, but a REPORTABLE assenger in the front seat who got out of he vehicle after the ehicle was struck. The owner of V2 stated she had ran inside th ocation, but was coming back out.No injuries to anyone in either EH'T TRAVELING STRAIGHT AHEAD IN THE MIDDLE WE ANE OF E. MAIN ST DID STRIKE VEH 2 (PICKUP TRUCK QUIPT WITH A SALTER UNIT ON A STEEL FLATBED) WHICH WAS ATTEMPTING TO EXIT FASTRAC PARKING LO VATION WAS ATTEMPTING TO EACH PASTRAC PARKING LE TRAVELING SY FROM THE EXIT ACROSS THE LEFT TURN ANE ONTO E MAIN ST AND INTO THE MIDDLE WB ANE.VEH 1 STRUCK VEH 2'S LEFT REAR PICKUP DRIVER INATTENTION 637 2 DAYLIGHT WEST REAR END 37794247 3/6/2019 1:50:00 PM WET CLEAR LAT BED WITH VEH 1'S RT FRONT LIGHT DAMAGE ASSEMBLY/ FRONT RT FENDER.NO INJURIES GSEMBELT FROM THE RUBEL FROM BOTHERS SEPORTED DRIVER 1 STATING DRIVING STRAIGHT AHEAD ON A SOLID GREEN LIGHT IN MIDDLE LANE.DRIVER 2 STATING THAT HE DID SEE VEH 1, BUT THOUGHT VEH 1 NAS FAR ENOUGH BACK THAT HE COULD SAFELY MAKE THE MERGE INTO MIDDLE WB LANE.NO CITY CAMERAS VAIL @ THIS LOCATION NO FURTHER TWAS Traveling SB on N Union Stapproaching where it injer with the Inner Loop ramp. V2 was exiting the Inner Loop onto N Jnion St about to make a left turn. Driver of V2 says that V1 had ter left turn blinker on and she assumed that V1 was about to get NON-REPORTABLI AILURE TO YIELD RIGHT OF 11:34:00 AM 2 DAYLIGHT CLEAR SOUTH RIGHT ANGLE 638 37785961 3/7/2019 DRY onto the on ramp so she began to enter the road. Driver of v1 say WAY he was going straight and did not have her blinker on and was i about to get on the Inner Loop. Driver of V1 says that V2 entered the road, not yielding the right of way and could not avoid striking

TE 213 (9/79)

TE 213 (9/79) ROUTE NO. OR STREET NAME: MONROE TOWN CITY P.I.N.: NOT APPLICABLE CASE No.: ADJACENT ROADWAY NETWORK FILE: BY: DATE: AT INTERSECTION WITH/OR BETWEEN: VILLAGE OF ROCHESTER 5/13/2020

	VILLAGE OF	ROCHESTER	2			SEE MAP					DATE:	5/13/2020	_
TIME PERIOD		FROM: 8/1/14	TO: 7/31/19	ENVIRONMEN Use Codes from at right) for these	MV 104 (shown	Light Conditions 1. Daylight 2. Dawn 3. Dusk 4. Dark Road Light 5. Dark Road Ut	ghted	Roadway Surfa 1. Dry 2. Wet 3. Muddy 4. Snow/Ice 5. Slush 10. Other	ce Condition: Weather: 1. Clear 2. Cloudy 3. Rain 4. Snow 5. Slee\/ Hail/Fre 6. Fog/Smog/Si 10. Other				
No. OF MONT	HS:		60	of VEHICLES	~	ONS	ΑΥ E ON	R		DIRECTION		MV 104 Police Report DESCRIPTION	REFERENCE MARKER
CRASH No.	CASE No.	DATE	TIME	No. of VE	SEVERITY	LIGHT	ROADWAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING FACTORS				WARRER
639	37785394	3/8/2019	7:24:00 AM	2	DAMAGE AND INJURY	DAYLIGHT	DRY	CLEAR	DRIVER INATTENTION	EAST	REAR END	TELAKNED FROM THE OWNER OF VZ THAT HIS CAR WAS	
640	37798568	3/8/2019	3:29:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	WET	SNOW	DRIVER INATTENTION	EAST		PARKED IN A WESTBOUND DIRECTION IN FRONT OF 289 LYNDHURST ST. THE CAR WAS LEFT UNATTENDED AND UNWATCHED FOR SEVERAL HOURS. WHEN OWNER 2 RETURNED TO HIS CAR HE NOTICED THAT THERE WAS RIGHT SIDE FRONT END DAMAGE OWNER 2 SAD HATT THE CAMERAS AT DELTA SONIC MAY HAVE CAUGHT THE NO.DENT. THE PROCESS TO REVIEW THE FOOTAGE IS OFTEN SEVERAL WEEKS! LADVESD OWNER 2 TO INFORM HIS NISURANCE COMPANY OF HIS FINDINGS. NO	
641	37802948	3/12/2019	12:26:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLOUDY	TURNING IMPROPER	NORTH-WEST		Driver 2 saled she was southbound on Sale S1 approaching Alen SL Driver 2 saled she had a green light to proceed frough the intersection southbound when vehicle 1 turned left in front of he and hit her vehicle. Driver 2 indicated that driver 1 turned left to go wesbound on Allen S1 in front of vehicle. 2 Witness 1 was southbound on Sales S1 in the eastbound burn lane. Witness 1 saled driver 1 turned left to go wesbound on Sales S1, and turned left to go wesbound on the S1. Driver 1 said she hit vehicle 2. There is a not left burn sign probibility wesbound turns onto Allen S1 from northbound staffs. Driver 1 did not doep the 18th control sign. Driver 2 had a valid NYS permit only with no licensed driver. The front center of vehicle 1 in the front driver side bumper of vehicle 2. No injuries observed or complained of No Oily cameras. WITNESS 1	ſ
642	37793504	3/13/2019	6:20:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLOUDY	FAILURE TO YIELD RIGHT OF WAY	NORTH	OVERTAKING	veh 1 was traveling straight/north on university ave. veh 1 was straight/inorth on university ave. veh 2 altempted to switch lanes into the path of veh 1 already occupying that lane. The 2 vehs struck causing dam, to hold vehs VT EIB OM MAIN ST PASSING N UNION ST WITH A STEADY	
643	37793502	3/13/2019	6:22:00 PM	1	PROPERTY DAMAGE AND INJURY	DAYLIGHT	DRY	CLOUDY	FAILURE TO YIELD RIGHT OF WAY	EAST	OTHER	GREEN LIGHT WHEN B1 WHO WAS TRAVELING S/B ON N UNION ON HIS BIKE FAILED TO STOP FOR THE RED LIGHT. V1 THEN STRUCK B1 CAUSING B1 TO LAND ON THE	
644	37800342	3/14/2019	8:25:00 PM	2	NON- REPORTABLE	DARK-ROAD LIGHTED	WET	CLEAR	BACKING UNSAFELY	SOUTH	REAR END	MANDSHEEL TO WAS ARRED UNOCCUPED WITH THE RO OUTSIDE OF THE VEHICLE PUMPING GAS, VI WAS BACKING OUT FROM A PARKING SPOT AND STRUCK THE FRONT OF V2 CAUSING MINOR DAMAGE TO THE FRONT BUMPER OF V2 NEITHER VEHICLE WAS TOWED AND NOBODY REPORTED	-
645	37806043	3/18/2019	10:30:00 AM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLOUDY	DRIVER NATTENTION	NORTH		AND MINIDES. ON THE ABOY: NOTED DATE AND TIME IRESPONDED TO 1066 BAY STREET FOR THE REPORT OF A MOTOR VEHICLE ACCORDINATION THAT HAPPENED AT THE NITERSECTION OF UNION STREET AND E MAIN STREET AND STREET AND E MAIN STREET ACHIEM THE ADD (20) STATED THAT SHE WAS ON UNION STREET FACING SOUTH WHEN SHE SLOWED DOWN APPROACHING E MAIN STREET. (20) STATED DOWN APPROACHING E MAIN STREET. (20) STATED THAT SHE HELT ET AND STATED THAT SHE HIT HER BRAKES AND ATTEMPTED TO SWERVE AWAY FROM (VI). BUT THAT THE PASSENCE OF OF (10) SIDE SWIPP DIT DE DRIVER SOE DOO OF (10) SAR SWED STREET. 10 OSESERVED DAMAGE TO (VI) WHICH APPEARED CONSISTENT WITH THE THE ARE AND STREET WHEN THE STREET WAS NOT THE STREET.	2
646	37802972	3/18/2019	2:53:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLOUDY	DRMER NEXPERIENCE	NORTH	RIGHT ANGLE	approaching Cumberland St. D1 states she had a green light to proceed northbournd and weblied 2 eithers turned eastbourd in Front other or came from Cumberland St. In an eastbourd direction in font of her. D1 said vehicle 2 drove in front of her and he front of vehicle 1 struck he passergen side of vehicle 2. Vehicle 1 came to rest north of he intersection on North Clinton Ave and vehicle 2 came to rest facing southwest at the intersection. Dhiver 2 stated we was southbourd on North Clinton Ave andiversities of west southbourd on North Clinton Ave andiversities of west southbourd on North Clinton Ave walking to turn left to ge eastbourd onto Cumberland St. D2 stated she had a yellow light and began to turn the When vehicle 1 was official southwest and states of the states of	

TE 213 (9/79)

TE 213 (9/79)													
COUNTY:	MONROE		P.I.N.:	NOT APPLICAL	BLE	ROUTE NO. OI				CASE No.:			
	TOWN		•			ADJACENT RO					FILE		-
	VILLAGE OF	ROCHESTER			_	AT INTERSECT SEE MAP	TION WITH/OR	BETWEEN:			DATE:		
TIME PERIOD		FROM: 8/1/14	TO: 7/31/19	ENVIRONMEN Use Codes from at right) for these	n MV 104 (shown e categories	n 1. Daylight 1. Dry 1. 2. Dawn 2. Wet 2. 3. Muddy 3. 4. Dark Road Lighted 4. Snowlice 4. 5. Dark Road Unlighted 5. Slush 5.				Weather: 1. Clear 2. Cloudy 3. Rain 4. Snow 5. Sleeth Hall Frezzing Rain 6. Fog/Smog/Smoke			
No. OF MONTH	HS:	6	50	S					10. 00101		¹ Use Codes from	MV 104 Police Report	
CRASH No.	CASE No.	DATE	TIME	No. of VEHICLES	SEVERITY	CONDITIONS	ROADWAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING FACTORS	DIRECTION	TYPE ¹	DESCRIPTION	REFERENCE MARKER
647	37802945	3/22/2019	11:26:00 AM	2	PROPERTY DAMAGE AND INJURY	DAYLIGHT	DRY	CLOUDY	VIEW OBSTRUCTED/LIMITED	SOUTH	RIGHT ANGLE	IZ was WB on N Union St approaching he intersection on N Union and Haaga Alfune Loop Exit. Vit was enting of the hinter Loop on In Union St. Vz proceeded through the intersection and was not acring any raffic control devices. V1 was facing a stop sign but had a vehicle parked on the north side of N Union Stotsburdied by the driver Agaposs view of on coming raffic. V1 altempted to pull on the vither aciding so, colleded with V2 causing damage to the passenger side of V2 and the tont of V1. The driver of V2 stated that she was experiencing shoulder pain as a result of the accident. AMR responded and rearspoint the driver to Stong. Driver 1 shaled that he could not see V2 coming due to the vehicles parked along side of N Union St obstructing his view. Driver 1 reported no hightiss. The passenger of V2 reported neck pain and was harsported to Strong by AMR. The passenger of V1 reported no injuries. The passenger of V1 reported no injury the original variety and v1 reported no injury the	
648	37812806	3/25/2019	11:20:00 AM	2	PROPERTY DAMAGE AND	DAYLIGHT	DRY	CLEAR	UNSAFE LANE CHANGE	SOUTH	OVERTAKING		
649	37830209	3/25/2019	2:30:00 PM	2	PROPERTY DAMAGE AND INJURY	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	NORTH	REAR END	(VZ) saled ne was at ne red light at the intersection of usespin aver and Cumberland st, in a NB direction on Joseph ave, when he was struck from beinhig V(VI), (VZ) did so stated that the light had turned from red to green just before he was struck, (VI) controborated rhese events. Soft whetities were driveable. Passenger of (VZ) did complain of minor neck pain, however	
650	37812826	3/27/2019	11:55:00 AM	2	INJURY	DAYLIGHT	DRY	CLEAR	DRIVER INATTENTION	NORTH	REAR END	DAWR'T STAYES THAT AS HE APPROACHED THE NTERSECTION THE LIGHT WAS GREEN, BUT VEH 2 WAS STILL STOPPED IN TRAFFIC, AS VEH 1 GOT CLOSER TO THE INTERSECTION, VEH 2 STILL WAS NOT MOWNE. DAWREN ET STATES THAT THE LIGHT TURNED YELLOW AND VEH 2 BEGAN TO MOVE FORWARD THEN STOPPED. DRIVER 1 SAYS HE THOUGHT VEH 2 WAS GONG TO CONTINUE THROUGH THE INTERSECTION AND DID NOT REAUEZ VEH 2 STOPPED. VEH 1 STRUCK VEH 2 ORIVER 1 STATES HE WAS TRAVELING AROUND 10 MPH. DAWRER 2 STATED THAT HE WAS AT THE LIGHT WHEN VEH 1 STRUCK VEH 2 DRIVER 2 COMPLAINED OF BACK PAIN. DRIVER 2 DID NOT WANT TO WAIT FOR EINS TO ARRIVE	
651	37846162	4/2/2019	10:23:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	BACKING UNSAFELY	EAST	RIGHT ANGLE	AND STATED HE WOULD CHECK WITH A DOCTOR ON THE ABOVE DATE AND TIME, IRSEPONDED TO AN MAY ON 216 CUMBERLAND ST, WHEN I ARRIVED ON SCENE I SPOKE WITH DRIVER OF VOJ. SHE STATED THAT WHEN SHE WENT INSDE THE BULDING OF 216 CUMBERLAND ST, TO CONDUCT BUSINESS SINDE AND WHEN SHE RETURNED SHE OBSERVED DAMAGE TO HER VEHICLE. THE VEHICLE THAT HAD STRUCK HER CAR WAS NO LONGER AT THE LOCATION, OWAS NOT PARKED IN A DESIGNATED PARKING SPOT ALONG THE BUILDING, UZ STATED THAT SHE DID NOT REQUIRE ANY MEDICAL ATTENTION, I FILLED OUT A TECH SHEET WITH PHOTOS OF THE DAMAGE. AT THE LOCATION OF THE INCIDENT NO CAMERAS WERE NITH ARRAD THAT COULD OSSETIVE	
652	37833279	4/8/2019	12:45:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLOUDY	DRIVER INATTENTION	EAST	REAR END	v2 was stopped in Iraflic facing east on east main street at the inner loop intersection. v1 was traveling eastbound behind v2. v1 rear ended v2 and left the scene in an unknown direction, there is minor damage to the rear of v2 no initigies.	
653	37835731	4/11/2019	12:46:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLOUDY	FOLLOWING TOO CLOSELY, PASSING OR LANE USAGE IMPROPERLY	SOUTH	REAR END	D2 slated she was in the wrong lane white attempting to surn left of Allen St. When D2 realized she was the wrong lane, she tyl to correct the lane when V1 rear ended V2. D1 slated that V2 slowed down while changing lanes causing V1 to impact V2 in the rear. No injuries reported at the scene. Both vehicle were cared by numers.	
654	37847477	4/18/2019	7:13:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	BACKING UNSAFELY, TURNING IMPROPER	NORTH	OVERTAKING	heading NIE on Nimon Strepening to make a left turn onto the inner loop in close proximity by 1. VI continued backing and stark V28apos so where 8 possess die quater pannel. Boh VI and V2 were conducting routine part oi in their marked part of cars. Boh VI and V2 Saled that they missed their Wilb turn onto the inner loop and were attempting to re-enter a position to properly turn onto the roadway. VI was P65-Fleet #131306. V2 was P55- Fleet #131319. Where of the officer-8 poss. were injured. The MVA was low speed. Officer Tucker took pictures. (See Tech	

ΤE	213	(9/79)

TE 213 (9/79)								-					
COUNTY:	MONROE		P.I.N.:	NOT APPLICA	BLE	ROUTE NO. OF ADJACENT RO.					CASE No.		_
	TOWN CITY					AT INTERSECT					FILE: BY:		-
	VILLAGE OF	ROCHESTER			-	SEE MAP	non without	DETWEEN.			DATE		-
TIME PERIOD		FROM: 8/1/14	TO: 7/31/19	ENVIRONMEN Use Codes from at right) for these	MV 104 (shown e categories	Light Conditions: 1. Daylight 2. Dawn 3. Dusk 4. Dark Road Lighted 5. Dark Road Unlighted		Roadway Surfa 1. Dry 2. Wet 3. Muddy 4. Snow/Ice 5. Slush 10. Other	te Condilion: Weather: 1. Clear 2. Cloudy 3. Rain 4. Snow 5. Sleet/Hail/Fre 6. Fog/Smog/Sn 10. Other				
No. OF MONTH	HS:	(50	LES								MV 104 Police Report	
CRASH No.	CASE No.	DATE	TIME	No. of VEHICLES	SEVERITY	CONDITIONS	ROADWAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING FACTORS	DIRECTION	TYPE ¹	DESCRIPTION VI WAS TRAVELING WESTBOUND ON E. MAIN STREET	REFERENCE MARKER
655	37847830	4/21/2019	8:53:00 PM	3	PROPERTY DAMAGE AND INJURY	DARK-ROAD LIGHTED	DRY	CLEAR	TRAFFIC CONTROL DEVICES DISREGARDED	WEST	OTHER	APPROACHING THE UNIVERSITY AVE / INNER LOOP INTERSECTION. V2 WAS TRAVELING NORTHBOUND ON UNIVERSITY AVE APPROACHING THE E. MAIN STREET INTERSECTION ATTEMPTING TO GET ON THE INTER LOOP AS WAS TRAVELING SOUTHBOUND ON THE INNER LOOP AS WAS TRAVELING SOUTHBOUND ON THE INNER LOOP AS WAS TRAVELING SOUTHBOUND ON THE INTERSECTION ATTEMPTING TO MAKE A LEFT TURN ONTO E. MAIN STREET INTERSECTION ATTEMPTING TO MAKE A LEFT TURN ONTO E. MAIN STREET INTERSECTION, THE TRAFFE LIGHT HE WAS FACING TURNED FROM YELOUTO RED AND THEN HE CAME TO A STOP, V2 SAID SHE WAS FACING A GREEN TRAFFE. LIGHT AND PROCEEDED TO ENTER THE INTERSECTION TO GET ONTO THE ENNER LOOP. V1 SAID SHE WAS FACING A GREEN TRAFFE. LIGHT AND PROCEEDED TO ENTER THE INTERSECTION OF A STOP, V2 SAID SHE WAS FACING A GREEN TRAFFE. LIGHT AND PROCEEDED TO ENTER THE INTERSECTION OF THE ENNER LOOP. V1 SAID SHE WAS FACING A GREEN TRAFFE. LIGHT AND PROCEEDED TO ENTER THE INTERSECTION OF A THE SAME TIME. V1 COLLIDED WITH V2 CAUSING V2 TO COLLIDE WITH V3 THREE WITHSESSES ON THE SCENE STATED TO ME THAT V1 RAN A RED LIGHT AND HIT V2 AND LOT THE SAME THE V1 COLLIDED WITH V2 WITH A WAS AND HIT V2 AND CAUSING V2 TO COLLIDE WITH V3 WAS AND HIT V2 AND CAUSING V2 TO COLLIDE WITH V3 WAS AND HIT V2 AND CAUSING V2 TO COLLIDE WITH V3 WAS AND HIT WAS AND HIT V3 WAS AND HIT WAS	
656	37868025	4/24/2019	10:57:00 AM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	BACKING UNSAFELY	WEST	REAR END	The driver of both vehicle 1 and 2 were parked in a Della Sonic parking lot Both vehicle 1 and 2 were backing out of their parking spots at the same time. Both drivers claimed that hey had the right of way. Both vehicle 1 and 2 backed into each other. The accident was very minor and no persons were injured in this accident.	
657	37862880	4/25/2019	1:09:00 AM	1	NON- REPORTABLE	DARK-ROAD LIGHTED	DRY	CLEAR	UNSAFE SPEED	EAST	OTHER	Idd conduct a traffic step on the above vehicle for having its head lamps of and driving. VI Was occupied by a male black driver and passenger. The vehicle did fee the traffic step, Iddi not chase the vehicle due to the chase not meeting RPDs chase policy. Shortly after a officer Sanfago observed VI parked and unoccupied. Both the driver and passenger were scene feeing the scene. VI did strike a out on I Lyndhurst st causing damage to the forth driver stop the man of the traffic strike the scene of the scene stop the scene of the scene of the scene of the scene strike the and rim. The traws fall this was caused by the other of VI driving at a high rate of speed. Lyndhurst SI is also a one-way street. VI was driving against the one-way. Photos of the scene and vehicle were sleave. No or by camera is in the area.	
658	37856140	4/26/2019	11:21:00 AM	2	PROPERTY DAMAGE AND INJURY	DAYLIGHT	WET	RAIN	DRIVER INATTENTION	SOUTH	LEFT TURN (AGAINST OTHER CAR)	heh 1 was traveling straightsouth on union st. 1 Veh 2 was traveling north on union st. Veh 2 bailed to yield the right-of-way and attempted to make a lelf hand furn in front veh 1. The two vehs struck causing damage and injury. 1 withess no cameras WITMESS 1 FLYNN, ELLAH M 812 GRAND AVE ROCHESTER WY MANDROOM DESCRIPTION.	
659	37857970	4/28/2019	5:11:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	UNSAFE LANE CHANGE	SOUTH	OVERTAKING	NAY 1,600,0000 SES 23(14.72) *Yet I slowing South on Cumberland at St. Paul Blvd in left hand turn lane. V-2 slowing South on Cumberland at St. Paul Blvd in straight lane. Driver&aposs of each vehicle claim that the other vehicle came into poposite lane striking other vehicle causing downance. Mo filtrides reported	
660	37888766	4/30/2019	1:52:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	PASSING TOO CLOSELY	SOUTH	OVERTAKING		
661	37888692	5/1/2019	10:11:00 AM	1	PROPERTY DAMAGE	DAYLIGHT	WET	CLOUDY	TRAFFIC CONTROL DEVICES DISREGARDED	NORTH	OTHER	THE OTHER OF VESTALED MATTE WAS TAVELING WEST DOOR OF E. WAIN	
662	37877623	5/5/2019	7:55:00 PM	2	PROPERTY DAMAGE AND NJURY	DAYLIGHT	DRY	CLEAR	TRAFFIC CONTROL DEVICES DISREGARDED	WEST	OTHER	St. As he approached the intersection at University Avr UD Inner Loop he believed his light was still green? As VI OD Inner Loop he believed his light was still green? As VI OD Inner Loop he believed his light was still green? As VI OD Inner Loop he believed his light was still green? As VI OD Inner Loop he light he seemed to the still he seemed any inquiries. The driver of VI2 Stabed hat she was traveling north bound on University Ava and lempted he to was fraveling north bound on University Ava and lempted he to was fraveling north bound on University Ava and lempted he to was the seemed and lempted to continue, simultaneously VI was traveling west bound. The said collision occurred. The driver of VI2 complained of pain to he left arm. She was transported to Strong Memorial hospital via AMIR gray 73 PV. VI was breed privately VI2 was breed via Police. (W) stated that she was in the lane just north of VI1. While she was at his intersection she boseved that the light was red for west bound raffic. She then observed VI1 vavel brought it with he said collision courring "PER THE AMENDMENT." Passenger two was also seen all Strong Hospital for lover back pain. An asterisk was placed next to mended and fasts. Changes were made on diagram per V2.	

TE 213 (9/79)

TE 213 (9/79)						ROUTE NO. OF	O CTDEET NAM	ır.							
	MONROE		P.I.N.:	NOT APPLICAL	BLE	ADJACENT RO					CASE No.:		_		
	TOWN CITY					AT INTERSECT					FILE:	PSC 5/13/2020	-		
	VILLAGE OF	ROCHESTER	!		_	SEE MAP					DATE	5/13/2020	-		
TIME PERIOD	Use Codes from MV 104 (st at right) for these categories				n MV 104 (shown e categories	Light Conditions: Roadway Suface Condition: Weather:									
No. OF MONTH	IS:	(50	ES							¹ Use Codes from	MV 104 Police Report			
CRASH No.	CASE No.	DATE	TIME	No. of VEHICLES	SEVERITY	CONDITIONS	ROADWAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING FACTORS	DIRECTION	TYPE ¹	DESCRIPTION	REFERENCE MARKER		
663	37880892	5/6/2019	12:15:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	UNSAFE LANE CHANGE	EAST	OVERTAKING	Weihie 2 was parked on the on Cumberland st lesing eastbound on the south side of the road uncought. Which it is a large backet truck owned by the City of Rochester. Weikie 1 was eastbound on Cumberland st approaching the intersection of Clinton avenue. Vehicle 1 alternipted to pull introd of Weihide 2 to entire a particed position. Weihide 1 turned to sharply and the rear causing damage. Driver of weihide 1 informed his supervisor. Teresa McEritee. Accident occurred on 05-66-19 and was being reported to RPD on 05-14-19. McEritee stated she documented in incident that day and was informed alter that they needed a police report. McEritee body choics of the demanded a police report. McEritee body choics of the demanded had been supported.			
664	37880832	5/11/2019	11:48:00 AM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	FALURE TO YIELD RIGHT OF WAY	EAST	RIGHT ANGLE	WHERE IT INTERSECTS WITH UNIVERSITY AVE. V2 WAS TRAVELING NB ON UNIVERSITY AVE APPROACHING WHERE IT INTERSECTS WITH E MAIN ST. DRIVER OF VI STATED THAT HE SAW THE GREEN ARROW AND MISTOOD IT AS A GREEN LICHT AND PROCEEDED THROUGH THE RED LICHT STRIKING V2 AS SHE HAD THE GREEN LICHT.			
665	37888725	5/13/2019	8:01:00 AM	2	NON- REPORTABLE	DAYLIGHT	WET	RAIN	FAILURE TO YIELD RIGHT OF WAY	SOUTH	SIDESWIPE	NAME AND A SECTION AND A SECTI			
666	37895972	5/21/2019	11:58:00 PM	1	NON- REPORTABLE	DARK-ROAD LIGHTED	DRY	CLEAR	PEDESTRIAN'S ERRORICONFUSION	EAST	OTHER	led rations in \$10th struck the 1921's field in orange. (1901 is no immerce year.) Cly of Rochester and vas operated by an employee of the Rochester Police Department, Olicer M. Williams. So: Williams was responding to an emergency at 672 E Mains St. Vehicle 1 was operating eastbound on Cumberland St at the intersection of Cumberland St and Joseph Ave when it struck Unit 2. Vehicle 1 on Cumberland St and Joseph Ave when it struck Unit 2. Vehicle 1 on Cumberland St. Unit 2 was a bioydist haveling northbound on the east side of Joseph Ave, crossing the intersection of Cumberland St. Unit 2 was a bioydist haveling northbound on the east side of Joseph Ave, crossing the intersection of Cumberland St. Unit 2 was a bioydist haveling northbound on the east side of Joseph Ave, crossing the intersection of Cumberland Tallic. Vehicle 1 sussished mitter of dampe to the forth tumper from the rear peg of Unit 2 as that was the cort glipt for method unit 12 did not sustain any damage. The driver of Unit 2 stated that he was not injured, as the accident did not case him to fall of of his bioyde. The driver of Unit 2 stated that he did not see the red light due to him looking at the green light one steet north of the intersection. The driver of Unit 2 stated for running a red light (1111 (dr)). I took photographs with my BWC. Tech Minchela responded and both photographs as was WITINESS 1.			
667	37901547	5/24/2019	3:27:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	FAILURE TO YIELD RIGHT OF WAY	NORTH	RIGHT ANGLE	100000000000000000000000000000000000000			
668	37903708	5/24/2019	9:02:00 PM	2	PROPERTY DAMAGE AND INJURY	DARK-ROAD LIGHTED	DRY	CLOUDY	FALURE TO YIELD RIGHT OF WAY	NORTH	RIGHT ANGLE	If was a twenty no on Linton Ave. Yz was sheening sto on Clinton Ave making a leit hand lum on to Cumberland St. Vz Lumed in fort of VI causing VI to shike Vz. Vz had compilaint of neck and head pain and was taken to Highland Hospila by AMR (799). Drive of VI had head pain and was taken to Strong Hospilal by AMR (7389). The passenger of VI had neck and head pain and was taken to Strong Hospila (Brighten rig 3069). Both prey beautiful part bright.			
669	37908151	5/29/2019	8:30:00 AM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLOUDY	FAILURE TO YIELD RIGHT OF WAY	NORTH-WEST	RIGHT TURN (AGAINST OTHER CAR)	Avenue. V-2 was parked in the median of N. Plymouth Ave., north of the Allen St. Intersection. V-2 pulled out of the median and merged into the northbound lane into the path of V-1, striking the drivers arons side.	1		
670	37913270	5/30/2019	4:49:00 PM	1	PROPERTY DAMAGE	DAYLIGHT	DRY	CLOUDY	ILLNESS	NORTH-EAST	OTHER	VI WAS HEADING IN BUT ONIVERSHIT YAF HEADING TO THE DAMED CALL SSUE AND LOST CONTROL OF VI STARTED HEADING NORTHEAST ONTO THE CUBE BAID INTO A BEAR BY BENCH VI CAME TO REST ON E MAIN ST FACING EIB DORKEF WAS NOT NUJURED BUT WAS TAKE TO STRONG WITH STARTED TO STRONG WITH STAR			
671	37945510	6/22/2019	6:08:00 PM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	NORTH-WEST	REAR END	vi was vest oit it ast wait is streetly pullwork by V. v. Vi atempted to be for a pediestrian in the crosswalk. V.2 which was following too closely failed to slow and struck the rear passenger side of VI causing minor damage to same. No damage observed to V.2. The operator of V2 admitted he was looking the other direction when the accident happened. Both unablished about forms cross. No includes reported.)		
672	37946890	6/24/2019	1:34:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLOUDY	DRIVER INATTENTION	NORTH	RIGHT ANGLE	THE ACCIDENT OCCURRED IN A POLICE VEHICLE			
673	37981802	6/27/2019	11:12:00 PM	2	PROPERTY DAMAGE AND INJURY	DARK-ROAD LIGHTED	DRY	CLEAR	OTHER (VEHICLE)	WEST	RIGHT ANGLE	OWNEDIOPERATED BY THE ROCHESTER POLICE DEPARTMENT WHILE RESPONDING TO AN EMERGENCY. OFFICER LINDAIRE WAS OPERATING VI. VI WAS TRAVELING WAS TRAVELING BOO UNIMPRESTIV VI STATED THAT THE TRAFFIC LIGHT HAD TURNED FROM VI HAD HIS EMERGENCY LIGHTS ACTIVATED. VI STATED THAT THE HEAD THE GREEN LIGHT AND DO NOT SET EMERGENCY LIGHTS AND THAT IS WHY HE PROCEEDED NIO THE WIFERSECTION CAUSING VI TO STRIKE VI. NO NUMERS. VI WAS TOWED FROM THE SCENE. VI HAD DAMAGE TO THE LEFT FRONT SIDE AND CORREC OF THE BUMPER ALSO, A BROKEN LEFT HEADLIGHT AND THE AR BAGS DEPLOYED. VI. HAD DAMAGE TO THE RIGHT FRONT SIDE BY THE FRONT TISCH WHELL AND THE AR BAGS DEPLOYED. VI. HAD DAMAGE TO THE RIGHT FRONT SIDE BY THE FRONT TISCH WHELL A DRIVER EXCHANGE FORM WAS PROVIDED ON SCENE PICTURES.			

TE	212	(0/70)

TE 213 (9/79)													
	MONROE P.I.N.: NOT APPLICABLE TOWN					ROUTE NO. OR STREET NAME: ADJACENT ROADWAY NETWORK					CASE No.: FILE:		
	CITY VILLAGE OF	ROCHESTER	!		_	AT INTERSECTION WITH/OR BETWEEN: SEE MAP					FILE: BY: PSC DATE: 5/13/2020		- - -
TIME PERIOD				ENVIRONMEN Use Codes from at right) for these	n MV 104 (shown	Light Conditions: Roadway Surface (1. Daylight 1. Dry 2. Dawn 2. Wel 3. Dusk 4. Dark Road Lighted 4. Snowlice 5. Dark Road Unlighted 5. Dork Dark Road Unlighted 10. Other			e Condition: Weather: 1. Clear 2. Cloudy 3. Rain 4. Snow 5. Sleet/Hall/Freezing Rain 6. Fog/Smog/Smoke 10. Other				
No. OF MONTH	IS:		50	10		10. Omer					¹Use Codes from	MV 104 Police Report	
CRASH No.	CASE No.	DATE	TIME	No. of VEHICLES	SEVERITY	CONDITIONS	ROAD WAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING FACTORS	DIRECTION	TYPE ¹	DESCRIPTION	REFERENCE MARKER
674	37971548	7/2/2019	1:58:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	FOLLOWING TOO CLOSELY	NORTH	REAR END	IZ WAS STOPPED AT ROUTE. MORE INBOUND DATABORN INCLINION AND WAITING AT A RED LIGHT. VI WAS DIRECTLY BEHIND V2 AND VI FRONT END STRUCK V2 REAR END CAUSING MINOR DAMAGE TO V2. DRIVER 2 GOT OUT OF THE VEHICLE TO CHECK ON DAMAGE AND STATES THAT VI BACKED UP, TURNED AROUND AND LETT THE SCENE COMES COUTH ON NORTH CLUNTOD, DRIVER 2 STATES THAT SHE SAW A MALE DRIVER AND FEMALE PASSENGER IN VI. NO NUIVIES REPORTED - WITNESS TO PORS OTH MEMORY SAFENDERS OF THE MEMORY	
675	37978728	7/13/2019	12:06:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	TRAFFIC CONTROL DEVICES DISREGARDED	NORTH	RIGHT TURN (AGAINST OTHER CAR)	WIB ON UNIVERSITY AVE. DRIVER OF VI. STATES THAT SHE ACCIDENTALLY WENT THROUGH A BED LIGHT AT THE NITERS CETON OF UNIVERSITY AVEN UNION ST AND STRUCK VIZ. DRIVER OF VIZ. SAID THAT SHE HAD A GREEN LIGHT WHILE SHE WAS DRIVING THROUGH THE INTERSECTION. DAMAGE WAS DONE TO THE DRIVERS SIDE FRONT BUMPER AND QUARTER PANEL OF VIZ. VZ WAS CARED FOR BY OWNER AND TOWED BY AAA. VI WAS ABLE TO BE DRIVEN AWAY FROM THE SCENE. NO.	;
676	37995549	7/15/2019	10:16:00 AM	2	NON- REPORTABLE	DAYLIGHT	DRY	CLEAR	PASSING OR LANE USAGE IMPROPERLY	EAST	OVERTAKING	INJ S AUNITED STATES PASTAL TRICK AND WAS ON THE NINEE LOOP OF FRAMIT PRAYELING EIR PASSING THROUGH THE TRAFFIC LIGHT, (VZ) WAS IN THE LANE TO CONTINUE TO TRAVEL STRAGHT THOUGHT THE INTERSECTION OF ST PAUL ST ONTO CUMBERCAND. (VI) WAS TO THE TO THE LEFT OF (VZ) ALSO TRAVELING EIR THROUGHT HE INTERSECTION IN THE LANE MARKED TO TURN LEFT OR GO STRAGHT AND CONTINUED STRAGHT ONTO CUMBERLAND. AS THE VEHICLES PASSED THROUGHT HE INTERSECTION ONTO CUMBERLAND, (DZ) STATES THAT (VI) WAS SIGHTLY AREAD OF HIM AND ATTEMPTED TO TRAVEL INTO HIS LANE CAUSING THE RIGHT SDIE GLASS PANEL OF (VI) TO MAKE CONTACT WITH THE LEFT SED MIRROR OF (VZ) (DI) STATES THAT (VZ) ENTERED HIS LANE. NO WITNESS ON SCENE.	
677	37978749	7/15/2019	1:00:00 PM	2	PROPERTY DAMAGE AND NJURY	DAYLIGHT	DRY	CLEAR	FALURE TO YIELD RIGHT OF WAY	SOUTH	RIGHT ANGLE	Direct 2 sheld she was northbound on Union SI swalling to burn let tool University Me. Driver 2 said she had a green light and saw whiche 1 north of her, approaching in a southern direction. Driver 2 sheld as she burned, vehicle 1 struck he front of her vehicle. Driver 2 sheld as she burned, vehicle 1 struck he front of her vehicle. Driver 2 sheld was southbound on Union SI approaching University Ave. Driver 1 said whele 2 bages in burn in tool of him and he applied his front brake lo slow down. Driver 1 said he local and struck vehicle 2 as a burned. Driver 1 said whele 2 bages in burn in tool of him and he applied his front brake lo slow down. Driver 1 said he could not slow down in time and struck vehicle 2 as a burned. Driver 1 was selected from the motorycle and landed on he southwest area of he intersection. Driver 1 did have a helmet on. Withess 1 stated north and southbound tratific had a green light. Withess 1 stated he hought vehicle 1 sped up as it approached he intersection in a southbound direction but had no further information at he time. Driver 1 was belon byton drivers had no further information at he time. Driver 1 was been b Strong Hospilal via ANIR #7899 with compaint of pain byton and next Powline 2 arisage deployed. No other liquires besteved or complained of. No cly cameras. RPD on scene. Both vehicles 2 browd by John &.	
678	38015278	7/18/2019	12:55:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	PASSING OR LANE USAGE IMPROPERLY	EAST	OVERTAKING	(W) DEPARTED BY (D) AND (W) DEPARTED BY (D); WERE MANNE A LEFTHAND TURN FROM THE NWERLOOP ONTO E MAN ST TRAVELING EASTBOUND, (VI) WAS IN HE OUTER LANE AND CUIT TO FAR INTO THE INTEROR LANE WHEN MAKING THE TURN ONTO E MAN ST, STRKING (V) ANIO CAUSING THE ABOVE-LISTED DAMAGE. MEITHER DRIVER OR THE ONE PASSENGER HAD ANY VISBLE SIGNS OF RUJRY AND REFUSED MEDICAL TREATMENT AT THE SCENE. BOTH VHEHICLES WERE DRIVEN FROM THE SCENE BY THEIR RESPECTIVE	

TE 213 (9/79)														
COUNTY:	MONROE P.I.N.: NOT APPLICABLE TOWN					ROUTE NO. OR STREET NAME: ADJACENT ROADWAY NETWORK					CASE No.: FILE: BY: PSC DATE: 5/13/2020			
	VILLAGE OF	ROCHESTER	ROCHESTER				AT INTERSECTION WITH/OR BETWEEN: SEE MAP					BY: PSC DATE: 5/13/2020		
TIME PERIOD				ENVIRONMEN Use Codes from at right) for these	MV 104 (shown	Light Conditions 1. Daylight 2. Dawn 3. Dusk 4. Dark Road Li 5. Dark Road U	ghted	Roadway Surface Condition:						
No. OF MONT	HS:		50	S							¹ Use Codes from MV 104 Police Report			
CRASH No.	CASE No.	DATE	TIME	No. of VEHICLES	SEVERITY	CONDITIONS	ROADWAY SURFACE CONDITION	WEATHER	APPARENT CONTRIBUTING FACTORS	DIRECTION	TYPE ¹	DESCRIPTION	REFERENCE MARKER	
679	38005501	7/19/2019	7:00:00 AM	1	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	DRIVER INATTENTION	SOUTH	OTHER	JULY WIS OPERATING SOUTHBOURD ON SAMIT PAUL. STREET ON THE WEST SIDE OF STREET CROSSING THE MTERSECTION OF CUMBERLAND STREET AND SAMIT PAUL STREET VI WAS ON CUMBERLAND STREET TURNING RIGHT ONTO SAMIT PAUL. STREET WHEN SHE TURNED IN FRONT OF UZ UZ STATED THAT VI DID NOT STOP WHELE HE WAS PASSING IN FRONT OF HER AND HER NEILLE HAD HIT HIS BIKE CAUSING HIM TO GET OFF HER SIEK. UZ STATED THAT HE WAS NOT HURT AND DI HAD GOTTEN OUT OF HER CAR AND ASKED HIM FHE WAS OKAY DILETTED THAT HE WAS NOT HURT AND DI HAD GOTTEN OUT OF HER CAR AND ASKED HIM FHE WAS OKAY DILETT HES SCIEN WITHOUT GOWING UZ ANY OF HER INFORMATION. UZ SAID THAT A PART OF VIABIPOS PORTER SDE BILMPER THAD FALLEN OF FAND HE GAVE DITHE PIECE BACK. UZ CONTINUED ON HIS WAY. WI STATED THAT IS WE WAS OPERATING HER VEHICLE ON CUMBERLAND STREET WHEN SHE SAMI VI TURN INTO UZ. WI SAID THAT IT WAS A RED LIGHT AT THE NERSECTION AND THAT VID DON'S TOP AND THAT IT ONLY SLOWED DOWN A LITTLE BEFORE SHE TURNED. WI THE WAS OKAY BUT SHE THEN LEFT. WI TOOK A PHOTO OF VI THAT HAD A NEWY ORK LICENSE PLATE HER HER SEC. THAT COMES BACK TO A ERRAY 2010 CHEVROLET MPALA. REGISTERED TO A ENEVES, JEFFREY D. D. BIT/791 IAT OR WAS LIVEN SEN VAN DELIVEN THEN LEFT. VID TOOK FAFE TO REH AFTER HIS MOTHER FOUND OUT TO CHECK FOR ANY NULRES. UWAS DESCHARGED WITHOUT ANY NULRIES. SULWS DESCHARGED WITHOUT ANY NULRIES. UWAS DEDCESSEDE WITHOUT ANY NULRIES. UWAS DEDCESSEDE WITHOUT ANY NULRIES. UWAS DESCHARGED WITHOUT ANY NULRIES. SULWS SIDDESSES HER DUT ON DESTANCE OF THE PREME SECTION OF WITHOUT ON THE TOOL TO CHECK FOR ANY NULRIES. UWAS DESCHARGED WITHOUT ANY NULRIES. SAUDDESSES ALT WITHOUT SOLD THE TOOL TOOL THE COME.		
680	37995621	7/20/2019	1:38:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	TURNING IMPROPER	EAST	OVERTAKING	(V2) WAS TRAVELING EIR ON CUMBERLAND ST FROM THE NNER LOOP OFF RAMP N THE LEFT TURN LANE TO TURN LEFT OWNTOS TPAUL. (V1) WAS TRAVELING N THE SAME DIRECTION ON CUBMBERLAND N THE LANE TO THE RIGHT OF (V2) V20 MADE THE LEFT TURN TO SHARP AND THE LEFT SIDE OF (V1) STRUCK THE RIGHT FRONT OF (V2) CAUSING DAMAGE. (V1) THEN LEFT THE SCENE WITHOUT STOPPON. (V1) WAS DESCRIBED AS A SMALL RED SEDAN BY (D2) AND (W), (W) WAS ABLE TO GET A COOD PLATE THAT MACHCHED THE DESCREPTION. HOWEVER (V1) WAS NOT LOCATED.		
681	37994725	7/24/2019	2:48:00 PM	2	PROPERTY DAMAGE	DAYLIGHT	DRY	CLEAR	DRIVER INATTENTION	NORTH	OVERTAKING	North Stin the far left (west) lane and V2 was also travelling north in the right (east) lane. The operator of V1 claimed that he was unware that he 2 hans would meep as he was travelling. The operator of V1 claimed, when the left and right lane merged, he struck the left side of V2 with his right side causing damages to the same. The operator of V2 gam he same recollection of the accident as the operator of V1. There were no injuries reported at		
682	38001046	7/28/2019	1:34:00 PM	2	PROPERTY DAMAGE AND INJURY	DAYLIGHT	DRY	CLOUDY	UNSAFE LANE CHANGE	EAST	OVERTAKING	WITHCE THIS SEASTOUND ON SERVICE. INDIVINATION IN THE FAR LEFT LANE. VEHICLE 2 ALSO E ASTBOUND ENTERED VEHICLE 1-RADROS SLAVE AND STRUCK VEHICLE- I ON THE RIGHT-FRONT PANEL. VEHICLE-I CONTINUED TO NORTH SDE OF RODA AND STRUCK CURB CAUGE DAMAGE TO FRONT-LEFT TIRE. OPERATOR OF VEHICLE-I STATED THAT HE MANITAINED HIS LANE THE ENTIRE THIS. OPERATOR OF VEHICLE 2 STATED THAT HE BELEVED IT WAS SAFE TO CHANGE LANES AND THAT HIS SERVED ON HIS LEFT LINEMINED WESTER CAND.		